RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R92-00171

INITIAL	CUSTOMER ORDER NO.
FPS-	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/23/91	01/03/92	CI 4-88	C6244905		700 280 REM MTN

ACCESSORIES W/STUDS SCOPE BASE

FROM:
WEAKNECHT SPTG GOODS
802 S 4TH STREET
P O BOX 434
HAMBURG PA 19526
USA

SHIP TO:
WEAKNECHT SPTG GOODS
802 S 4TH STREET
P O BOX 434
HAMBURG PA
USA 19526

CUST NO:038886 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		1-16-92	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	Gun fires when you take safety off					
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT Unable to duplicate complaint, however, disassembly of rifle revealed inside of trigger assembly contains sand and internal parts are not moving freely. Further examination of underside of action revealed more dirt (including sand and sand). Apparently, rifle has been set at some time and was not properly maintained.

Trigger pull 5 pounds; sear-off .010"

PARTS

COMMENTS Offer replacement trigger assembly at ≠ normal cost as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
DE					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91