OPERATIONS

12

T.	OP. No.	OPERATION	DEPT.
	28.	Inspect hardness	51
	32.	Black Oxide	79
9	34-S	Torch Draw to permit adjusting.	51
	~~33V.~~	~~Torch draw to permit adjustment of Lever Arm (Expires 9/6/74) (Part #26585 only) (20,000 pcs.)~~	~~51~~
9	~~35V.~~	~~Gage Safety (19,180 pcs. only) (Expires 12/13/74) To [illegible]~~	~~62~~
9	~~37V~~	~~Torch Draw to permit adjustment (50% pcs. only) (Expires 12/13/74)~~	~~51~~
	~~38V.~~	~~Adjust Lever Arm to gage (50% only) (Expires 12/13/74)~~	~~79~~
		To Dispatch Area -	

DATES AND REASONS FOR REVISIONS

12/13/74 - Add 34-S - Prosser - 273497

ly PAGE 1 OF 1

2900
00 LH