M-700 TRIGGER HOUSING 11-30-78 KLB

Serial No.	Safety Lock	Safety Lock	Safety Lock	Safety Lock	Safety Lock	Safety Lock
1	OK	OK	OK	OK	OK	OK
2	OK	OK	OK	OK	OK	OK
3	OK	OK	OK	OK	OK	OK
4	OK	OK	OK	OK	OK	OK
5	OK	OK	OK	OK	OK	OK
6	OK	OK	OK	OK	OK	OK
7	OK	OK	OK	OK	OK	OK
8	OK	OK	OK	OK	OK	OK
9	OK	OK	OK	OK	OK	OK
10	OK	OK	OK	OK	OK	OK
11	OK	OK	OK	OK	OK	OK
12	OK	OK	OK	OK	OK	OK
13	OK	OK	OK	OK	OK	OK
14	OK	OK	OK	OK	OK	OK
15	OK	OK	OK	OK	OK	OK
16	OK	OK	OK	OK	OK	OK
17	OK	OK	OK	OK	OK	OK
18	OK	OK	OK	OK	OK	OK
19	OK	OK	OK	OK	OK	OK
20	OK	OK	OK	OK	OK	OK
21	OK	OK	OK	OK	OK	OK
22	OK	OK	OK	OK	OK	OK
23	OK	OK	OK	OK	OK	OK
24	OK	OK	OK	OK	OK	OK
25	OK	OK	OK	OK	OK	OK
26	OK	OK	OK	OK	OK	OK
27	OK	OK	OK	OK	OK	OK
28	OK	OK	OK	OK	OK	OK
29	OK	OK	OK	OK	OK	OK
30	OK	OK	OK	OK	OK	OK

Fails - .005 Shim will not pass between connector & Stock

Fails - Firing Pin Head will fall when Safety Released
OK - Firing Pin Head will not fall when Safety Released

30 Rifles Audited
22 "failures"

.22
÷30
.73% failure rate

CONFIDENTIAL-SUBJECT TO PROTECTIVE ORDER
KINZER V. REMINGTON

47 1323

K+E

R2549053