Model 722 .257 cal.

Date 6-8-48

Lowe Gentner Dipper

F.T. No.	Rounds Fired	Malfunctions: Firing	Unlocking	Primary Extraction	Secondary Extraction	Ejection	Cocking	Feeding	Loading	Locking	Breakages	Replacements	Gun Failures	Adjustments	Remarks
															Gun # 33630
	0 - 20	OK													#532
	21 - 40	OK													"
	41 - 60							1							override 3rd shell - slow R 85
	61 - 80							1							" " " " "
								1							" " medium
	81 - 100							1							" " slow (Western 80-[illegible]
						1									2nd & 3rd shell
	101 - 120							1							override 3rd shell slow (Western 80-[illegible]
	121 - 140	OK													(Western 80-[illegible]
	141 - 160	OK													
	161 - 180							1							override 3rd shell #5325
	181 - 200	1													hang-fire Wm K250
								1							override 3rd shell - slow