Model 722 .257 Cal

Date 6/11

ZOLLER Gun # 33647

S.T. No.	Rounds Fired	Firing	Unlocking	Primary Extraction	Secondary Extraction	Ejection	Cocking	Feeding	Loading	Locking	Breakages	Replacements	Gun Failures	Adjustments	Remarks
															with K1701C
	1 - 20	OK													Bolt overrides last Rd
	21 - 40							11							SS
	41 - 60							1							on R85- Fast bolt overriding causing stem chamber last rd
	61 - 80							1							S
	81 - 100							11							with K2505C
	101 - 120							11							11 SS 11 with K1482C
	121 - 140							111							SSS K1483C
	141 - 160							1							F 5325-
	161 - 180							11				BOLR			(By pulling bolt back slow
	181 - 200							1					11		bolt overrides most every time on all 3 guns)