BARBER - PRESALE R 0101512

V. Gilbert King 11-7-60

Model 721 - 722 Change to Model 700 Suggested changes to be made in 1961 Barrel, Receiver and Stock production

Receiver
1. Change Hang cut hole in 721-722 - this would require a change in sanding in 721-722 Stocks
2. Omit Bolt Stop Pin hole and change to 1 hole on Bolt Stop Pin hole - Requires new Bolt Stop Spring
3. Round corners of tang

This also affects in slot-X

Barrel
1. Increase OD at muzzle of Barrel .020" - per [illegible] this would not affect Stocks
2. Barrel lenght change

Remington table in Sales Dept of 7-2-60
- 30-06
- 280 Rem
- 270 Win
- 308 Win
- 243 Win

Reduce Barrel lenght from 22" to 20"

- 300 H&H

Remains the same as at present 24" - large OD Barrel

Commercial Sp. bbl. Short Action
- 222 Rem
- 222 Mag

Suggested that Model 700 to change from large OD to standard
Reduce Barrel from 24" to 20"

Other changes that possibly could be made during 1961 to models 721-722

Safety
1. Improve function - no visual change

Changes to be made for Model 700 introduction

Stock
5 Types
1 A and AJL Long Action - 2
3 A and AJL Short Action - 4
5 AJL Mag - Medium Barrel, long action

Bolt Handle
This change also affects the inside of 40X

TRIG. Gd. ~~Floor Plate~~ and Trigger
This change also affects the inside of 40X

Write-off Some of 725 Stocks this year?

CONFIDENTIAL-SUBJECT TO PROTECTIVE ORDER
KINZER V. REMINGTON

BARBER - PRESALE R 0101512

R2502500