[redacted]CE CENTERFIRE

Field Function

REPROT NO.: 832281 PAGE NO. 5

DATE: MODEL: 700 BDL CAL. GAUGE: 30/06 SERIAL NO.

PREVIOUS ROUNDS

TEST TITLE: CHROME PLATED W/700 INJECTION MOLDED FOLLOWER EVAL.

TTL. RDS. FIRED:
TTL. MALFUNCTIONS:
MALFUNCTION RATE:

"MALFUNCTIONS"

AMMUNITION Load Size	SHOOTER	NO. OF ROUNDS FIRED	FAILED	FAILED CONTROL	FAILED EJECT	FAILED EXTRACT	FAILED FEED	FEED FROM MAG. 1st LATCH	FEED FROM MAG. 2nd LATCH	SHELL STICKS MAG.	POWER OVERRIDE	FAILED TO FEED	STEM CHAMBER BOLT	STEM CHAMBER BOLT	STEM CHAMBER BOLT	STEM CHAMBER BOLT	SHELL JUMPS MAG.	FOLLOWER BINDS	LOADING	BOLT OVERRIDE	FAILED TO FIRE	COCKED & DROP	SEPARATE	ADJUSTMENTS	REPLACEMENTS	BOLT MALFUNCTIONS	REMARKS (ON BACK) YES	REMARKS (ON BACK) NO
FED 200gr BtSp S		5																										
M		5																										
F		5																										
ALT.		5																										
FED 165gr BtSp S		5																										
M		5																										
F		5																										
ALT.		5																										
FED 180 Nosler S		5																										
M		5																										
F		5																										
ALT.		5																										
TOTAL (PER MAL.)																												