Product Safety Subcommittee Meeting Minutes

Minute No.	Date		
1	Not Produced	Missing	
2	4/2/75	Examine Guns Returned From Texas 4 M600 FSR	Report
3	4/23/75	Research Investigations M600, 788, 580 Design Analysis	Report
		Test Design Change	Report
		Study & Pub. Safe	Report
		Safety Review Gunsmith Reports, Arms Repair Data, Usage	Report
		Production Reviewing QC Procedures + Manual Recommending	Report
4	6/20/75		
	1 Year & Months Missing		
	10/23/78	Research Begin Exam of All Bolt Action Rifles To See If Safety	Report
	10/26/78		
	10/27/78		
	10/30/78	Production Change Very Replacement Trigger Assembly Now 10% Now	
	11/3/78		
	11/17/78		
	1/2/79	200 + 19 Pre-1975 M700 Returned, 3 With FSR	Report
		Remington Sample Investigations 1% Pre-1975 M700 FSR	Report
	1/16/79		
	2/5/79		
	2/23/79		
	4/6/79		
	6/22/79		