

7/3/00

Remington Box Bottom

DSM-Part

Weights

Cav. #1. = 7.9 grs.

Cav. #2. = 8.3 grs.

RTP-Part

83

#1. = 9.5

#2. = 9.9

Dimension # Cav. #1 #2

1. 1.234, 1.237
 (-.005), (-.002)

2. 3.816, 3.817
 (-.003), (-.002)

3. .047, .047
 O.K., O.K.

4. 3.758, 3.760
 (+.020), (+.022)

Cav. #1, #2

1.239, 1.235
 O.K., (-.004)

3.823, 3.824
 O.K., O.K.

.055, .051
 O.K., O.K.

3.763, 3.766
 (+.023), (+.026)


MF0717

Press Ctrl+P to Print

FORM 20A

Start with value and add proven technology

CHANGE



EDMMS
CINCINN. OH.

LAURENCE BOCK

↳ \$34,000

ASAC FORM 20C
\$29,000

EDM HAMILTON
BOOTH # 4010


ALL SELF
FERTIGER HONG

(800) 367 1109

FIXTURE 3000
~1 MINUTE

80 DIA BORE ~ 40K

~ 3mm - P. 83
80K
40K



250. FLOW HOUR
SILICON CARBIDE

- The tradition of EDM know-how
- High efficiency from roughing to finishing
- Improved performances with the CT patented ISOCUT

Machine

X, Y, Z travel	in 11.82 x 7.88 x 11.82
Max. workpiece weight	lbs 1102.3
Max. electrode weight	lbs 132.27
Min./max. chuck to table distance	in 9.85/21.67
Weight of installation without dielectric	lbs 2425.06

Worktank

Type of tank	Fixe tank
Work tank dimensions L x W x H	32.308x 19.7 x 11.82
Work table dimension L x W	in 19.7 x 13.79

Dielectric System

Filtering system	2
Total reservoir capacity	g 61.6

Generator

Standard machining current	A 32
----------------------------	------


Options

Additional power module	A 32
DRO	Digital Read out

http://www.charmillesus.com/prod/robo_popup/form20a.html

8/16/00

MF0718



The technical data are not binding. They are not warranted characteristics and are subject to change.


Please consult the General Sales Conditions of Charmilles Technologies SA.

last updated 26.06.00.

BACK TO TOP ▲

Close

CONFIDENTIAL



KLINGELHOFER CORPORATION

FINE MACHINE TOOLS SINCE 1929

165 MILL LANE, P.O. BOX 1098, MOUNTAINSIDE, NEW JERSEY 07092

908 232-7200 • FAX 908 232-1841

August 23, 2000

Mr. Jim Gooch
Remington Arms Co., Inc.
22 Rifle Trail
Hickory, KY 42051

Subject: Wagner Model WAS-70

Dear Mr. Gooch:

In reference to our phone conversation of today concerning your larger diameter and longer lengths, we offer the following explanation.

The machine that you purchased in 1996 was supplied with a 24" length gauge. This length gauge was designed only for smaller diameter material. When you get into larger diameters or longer lengths, you will need to support the entire cutoff piece so that it will not sag. With your present machine, when the part sags, it pinches the saw blade and if it is too heavy, it will damage the discharge chute. For larger diameter, longer parts, we offer a discharge conveying system as shown in the attached catalog. This system completely supports the cutoff piece and then tilts it to the front of the machine parallel to the floor. This system is shown on the front page of our catalog and also on page 5.

For reference, the following is a description and a price:

Discharge Conveyor:
(Manually set length gauge)

Tilt type roller support track connected to the sawing machine for cutoffs from 1½" up to 40". Cut pieces are tilted to the front. A trap door sorting device is provided to separate crop and remnant pieces from the good cutoffs. A container is included to collect the scrap pieces.

Manually positioned length gauge for cutoffs from 1½" to 40". The length gauge is easily traversed due to its roller guidance. It is locked into position by means of clamping levers. The arm is raised and lowered by an hydraulic cylinder. The cut length is set according to a scale with micrometer settings of .002" provided.

PRICE of tilt table with manually positioned length gauge for cutoffs 1½" up to 40" \$ 14,750.00

MF0720

Remington Arms Co., Inc.

- 2 -

August 23, 2000

Terms are F.O.B. Mountainside, NJ, net 30 days.

Delivery: approximately 16 - 18 weeks.

Our quotation does not include installation of the tilt table. There are electrical, hydraulic and mechanical changes that must be made on your machine. Based on past experience, we strongly recommend that you hire one of our servicemen to assist you in the installation. The charge for this assistance would be \$600.00 per day plus travel and living expenses. With the proper help from your maintenance department, the complete installation should not take more than 2 - 2½ days.

If further information is needed or we can help in any way, please feel free to call. 83

Very truly yours,

KLINGELHOFER CORPORATION

Fred E. Schaefer
Fred E. Schaefer
Vice President

FES/af

Enc.: Klingelhofer Sawing & Deburring Machines
Klingelhofer Circular Saw Blades

MF0721

Material Requisn. Item S C R Qty. I A Release strategy	Short text Requested qty. Un Req. val. Cur Release indicator	Deliv. date Release date Release option	PGp Requester Trackg.no. Release option	Mat. gp. Plnt SLoc Spl. MC
X	SAMPLES BOLT		M09	RAW
1000528453 00010	44.000 EA	D 08/31/2000	GOLEMBOSKIMR	MAY
N R A NB Z	86.25 USD	08/29/2000	HELMERGA	
S1	B APPROVED FOR PURCHAS Release effected			
X	PRE-EMPLOYMENT DRUG SCREEN AND PHYSICAL		M09	MISC
1000528455 00010	2.000 EA	D 08/31/2000	GOLEMBOSKIMR	MAY
N R A NB K	242.00 USD	08/29/2000	HALEYMA	
S1	B APPROVED FOR PURCHAS Release effected			
X	CU-STRIP L CUSTRIL		M09	07
1000528457 00010	1,575 LB	D 09/08/2000	GOLEMBOSKIMR	MAY
N R A NB Z	834.75 USD	08/29/2000	SACHARNOSK	
S1	B APPROVED FOR PURCHAS Release effected			
X	#22867 ABSORB UNIVERSAL PAD		M09	06
1000528458 00010	3.000 EA	D 09/08/2000	GOLEMBOSKIMR	MAY
N R A NB Z	126.00 USD	08/29/2000	HOBBSJM	
S1	B APPROVED FOR PURCHAS Release effected			
X	#36675 THREADED ROD 1/4", 20 UNC. 36" ME		M09	06
1000528458 00020	3.000 EA	D 09/08/2000	GOLEMBOSKIMR	MAY
N R A NB Z	15.54 USD	08/29/2000	HOBBSJM	
S1	B APPROVED FOR PURCHAS Release effected			
X	#23928 TIE, CABLE, 1/16" TO 4"		M09	06
1000528458 00030	25.000 EA	D 09/08/2000	GOLEMBOSKIMR	MAY
N R A NB Z	9.80 USD	08/29/2000	HOBBSJM	
S1	B APPROVED FOR PURCHAS Release effected			
X	#23925 TIE, CABLE, SELF-LOCKING		M09	06
1000528458 00040	50.000 EA	D 09/08/2000	GOLEMBOSKIMR	MAY
N R A NB Z	12.77 USD	08/29/2000	HOBBSJM	
S1	B APPROVED FOR PURCHAS Release effected			
X	#23923 TIE, CABLE, SELF-LOCKING		M09	06
1000528458 00050	100.000 EA	D 09/08/2000	GOLEMBOSKIMR	MAY
N R A NB Z	10.53 USD	08/29/2000	HOBBSJM	
S1	B APPROVED FOR PURCHAS Release effected			
X	#23924 TIE, CABLE 7.81", TY-RAP		M09	06
1000528458 00060	100.000 EA	D 09/08/2000	GOLEMBOSKIMR	MAY
N R A NB Z	18.93 USD	08/29/2000	HOBBSJM	
S1	B APPROVED FOR PURCHAS Release effected			
X	#16031 FITTING, HEX HEAD PLUG 3/4" PIPE		M09	06
1000528458 00070	2.000 EA	D 09/08/2000	GOLEMBOSKIMR	MAY
N R A NB Z	3.25 USD	08/29/2000	HOBBSJM	
S1	B APPROVED FOR PURCHAS Release effected			
X	#16028 FITTING, HEX HEAD PLUG 1/4"		M09	06
1000528458 00080	4.000 EA	D 09/08/2000	GOLEMBOSKIMR	MAY
N R A NB Z	1.78 USD	08/29/2000	HOBBSJM	
S1	B APPROVED FOR PURCHAS Release effected			
X	#32570 WASHER FENDER 3/16"		M09	06
1000528458 00090	100.000 EA	D 09/08/2000	GOLEMBOSKIMR	MAY
N R A NB Z	10.19 USD	08/29/2000	HOBBSJM	
S1	B APPROVED FOR PURCHAS Release effected			
X	#32572 WASHER, FENDER 1/4", 1"		M09	06
1000528458 00100	100.000 EA	D 09/08/2000	GOLEMBOSKIMR	MAY
N R A NB Z	10.19 USD	08/29/2000	HOBBSJM	
S1	B APPROVED FOR PURCHAS Release effected			
X	#42751 SCREW, CAP MB, 25MM, SOCKET		M09	06
1000528458 00110	50.000 EA	D 09/08/2000	GOLEMBOSKIMR	MAY
N R A NB Z	18.12 USD	08/29/2000	HOBBSJM	
S1	B APPROVED FOR PURCHAS Release effected			
X	#33592 SCREW, CAP, #10, 24 UNC, 3/4"		M09	06
1000528458 00120	50.000 EA	D 09/08/2000	GOLEMBOSKIMR	MAY
N R A NB Z	3.75 USD	08/29/2000	HOBBSJM	

MF0722

Material	Short text	PGp	Mat. gp.
Requisn. Item	Requested qty. Un Deliv. date Requester	Plnt SLoc	
S C R Qty. I A	Req. val. Cur Release date Trackg.no.	SPl. MC	
Release strategy	Release indicator Release option		
S1	B APPROVED FOR PURCHAS Release effected		
X	#-33589-1 SCREW, CAP, #10, 24 UNC 3/8" M09 06		
1000528458 00130	50.000 EA D 09/08/2000 GOLEMBOSKIMR MAY		
N R A NB Z	3.35 USD 08/29/2000 HOBBSJM		
S1	B APPROVED FOR PURCHAS Release effected		
X	#33840 SCREW, SELF-TAPPING, #12, 1" HEX M09 06		
1000528458 00140	100.000 EA D 09/08/2000 GOLEMBOSKIMR MAY		
N R A NB Z	13.97 USD 08/29/2000 HOBBSJM		
S1	B APPROVED FOR PURCHAS Release effected		
X	#33833 SCREW, SELF TAPPING, #10, 1" HEX M09 06		
1000528458 00150	100.000 EA D 09/08/2000 GOLEMBOSKIMR MAY		
N R A NB Z	10.69 USD 08/29/2000 HOBBSJM		
S1	B APPROVED FOR PURCHAS Release effected		
X	#32106 SCRW, SELF TAPPING #12, 1" PAN M09 06		
1000528458 00160	25.000 EA D 09/08/2000 GOLEMBOSKIMR MAY		
N R A NB Z	2.28 USD 08/29/2000 HOBBSJM		
S1	B APPROVED FOR PURCHAS Release effected		
X	#32108 SCREW, SELF-TAPPING #12, 1-1/2" M09 06		
1000528458 00170	25.000 EA D 09/08/2000 GOLEMBOSKIMR MAY		
N R A NB Z	3.49 USD 08/29/2000 HOBBSJM		
S1	B APPROVED FOR PURCHAS Release effected		
X	#32112 SCREW, SELF-TAPPING 1/4" M09 06		
1000528458 00180	50.000 EA D 09/08/2000 GOLEMBOSKIMR MAY		
N R A NB Z	4.55 USD 08/29/2000 HOBBSJM		
S1	B APPROVED FOR PURCHAS Release effected		
X	#32114 SCREW, SELF-TAPPING, 1/4", 3/4" P M09 06		
1000528458 00190	25.000 EA D 09/08/2000 GOLEMBOSKIMR MAY		
N R A NB Z	2.87 USD 08/29/2000 HOBBSJM		
S1	B APPROVED FOR PURCHAS Release effected		
X	#32116 SCREW, SELF-TAPPING, 1/4", 1" M09 06		
1000528458 00200	25.000 EA D 09/08/2000 GOLEMBOSKIMR MAY		
N R A NB Z	3.47 USD 08/29/2000 HOBBSJM		
S1	B APPROVED FOR PURCHAS Release effected		
X	#24114 CLAMP, HOSE/TUBING, WORM, 1-1/2" M09 06		
1000528458 00210	10.000 EA D 09/08/2000 GOLEMBOSKIMR MAY		
N R A NB Z	4.62 USD 08/29/2000 HOBBSJM		
S1	B APPROVED FOR PURCHAS Release effected		
X	#67318253 BIT SET M09 03		
1000528459 00010	2.000 EA D 08/31/2000 GOLEMBOSKIMR MAY		
N R A NB Z	23.96 USD 08/29/2000 GOOCHJC		
S1	B APPROVED FOR PURCHAS Release effected		
X	#89773600 CABINET M09 03		
1000528459 00020	1.000 EA D 08/31/2000 GOLEMBOSKIMR MAY		
N R A NB Z	674.18 USD 08/29/2000 GOOCHJC		
S1	B APPROVED FOR PURCHAS Release effected		
X	#01763853 CUSH-GRIP SCREWDRIVER M09 03		
1000528459 00030	2.000 EA D 08/31/2000 GOLEMBOSKIMR MAY		
N R A NB Z	12.86 USD 08/29/2000 GOOCHJC		
S1	B APPROVED FOR PURCHAS Release effected		
X	#89767420 DELUXE GROUND/ BONDWIRE M09 03		
1000528459 00040	10.000 EA D 08/31/2000 GOLEMBOSKIMR MAY		
N R A NB Z	202.50 USD 08/29/2000 GOOCHJC		
S1	B APPROVED FOR PURCHAS Release effected		
X	#06695027 1/4" HEX DRIVE BIT HOLDERS M09 03		
1000528459 00050	4.000 EA D 08/31/2000 GOLEMBOSKIMR MAY		
N R A NB Z	36.80 USD 08/29/2000 GOOCHJC		
S1	B APPROVED FOR PURCHAS Release effected		
X	#88349824 EKLIND BALL HEX KEY M09 03		
1000528459 00060	5.000 EA D 08/31/2000 GOLEMBOSKIMR MAY		

MF0723

Material Requisition S C R Qty. I A Release strategy	Item	Short text Requested qty. Un Deliv. date Req. val. Cur Release date Release indicator	PGp Requester Trackg.no. Release option	Mat. gp. Plnt SLoc SPL. MC
N R A NB S1	Z	44.95 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		
X 1000528459	00070	#88349857 EKLIND BALL HEX KEY SET 5.000 EA D 08/31/2000 GOLEMBOSKIMR 39.95 USD 08/29/2000 GOOCHJC	M09 03 MAY	
N R A NB S1	Z	B APPROVED FOR PURCHAS Release effected		
X 1000528459	00080	#01763911 KELIN CUSH-GRIP SCREWDRIVER 2.000 EA D 08/31/2000 GOLEMBOSKIMR 11.06 USD 08/29/2000 GOOCHJC	M09 03 MAY	
N R A NB S1	Z	B APPROVED FOR PURCHAS Release effected		
X 1000528459	00090	#01831783 KELIN STRIPPER/CUTTE 1.000 EA D 08/31/2000 GOLEMBOSKIMR 9.70 USD 08/29/2000 GOOCHJC	M09 03 MAY	
N R A NB S1	Z	B APPROVED FOR PURCHAS Release effected		
X 1000528459	00100	#55091307 CHANNELLOCK PLIERS 2.000 EA D 08/31/2000 GOLEMBOSKIMR 19.24 USD 08/29/2000 GOOCHJC	M09 03 MAY	
N R A NB S1	Z	B APPROVED FOR PURCHAS Release effected		
X 1000528459	00110	#76562214 CRESCENT WRENCH 2.000 EA D 08/31/2000 GOLEMBOSKIMR 19.24 USD 08/29/2000 GOOCHJC	M09 03 MAY	
N R A NB S1	Z	B APPROVED FOR PURCHAS Release effected		
X 1000528460	00010	#68501 JERGENS BALL LOCK 10.000 EA D 08/31/2000 GOLEMBOSKIMR 60.30 USD 08/29/2000 GOOCHJC	M09 03 MAY	
N R A NB S1	Z	B APPROVED FOR PURCHAS Release effected		
X 1000528460	00020	#68503 JERGENS BALL LOCK 10.000 EA D 08/31/2000 GOLEMBOSKIMR 63.50 USD 08/29/2000 GOOCHJC	M09 03 MAY	
N R A NB S1	Z	B APPROVED FOR PURCHAS Release effected		
X 1000528461	00010	3/4 EMT CONDUIT 10' 200.000 FT D 08/31/2000 GOLEMBOSKIMR 68.00 USD 08/29/2000 CHOATECH	M09 16 MAY	
N R A NB S1	Z	B APPROVED FOR PURCHAS Release effected		
X 1000528462	00010	#940-0008 ROTO FINISH PORTABLE COMPOUND 1.000 EA D 09/08/2000 GOLEMBOSKIMR 1,361.00 USD 08/29/2000 GOOCHJC	M09 17 MAY	
N R A NB S1	Z	B APPROVED FOR PURCHAS Release effected		
X 1000528763	00010	HP 82298A TONER CARTRIDGE 1.000 EA D 08/31/2000 GOLEMBOSKIMR 99.99 USD 08/29/2000 HUTSONLR	M09 02 MAY	
N R A NB S1	Z	B APPROVED FOR PURCHAS Release effected		
X 1000528763	00020	SOF 1505 IVORY TWISSTOP 1.000 EA D 08/31/2000 GOLEMBOSKIMR 5.20 USD 08/29/2000 HUTSONLR	M09 02 MAY	
N R A NB S1	Z	B APPROVED FOR PURCHAS Release effected		
X 1000528763	00030	AVE CV1105WE 1.000 EA D 08/31/2000 GOLEMBOSKIMR 2.29 USD 08/29/2000 HUTSONLR	M09 02 MAY	
N R A NB S1	Z	B APPROVED FOR PURCHAS Release effected		
X 1000528763	00040	AVE CV1110WE 1.000 EA D 08/31/2000 GOLEMBOSKIMR 2.29 USD 08/29/2000 HUTSONLR	M09 02 MAY	
N R A NB S1	Z	B APPROVED FOR PURCHAS Release effected		
X 1000528765	00010	3 GAL THREADED CUTTING OIL 3.000 EA D 08/31/2000 GOLEMBOSKIMR 32.85 USD 08/29/2000 GOOCHJC	M09 MISC MAY	
N R A NB S1	Z	B APPROVED FOR PURCHAS Release effected		
X		CAN OF CEMENT M09 MISC		

MF0724

Material Requisition. S C R Qty. I A Release strategy	Item	Short text Requested qty. Un Deliv. date Requester Req. val. Cur Release date Trackg.no. Release indicator Release option	PGp	Mat. gp. Plnt SLoc SPL. MC
X	1000528765 00020 N R A NB Z S1	4.000 EA D 08/31/2000 GOLEMBOSKIRM MAY 15.56 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		
		CLEANER	M09	MISC
X	1000528765 00030 N R A NB Z S1	3.000 EA D 08/31/2000 GOLEMBOSKIRM MAY 8.97 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		
		CEMENT	M09	MISC
X	1000528765 00040 N R A NB Z S1	4.000 EA D 08/31/2000 GOLEMBOSKIRM MAY 11.96 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		
		INSULATING SEALANT	M09	MISC
X	1000528765 00050 N R A NB Z S1	3.000 EA D 08/31/2000 GOLEMBOSKIRM MAY 14.07 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		
		ESTIMATED KY SALES TAX 6%	M09	MISC
X	1000528765 00060 N R A NB Z S1	1.000 EA D 08/31/2000 GOLEMBOSKIRM MAY 5.00 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		
		1 X 4- 8 #2 SPRUCE	M09	45
X	1000528766 00010 N R A NB Z S1	24.000 EA D 08/31/2000 GOLEMBOSKIRM MAY 11.52 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		
		2 X 4- 92 5/8	M09	45
X	1000528766 00020 N R A NB Z S1	30.000 EA D 08/31/2000 GOLEMBOSKIRM MAY 77.70 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		
		2 X 6- 10	M09	45
X	1000528766 00030 N R A NB Z S1	9.000 EA D 08/31/2000 GOLEMBOSKIRM MAY 50.04 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		
		1 X 4- 1/2 AC	M09	45
X	1000528766 00040 N R A NB Z S1	3.000 EA D 08/31/2000 GOLEMBOSKIRM MAY 51.84 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		
		2 X 4- 10	M09	45
X	1000528766 00050 N R A NB Z S1	9.000 EA D 08/31/2000 GOLEMBOSKIRM MAY 27.99 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		
		4 X 8- 7/16	M09	45
X	1000528766 00060 N R A NB Z S1	8.000 EA D 08/31/2000 GOLEMBOSKIRM MAY 127.92 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		
		#16 NAILS	M09	45
X	1000528766 00070 N R A NB Z S1	10 LB D 08/31/2000 GOLEMBOSKIRM MAY 9.80 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		
		#6 GALV. NAILS	M09	45
X	1000528766 00080 N R A NB Z S1	5 LB D 08/31/2000 GOLEMBOSKIRM MAY 4.90 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		
		ESTIMATED KY SALES TAX 6%	M09	45
X	1000528766 00090 N R A NB Z S1	1.000 EA D 08/31/2000 GOLEMBOSKIRM MAY 21.70 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		
		WAGNER BRAKE PARTS	M09	MISC
X	1000528767 00010 N R A NB Z S1	96.000 EA D 08/31/2000 GOLEMBOSKIRM MAY 45.12 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected		

MF0725

Material Requisition. S C R Oty. I A Release strategy	Item	Short text Requested qty. Un Deliv. date Requester Req. val. Cur Release date Trackg.no. Release indicator Release option	PGp	Mat. gp. Plnt SLoc Spl. MC
X	1000528767 00020 N R A NB Z S1	GATES HYDRAULIC FITTING G25170-0808 2.000 EA D 08/31/2000 GOLEMBOSKIMR 12.26 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected	M09	MISC MAY
X	1000528767 00030 N R A NB Z S1	GATES HYDRAULIC FITTINGS G25180-0808 2.000 EA D 08/31/2000 GOLEMBOSKIMR 27.78 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected	M09	MISC MAY
X	1000528767 00040 N R A NB Z S1	GATES HYDRAULIC FITTING GAT 70607 20.000 EA D 08/31/2000 GOLEMBOSKIMR 5.80 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected	M09	MISC MAY
X	1000528767 00050 N R A NB Z S1	ESTIMATED KY SALE TAX 6% 1.000 EA D 08/31/2000 GOLEMBOSKIMR 5.46 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected	M09	MISC MAY
X	1000528769 00010 N R A NB Z S1	#8505 SUGAR 2.000 EA D 08/31/2000 GOLEMBOSKIMR 4.00 USD 08/29/2000 HUTSONLR B APPROVED FOR PURCHAS Release effected	M09	MISC MAY
X	1000528769 00020 N R A NB Z S1	#8401 FRENCH VANILLA CREAMER 1.000 EA D 08/31/2000 GOLEMBOSKIMR 3.00 USD 08/29/2000 HUTSONLR B APPROVED FOR PURCHAS Release effected	M09	MISC MAY
X	1000528770 00010 N R A NB Z S1	HEX KEY SET 2-8MM FOLDUP 1.000 EA D 08/31/2000 GOLEMBOSKIMR 5.69 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected	M09	MISC MAY
X	1000528770 00020 N R A NB Z S1	HEX KEY SET 5/64-1/4 FOLDUP 1.000 EA D 08/31/2000 GOLEMBOSKIMR 4.58 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected	M09	MISC MAY
X	1000528770 00030 N R A NB Z S1	CARBIDE BLADE 3 PAK 7-1/4" 1.000 EA D 08/31/2000 GOLEMBOSKIMR 29.77 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected	M09	MISC MAY
X	1000528770 00040 N R A NB Z S1	BLUE MAX BLADE 7-1/4" 2.000 EA D 08/31/2000 GOLEMBOSKIMR 19.76 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected	M09	MISC MAY
X	1000528771 00010 N R A NB F S1	PROOF TEST BOX FABRICATED 1.000 EA D 08/31/2000 GOLEMBOSKIMR 5,050.00 USD 08/29/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected	M09	TOOLING MAY
X	1000528772 00010 N R A NB Z S1	BIOHAZARD BAG, 10 GALLON 1.000 EA D 08/31/2000 GOLEMBOSKIMR 20.12 USD 08/29/2000 HALEYMA B APPROVED FOR PURCHAS Release effected	M09	02 MAY
X	1000528772 00020 N R A NB Z S1	ESTIMATED KY SALES TAX 6% 1.000 EA D 08/31/2000 GOLEMBOSKIMR 1.21 USD 08/29/2000 HALEYMA B APPROVED FOR PURCHAS Release effected	M09	02 MAY
X	1000528873 00010 N R A NB Z S1	#03680949 0.1230 CLASS XX NOGO RING GAGE 1.000 EA D 08/31/2000 GOLEMBOSKIMR 91.25 USD 08/29/2000 ZAJKJJ B APPROVED FOR PURCHAS Release effected	M09	03 MAY
X	1000528874 00010 N R A NB Z	#82284266 14-7/8 X 3 LONG DIVIDERS 288.000 EA D 08/11/2000 GOLEMBOSKIMR 708.48 USD 08/29/2000 HOBBSJM	M09	MISC MAY

MF0726

Material	Short text	PGp	Mat. gp.
Requisn. Item	Requested qty. Un Deliv. date Requester	Plnt SLoc	
S C R Qty. I A	Req. val. Cur Release date Trackg.no.	Spl. MC	
Release strategy	Release indicator	Release option	
S1	B APPROVED FOR PURCHAS Release effected		
X 1000528875 00010	MAGAZINE SPRING RECEIVING GA C-K-10514 M09 TOOLING		
N R A NB K	1.000 EA D 09/22/2000 GOLEMBOSKIMR MAY		
S1	180.00 USD 08/29/2000 HELMERGA		
X	B APPROVED FOR PURCHAS Release effected		
1000528876 00010	WHEEL ARBOR #WA001449 M09 MISC		
N R A NB Z	1.000 EA D 09/08/2000 GOLEMBOSKIMR MAY		
S1	610.60 USD 08/29/2000 CHOATECH		
X	B APPROVED FOR PURCHAS Release effected		
1000528876 00020	ENDCAP # SP001426 M09 MISC		
N R A NB Z	1.000 EA D 09/08/2000 GOLEMBOSKIMR MAY		
S1	102.84 USD 08/29/2000 CHOATECH		
X	B APPROVED FOR PURCHAS Release effected		
1000528877 00010	1/4-20 NYLON SCREW #67345447 M09 MISC		
N R A NB Z	100.000 EA D 08/31/2000 GOLEMBOSKIMR MAY		
S1	5.30 USD 08/29/2000 CHOATECH		
X	B APPROVED FOR PURCHAS Release effected		
1000528877 00020	10-24 NYLON SCREW #67345082 M09 MISC		
N R A NB Z	100.000 EA D 08/31/2000 GOLEMBOSKIMR MAY		
S1	4.75 USD 08/29/2000 CHOATECH		
X	B APPROVED FOR PURCHAS Release effected		
1000528877 00030	STRIPPER #01831825 M09 MISC		
N R A NB Z	1.000 EA D 08/31/2000 GOLEMBOSKIMR MAY		
S1	8.82 USD 08/29/2000 CHOATECH		
X	B APPROVED FOR PURCHAS Release effected		
1000528878 00010	#70285T61 URINAL TABS M09 MISC		
N R A NB Z	8.000 EA D 08/31/2000 GOLEMBOSKIMR MAY		
S1	112.00 USD 08/29/2000 CHOATECH		
X	B APPROVED FOR PURCHAS Release effected		
1000528878 00020	#5501K39 10" HOSE M09 MISC		
N R A NB Z	5.000 FT D 08/31/2000 GOLEMBOSKIMR MAY		
S1	32.75 USD 08/29/2000 CHOATECH		
X	B APPROVED FOR PURCHAS Release effected		
1000528878 00030	#5945K43 10" HOSE CLAMP M09 MISC		
N R A NB Z	2.000 EA D 08/31/2000 GOLEMBOSKIMR MAY		
S1	11.88 USD 08/29/2000 CHOATECH		
X	B APPROVED FOR PURCHAS Release effected		
1000528878 00040	#5648K25 CLEAR 1/4" TUBING M09 MISC		
N R A NB Z	100.000 FT D 08/31/2000 GOLEMBOSKIMR MAY		
S1	26.00 USD 08/29/2000 CHOATECH		
	B APPROVED FOR PURCHAS Release effected		

MF0727

Cost center 0000028200

Material	Requish.	Item	Short text	Un	Deliv. date	Requester	PGp	Mat. gp.
S C R Qty.	I A		Requested qty.	Un	Release date	Trackg.no.	Plnt	SLoc
			Ordered qty.	Un			SPl.	MC
1000528453	00010		SAMPLES BOLT			M09	RAW	
N R A NB	Z		44.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY	
					08/29/2000	HELMERGA		
1000528457	00010		CU-STRIP L CUSTRIL			M09	07	
N R A NB	Z		1,575 LB	D	09/08/2000	GOLEMBOSKIMR	MAY	
					08/29/2000	SACHARNOSK		
1000528459	00010		#67318253 BIT SET			M09	03	
N R A NB	Z		2.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY	
					08/29/2000	GOOCHJC		
1000528459	00020		#89773600 CABINET			M09	03	
N R A NB	Z		1.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY	
					08/29/2000	GOOCHJC		
1000528459	00030		#01763853 CUSH-GRIP SCREWDRIVER			M09	03	
N R A NB	Z		2.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY	
					08/29/2000	GOOCHJC		
1000528460	00010		#68501 JERGENS BALL LOCK			M09	03	
N R A NB	Z		10.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY	
					08/29/2000	GOOCHJC		
1000528460	00020		#68503 JERGENS BALL LOCK			M09	03	
N R A NB	Z		10.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY	
					08/29/2000	GOOCHJC		
1000528461	00010		3/4 EMT CONDUIT 10'			M09	16	
N R A NB	Z		200.000 FT	D	08/31/2000	GOLEMBOSKIMR	MAY	
					08/29/2000	CHOATECH		
1000528462	00010		#940-0008 ROTO FINISH PORTABLE COMPOUND			M09	17	
N R A NB	Z		1.000 EA	D	09/08/2000	GOLEMBOSKIMR	MAY	
					08/29/2000	GOOCHJC		
1000528766	00010		1 X 4- 8 #2 SPRUCE			M09	45	
N R A NB	Z		24.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY	
					08/29/2000	GOOCHJC		
1000528766	00020		2 X 4- 92 5/8			M09	45	
N R A NB	Z		30.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY	
					08/29/2000	GOOCHJC		
1000528766	00030		2 X 6- 10			M09	45	
N R A NB	Z		9.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY	
					08/29/2000	GOOCHJC		
			4 X 8- 1/2 AC			M09	45	

710 start up

BARBER - 5.22.06#0010678

Confidential - ~~BARBER~~ - 5.22.06#0010678 Order
Williams v. Remington

ME0728

Cost center 0000028200

Material Requisn. S C R Qty. I A	Item	Short text Requested qty. Ordered qty.	Un	Deliv. date Release date	PGp Requester Trackg.no.	Mat. gp. Plnt SLoc Spl. MC
1000528766	00040	3.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY
N R A NB	Z			08/29/2000	GOOCHJC	
		2 X 4- 10			M09	45
1000528766	00050	9.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY
N R A NB	Z			08/29/2000	GOOCHJC	
		4 X 8- 7/16			M09	45
1000528766	00060	8.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY
N R A NB	Z			08/29/2000	GOOCHJC	
		#16 NAILS			M09	45
1000528766	00070	10 LB	D	08/31/2000	GOLEMBOSKIMR	MAY
N R A NB	Z			08/29/2000	GOOCHJC	
		#6 GALV. NAILS			M09	45
1000528766	00080	5 LB	D	08/31/2000	GOLEMBOSKIMR	MAY
N R A NB	Z			08/29/2000	GOOCHJC	
		ESTIMATED KY SALES TAX 6%			M09	45
1000528766	00090	1.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY
N R A NB	Z			08/29/2000	GOOCHJC	
		WAGNER BRAKE PARTS			M09	MISC
1000528767	00010	96.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY
N R A NB	Z			08/29/2000	GOOCHJC	
		GATES HYDRAULIC FITTING G25170-0808			M09	MISC
1000528767	00020	2.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY
N R A NB	Z			08/29/2000	GOOCHJC	
		GATES HYDRAULIC FITTINGS G25180-0808			M09	MISC
1000528767	00030	2.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY
N R A NB	Z			08/29/2000	GOOCHJC	
		GATES HYDRAULIC FITTING GAT 70607			M09	MISC
1000528767	00040	20.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY
N R A NB	Z			08/29/2000	GOOCHJC	
		ESTIMATED KY SALE TAX 6%			M09	MISC
1000528767	00050	1.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY
N R A NB	Z			08/29/2000	GOOCHJC	
		HEX KEY SET 2-8MM FOLDUP			M09	MISC
1000528770	00010	1.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY
N R A NB	Z			08/29/2000	GOOCHJC	
		HEX KEY SET 5/64-1/4 FOLDUP			M09	MISC
1000528770	00020	1.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY

BARBER - 5.22.06/0010679

ME0729

Confidential - ~~BARBER~~ - 5.22.06/0010679 Order
Williams v. Remington

Cost center 0000028200

Material	Requish.	Item	Short text	Un	Deliv. date	Requester	PGp	Mat. gp.
S C R Qty.	I A		Requested qty.	Un	Release date	Trackg.no.		Plnt SLoc
			Ordered qty.	Un				SPl. MC
N R A NB		Z			08/29/2000	GOOCHJC		
1000528770		00030	CARBIDE BLADE 3 PAK 7-1/4"			M09		MISC
N R A NB		Z	1.000 EA	D	08/31/2000	GOLEMBOSKIMR		MAY
					08/29/2000	GOOCHJC		
1000528770		00040	BLUE MAX BLADE 7-1/4"			M09		MISC
N R A NB		Z	2.000 EA	D	08/31/2000	GOLEMBOSKIMR		MAY
					08/29/2000	GOOCHJC		
1000528873		00010	#03680949 0.1230 CLASS XX NOGO RING GAGE			M09		03
N R A NB		Z	1.000 EA	D	08/31/2000	GOLEMBOSKIMR		MAY
					08/29/2000	ZAKJJI		
1000528874		00010	#82284266 14-7/8 X 3 LONG DIVIDERS			M09		MISC
N R A NB		Z	288.000 EA	D	08/11/2000	GOLEMBOSKIMR		MAY
					08/29/2000	HOBSJUM		
1000528875		00010	MAGAZINE SPRING RECEIVING GA C-K-10314			M09		TOOLING
N R A NB		K	1.000 EA	D	09/22/2000	GOLEMBOSKIMR		MAY
					08/29/2000	HEIMERGA		

BARBER - 5.22.06/0010680

Confidential - ~~Subsequent~~ - 5.22.06/0010680 Order
Williams v. Remington

ME0730

Order 000000292068

Material		Short text		PGp	Mat. gp.	
Requisn.	Item	Requested qty.	Un	Deliv. date	Requester	Plnt SLoc
S C R Qty.	I A	Ordered qty.	Un	Release date	Trackg.no.	SP1. MC
1000528771 00010		PROOF TEST BOX FABRICATED		M09	TOOLING	
N R A NB F		1.000 EA	D	08/31/2000	GOLEMBOSKIMR	MAY
				08/29/2000	GOOCHJC	

BARBER - 5.22.06r0010681

83

MF0731

Confidential - Subject - 5.22.06r0010681 Order
Williams v. Remington



Remington Arms Co., Inc.
R&D Technical Center
315 W. Ring Road
Elizabethtown, KY 42701

Phone: 270-769-7600
Fax: 270-737-9576

Date: 8-28-00

No. of pages including cover sheet: 3

TO:

From:

MATT GOREMANSKI

MIKE K.

Phone

Fax Phone

CC:

Phone

Fax Phone

83

REMARKS:

☐ Urgent

☐ For your review

☐ Reply ASAP

☐ Please comment

RECOVER INSERT SUPPORT QUOTES - CALL ME TO DISCUSS.

THANKS

MIKE

P.S. I HAVE PLACED AN ORDER FOR (35) PCS FOR
DAT, DUE 9/5/00.

**The information contained in this FAX is confidential and/or privileged. The FAX is intended to be reviewed initially by only the individual named above. If the reader of this transmittal page is not the intended recipient or a representative, you are hereby notified that any review, dissemination or copying of this FAX or information contained herein is prohibited. If you have received this FAX in error, please immediately notify the sender or telephone and return this FAX to the sender at the above address. Thank you.

MF0732

Confidential - Subject: Protective Order
BARBER - 5.22.06r0010682
Williams v. Remington

BARBER - 5.22.06r0010683

Triangle
Precision
Industries, Inc.

Since 1982

ISO9002

TRIANGLE PRECISION IND. INC.
1650 WOODMAN CENTER DRIVE
KETTERING, OH 45420

Ph: (937) 299-6776 Fax: (937) 299-7340

Quotation

Number: 7911


Date: 25-Aug-00

To REMINGTON ARMS CO., INC.
315 W. RING ROAD
ELIZABETHTOWN, KY 42701 USA

Mail To MIKE KEENY
REMINGTON ARMS CO., INC.
315 W. RING ROAD
ELIZABETHTOWN, KY 42701 USA

Ph: (270) 769-7600 Fax: (270) 737-8576

Ph: 270-769-7610 Fax: (270) 737-8576


Terms	Ship Via		Salesperson
Net 30 days			
Quantity	Description	Unit Price	Amount
30,000	QUOTE DURATION: 90 DAYS WE ARE PLEASED TO PRESENT OUR QUOTE ON THE FOLLOWING Quote: 7911 Part: C-300-479 RECEIVER INSERT SUPPORT Rev:	\$1.14 / each	\$34,200.00
1	Quote: 7912 Part: C-300-479 TOOLING Rev: FOB: TRIANGLE IF YOU HAVE ANY QUESTIONS ABOUT THIS QUOTE PLEASE CONTACT DAVE BAKAN	\$8,670.00 / each	\$8,670.00
	WE APPRECIATE THE OPPORTUNITY TO QUOTE TO YOU ON THE ABOVE, AND AWAIT YOUR REPLY.  AUTHORIZED SIGNATURE		

P.2

Page 1 of 1

AUG 26 00 07:19AM TRIANGLE PRECISION

MF0733



ISO9002

TRIANGLE PRECISION IND. INC.
1650 WOODMAN CENTER DRIVE
KETTERING, OH 45420

Ph: (937) 299-6776 Fax: (937) 299-7340

Quotation	
Number: 7909	Date: 25-Aug-00

To	REMINGTON ARMS CO., INC. 315 W. RING ROAD ELIZABETHTOWN, KY 42701 USA
----	---

Ph: (270) 769-7800 Fax: (270) 737-9576

Mail To	MIKE KEENY REMINGTON ARMS CO., INC. 315 W. RING ROAD ELIZABETHTOWN, KY 42701 USA
---------	---

Ph: 270-769-7610 Fax: (270) 737-9576

Terms		Ship Via		Salesperson
Net 30 days				
Quantity	Description	Unit Price	Amount	
1,500	QUOTE DURATION: 90 DAYS WE ARE PLEASED TO PRESENT OUR QUOTE ON THE FOLLOWING: Quote: 7908 Part: C-300-479 RECEIVER INSERT SUPPORT	\$7.00 / each	\$10,500.00	
1	Quote: 7910 Part: C-300-479 TOOLING FOB: TRIANGLE IF YOU HAVE ANY QUESTIONS ABOUT THIS QUOTE PLEASE CONTACT DAVE BAKAN	\$1,361.00 / each	\$1,361.00	
	WE APPRECIATE THE OPPORTUNITY TO QUOTE TO YOU ON THE ABOVE, AND AWAIT YOUR REPLY. <i>David J. Bakan</i> AUTHORIZED SIGNATURE			

Magnetic Particle Inspection Accessories

MAGNAFLUX offers a complete line of magnetic particle equipment as well as processing materials designed specifically for the NDT industry.

The selection guide below lists the variety of MAGNAFLUX tools and accessories designed to enhance the accuracy and sensitivity of your penetrant nondestructive testing. All MAGNAFLUX accessories are designed to meet major military and industrial specifications.

Local sales representatives and distributors are also available to help you find the right equipment for your NDT needs.

- Contacts and Coils for Wet Horizontal Units
- Central Conductors, Flat Magnetizing Coil and Adaptors
- Prod Sets and Assemblies
- Control Cables and Connectors
- Wet Particle Bath Sprayers
- Portable Powder Blower and Spray Bulb
- Test Pieces
- Field Indicators
- Centerfuge Tubes
- Monitoring Devices
- Black Light Systems
- Yoke and Yoke Kits
- Magnetic Particle Kits

CONTACTS AND COILS FOR WET HORIZONTAL UNITS

Copper braid pads and lead contact plates prevent burning by ensuring good electrical contact between test part and contact heads. Coils mount on rails of wet horizontal units for detection of transverse cracks on parts.



A) Lead Contact Plate (#605647)

- Duplicates original headstock/tailstock contact plates
- Soft lead plate provides excellent contact
- 1/4" x 6 3/4" x 6 5/8"
- Fits all units except A-915 and MAG Series units

B) Heavy-Duty Lead Contact Plate (#605657)

- Braided copper impregnated with lead
- Lasts up to 10 times longer than solid lead contact plates
- 1/4" x 6 3/4" x 6 5/8"
- Fits all units except A-915 and MAG Series units

C) Lead Contact Plate (#169542)

- Similar to #605647, fits A-915 and MAG Series units
- 1/4" x 5 1/4" x 6 3/4"



A) Double-Braided Pad with V-Block (#18948)

http://www.magnaflux.com/magnaflux/magnetic_particle_accessories.html

8/24/00


MF0735



- Heavy copper braid over neoprene base
- Molded-in V-block centers and supports test parts
- Flexible, provides contact over greater surface area
- Reversible — two wear faces
- Fits all units except A-915 and MAG Series units


B) Double-Braided Pad with Clip (#18949)

- Similar to #18948, but clips over headstock of A-915 and MAG Series units



Replacement Pad (#1848)

- Replacement copper pad for #18948 or #18949



12" Coil (#28501), 16" Coil (#28511), 20" Coil (#28531), 25" Coil (#28541)

- 5-turn coils in various diameters for all units, except A-915 and MAG III Series units

Coil Base (#26193)

- For use with coils on all units, except for A-915 and MAG Series units

12" Coil (#169584)

- 5-turn coil, similar to #28501
- Fits A-915 and MAG III Series units

Coil Base (#169579)

- For use with #169584 on A-915 and MAG III Series units

Coil Base (#196715)

- For use on MAG IV, MAG V and MAG VI units only



RETURN TO TOP

CENTRAL CONDUCTORS, FLAT MAGNETIZING COIL AND ADAPTORS

Copper braid pads and lead contact plates prevent burning by ensuring good electrical contact between test part and contact heads. Coils mount on rails of wet horizontal units for detection of transverse cracks on parts.



Flat Magnetizing Coil (#611700)


- Accessory for use with any magnetic particle unit or power pack
- Non-contact method of applying field
- Allows for quick, easy processing of small parts, such as fasteners, ring-like parts...several parts at a time
- Product Data Sheet



Central Conductors

These solid copper rods provide circular magnetization of hollow parts. Three sizes are available.

- A) 3/4" x 24" (#111203)
- B) 1" x 18" (#111204)
- C) 1/2" x 12" (#111202)



A) Small Parts Adaptor, Headstock (#28470)

- Enables inspection of small parts such as bolts, screws and pins on wet horizontal units
- Solid copper, mounts to headstock

B) Small Parts Adaptor, Tailstock (#28471)

- Used with #28470 above, mounts to tailstock
- Includes an adjustable miniature steadyrest




RETURN TO TOP

PROD SETS AND ASSEMBLIES

Hand-held electrodes enable magnetizing current to pass through sections of welds, castings, forgings and large fabrications.

All prod sets:

- Require additional power cables, purchased separately (see Cables and Connectors)
- Include either solid tips (for maximum wear) or braid tips (for better contact) and 20' control cable with trigger in handle
- Available with either 3 PTL plug for P-Series or 4 PTL plug for M-Series, CRV, CSQ and CSV Series power packs



Standard Prod Set (#157662)

- Individual contact prods offer maximum flexibility in prod-spacing and magnetizing of complex-shaped parts
- With 3 PTL plug for P-Series portable power packs

Prod Set (#157660)

- Same as #157662, but with 4 PTL plug
- Replacement Tip (#152652) also available



Braided Tip Prod Set (#186195)


- Similar to #157662, but with braid tips for better contact



- With 3 PTL plug for P-Series portable power packs

Braided Tip Prod Set (#186194)

- Same as #186195, but with 4 PTL plug
- Braided Replacement Tip (#78103) also available



Braided Conversion Assembly (#186202)

- Converts solid tips to braid tips — two required



RETURN TO TOP

CONTROL CABLES AND CONNECTORS

Rubber-covered flexible cables are available in standard lengths of 10', 15', and 20' with your choice of either end or lug connectors. Individual connectors to replace those worn or damaged in use are also available.



Remote Control Cable, 15' (#157657)

- Allows remote energization of portable power packs
- Standard with 3 PTL plug



Remote Palm Button (#169621)

- Mounts on side of MAG Kit for energizing current from power pack
- Standard with 3 PTL plug

Standard 4/0 Cable Assemblies

Part #	Length (Feet)	Fittings
11300	10	Lugs at both ends
11301	10	Lug and eitherend
11302	10	Eitherends at both ends
11306	15	Lugs at both ends
11307	15	Lug and eitherend
11308	15	Eitherends at both ends
11312	20	Lugs at both ends
11313	20	Lug and eitherend


http://www.magnaflux.com/magnaflux/magnetic_particle_accessories.html

8/24/00

MF0738

11314	20	Eitherends at both ends
-------	----	-------------------------

Custom 4/0 and 1 million circular mill cable assemblies are also available



A) 4/0 Eitherend Connector (#1238)

- Allows quick cable disconnect for maximum flexibility

B) 4/0 Lug (#2590)

- For permanent attachment to magnetizing equipment

C) Eitherend Lug Adaptor (#1574)

- Changes lug terminals to eitherend terminals

D) Eitherend Lug Adaptor, 90° (#1576)

- Similar to #1574, but at a 90° angle



RETURN TO TOP

CONTROL CABLES AND CONNECTORS

MAG Kit Pump (#69390)




- To be used with the MAG Kit bench unit
- Provides continuous spray and re-capture of MAGNAGLO bath
- Includes hose, nozzle, fittings, 5-gallon pail
- Operates on standard 115V, 50-60 Hz, single phase line current



RETURN TO TOP

PORTABLE POWDER BLOWER AND POWDER SPRAY BULB

Portable Powder Blower (#58600)



- Lightweight gun for applying Magnaflux dry powders in production conditions
- Regulated air-only blowoff removes excess powder
- Requires only 20 psi air supply



Powder Spray Bulb (#501232)

- Lightweight, easy-to-use spray bulb for applying Magnaflux dry powders
- Cap removes for easy filling

http://www.magnaflux.com/magnaflux/magnetic_particle_accessories.html

8/24/00


MF0739



RETURN TO TOP

TEST PIECES WITH ARTIFICIAL DEFECTS

Quantitative Quality Indicators (QQI) Artificial flaw shim standards for MPI increase productivity by minimizing magnetizing "shots". Are placed on part surface to verify field direction and relative strength. Particularly useful for balancing multi-directional fields. Approved by major specifications including ASTM E 1444 (replaced MIL-STD-1949A).

**A) Standard QQI Model KSC 230 (#519630)**

- Basic circular and crossed bar flaw configuration suitable for longitudinal and circular fields
- .0006" flaw depth amounts to 30% of shim thickness

B) Miniature QQI Model KSC 4-230 (#519631)


- Similar to KSC 230, except miniature design for small areas on test part
- Four circles per sheet may be cut apart for individual use

C) Variable Depth QQI Model KSCT 234 (#519632)


- For more quantitative work, three concentric circular flaws of differing depth, .0004", .0006", and .0008" (20%, 30%, 40%)

Ketos Test Ring (#159999)


- Drilled holes simulate subsurface discontinuities
- Form surface indications at various magnetizing current levels
- Meets ASTM E 1444 (replaced MIL-STD-1949A) requirements

**Magnetic Particle Test Bar (#189838)**

- Contains coarse and fine artificial surface and subsurface defects in both directions
- Meets or exceeds most industrial and military specifications for artificial test specimens, including MIL-STD-271

**Pie Field Indicator (#169799)**


- Used to establish adequacy of field per requirements of MIL-STD-271, ASTM E709 and ASTM E 1444 (replaced MIL-STD-1949A)



RETURN TO TOP

FIELD INDICATORS

A) Field Indicator (#2480)



- Rugged, pocket-size meter used to indicate residual magnetism remaining in part after demagnetization
- Inexpensive unit cannot be recalibrated


B) 10 Gauss Calibrated Indicator (#505056)

- Offers highly accurate measurement of residual leakage field in parts after demagnetization
- Accurate to ± 0.3 gauss. Scale range of 10-0-10
- Meets requirements of McDonnell-Douglas specifications

C) 20 Gauss Calibrated Indicator (#105645)

- Accurate to ± 0.5 gauss. Scale range of 20-0-20

Digital Hall Effect Probe Gaussmeter (#521043)




- Hand-held meter measures AC and DC magnetic field strength in Gauss
- Includes meter, transverse probe, probe extension cable, zero gauss chamber, four "AA" batteries, operation manual and carrying case
- Axial probe (#A-4048-002) available as an option



CENTRIFUGE TUBES

With MAGNAFLUX centrifuge tubes, you can monitor the concentration and level of contamination of magnetic particles in MAGNAFLUX or MAGNAGLO baths.

A) 14A Centrifuge Tube (#8493)



- 100 ml, 0-1.0 ml in 0.05 increments
- For use with #14A, #14AM and #20B MAGNAGLO fluorescent materials

7C/9C Centrifuge Tube (#2461)

- 100 ml, 0-1.5 ml in 0.10 increments
- For Magnaflux color-contrast materials including #7C, #9C and #9CM

MG-410 Centrifuge Tube (#507923)

- 100 ml, 0-0.2 ml in 0.01 increments
- For use with MG-410

B) Centrifuge Tube Stand (#1837A)


- Safely holds centrifuge tubes when mixing bath concentrations




RETURN TO TOP

MONITORING DEVICES

Easy-to-use test meters verify the accuracy of the built-in ammeter of standard wet horizontal magnetic particle units and power packs.

**Digital AC/FW/HWDC Test Meter Kit (#600355)**

- For all AC, Full Wave and Half Wave DC (FWDC & HWDC) wet horizontal units
- For all portable, mobile, stationary and multi-directional power packs up to 20,000 amps
- Includes calibrated meter, shunt, leads, operating instructions and carrying case with shoulder strap

**Analog HW Meter (#10095)**


- For HWDC portable and mobile power packs up to 4,000 amps

Analog HW Meter (#10098)

- For HWDC portable and mobile power packs up to 6,000 amps

Analog FW Test Meter (#10090)

- For FWDC wet horizontal units and stationary power packs up to 6,000 amps

**Quick Break Tester (#148335)**

- Quickly and accurately confirms function status of "quick break" circuitry in three phase FWDC magnetic particle units
- Manufactured for compliance to ASTM E 1444 specification requirements (replaced MIL-STD-1949A)



RETURN TO TOP

Material Requisition. S C R Qty. I A Release strategy	Item	Short text Requested qty. Un Deliv. date Req. val. Cur Release date Trackg.no. Release indicator Release option	PGP Requester	Mat. gp. Plnt SLoc SPL. MC
X	1000525405 00010 N R A NB Z S1	WASTE REMOVAL 1.000 EA D 08/21/2000 GOLEMBOSKIMR 618.00 USD 08/18/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected	M09	SERVICE MAY
X	1000525405 00020 N R A NB Z S1	FUEL SURCHARGE 1.000 EA D 08/21/2000 GOLEMBOSKIMR 2.90 USD 08/18/2000 GOOCHJC B APPROVED FOR PURCHAS Release effected	M09	SERVICE MAY
X	1000525406 00010 N R A NB Z S1	710 MAG BOX SPRING GAGE 2.000 EA D 08/21/2000 GOLEMBOSKIMR 305.00 USD 08/18/2000 CHOATECH B APPROVED FOR PURCHAS Release effected	M09	MISC MAY
X	1000525407 00010 N R A NB K S1	TESTING FOR PROSPECTIVE EMPLOYEES 2.000 EA D 08/21/2000 GOLEMBOSKIMR 130.00 USD 08/18/2000 HALEYMA B APPROVED FOR PURCHAS Release effected	M09	MISC MAY
X	1000525407 00020 N R A NB K S1	TESTING FOR PROSPECTIVE EMPLOYEES 3.000 EA D 08/21/2000 GOLEMBOSKIMR 225.00 USD 08/18/2000 HALEYMA B APPROVED FOR PURCHAS Release effected	M09	MISC MAY
X	1000525410 00010 N R A NB Z S1	WEILER MINATURE END BRUSH 3/16 #26136 5.000 EA D 08/21/2000 GOLEMBOSKIMR 15.30 USD 08/18/2000 ZAJKJJ A AWAITING APPROVAL Release possible	M09	MISC MAY
X	1000525410 00020 N R A NB Z S1	WEILER MINATURE END BRUSH 1/4 #26138 5.000 EA D 08/21/2000 GOLEMBOSKIMR 17.10 USD 08/18/2000 ZAJKJJ A AWAITING APPROVAL Release possible	M09	MISC MAY
X	1000525410 00030 N R A NB Z S1	WEILER MINATURE END BRUSH 5/16 #26146 5.000 EA D 08/21/2000 GOLEMBOSKIMR 16.98 USD 08/18/2000 ZAJKJJ A AWAITING APPROVAL Release possible	M09	MISC MAY
X	1000525410 00040 N R A NB Z S1	WEILER MINATURE END BRUSH 135 #26906 5.000 EA D 08/21/2000 GOLEMBOSKIMR 31.00 USD 08/18/2000 ZAJKJJ A AWAITING APPROVAL Release possible	M09	MISC MAY
X	1000525410 00050 N R A NB Z S1	FREIGHT CHARGES 1.000 EA D 08/21/2000 GOLEMBOSKIMR 3.25 USD 08/18/2000 ZAJKJJ A AWAITING APPROVAL Release possible	M09	MISC MAY
X	1000525411 00010 N R A NB Z S1	WIREBURN HOLE IN BLOCK 1.000 EA D 08/22/2000 GOLEMBOSKIMR 87.50 USD 08/18/2000 CHOATECH B APPROVED FOR PURCHAS Release effected	M09	MISC MAY
X	1000525412 00010 N R A NB Z S1	CD MAILERS (MELISSA) 4.000 EA D 08/22/2000 GOLEMBOSKIMR 2.88 USD 08/18/2000 HUTSONLR B APPROVED FOR PURCHAS Release effected	M09	02 MAY
X	1000525412 00030 N R A NB Z S1	#00434 MYLAR TABS (MELISSA) 1.000 EA D 08/22/2000 GOLEMBOSKIMR 5.45 USD 08/18/2000 HUTSONLR B APPROVED FOR PURCHAS Release effected	M09	02 MAY
X	1000525412 00040 N R A NB Z S1	"RECEIVED" STAMP (MELISSA) 1.000 EA D 08/22/2000 GOLEMBOSKIMR 7.16 USD 08/18/2000 HUTSONLR B APPROVED FOR PURCHAS Release effected	M09	02 MAY
X	1000525412 00050 N R A NB Z	TAPE FLAGS (MELISSA) 2.000 EA D 08/22/2000 GOLEMBOSKIMR 3.18 USD 08/18/2000 HUTSONLR	M09	02 MAY

MF0743

Material	Short text	PGp	Mat. gp.
Requish. Item	Requested qty. Un Deliv. date Requester	Plnt SLoc	
S C R Qty. I A	Req. val. Cur Release date Trackg.no.	Spl. MC	
Release strategy	Release indicator Release option		
S1	B APPROVED FOR PURCHAS Release effected		
X	ELD 20241 FILE (MELISSA) M09 02		
1000525412 00060	1.000 EA D 08/22/2000 GOLEMBOSKIMR MAY		
N R A NB Z	29.95 USD 08/18/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	27410 BLACK PENS (SUPPLY CLOSET) M09 02		
1000525412 00070	48.000 EA D 08/22/2000 GOLEMBOSKIMR MAY		
N R A NB Z	3.96 USD 08/18/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	AMETECH TACHOMETER M09 MISC		
1000525553 00010	1.000 EA D 08/25/2000 GOLEMBOSKIMR MAY		
N R A NB Z	307.00 USD 08/18/2000 GOOCHJC		
S1	B APPROVED FOR PURCHAS Release effected		
X	UNIFORM RENTAL WEEK ENDING 07/28/2000 M09 MISC		
1000525554 00010	1.000 EA D 08/21/2000 GOLEMBOSKIMR MAY		
N R A NB K	273.94 USD 08/18/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	UNIFORM RENTAL WEEK ENDING 08/04/2000 M09 MISC		
1000525554 00020	1.000 EA D 08/21/2000 GOLEMBOSKIMR MAY		
N R A NB K	292.54 USD 08/18/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	UNIFORM RENTAL WEEK ENDING 08/11/2000 M09 MISC		
1000525554 00030	1.000 EA D 08/21/2000 GOLEMBOSKIMR MAY		
N R A NB K	264.27 USD 08/18/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	UNIFORM RENTAL WEEK ENDING 08/18/2000 M09 MISC		
1000525554 00040	1.000 EA D 08/21/2000 GOLEMBOSKIMR MAY		
N R A NB K	336.41 USD 08/18/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	REPAIR CLECO NUTRUNNER M09 03		
1000525794 00010	2.000 EA D 09/08/2000 GOLEMBOSKIMR MAY		
N R A NB Z	150.32 USD 08/21/2000 TRUAXSF		
S1	B APPROVED FOR PURCHAS Release effected		
X	GLOVES-SIZE L 9-9-1/2 M09 01		
1000525795 00010	6.000 EA D 08/25/2000 GOLEMBOSKIMR MAY		
N R A NB Z	23.70 USD 08/21/2000 CHAVISWT		
S1	B APPROVED FOR PURCHAS Release effected		
X	#0714 BANDAGE, FINGERTIP M09 02		
1000525796 00010	1.000 EA D 08/22/2000 GOLEMBOSKIMR MAY		
N R A NB Z	7.46 USD 08/21/2000 HALEYMA		
S1	B APPROVED FOR PURCHAS Release effected		
X	#0743 BANDAGE, LARGE PATCH M09 02		
1000525796 00020	1.000 EA D 08/22/2000 GOLEMBOSKIMR MAY		
N R A NB Z	7.30 USD 08/21/2000 HALEYMA		
S1	B APPROVED FOR PURCHAS Release effected		
X	#1431 DILOTAB M09 02		
1000525796 00030	1.000 EA D 08/22/2000 GOLEMBOSKIMR MAY		
N R A NB Z	10.45 USD 08/21/2000 HALEYMA		
S1	B APPROVED FOR PURCHAS Release effected		
X	#1446 TRIAL ANTACID M09 02		
1000525796 00040	1.000 EA D 08/22/2000 GOLEMBOSKIMR MAY		
N R A NB Z	10.45 USD 08/21/2000 HALEYMA		
S1	B APPROVED FOR PURCHAS Release effected		
X	#1801 3-IN-1 ANTIBIOTIC OINT. M09 02		
1000525796 00050	1.000 EA D 08/22/2000 GOLEMBOSKIMR MAY		
N R A NB Z	8.35 USD 08/21/2000 HALEYMA		
S1	B APPROVED FOR PURCHAS Release effected		
X	#X6065 TOMAHAWK BLACK/CLEAR LENS M09 02		
1000525796 00060	12.000 EA D 08/22/2000 GOLEMBOSKIMR MAY		

MF0744

Cost center 0000028200

Material	Item	Short text	PGp	Mat. gp.
Requisn.		Requested qty. Un	Deliv. date	Requester
S C R QTY. I A		Ordered qty. Un	Release date	Trackg.no.
				Plnt SLoc
				SPL. MC
-	1000525406 00010	710 MAG BOX SPRING GAGE	M09	MISC
	N R A NB Z	2.000 EA D 08/21/2000	GOLEMBOSKIMR	MAY
			08/18/2000	CHOATECH
-	1000525410 00010	WEILER MINATURE END BRUSH 3/16 #26136	M09	MISC
	N R A NB Z	5.000 EA D 08/21/2000	GOLEMBOSKIMR	MAY
			08/18/2000	ZAJKJJ
-	1000525410 00020	WEILER MINATURE END BRUSH 1/4 #26138	M09	MISC
	N R A NB Z	5.000 EA D 08/21/2000	GOLEMBOSKIMR	MAY
			08/18/2000	ZAJKJJ
-	1000525410 00030	WEILER MINATURE END BRUSH 5/16 #26146	M09	MISC
	N R A NB Z	5.000 EA D 08/21/2000	GOLEMBOSKIMR	MAY
			08/18/2000	ZAJKJJ
-	1000525410 00040	WEILER MINATURE END BRUSH 135 #26908	M09	MISC
	N R A NB Z	5.000 EA D 08/21/2000	GOLEMBOSKIMR	MAY
			08/18/2000	ZAJKJJ
-	1000525411 00010	WIREBURN HOLE IN BLOCK	M09	MISC
	N R A NB Z	1.000 EA D 08/22/2000	GOLEMBOSKIMR	MAY
			08/18/2000	CHOATECH
-	1000525797 00010	# C-K-10510-A	M09	03
	N R A NB Z	2.000 EA D 09/08/2000	GOLEMBOSKIMR	MAY
			08/21/2000	ZAJKJJ
-	1000525797 00020	#C-K-10510-B	M09	03
	N R A NB Z	4.000 EA D 09/08/2000	GOLEMBOSKIMR	MAY
			08/21/2000	ZAJKJJ
-	1000525797 00030	#C-K-10510-C	M09	03
	N R A NB Z	4.000 EA D 09/08/2000	GOLEMBOSKIMR	MAY
			08/21/2000	ZAJKJJ

BARBER - 5.22.06/0010695

ME0745

Confidential - ~~Subsequent~~ - 5.22.06/0010695 Order
Williams v. Remington



FACSIMILE

Date: 7/10/00

TO: Kristen

FROM: Raymond P. McKinney
National Sales/Marketing Manager

ATTN: Remington Industries

OMNI TECHNOLOGIES
CORPORATION

3742 Long Grove Avenue
Port Orange, FL 32119

Phone:

Phone: (904) 756-7547

FAX: 270 852 3233

FAX: (904) 756-8443

Page 1 of 2

ENCLOSED ARE THE SPECS FOR THE B49 Z4 ALLOY. MAKE SURE
THE HEAT TREAT TIME WAS SLIGHTLY INCREASED OVER THE 56%
SILVER DIRECTIONALLY SPEED OUT. LET ME KNOW WHAT
YOUR CYCLE TIME IS AS WE MAY NEED TO MODIFY THE
FLUX IF OVER 45 SECONDS WITH INDUCTION

THANKS
E

E-mail: RAYMONDRPM@aol.com
Corporate Headquarters: 334 Calef Highway, Epping, NH 03042 Phone: (603) 679-2211; Fax: (603) 679-1131

MF0746

**SILVER BRAZING ALLOYS**

LTB NO.	AMS	AWS	Ag	Cu	Zn	Cd	OTHERS	LIQUIDUS F C		SOLIDUS F C	
LTB 1	4769B	Spec BAg-1	45	15	16	24	—	1145	620	1125	605
LTB 1a	4770F	BAg-1a	50	15.5	16.5	18	—	1175	635	1160	625
LTB 2	4768D	BAg-2	35	28	21	18	—	1295	700	1125	605
LTB 2a		BAg-2a	30	27	23	20	—	1310	710	1125	605
LTB 3	4771D	BAg-3	50	15.5	15.5	16	3 Ni	1270	690	1170	630
LTB 4		BAg-4	40	30	28	—	2Ni	1435	780	1220	660
LTB 5		BAg-5	45	30	25	—	—	1370	745	1225	665
LTB 6		BAg-6	50	34	16	—	—	1425	775	1250	675
LTB 7		BAg-7	56	28	17	—	5 Sn	1205	650	1145	620
LTB 8		BAg-8	72	28	—	—	—	1435	780	1435	780
LTB 8a		BAg-8a	72	27.5	—	—	0.5 Li	1410	765	1410	765
LTB 9		BAg-9	65	20	15	—	—	1325	720	1240	670
LTB 10		BAg-10	70	20	10	—	—	1360	740	1275	690
LTB 13	4772E	BAg-13	54	40	5	—	1 Ni	1575	857	1325	718
LTB 13a	4765A	BAg-13a	56	42	—	—	2 Ni	1640	895	1420	770
LTB 18	4773B	BAg-18	60	30	—	—	10 Sn	1325	720	1115	600
LTB 19	4757B	BAg-19	92.5	7.25	—	—	0.25 Li	1635	891	1435	780
LTB 20		BAg-20	30	38	32	—	—	1410	765	1250	675
LTB 21	4774B	BAg-21	63	28.5	—	—	2.5 Ni 6 Sn	1475	800	1275	690
LTB 22		BAg-22	49	16	23	—	4.5 Ni 7.5 Mn	1290	700	1260	680
LTB 23	4766C	BAg-23	85	—	—	—	15 Mn	1780	970	1760	960
LTB 24		BAg-24	50	20	28	—	2 Ni	1305	705	1220	660
LTB 25		BAg-25	20	40	35	—	5 Mn	1455	790	1360	740
LTB 26		BAg-26	25	38	33	—	2 Ni 2 Mn	1475	800	1305	705
LTB 27		BAg-27	25	35	28.5	13.5	—	1375	745	1125	605
LTB 28		BAg-28	40	30	28	—	2 Sn	1310	710	1200	65

OMNI TECHNOLOGIES manufactures a complete line of silver brazing alloys. OMNI LTB pastes are manufactured using the highest purity, oxide-free, spherical brazing powders. Our constituent blending with carefully formulated fluxes and suspending agents provides precision brazing performance with unparalleled rheological homogeneity.

MF0747

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

06/29/00

C:\WINDOWS\Desktop\710 Capital & Start up Costs.xls\710 capital by operation

In House Capital

Part Name	Operation	Equipment	Capital Required	Capital Actual	(Under)/ Over	Date Ordered	Expected Delivery Date	PO #
Barrel	Cut off		\$0		0			
	Drill	cones	\$9,960	0	(9,960)	canceled		
	Ream		\$0		0			
	Rifle	gages	\$9,800	15,747	5,947			
	Wash & Stress Relieve	baskets	\$6,900		(6,900)			
	Turn	gages	\$10,100		(10,100)			
	Face & Chamber	gages	\$33,300	32,949	(351)			See BBL Capital O
	Face & Chamber	machine	\$222,880	226,500	3,620	12/21	4/7	M017457
	Cut off and Crown	chuck	\$15,000	8505	(6,495)	2/15	2/29	M016749
	wash and eddy current test	machine	\$75,000	84000	9,000			
OP 70	Induction Harden	machine	\$166,000	153,500	(12,500)	1/17	4/20	M017471
	Inspect Hardness	machine	\$12,000	13,800	1,800	1/28	2/29	M016619
	Drill and tap sight	fix & gages	\$7,600	3000	(4,600)	3/14	4/11	M016948
	Roll mark	fix & gages	\$6,300		(6,300)			
	Angularity Straighten	fix & gages	\$3,500		(3,500)			
	Centerless Polish		\$0	0	0			
	Glass Bead Blast	fixtures	\$2,500	0	(2,500)			
	Color	racks	\$6,000	0	(6,000)			
	Inspect Purchased Part							
	Blank	gage	\$2,500	3,635	1,135			
Bolt Head	Superabrasive Grind Lugs	fix & gage	\$43,800		(43,800)			
	Carpenter Extrusion Die		2800					m017611
	CNC Machine Bolt Face							
	Complete	fix & gage	\$174,784	115,000	(59,784)	4/6	5/9/00	M017574
	CNC Machine Cam Cuts							
	Ejector Retaining Pin Hole	fix & gage	\$15,000	10,000	(5,000)			
	CNC Machine Bolt Head							
	Retaining Pin Hole	fix & gage	\$15,000		(15,000)			
	Vendor fixturing			2,090				m017607
	Punch Form Extruder							
Bolt Body	Rotator Notch	fix & gage	\$10,000		(10,000)			
	Vendor Heat Treat		\$0		0			
	Inspect for Hardness		\$0		0			
	Black Oxide		\$0	2,440	2,440			M018307
	Inspect Purchased Part							
	Blank	gage	\$2,000	2,837	837	2/4/00	3/1/00	M016649
	Machine Cam Cuts	machine	\$0		0			
	Assemble Braze Bolt	machine	\$90,000	59,635	(30,365)	31-Jan	8-May	M17490
	Door interlock			1,530			7-Jun	M018521
	Exhaust Fan and Duct			2,986			31-Jul	M018676
Receiver	Deplate	tanks	\$9,500		(9,500)			
	Eddy Current Test		\$0		0			
	Glass Bead Blast	fix	\$2,500		(2,500)			
	Black Oxide		\$0		0			
	Inspect Purchased Part							
	Blank	gage	\$2,500	2838	338			See M016649
	Machine A-load	Machine	\$461,831		(461,831)			
	CMM		\$52,000	52400	400	4-Feb	15-Feb	M17492
	Machine B-load		\$0		0			
	Vibratory tumble deburr		\$0		0			

MF0748

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

06/29/00

C:\WINDOWS\Desktop\710 Capital & Start up Costs.xls\710 capital by operation

Barrel Assembly	Press Receiver to Barrel	fixture	\$0	5811	5,811			
	Inspect for straightness	gage	\$3,500	0	(3,500)			
Final Assembly	Gallery	100yd range	\$100,000	0	(100,000)			
		snails	\$30,000	11000	(19,000)	2/22/00	3/31/00	M016804
		snails		16600		4/4/00	5/15/00	M018084
		HVAC	\$25,000	0	(25,000)			
		other	\$10,000	15202	5,202			
				0				
			\$100,000	0	(100,000)			
			\$65,000	460,000	395,000		7/1/00	
TOTAL IN HOUSE CAPITAL			\$1,801,755	1,306,605	(\$495,150)			

Purchased Parts

Part #	Part Name	Capital	Tool	Capital Actual	Date Ordered	Expected Delivery Date	PO #
300327	Receiver Insert	48,000	Mold	46,227	1/20	3/29	M017478
300333	Side Plate	10,000	Stamping Die	7500	1/26	4/11	M017491
300334	Safety Arm	23,880	Stamping Die	19,900	1/26	2/28	M017486
300345	Bolt Stop	6,820	FIM	5500	1/25	3/15	M017477
300361	Recoil Bracket	2,225	Stamping Die	850	1/19	3/27	M017484
300360	Bolt Handle Blank	12,800	Insert Cast Die	6895	1/24		
300366	Bolt H. Braze Shim	0	Use Paste	0	canceled		
300368	Bolt Plug	38,088	Mold	38,000	12/14	3/21	M017443
300336	Firing pin head	28,000	MIM Mold	16,000	1/14	3/16	M017470
300382	Mag Latch	53,480	Mold	31,806	1/11	4/24	M017465
300363	Magazine Box	28,000	Mold	83,000	3/6	6/9	M017530
300364	Magazine Follower	33,300	Mold	0	see Mag Bottom		M017466
300365	Magazine Bottom	47,880	Mold	73,786	1/12	4/17	M017466
	Stock	150,300	Mold	145,300	12/13	3/29	M017435
	Stock Cam Bed	0	Die	0			
	PPI	38000	See PPI Detail	16850			
} follower and Box bottom family mold							
TOTAL VENDOR CAPITAL		\$495,773		\$ 490,314		(5,459)	

Addition Items Unbudgeted

Trigger	0	PM Die	16,000	16,000	14-Jan	16-Mar	M017487
Bolt Plug Insert	0	Extrusion die	2250	2,250	20-Jan	29-Mar	M017479
Tumbler	0	MIM Mold	20,000	20,000	20-Jan	29-Mar	M017480
Micro Centric Chuck	0	Chuck head	3645	3,645	21-Jan	10-Feb	M016555
bolt handle mold #2	0	mold	8595	8,595		18-Jun	
Magazine Spring	0	Stamping Die	16044	16,044	4-Feb	27-Apr	M017497
Comparator for trigger adj.	0	Comparator	2899	2,899	16-Jun	30-Jun	M018591
Comp fixture (trigger adj)	0	E-10462	5530	5,530	10-Mar	10-Apr	M016929
Stock Drilling Fixture	0	Fixture	7500	7,500	27-Mar	20-Apr	M017559
2nd stock Cooling Fixture	0	Fixture	6000	6,000			
F&S Marker	0	Stamp Mach	4250	4,250	13-Apr	19-May	M018158
Orbitform	0	nveter	11,100	11,100	4-Apr	19-May	M018075
Proof Device	0	Device	5,052	5,052	4-Apr	28-Apr	M018069
Trigger Pull Gage	0	Gage	5,995	5,995	18-May	26-Jun	M018374
Load Cell	0	Gage	2,000	2,000	22-May	26-Jun	M018417
Install Buss for Maint.	0	Electric Buss	10,600	10,600	15-Jun	30-Jun	M018561
Bbl assembly fixture	0	E-10491	4,600	4,600	19-Jun	27-Jun	M018615
TOTAL UNBUDGETTED			132,060	132,060			

MF0749

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

06/29/00

C:\WINDOWS\Desktop\710 Capital & Start up Costs.xls\710 capital by operation

CONFIDENTIAL 83

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

06/29/00

C:\WINDOWS\Desktop\[710 Capital & Start up Costs.xls]710 capital by operation

Total Budget	\$2,297,528	Outstanding Purchases	\$112,400
Total Committed	\$ 1,928,979	Remainder to Budget	-\$93,282
		Projected Capital Spending Over/(under)	205,682
Remaining	\$368,549		
Free Markets Avoidance	\$461,831		
Remainder to Budget w/ FM savings	-\$93,282		

CONFIDENTIAL

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

06/29/00

C:\WINDOWS\Desktop\710 Capital & Start up Costs.xls\710 capital by operation

Total Budget	\$2,297,528
Remaining based on \$2.3MM budget	\$368,549

Total Committed	\$	1,926,979
Free Markets Avoidance		\$461,831
Future Purchases		(\$93,282)
Outstanding Purchases		\$492,200

CONFIDENTIAL

BARBER - 5.22.06r0010703

Part #	Part Name	Vendor	Qty on order	Qty Received	Qty on Hand	Approved	PPO	Vendor Contact	Comments
15161	front screw bushing	ilion	6000	6000	5629	yes	y		rev. 11
15400	trigger spring	ilion	6000	6000	6131	yes	y		rev. 11
15481	trigger stop screw	ilion	6000	6000	6000	?	y		part # 300426
15666	sear safety cam	ilion	4000	4000	3958	?	y		rev. 24
17043	safety pivot pin	ilion	5000	5000	5016	yes	y		rev. 33
17044	safety snap washer	balax incorporated	6000	6000	6009	yes	y		rev. 26
17047	sear spring	ilion	6000	6000	6085	yes	y		rev. 26
17053	front trigger screw	pacific precision grinding	7500	7500	7718	yes	y		rev. 32
19461	trigger connector	ilion	6000	3000	3000	yes	y		rev. 21
91128	trigger engagement screw	ilion	2000	2000	2000	yes	y		?
93712	extractor	ilion	6000	3000	5921	yes	y		rev. 2
94084	front sights (.270/30-06)	ilion	3000	3000	2011	yes	y		rev.26 mixed with magnum sights
94095	front sights (magnum)	ilion			988	yes	y		rev. 17
94555	ejector pin	ilion	6000	4000	4029	yes	y		rev. 1
94657	front sight ramp	ilion	3100	3100	3105	yes	y		rev. 33
94996	sling swivel studs	michael's oregon	10000				y		
97971	grip cap	oneida	7000	7000	7000	yes	y		rev. 0
97973	recoil pad	oneida	6000	6000	6000	yes	y		rev. 26
98008	recoil pad screw	ilion	10000	10000	9913	yes	y		rev. 7
104131	front takedown screw	komar screw corporation	20000				y		
104133	middle takedown screw	ilion	5000	2000	2000		y		rev. ?
109835	trigger	ilion	1500	200	199	?	y		
201217	bolt plug tumbler spring	ilion	5000	5000	5000	yes	y		rev. 0
201224	lock plunger	ilion	1000	1000	884	no	y		part # 300466
300327	receiver insert	hanson	1000				N		
300328	side plate pin	iseli	60000	20000	3980	yes	y		rev. 3
300329	bolt handle pin	automatic swiss	20000	10500	5379	yes	y		rev. 3
300330	bolt assembly pin	automatic swiss	20000	3181	9953	yes	y	APPROVED	rev. A
300334	firing pin	quicktek	20000		421	yes	y	faxed vendor	rev. D length too long
300335	firing pin tip	quicktek	20000	10	492	yes	y		rev. 5
300336	firing pin head	megamet	100	900	900	no	N		rev. I waiting for new parts
300339	bolt body	ippilito & hauser	1000				N		
300340	receiver	ippilito & hauser	1000 each vendor		142		N		
300342	ejector	iseli	20000	10075	10046	yes	y		rev.3
300345	bolt stop	sterling	400	521	521	yes	y	APPROVED	rev. 17
300346	bolt plug insert	anderson screw	21399	1399	877	yes	y		rev. F 105 parts???anderson
300347	threaded insert	precision fasteners	5000	5000	4937	yes	y		rev. B
300351	pivot pin	swiss precision	60000		11,800	yes	y	APPROVED	rev. B
300360	bolt handle blank	north american	100			yes	N		

ME0753

Confidential - ~~Shriener~~ - 5:22 PM 6/6/07
Williams v. Remington

300362	magazine latch	par 4	20000		740	yes	y		rev. 8
300363	magazine box	deer park die & stamping	20000		458	yes	y	samples 7/19	rev. 15
300364	follower	par 4	100000		115	no	y		rev. 24 missed revisions
300365	magazine box bottom	par 4	100000		203	yes	y		rev. 23
300367	ejector spring	midstate spring	20000	20000	20117	yes	y		rev. D
300368	bolt plug	kellems & coe tool co	50		38	yes	N		rev. 9
300371	latch pivot pin	automatic swiss	20000	11000	11005	yes	y		rev. B
300398	latch spring	midstate spring	20000	20000	5100	yes	y	APPROVED	rev. B
300399	firing pin spring	midstate spring	20000	19860	19978	yes	y		rev. E
300405	magazine spring	valley tool and die	1000	1000	996	?	N	new tool samp. 6/29	rev. A profile off
300407	safety spring	midstate spring	21000	21000	21115	yes	y		rev. 4
300408	safety arm	square stamping	20000		1613	yes	y	1000 pc. ASAP	rev. 16
300420	tumbler blank	megamet	100		1100		N		300418?
300425	takedown screw	komar screw corporation	20000		10797	yes	y		rev. 0
300426	trigger stop screw	alliance fastener	21000	2303	11033		y		rev. C
300427	spring retainer	iseli	22000		0	no	y	due 6/19	rev. C waiting for new parts
300434	bolt head blank	quicktek	22000		10	yes	y		rev. 1
300437	stock	par 4	150				N		
300441	scope rail	minalex	10000				y		
300448	trigger engagement screw	alliance fastener	21000	2500	10769		y		rev. C mat. Change to 12L14
300454	recoil bracket blank	square stamping	20000	5115	110	yes	y		
300456	side plate blank	square stamping	20000	1425	1487	yes	y		rev. ? 1375 black oxidized
300463	trigger pivot pin	swiss precision	500	550	488		N	due 6/26	
300464	sear retaining pin	swiss precision	500	550	561		N	due 6/26	
300465	pin retaining clip	motion industries	1500	200	500	yes	y		rev. A
300466	lock plunger	iseli	2000				N	due 7/17	
300333	side plate	square stamping			1487	yes			Black oxidized

FYI
mm

FAXED
7-28-00
mm

7/28/00

TO: MR. CHUCK ULINSKI / QUICK-TEK

FROM: MS. METTY MORGAN / REMINGTON

Chuck,

Would you please fax to me at your earliest convenience, an updated quote on the cost to manufacture the 710 bolt head in the following stages:
Quote the bolt head each way out of both material types, round and extruded.

- 1.) Blank without any face machining
- 2.) Blank with face machining
- 3.) Blank complete with face machining and EDM

I need these quotes to update my files. There has been so much going on, I am not sure where my cost for what, is right now.

Thanks Chuck,

Sincerely,

Metty
mm

MF0755



custom manufacturing solutions
Injection molds • plastic & metal components

4073 Wedgeway Court
Earth City, Missouri 63045
(314) 739-4499 • Fax (314) 739-5281
www.megamet.com

July 12, 2000
Jerry Helmer
270-856-3233


Jerry,

To meet the dimension requirements on the J-Lock tumbler we would have to remake the slide that forms the J. Megamet built the current slide to the nominal dimension with allowances for shrink. Since the part appears undersized we would make the new slide to the maximum allowed dimension after shrink.

We would require one week, 40 man-hours, to remake this part. We will not proceed to make this change unless instructed by Remington.

Please advise on any questions.

Sincerely,


Jim Mullineaux
President & COO

7/17/00
To: MATT & JOE
FROM: JERRY

FYI.

MF0756

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

01/12/00

C:\WINDOWS\Desktop\m710\summary of capital.xls\710 capital by operation

In House Capital

Part Name	Operation	Equipment	Capital Required	Capital Actual	Date Ordered	Expected Delivery Date
Barrel	Cut off		\$0			
	Drill	cones	\$9,960			
	Ream		\$0			
	Rifle	gages	\$9,800	HAUSER/MORRIS/DATK - 5.22.06		
	Wash & Stress Relieve	baskets	\$6,900	HAUSER/MORRIS		
	Turn	gages	\$10,100	ZACK/DICK		
	Face & Chamber	gages	\$33,300	ZACK/MORRIS/DICK/MORRIS		
	Face & Chamber	machine	\$222,880	ZACK/DICK/LEE		
	Cut off and Crown	chuck	\$15,000	ZACK/DICK		
	wash and eddy current test	machine	\$75,000	ZACK - MACHINE FOR 710		
	Induction Harden	machine	\$166,000	ZACK/MORRIS/TAYLOR		
	Inspect Hardness	machine	\$12,000	HAUSER		
	Drill and tap sight	fix & gages	\$7,600	ZACK/DICK		
	Roll mark	fix & gages	\$6,300			
	Angularity Straighten	fix & gages	\$3,500			
	Centerless Polish		\$0	GOOD		
	Glass Bead Blast	fixtures	\$2,500	GOOD		
	Color	racks	\$6,000	GOOD		
Bolt Head	Inspect Purchased Part Blank	gage	\$2,500	MORRIS/HAUSER		
	Superabrasive Grind Lug	fix & gage	\$43,800	KASTAN/ZACK/HAUSER		
	CNC Machine Bolt Face	fix & gage	\$174,784	MORRIS/ZACK/HAUSER		
	CNC Machine Cam Cuts	fix & gage				
	Ejector Retaining Pin Hole	fix & gage	\$15,000	KASTAN		
	CNC Machine Bolt Head	fix & gage	\$15,000	KASTAN		
	Retaining Pin Hole	fix & gage				
	Punch Form Extractor	fix & gage	\$10,000	ZACK/KASTAN/LEE		
	Rotation Notch		\$0	MORRIS		
	Vendor Heat Treat		\$0	HAUSER		
	Inspect for Hardness		\$0	GOOD		
	Black Oxide		\$0	GOOD		
Bolt Body	Inspect Purchased Part Blank	gage	\$2,000	HAUSER		
	Machine Cam Cuts	machine	\$0	ZACK		
	Assemble Braze Bolt	machine	\$90,000	KASTAN		
	Deplate	tanks	\$9,500	KASTAN/TAYLOR		
	Eddy Current Test		\$0	ZACK		
	Glass Bead Blast	fix	\$2,500	GOOD		
	Black Oxide		\$0	GOOD		
Receiver	Inspect Purchased Part Blank	gage	\$2,500	HAUSER		
	Machine A-load	machine & CMM	\$513,831	MORRIS/JOE		
	Machine B-load		\$0			

Morgan, Metty E.

From: Golemboski, Matt R.
Sent: Wednesday, July 26, 2000 6:46 AM
To: Morgan, Metty E.
Subject: firing pin tip and firing pins for m710

Please order these parts 3000 a month Starting Sept 5 through Dec 1.
12,000 pc total to be delivered by Dec. 1.

Matt Golemboski
Plant Manager, Mayfield

PPO - DONE
20,000 EA
ON PO
MO17441

updated DELIVERY
SCHEDULE Today
per this E-MAIL

* Chuck WANTED All
20,000 DELIVERED this YEAR
I scheduled 5,000 per Mo.

FYI
Metty
😊

Estimated Time for Magnetic Particle Testing:

Operations:

1. Set Barrel into machine, step foot pedal to clamp machine.
2. Turn knob to DC
3. Set amperage to 1000 for head shot # 1 (For viewing chamber area)
4. Spray magnetic particle solution bath over barrel
5. Magnetize barrel
6. Make visual inspection of barrel with "spot" beam black light.
7. Set amperage to 500 for head shot # 2 (For viewing muzzle end)
8. Follow steps 4 thru 6.
9. Demagnetize barrel
10. Turn amperage knob to 500 amps for coil shot # 1
11. Move coil to position about 5 inches from the chamber end of the barrel
12. Follow steps 4-6
13. Set amperage to 300 for coil shot # 2
14. Follow step 4 thru 6
15. Demagnetize the barrel for both shots.
16. Wash barrel with water and dry

Coil: 1:19:00 per barrel

# Barrels	Elapsed Time @ 100% HRS		
100	119		2.0
200	238		4.0
300	357		6.0
400	476		7.9
500	595		9.9
1000	1190		19.8

Elapsed time @ 65%	HRS
77.35	1.3
154.7	2.6
232.05	3.9
309.4	5.2
386.75	6.4
773.5	12.9

For 65% = 0.01667 HRS/BAL

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

01/12/00

C:\WINDOWS\Desktop\m710[summary of capital.xls]710 capital by operation

	Vibratory tumble deburr		\$0			
Barrel Assembly	Press Receiver to Barrel	fixture	\$0	<i>Correct</i>		
	Inspect for straightness	gage	\$3,500	<i>Correct</i>		
Final Assembly	Gallery	100yd range	\$100,000	<i>TRAX</i>		
		snails	\$30,000			
		HVAC	\$25,000			
		other	\$10,000			
			\$100,000			
			\$65,000			

\$1,801,755

Purchased Parts

Part #	Part Name	Capital	Tool	Capital Actual	Date Ordered	Expected Delivery Date
300327	Receiver Insert	48,000	Mold			
300333	Side Plate	40,000	Stamping Die			
300334	Safety Arm	23,880	Stamping Die			
300345	Bolt Stop	6,820	PM			
300351	Recoil Bracket	2,225	Stamping Die			
300360	Bolt Handle Blank	12,800	Invest Cast Die			
300366	Bolt H. Braze Shim	0	Use Paste			
300368	Bolt Plug	38,088	Mold			
300336	Firing pin head	23,000	MIM Mold			
300362	Mag Latch	33,480	Mold			
300363	Magazine Box	28,000	Mold			
300364	Magazine Follower	33,300	Mold			
300365	Magazine Bottom	47,880	Mold			
	Stock	150,300	Mold			
	Styrofoam Bed	0	Die			
	PPI	38000				
		\$495,773				

Total	\$2,297,528
Installation	\$0
	<u>\$2,297,528</u>

MF0760

Who Does What as of Mon. 1/17/00
Individual Task Summary

Phase I: Machine Area

1. Joe & Kristan: Meeting today at 1:00 P.M. to go over part processing in plant to produce a visual flow chart.

Take into account all products that presently are routed through the plant for the purpose of manufacturing. Develop a product routing chart using simple TQM process symbols.

ATTENTION: Kristan: After meeting with Joe a flow chart will be created.
The first meeting with ADHOCC team members will begin 1/18/00 @ 5:00 a.m. for third shift. This meeting time will be at the same time until a final design is completed during the week of Jan 30, 2000

Develop Routing Sheet in Visio to have a visual that team members can understand the operations they are working with to improve the plant layout.

2. Tommy & Shelley -----100% Complete 1/17/00

Choose the people from all shifts that are free to develop machine list. The machine list will then be place into an Excel spreadsheet in alphabetical order, number of machines, name of location, and type of product that flows through machine.

3. Tommy & Shelley-----100% Complete 1/17/00

Miscellaneous equipment includes testing equipment, tables, trash cans, and tools need for specific operations. A spreadsheet needs to be developed in the same manner as the machine list.

4. Scott (Tommy & Shelley) ----100% Complete 1/17/00 Matt G. forwarded me a copy of the last time study completed. This will be applied

A time study needs to be done on all processes within the plant. The time study is important for the team because it will show machining cells where bottlenecks are created. An inventory storage bin or table may have to be place in these specific areas because of the bottlenecks.

MF0761

5. All Team Members

All members of the plant will be utilized during the duration of this task on a daily basis. Each meeting will go over specific part routings and the order in which machines will be grouped to complete the product routing.

6. **Maintenance**—Costing has already been established in the past. Incurring problems exist around how the machine moving equipment will enter and exit the plant. Currently the route taken is the 12" overhead door on the South West corner of the building. Future plans for construction of a gun range will close this area. **Question:** *Where are the moving machines going to enter and exit the building? What are our options?*

The cost of moving machines and electrical hook-up will be up to maintenance. A cost sheet should be developed showing the min. and max. requirements of the Visio layouts.

7. Team Members

Develop Proposal
Finalize Proposal

Phase II: Assembly Area

All task applied towards the assembly area will be already be established by the Assembly Team. The two teams will then meet to produce the assembly layout after Phase I is complete.

On Thursday John Stairs may need to be present in the core meeting to understand about ideas that need to be viewed in developing the assembly side of the layout.

MF0762

All Other Word Processors



Follow the general formatting instructions below or use Avery FAXFACTS to request Bulletin 1150 to get specific instructions for:

- Microsoft® Word for Windows® 2.0
- Microsoft® Works 4.0 for Windows® 95
- WordPerfect® 5.1
- Lotus® Word Pro
- Lotus® Ami Pro®

See under Avery Technical Support below.

1. Set Page Margins as follows:
Left 2.25" Top 1.167"
Right 2.25" Bottom 1.0"
2. Set two center-aligned tabs. Set the first tab at 1", and the second tab at 3".
3. Set line spacing (or line height) to 0.33". (If your program displays line spacing in points or another measurement unit, you can still enter a dimension in inches if you include the inch mark.) If options are available, set spacing to "exactly" or "fixed." (The terms vary from one program to another.) Do not set to "at least" or "auto."
4. Press the Tab key once to move to the first tab stop. Type your text for the first insert. Press the Tab key to move to the second tab stop, and type the same text again. (This becomes the other side of the insert.)



5. Press Enter to move to the next row. You can repeat step 4 to enter up to 26 rows of inserts.
6. In your word processor or on your printer's control panel, select the printer's manual feed tray.
7. When done entering text, follow **Printing Instructions**.

Avery Technical Support

Avery offers free Technical Support Bulletins to assist you in formatting and printing Avery Tab Inserts. For fastest response, use our FaxFacts service. To order, pick up the phone on your fax machine and call FaxFacts to request Bulletin 1150.



FAXFACTS (available 24 hours a day)
(818) 584-1681

If you don't have a fax machine, or your's is one of the few that doesn't work with FaxFacts, call or fax Avery Technical Support and we will send the bulletins to you.

Avery Technical Support (214) 389-3699
Technical Support
Fax (214) 446-2717
CompuServe GO AVERY

Avery Dividers are made with:

- Recycled Paper (20% Post Consumer Content)
- Recycled Packaging (26% Post Consumer Content)

Post Consumer Content Reduces Landfill

Avery™ Tab Inserts for Dividers - 5 Tab



Printing Instructions

Print a test sheet

1. Send the print command from your word processor.
2. Insert a sheet of plain paper in your printer's Manual Feed Tray.
Note: On some printers you must open the printer's front door to use the Manual Feed Tray.
3. If your printer does not pick up the sheet, press **On Line** or **Continue**.
4. Hold printed test sheet against insert sheet to check alignment. Adjust as needed.



For more detailed printing instructions and specific instructions on how to adjust the alignment of your text, use Avery FaxFacts to request Bulletin 1150.

Print your inserts

5. Load the insert sheet and print using your printer's manual feed tray.

Printing on Half-Sheets

ONLY for printers capable of feeding 8 1/2" x 5 1/2" paper sizes including...

- HP® LaserJet® 4P, 4MP, 5P, 5MP
- Many InkJet printers

1. Split the sheet of inserts in half (horizontally).
2. Always feed the non-perforated edge into the printer first.



**Order Your Formatting
Disk from Avery Today!**

Disk contains templates for quick formatting of Avery's Tab Inserts for Dividers, Index Maker® Dividers, Ready Index® Dividers, and more. Disk is compatible with most popular Word Processing Programs.

Order the disk through the Avery Dennison Consumer Service Center for only \$3.95. To order call 1-800-252-8379.



**AYER
DENNISON**

Office Products
Diamond Bar, CA 91765 ASSEMBLED IN MEXICO

© 1996 Avery Dennison Corporation. Printed in USA.
Avery is a trademark and Index Maker and Ready Index are registered trademarks of Avery Dennison Corporation.
All other brand and product names are trademarks, registered trademarks or service marks of their respective holders.

Product Guarantee

Avery is committed to providing you with quality products, and will gladly replace any product which does not provide complete satisfaction. We also welcome your comments and suggestions. Please send your correspondence with product code to:

Avery Office Products Consumer Service Center
P.O. Box 5244
Diamond Bar, CA 91765-4000

ASSEMBLED IN MEXICO

MF0763

Microsoft® Word

for Windows® 6.0 or
for Windows® 95 7.0



Avery™ Tab Inserts for Dividers - 5 Tab

1. Click the **Tools** menu and choose **Envelopes and Labels**.
2. Click the **Labels** tab, then click the **Options** button.
3. In the **Product Number** list, click **Worksaver 5 - Tabs**.
4. While still in the **Label Options** dialog box, set tray to **Manual Feed** (if available). Then click the **Details** button.
5. Make the following settings:

Top Margin	1.17"
Side Margin	2.25"
Horizontal Pitch	2"
Label Width	2"
Number Across	2
Number Down	26

 Then click **OK**.
6. Click **OK** in the message box that appears.
7. Click **OK** in the **Label Options** box. Then click **New Document**.

8. Hold down the **Ctrl** key and press **A** to select the whole table. Then hold down the **Ctrl** key and press **E** to use center alignment. Position the cursor in the top left insert.
9. Type your text in the left insert, then use the **TAB** key to move to the right insert. Type the same text again for a double-sided insert.



10. Press the **TAB** key to position the cursor on the next row of tab inserts. Repeat step 9 to create up to 26 rows of inserts.
11. Turn page over and follow **Printing Instructions**.

WordPerfect®

6.0, 6.1 or 7.0 for
Windows®

1. Click the **Format** menu (WordPerfect 6.1 and 7.0) or **Layout** menu (WordPerfect 6.0). Choose **Labels**.
*Note: If you have followed the formatting instructions before, select **Avery Tab Inserts Dividers5** (the label size you created). Then click **Select** and go to step 6.*
2. In the **Labels** list, click:
WT-213-5 WorkSaver (Front)
for WordPerfect 6.0 & 6.1
Avery WorkSaver 5-Tab
for WordPerfect 7.0.
Then click **Create**.
3. In the **Label Description** box, type **Avery Tab Inserts Dividers5**. In the **Label Type** box, select **Laser**.
4. Make the following settings:

Labels Per Page	
Rows	26
Top Left Label	
Top Edge	1.17"
Left Edge	2.25"
Distance Between Labels	
Columns	0

 Then click **OK**.
5. Click the **Select** button in the **Labels** dialog box.
6. Click the **Edit** menu, choose **Select**, then choose **All**. Press **Ctrl+E** to use center alignment. Position cursor in the insert (entry field).
7. Type your text in the left insert, then use the **Ctrl+Enter** key to move to the right insert. Type the same text again for a double-sided insert.



8. Press **Ctrl+Enter** to position the cursor on the next row of inserts. You can repeat step 7 to create up to 26 rows of inserts.
9. Turn page over and follow **Printing Instructions**.

All Other
Word Processors
Turn Page Over

RM 1278M

MF0764

Pass List

83

CONFIDENTIAL

MF0765

MATT, FYI.

4/25/00

Elizabethtown Research Division

JERRY

PARTS LIST #YYY

Date: Model 710

Supersedes Previous Model XXX

04/25/00 Bolt Action

Parts List #AAA

Centerfire Rifle R.H.

Sheet 1 Dotted line (- - -)
 of 2 indicates same part number

30-06 270 7mm 300
 Rem Mag Win Mag

DWG. NO.	PART NAME	PART NUMBERS
----------	-----------	--------------

RAMAC #

DOCUMENT ENVELOPE ASSEMBLY

Document Envelope
 Instruction Book
 Product Owners Card
 Remington Authorized Gunsmith
 Safety Booklet
 Remington Museum Flyer
 Oval Label

XXXX

1649

XXXX

1426

3413

3499

3475

3491

CARTON ASSEMBLY

Box & Envelope Label
 (Label To Read "Model 710")

993002

NOTE: THE ABOVE PARTS ARE FOR PACKAGING ONLY

C-305410-E	BARREL ASSEMBLY COMPLETE	305410	305411	305412	305413
C-300462-	BARREL ASSY COMPLETE MARKING				
C-305400-	BARREL ASSEMBLY	305400	305401	305402	305403
B-305315-25	BARREL	305315	305316	305317	305318
	BARREL MATERIAL #1246	300447			
D-305465-	BARREL MARKING				
E-300340-20	RECEIVER	300340			
D-300401-E	RECEIVER INSERT ASSEMBLY COMPLETE	300401			
C-300400-	RECEIVER INSERT ASSEMBLY	300400			
1E-300327-17	RECEIVER INSERT	300327			
2E-300327-30					
A-300347-B	THREADED INSERT	300347			
C-300333-7	SIDE PLATE (Blk. 300452)	300333			
A-300328-3	SIDE PLATE (Blk. 2)	300328			
C-15666	SEAR SAFETY CAM (Blk. C-91919)	15666			
B-300351-A	PIVOT PIN	300351			
B-300463-	TRIGGER PIVOT PIN	300463			
B-300464-	SEAR RETAINING PIN	300464			
A-300465-	PIN RETAINING CLIP (2)	300465			
A-17047	SEAR SPRING	17047			
D-109835-2	TRIGGER	109835			
D-201342-F2	TRIGGER BLANK	201342			
C-19461	TRIGGER CONNECTOR (Blk. C-91921)	19461			
B-17053	TRIGGER SCREW FRONT (Blk. B-91920)	17053			
B-300448-A	TRIGGER ENGAGEMENT SCREW	300448			
A-15400	TRIGGER SPRING	15400			
A-300426-A	TRIGGER STOP SCREW	300426			
D-300408-16	SAFETY (Blk. 300455)	300408			
B-17043	SAFETY PIVOT PIN (Blk. B-91918)	17043			
B-17044	SAFETY SNAP WASHER (Blk. 200042)	17044			
B-300407-4	SAFETY SPRING	300407			
C-300345-16	BOLT STOP (Blk. 300453)	300345			
B-17034	RECEIVER PLUG SCREW (4)	17034			
B-300361-D	RECOIL BRACKET (Blk. 300454)	300361			
B-305475-	BOLT ASSEMBLY COMPLETE	305475		305476	
B-300403-A	BOLT BODY ASSEMBLY	300403			
D-300339-16	BOLT BODY	300339			
C-300370-E	BOLT HANDLE	300370			
D-300360-I	BOLT HANDLE BLANK	300360			
A-300329-3	BOLT HANDLE PIN	300329			
B-305390-2	BOLT HEAD ASSEMBLY	305390		305391	
E-300338-24	BOLT HEAD (30-06, 270)	300338			
C-300416-F	BOLT HEAD (7mm Rem, 300 Win)			300416	
D-300434-	BOLT HEAD BLANK	300434			
C-93712	EXTRACTOR	93712			
C-97322	30-06, 270 (Blk. 93711)			97322	
C-27340	7mm Rem, 300 Win (Blk. 97321)			27341	
B-300342-3	EXTRACTOR RIVET	300342			
A-300367-C	EJECTOR	300367			
	EJECTOR SPRING				

MF0766

Elizabethtown Research Division

PARTS LIST #YYY

Date: Model 710

Supersedes Previous Model XXX

04/25/00 Bolt Action

Parts List #AAA

Centerfire Rifle R.H.

Sheet 2 Dotted line (- - -)
of 2 indicates same part number

30-06

270

7mm

Rem Mag

300

Win Mag

DWG. NO.	PART NAME	PART NUMBERS			
A-94555	EJECTOR PIN	94555	----	----	----
B-300330-A	BOLT ASSEMBLY PIN	300330	----	----	----
BOLT ASSEMBLY COMPLETE CONT'D					
B-300404-A	FIRING PIN ASSEMBLY	300404	----	----	----
D-300368-6	BOLT PLUG	300368	----	----	----
B-300346-F	BOLT PLUG INSERT	300346	----	----	----
B-300418-B	TUMBLER	300418	----	----	----
D-300420-D	TUMBLER BLANK	300420	----	----	----
C-201224	LOCK PLUNGER (Blk. 201223)	201224	----	----	----
A-201217	LOCK SPRING	201217	----	----	----
A-300427-A	SPRING RETAINER	300427	----	----	----
C-300334-D	FIRING PIN (Blk. 300452)	300334	----	----	----
C-300335-5	FIRING PIN TIP (Blk. 300451)	300335	----	----	----
C-300336-I	FIRING PIN HEAD (Blk. 300450)	300336	----	----	----
A-300399-E	FIRING PIN SPRING	300399	----	----	----
FRONT SIGHT					
C-15373	30-06, 270 (Blk. 90393)	94084	----	----	----
B-14659	7mm REM, 300 WIN	94095	----	----	----
B-28510	FRONT SIGHT RAMP (Blk. B-16724)	94657	----	----	----
B-28505	FRONT SIGHT RAMP SCREW (2) (Blk. 90347)	28505	----	----	----
B-103145	REAR SIGHT ASSEMBLY	103145	----	----	----
A-90906	ELEVATION SCREW	90906	----	----	----
C-93905	REAR SIGHT ADJUSTURE (Blk. C-93906)	94333	----	----	----
C-103530	REAR SIGHT BASE (Blk. 94023)	103530	----	----	----
C-93904	REAR SIGHT SLIDE (Blk. C-93907)	94335	----	----	----
B-90904	WINDAGE SCREW (Blk. 91911)	90904	----	----	----
B-28505	REAR SIGHT BASE SCREW (2) (Blk. 90347)	28505	----	----	----
B-305455-A	STOCK ASSEMBLY COMPLETE	305455	----	----	----
E-300437	STOCK	300437	----	----	----
B-15161	FRONT SCREW, BUSHING (Blk. 91915)	15161	----	----	----
C-97971	GRIP CAP	97971	----	----	----
D-97973	RECOIL PAD	97973	----	----	----
C-97972	RECOIL PAD SPRINGER	97972	----	----	----
A-98008	RECOIL PAD SCREW (2)	98008	----	----	----
C-300362-8	MAGAZINE LATCH	300362	----	----	----
B-300398-16	LATCH SPRING	300398	----	----	----
B-300371-B	LATCH PLATE PIN	300371	----	----	----
B-15356	SLING SWIVEL STUD (2)	94996	----	----	----
C-104131	FRONT TAKE DOWN SCREW (Blk. 104141)	104131	----	----	----
C-104133	MIDDLE TAKE DOWN SCREW (Blk. 104143)	104133	----	----	----
B-300425	REAR TAKE DOWN SCREW	300425	----	----	----
B-305395	MAGAZINE ASSEMBLY	305395	----	----	----
E-300363-14	MAGAZINE BOX (Blk. 300449)	300363	----	----	----
D-300364-17	MAGAZINE FOLLOWER	300364	----	----	----
D-300365-21	MAGAZINE BOTTOM	300365	----	----	----
B-300446-	BOTTOM ARTWORK		----	----	----
C-300405-A	MAGAZINE SPRING	300405	----	----	----

FOR ACCESSORY SALES

D-300441-A	SCOPE RAIL	300441
B-28505	SCREW (4 REQ'D)	28505

MF0767

Elizabethtown Research Division

PARTS LIST #YYY

Date: Model 710

Supersedes Previous Model XXX

03/02/00 Bolt Action

Parts List #AAA

Centerfire Rifle R.H.

Sheet 1 Dotted line (- - -)
 of 2 indicates same part number

30-06 270

7mm
Rem Mag300
Win Mag

DWG. NO.	PART NAME	PART NUMBERS
----------	-----------	--------------

RAMAC

DOCUMENT ENVELOPE ASSEMBLY

XXXX

Document Envelope

1649

Instruction Book

XXXX

Product Owners Card

1426

Remington Authorized Gunsmith

3413

Safety Booklet

3499

Remington Museum Flyer

3475

Oval Label

3491

CARTON ASSEMBLY

Box & Envelope Label

993002

(Label to Read "Model 710")

NOTE: THE ABOVE PARTS ARE FOR PACKAGING ONLY

C-305410-	BARREL ASSEMBLY COMPLETE	305410	3054 1	305411	305413
C-305400-	BARREL ASSEMBLY	305400	305401	305402	305403
E-305315-21	BARREL (Blank 300447)	305315	305316	305317	305318
D-305465-	BARREL MARKING				
E-300340-19	RECEIVER	300340			
D-300401-A	RECEIVER INSERT ASSEMBLY COMPLETE	300401			
C-300400-	RECEIVER INSERT ASSEMBLY	300400			
1E-300327-17	RECEIVER INSERT	300327			
2E-300327-30					
A-300347-A	THREADED INSERT	300347			
C-300333-5	SIDE PLATE	300333			
A-300328-2	SIDE PLATE PIN (2)	300328			
C-15666	SEAR SAFETY CAM (Blk. B-91919)	15666			
B-300351-	PIVOT PIN (Blk. B-91919)	300351			
A-17047	SEAR SPRING	17047			
C-300435-C	TRIGGER (Blk. 300435)	300435			
C-19461	TRIGGER CONNECTOR (Blk. B-91921)	19461			
B-17053	TRIGGER SCREW FRONT (Blk. B-91920)	17053			
B-300448-	TRIGGER ENGAGEMENT SCREW	300448			
A-15400	TRIGGER SPRING	15400			
A-300426-	TRIGGER STOP SCREW	300426			
D-300408-16	SAFETY	300408			
B-17043	SAFETY PIVOT PIN (Blk. B-91918)	17043			
B-17044	SAFETY SNAP WASHER (Blk. 200042)	17044			
B-300407-	SAFETY SPRING	300407			
C-300345-10	BOLT STOP	300345			
B-17034	RECEIVER PLUG SCREW (4)	17034			
B-300361-B	RECOIL BRACKET	300361			
B-300403-	BOLT BODY ASSEMBLY	300403			
D-300339-16	BOLT BODY	300339			
C-300370-C	BOLT HANDLE	300370			
D-300360-C	BOLT HANDLE BLANK	300360			
A-300329-2	BOLT HANDLE PIN	300329			
B-305390-2	BOLT HEAD ASSEMBLY	305390	305391		
E-300338-18	BOLT HEAD (30-06, 270)	300338			
C-300416-F	BOLT HEAD (7mm Rem, 300 Win)		300416		
D-300434-	BOLT HEAD BLANK	300434			
C-93712	EXTRACTOR				
C-97322	30-06, 270 (Blk. 93711)	93712			
C-27340	7mm Rem, 300 Win (Blk. 97321)			97322	
B-300342-2	EXTRACTOR RIVET			27341	
A-300367-	EJECTOR	300342			
A-94555	EJECTOR SPRING	300367			
B-300330-	EJECTOR PIN	94555			
B-300404-A	BOLT ASSEMBLY PIN	300330			
D-300368-5	FIRING PIN ASSEMBLY	300404			
B-300346-D	BOLT PLUG	300368			
B-300418-B	BOLT PLUG INSERT	300346			
D-300420-D	TUMBLER	300418			
	TUMBLER BLANK	300420			

MF0768

Elizabethtown Research Division

PARTS LIST #YYY

Date: Model 710

Supersedes Previous Model XXX

03/02/00 Bolt Action

Parts List #AAA

Centerfire Rifle R.H.

Sheet 2 Dotted line (- - -)
of 2 indicates same part number

30-06 270 7mm 300
Rem Mag Win Mag

DWG. NO.	PART NAME	PART NUMBERS
----------	-----------	--------------

FIRING PIN ASSY CONTINUED

C-201224	LOCK PLUNGER (Blk. 201223)	201224	----	----	----
A-201217	LOCK SPRING	201217	----	----	----
A-300427	SPRING RETAINER	300427	----	----	----
C-300334-A	FIRING PIN	300334	----	----	----
C-300335-2	FIRING PIN TIP	300335	----	----	----
C-300336-G	FIRING PIN HEAD	300336	----	----	----
A-300399-D	FIRING PIN SPRING	300399	----	----	----
	FRONT SIGHT				
C-15373	30-06, 270 (Blk. 90393)	94084	----	----	----
B-14659	7mm REM, 300 WIN			94095	----
B-28510	FRONT SIGHT RAMP (Blk. B-16724)	94657	----	----	----
B-28505	FRONT SIGHT RAMP SCREW (2) (Blk. 90347)	28505	----	----	----
B-103145	REAR SIGHT ASSEMBLY	103145	----	----	----
A-90906	ELEVATION SCREW	90906	----	----	----
C-93905	REAR SIGHT ADJUSTURE (Blk. C-93906)	94333	----	----	----
C-103530	REAR SIGHT BASE (Blk. 94023)	103530	----	----	----
C-93904	REAR SIGHT SLIDE (Blk. C-93907)	94335	----	----	----
B-90904	WINDAGE SCREW (Blk. 91911)	90904	----	----	----
B-28505	REAR SIGHT BASE SCREW (2) (Blk. 90347)	28505	----	----	----
B-305455	STOCK ASSEMBLY COMPLETE	305455	----	----	----
E-300437	STOCK	300437	----	----	----
B-15161	FRONT SCREW BUSHING (Blk. 91915)	15161	----	----	----
C-97971	GRIP CAP	97971	----	----	----
D-97973	RECOIL PAD	97973	----	----	----
C-97972	RECOIL PAD BACKER	97972	----	----	----
A-98008	RECOIL PAD SCREW (2)	98008	----	----	----
C-300362-8	MAGAZINE LATCH	300362	----	----	----
B-300398-B	LATCH SPRING	300398	----	----	----
B-300371-A	LATCH PIVOT PIN	300371	----	----	----
B-15358	SLING SWIVEL STUD (2)	15358	----	----	----
C-104125	FRONT TAKE DOWN SCREW (Blk. 104141)	104131	----	----	----
C-104125	MIDDLE TAKE DOWN SCREW (Blk. 104143)	104133	----	----	----
B-300425-	REAR TAKE DOWN SCREW	300425	----	----	----
B-305395-	MAGAZINE ASSEMBLY	305395	----	----	----
E-300363-14	MAGAZINE BOX	300363	----	----	----
D-300364-20	MAGAZINE FOLLOWER	300364	----	----	----
D-300364-20	MAGAZINE BOTTOM	300365	----	----	----
B-300405-	BOTTOM ARTWORK				
B-300405-	MAGAZINE SPRING	300405	----	----	----

FOR ACCESSORY SALES

C-300441-A	SCOPE RAIL	300441
B-28505	SCREW (4 REQ'D)	28505

MF0769

Elizabethtown Research Division

PARTS LIST #YYY

Date: Model 710

Supersedes Previous Model XXX

02/28/00 Bolt Action

Parts List #AAA

Centerfire Rifle R.H.

Sheet 1 Dotted line (- - -)

of 2 indicates same part number

30-06 270

7mm
Rem Mag

300
Win Mag

DWG. NO. PART NAME PART NUMBERS

RAMAC #

DOCUMENT ENVELOPE ASSEMBLY

Document Envelope
Instruction Book
Product Owners Card
Remington Authorized Gunsmith
Safety Booklet
Remington Museum Flyer
Oval Label

XXXX

1649
XXXX
1426
3413
3499
3475
3491

CARTON ASSEMBLY

Box & Envelope Label
(Label To Read "Model 710")

993002

NOTE: THE ABOVE PARTS ARE FOR PACKAGING ONLY

C-305410-	BARREL ASSEMBLY COMPLETE	305410	305411	305412	305413
C-305400-	BARREL ASSEMBLY	305400	305401	305402	305403
E-305315-21	BARREL	305315	305316	305317	305318
D-305465-	BARREL MARKING				
E-300347-19	RECEIVER	300340			
D-300401-A	RECEIVER INSERT ASSEMBLY COMPLETE	300401			
C-300400-	RECEIVER INSERT ASSEMBLY	300400			
1E-300327 17	RECEIVER INSERT	300327			
2E-300427-30					
A-300347-A	THRFADED INSERT	300347			
C-300333-5	SIDE PLATE	300333			
A-300328-2	SIDE PLATE PIN (2)	300328			
C-15666	SEAR SAFETY CAM (Blk. C-91919)	15666			
B-300351-	PIVOT PIN (3)	300351			
A-17047	SEAR SPRING	17047			
C-300435-C	TRIGGER (Blk. 300435)	300435			
C-19461	TRIGGER CONNECTOR (Blk. C-91920)	19461			
B-17053	TRIGGER SCREW FRONT (Blk. B-91920)	17053			
B-300448-	TRIGGER ENGAGEMENT SCREW	300448			
A-15400	TRIGGER SPRING	15400			
A-300426-	TRIGGER STOP SCREW	300426			
D-300408-16	SAFETY	300408			
B-17043	SAFETY PIVOT PIN (Blk. B-91918)	17043			
B-17044	SAFETY SNAP WASHER (Blk. 200042)	17044			
B-300407-3	SAFETY SPRING	300407			
C-300345-10	BOLT STOP	300345			
B-17034	RECEIVER PLUG SCREW (4)	17034			
B-300361-B	RECOIL BRACKET	300361			
B-300403-	BOLT BODY ASSEMBLY	300403			
D-300339-16	BOLT BODY	300339			
E-300370-C	BOLT HANDLE	300370			
D-300360-C	BOLT HANDLE BLANK	300360			
A-300329-2	BOLT HANDLE PIN	300329			
B-305390-2	BOLT HEAD ASSEMBLY	305390		305391	
E-300338-18	BOLT HEAD (30-06, 270)	300338			
C-300416-F	BOLT HEAD (7mm Rem, 300 Win)			300416	
D-300434-	BOLT HEAD BLANK	300434			
C-93712	EXTRACTOR				
C-97322	30-06, 270 (Blk. 93711)	93712			
C-27340	7mm Rem, 300 Win (Blk. 97321)			97322	
B-300342-2	EXTRACTOR RIVET			27341	
A-300367-	EJECTOR	300342			
A-94555	EJECTOR SPRING	300367			
B-300330-	EJECTOR PIN	94555			
B-300404-A	BOLT ASSEMBLY PIN	300330			
D-300368-5	FIRING PIN ASSEMBLY	300404			
B-300346-D	BOLT PLUG	300368			
B-300418-B	BOLT PLUG INSERT	300346			
D-300420-D	TUMBLER	300418			
	TUMBLER BLANK	300420			

MF0770

Elizabethtown Research Division

PARTS LIST #YYY

Date: Model 710

Supersedes Previous Model XXX

02/28/00

Bolt Action

Parts List #AAA

Centerfire Rifle R.H.

Sheet 2 Dotted line (- - -)
 of 2 indicates same part number

30-06 270

7mm
Rem Mag300
Win Mag

DWG. NO.	PART NAME	PART NUMBERS			
FIRING PIN ASSY CONTINUED					
C-201224	LOCK PLUNGER (Blk. 201223)	201224	----	----	----
A-201217	LOCK SPRING	201217	----	----	----
A-300427	SPRING RETAINER	300427	----	----	----
C-300334-A	FIRING PIN	300334	----	----	----
C-300335-2	FIRING PIN TIP	300335	----	----	----
C-300336-G	FIRING PIN HEAD	300336	----	----	----
A-300399-D	FIRING PIN SPRING	300399	----	----	----
FRONT SIGHT					
C-15373	30-06, 270 (Blk. 90393)	94084	----	----	----
B-14659	7mm REM, 300 WIN			94095	----
B-28510	FRONT SIGHT RAMP (Blk. B-16724)	94659	----	----	----
B-28505	FRONT SIGHT RAMP SCREW (2) (Blk. 90347)	28505	----	----	----
B-103145	REAR SIGHT ASSEMBLY	103145	----	----	----
A-90906	ELEVATION SCREW	90906	----	----	----
C-93905	REAR SIGHT ADJUSTURE (Blk. C-93906)	94333	----	----	----
C-103530	REAR SIGHT BASE (Blk. 94023)	103530	----	----	----
C-93904	REAR SIGHT SLIDE (Blk. C-93907)	94335	----	----	----
B-90904	WINDAGE SCREW (Blk. 91911)	90904	----	----	----
B-28505	REAR SIGHT BASE SCREW (2) (Blk. 90347)	28505	----	----	----
B-305455	STOCK ASSEMBLY COMPLETE	305455	----	----	----
E-300437	STOCK	300437	----	----	----
A-15161	FRONT SCREW BUSHING (Blk 91915)	15161	----	----	----
C-97971	GRIP CAP	97971	----	----	----
D-97973	RECOIL PAD	97973	----	----	----
C-97972	RECOIL PAD BACKER	97972	----	----	----
A-98008	RECOIL PAD SCREW (2)	98008	----	----	----
C-300362-7	MAGAZINE LATCH	300362	----	----	----
B-300398-B	LATCH SPRING	300398	----	----	----
B-300371-A	LATCH PIVOT PIN	300371	----	----	----
B-15358	SLING SWIVEL STUD (2)	15358	----	----	----
C-104125	FRONT TAKE DOWN SCREW (Blk. 104141)	104131	----	----	----
C-104125	MIDDLE TAKE DOWN SCREW (Blk. 104143)	104133	----	----	----
B-300425-	REAR TAKE DOWN SCREW	300425	----	----	----
B-305395-	MAGAZINE ASSEMBLY	305395	----	----	----
E-300363-14	MAGAZINE BOX	300363	----	----	----
D-300364-16	MAGAZINE FOLLOWER	300364	----	----	----
D-300365-28	MAGAZINE BOTTOM	300365	----	----	----
B-300446	BOTTOM PARTWORK		----	----	----
C-300405	MAGAZINE SPRING	300405	----	----	----

FOR ACCESSORY SALES

B-300441-A SCOPE RAIL 300441
 B-28505 SCREW (4 REQ'D) 28505

MF0771

Elizabethtown Research Division

PARTS LIST #YYY

Date: Model 710

Supersedes Previous Model XXX

01/17/00 Bolt Action

Parts List #AAA

Centerfire Rifle R.H.

heet	1	Dotted line (- - -)				
of	2	indicates same part number	30-06	270	7mm Rem Mag	300 Win Mag

DWG. NO.	PART NAME	PART NUMBERS
----------	-----------	--------------

RAMAC

DOCUMENT ENVELOPE ASSEMBLY

Document Envelope	XXXX	----	----	----
Instruction Book	1649	----	----	----
Product Owners Card	xxxx	----	----	----
Remington Authorized Gunsmith	1426	----	----	----
Safety Booklet	3413	----	----	----
Remington Museum Flyer	3499	----	----	----
Oval Label	3475	----	----	----
	3491	----	----	----

CARTON ASSEMBLY

Box & Envelope Label	993002	----	----	----
(Label To Read "Model 710")				

NOTE: THE ABOVE PARTS ARE FOR PACKAGING ONLY

C-305410-	BARREL ASSEMBLY COMPLETE	305410	305411	305412	305413
C-305400-	BARREL ASSEMBLY	305400	305401	305402	305403
E-305315-11	BARREL	305315	305316	305317	305318
E-300340-19	RECEIVER	300340			
D-300401-A	RECEIVER INSERT ASSEMBLY COMPLETE	300401			
C-300400-	RECEIVER INSERT ASSEMBLY	300400			
1E-300327-17	RECEIVER INSERT	300327			
2E-300327-29					
A-300347-A	THREADED INSERT	300347			
C-300333-5	SIDE PLATE	300333			
A-300328-1	SIDE PLATE PIN (2)	300328			
-15666	SEAR SAFETY CAM (Blk. C-91919)	15666			
B-300351-	PIVOT PIN (3)	300351			
A-17047	SEAR SPRING	17047			
C-300435-	TRIGGER (Blk. 300435)	300435			
C-19461	TRIGGER CONNECTOR (Blk. C-91921)	19461			
B-17053	TRIGGER SCREW FRONT (Blk. B-91920)	17053			
B-91128	TRIGGER ENGAGEMENT SCREW (Blk. B-91922)	91128			
A-15400	TRIGGER SPRING	15400			
A-300426-	TRIGGER STOP SCREW	300426			
D-300408-	SAFETY	300408			
E-17043	SAFETY PIVOT PIN (Blk. B-91918)	17043			
B-17044	SAFETY SNAP WASHER (Blk. 200042)	17044			
B-300407-	SAFETY SPRING	300407			
C-300345-5	BOLT STOP	300345			
B-17034	RECEIVER PLUG SCREW (4)	17034			
B-300361-	RECOIL BRACKET	300361			
B-300403-	BOLT BODY ASSEMBLY	300403			
B-300339-16	BOLT BODY	300339			
C-300370-B	BOLT HANDLE	300370			
C-300360-B	BOLT HANDLE BLANK	300360			
A-300329-2	BOLT HANDLE PIN	300329			
B-305390-2	BOLT HEAD ASSEMBLY	305390		305391	
E-300338-17	BOLT HEAD (30-06, 270)	300338			
C-300416-	BOLT HEAD (7mm Rem, 300 Win)			300416	
D-300434-	BOLT HEAD BLANK	300434			
C-93712	EXTRACTOR				
C-97322	30-06, 270 (Blk. 93711)	93712			
C-27340	7mm Rem, 300 Win (Blk. 97321)			97322	
B-300342-2	EXTRACTOR RIVET			27341	
A-300367-	EJECTOR	300342			
A-94555	EJECTOR SPRING	300367			
B-300330-	EJECTOR PIN	94555			
B-300404-A	BOLT ASSEMBLY PIN	300330			
-300368-5	FIRING PIN ASSEMBLY	300404			
-300346-	BOLT PLUG	300368			
B-300418-B	BOLT PLUG INSERT	300346			
D-300420-C	TUMBLER	300418			
	TUMBLER BLANK	300420			

MF0772

Elizabethtown Research Division

PARTS LIST #YYY

Date: Model 710

Supersedes Previous Model XXX

01/17/00 Bolt Action

Parts List #AAA

Centerfire Rifle R.H.

Sheet 2 Dotted line (- - -)

of 2 indicates same part number

30-06

270

7mm
Rem Mag300
Win Mag

DWG. NO.	PART NAME	PART NUMBERS			
C-201224	LOCK PLUNGER (Blk. 201223)	201224	----	----	----
	FIRING PIN ASSY CONTINUED				
A-201217	LOCK SPRING	201217	----	----	----
A-300427	SPRING RETAINER	300427	----	----	----
C-300334-A	FIRING PIN	300334	----	----	----
C-300335-2	FIRING PIN TIP	300335	----	----	----
C-300336-F	FIRING PIN HEAD	300336	----	----	----
A-300399-D	FIRING PIN SPRING	300399	----	----	----
	FRONT SIGHT				
C-15373	30-06, 270 (Blk. 90393)	94084	----		
B-14659	7mm REM, 300 WIN			94095	----
B-28510	FRONT SIGHT RAMP (Blk. B-16724)	94657	----		----
B-28505	FRONT SIGHT RAMP SCREW (2) (Blk. 90347)	28505	----		----
B-103145	REAR SIGHT ASSEMBLY	103145	----		----
A-90906	ELEVATION SCREW	90906	----		----
C-93905	REAR SIGHT ADJUSTURE (Blk. C-93906)	94333	----		----
C-103530	REAR SIGHT BASE (Blk. 94023)	103530	----		----
C-93904	REAR SIGHT SLIDE (Blk. C-93907)	94335	----		----
B-90904	WINDAGE SCREW (Blk. 91911)	90904	----		----
B-28505	REAR SIGHT BASE SCREW (2) (Blk. 90347)	28505	----		----
B-305455	STOCK ASSEMBLY COMPLETE	305455	----		----
E-300437	STOCK	300437	----		----
B-15161	FRONT SCREW BUSHING (Blk 91915)	15161	----		----
C-97971	GRIP CAP	97971	----		----
D-97973	RECOIL PAD	97973	----		----
C-97972	RECOIL PAD BACKER	97972	----		----
A-98008	RECOIL PAD SCREW (2)	98008	----		----
~300362-7	MAGAZINE LATCH	300362	----		----
-300398-B	LATCH SPRING	300398	----		----
B-300371-A	LATCH PIVOT PIN	300371	----		----
B-300096-7-496	SLING SWIVEL STOP (2)	300096	----		----
C-104125	FRONT TAKE DOWN SCREW (Blk. 104141)	104131	----		----
C-104125	MIDDLE TAKE DOWN SCREW (Blk. 104141)	104133	----		----
B-300425-	REAR TAKE DOWN SCREW	300425	----		----
B-305395-	MAGAZINE ASSEMBLY	305395	----		----
E-300363-11	MAGAZINE BOY	300363	----		----
D-300364-6	MAGAZINE FOLLOWER	300364	----		----
D-300365-8	MAGAZINE BOTTOM	300365	----		----
C-300405	MAGAZINE SPRING	300405	----		----
	FOR ACCESSORY SALES				
B-300441-	SCOPE RAIL	300441			
B-28505	SCREW (4 REQ'D)	28505			

MF0773

Elizabethtown Research Division

PARTS LIST #YYY

Date: Model 710

Supersedes Previous Model XXX

12/02/99 Bolt Action

Parts List #AAA

Centerfire Rifle R.H.

Sheet 1 Dotted line (- - -)

of 2 indicates same part number

30-06 270

7mm 300
Rem Mag Win Mag

DWG. NO.	PART NAME	PART NUMBERS
----------	-----------	--------------

RAMAC

DOCUMENT ENVELOPE ASSEMBLY

Document Envelope	XXXX	----	----	----
Instruction Book	1649	----	----	----
Product Owners Card	XXXX	----	----	----
Remington Authorized Gunsmith	1426	----	----	----
Safety Booklet	3413	----	----	----
Remington Museum Flyer	3499	----	----	----
Oval Label	3475	----	----	----
	3491	----	----	----

CARTON ASSEMBLY

Box & Envelope Label	993002	----	----	----
(Label To Read "Model 710")				

NOTE: THE ABOVE PARTS ARE FOR PACKAGING ONLY

C-305410-	BARREL ASSEMBLY COMPLETE	305410	305411	305412	305413
C-305400-	BARREL ASSEMBLY	305400	305401	305402	305403
E-305315-11	BARREL	305315	305316	305317	305318
E-300340-8	RECEIVER	300340	----	----	----
D-300401-A	RECEIVER INSERT ASSEMBLY COMPLETE	300401	----	----	----
C-300400-	RECEIVER INSERT ASSEMBLY	300400	----	----	----
1E-300327-17	RECEIVER INSERT	300327	----	----	----
2E-300327-29					
A-300347-A	THREADED INSERT	300347	----	----	----
C-300333-5	SIDE PLATE	300333	----	----	----
A-300328-1	SIDE PLATE PIN (2)	300328	----	----	----
C-15666	SEAR SAFETY CAM (Blk. C-91921)	15666	----	----	----
B-300351-	PIVOT PIN (3)	300351	----	----	----
A-17047	SEAR SPRING	17047	----	----	----
C-19461	TRIGGER (Blk. C-91912)	15280	----	----	----
C-19461	TRIGGER CONNECTOR (Blk. C-91921)	19461	----	----	----
B-17053	TRIGGER SCREW FRONT (Blk. B-91920)	17053	----	----	----
B-91128	TRIGGER ENGAGEMENT SCREW (Blk. B-91922)	91128	----	----	----
A-15400	TRIGGER SPRING	15400	----	----	----
A-300426	TRIGGER STOP SCREW	300426	----	----	----
D-300407	SAFETY	300408	----	----	----
B-17043	SAFETY PIVOT PIN (Blk. B-91918)	17043	----	----	----
B-17044	SAFETY SNAP WASHER (Blk. 200042)	17044	----	----	----
B-300407	SAFETY SPRING	300407	----	----	----
C-300345	BOLT STOP	300345	----	----	----
B-17034	RECEIVER PLUG SCREW (4)	17034	----	----	----
B-300361	RECOIL BRACKET	300361	----	----	----
B-300403	BOLT BODY ASSEMBLY	300403	----	----	----
B-300339-5	BOLT BODY	300339	----	----	----
C-300370-	BOLT HANDLE	300370	----	----	----
D-300360-	BOLT HANDLE BLANK	300360	----	----	----
A-300329-2	BOLT HANDLE PIN	300329	----	----	----
B-305390-2	BOLT HEAD ASSEMBLY	305390	----	305391	----
E-300338-17	BOLT HEAD (30-06, 270)	300338	----	----	----
C-300416-	BOLT HEAD (7mm Rem, 300 Win)	----	----	300416	----
D-300424-	BOLT HEAD BLANK	300424	----	----	----
C-93712	EXTRACTOR 30-06, 270 (Blk. 93711)	93712	----	----	----
C-97322	7mm Rem, 300 Win (Blk. 97321)	----	----	97322	----
C-27340	EXTRACTOR RIVET	----	----	27341	----
B-300342-1	EJECTOR	300342	----	----	----
A-300367-	EJECTOR SPRING	300367	----	----	----
A-94555	EJECTOR PIN	94555	----	----	----
B-300330-	BOLT ASSEMBLY PIN	300330	----	----	----
B-300404-A	FIRING PIN ASSEMBLY	300404	----	----	----
C-300368-4	BOLT PLUG	300368	----	----	----
B-300346-	BOLT PLUG INSERT	300346	----	----	----
B-300418-	TUMBLER	300418	----	----	----
D-300420-A	TUMBLER BLANK	300420	----	----	----

MF0774

Elizabethtown Research Division

PARTS LIST #YYY

Date: Model 710

Supersedes Previous Model XXX

12/02/99 Bolt Action

Parts List #AAA

Centerfire Rifle R.H.

Sheet 2 Dotted line (- - -)

of 2 indicates same part number

30-06

270

7mm

300

Rem Mag

Win Mag

DWG. NO.	PART NAME	PART NUMBERS			
C-201224	LOCK PLUNGER (Blk. 201223)	201224	----	----	----
	FIRING PIN ASSY CONTINUED				
A-201217	LOCK SPRING	201217	----	----	----
A-300427	SPRING RETAINER	300427	----	----	----
C-300334-A	FIRING PIN	300334	----	----	----
C-300335-2	FIRING PIN TIP	300335	----	----	----
C-300336-B	FIRING PIN HEAD	300336	----	----	----
A-300399-D	FIRING PIN SPRING	300399	----	----	----
	FRONT SIGHT				
C-15373	30-06, 270 (Blk. C-90393)	94084	----	----	----
B-14659	7mm REM, 300 WIN			94095	----
B-28510	FRONT SIGHT RAMP (Blk. B-16724)	94657	----	----	----
B-28505	FRONT SIGHT RAMP SCREW (2) (Blk. 90347)	28505	----	----	----
B-103145	REAR SIGHT ASSEMBLY	103145	----	----	----
A-90906	ELEVATION SCREW	90906	----	----	----
C-93905	REAR SIGHT APERTURE (Blk. C-93906)	94333	----	----	----
C-103530	REAR SIGHT BASE (Blk. 94023)	103530	----	----	----
C-93904	REAR SIGHT SLIDE (Blk. C-93907)	94335	----	----	----
B-90904	WINDAGE SCREW (Blk. 91911)	90904	----	----	----
B-28505	REAR SIGHT BASE SCREW (2) (Blk. 90347)	28505	----	----	----
B-305455	STOCK ASSEMBLY COMPLETE	305455	----	----	----
	STOCK				
B-15161	FRONT SCREW BUSHING (Blk 91915)	15161	----	----	----
C-97971	GRIP CAP	97971	----	----	----
D-97973	RECOIL PAD	97973	----	----	----
C-97972	RECOIL PAD BACKER	97972	----	----	----
A-98008	RECOIL PAD SCREW (2)	98008	----	----	----
C-300362-4	MAGAZINE LATCH	300362	----	----	----
B-300398-B	LATCH SPRING	300398	----	----	----
B-300371-A	LATCH PIVOT PIN	300371	----	----	----
B-300096	SLING SWIVEL STUD (2)	300096	----	----	----
C-104125	FRONT TAKE DOWN SCREW (Blk. 104131)	104131	----	----	----
C-104125	MIDDLE TAKE DOWN SCREW (Blk. 104133)	104133	----	----	----
B-300425-	REAR TAKE DOWN SCREW	300425	----	----	----
B-305395-	MAGAZINE ASSEMBLY	305395	----	----	----
E-300363-9	MAGAZINE BOX	300363	----	----	----
D-300364-4	MAGAZINE FOLLOWER	300364	----	----	----
D-300365-8	MAGAZINE BOTTOM	300365	----	----	----
C-300405-	MAGAZINE SPRING	300405	----	----	----

MF0775

Elizabethtown Research Division

PARTS LIST #YYY

Date: Model 710

Supersedes Previous Model XXX

11/11/99 Bolt Action

Parts List #AAA

Centerfire Rifle R.H.

Sheet 1 Dotted line (- - -)

of 2 indicates same part number

30-06

270

7mm

300

Rem Mag

Win Mag

DWG. NO.	PART NAME	PART NUMBERS
----------	-----------	--------------

RAMAC #

DOCUMENT ENVELOPE ASSEMBLY

Document Envelope 1649
 Instruction Book xxxx
 Product Owners Card 1426
 Remington Authorized Gunsmith 3413
 Safety Booklet 2499
 Remington Museum Flyer 3475
 Oval Label 3491

CARTON ASSEMBLY

Box & Envelope Label 493002
 (Label To Read "Model 710")

NOTE: THE ABOVE PARTS ARE FOR PACKAGING ONLY

C-305410-	BARREL ASSEMBLY COMPLETE	305410	305411	305412	305413
C-305400-	BARREL ASSEMBLY	305400	305401	305402	305403
E-305315-11	BARREL	305315	305316	305317	305318
E-300340-8	RECEIVER	300340			
D-300401-A	RECEIVER INSERT ASSEMBLY COMPLETE	300401			
C-300400-	RECEIVER INSERT ASSEMBLY	300400			
1E-300327-17	RECEIVER INSERT	300327			
2E-300327-29					
A-300347-A	THREADED INSERT	300347			
C-300333-5	SIDE PLATE	300333			
A-300328-1	SIDE PLATE PIN (2)	300328			
C-15666	SEAR SAFETY CAM (Blk. C-91921)	15666			
B-300351-	PIVOT PIN (3)	300351			
A-17047	SEAR SPRING	17047			
C-15280	TRIGGER (Blk. C-91921)	15280			
C-19461	TRIGGER CONNECTOR (Blk. C-91921)	19461			
B-17053	TRIGGER SCREW FRONT (Blk. B-91920)	17053			
B-91128	TRIGGER ENGAGEMENT SCREW (Blk. B-91922)	91128			
A-15400	TRIGGER SPRING	15400			
A-300426	TRIGGER STOP SCREW	300426			
D-300408-7	SAFETY	300408			
B-17043	SAFETY PIVOT PIN (Blk. B-91918)	17043			
B-17044	SAFETY SNAP WASHER (Blk. 200042)	17044			
B-300407-1	SAFETY SPRING	300407			
C-300345-3	BOLT STOP	300345			
B-17034	RECEIVER PLUG SCREW (4)	17034			
B-300361-	RECOIL BRACKET	300361			
B-300403-	BOLT BODY ASSEMBLY	300403			
D-300339-5	BOLT BODY	300339			
C-300370-	BOLT HANDLE	300370			
C-300360-	BOLT HANDLE BLANK	300360			
A-300329-2	BOLT HANDLE PIN	300329			
B-305390-2	BOLT HEAD ASSEMBLY	305390	305391		
E-300338-17	BOLT HEAD (30-06, 270)	300338			
C-300416-	BOLT HEAD (7mm Rem, 300 Win)		300416		
	EXTRACTOR				
C-93712	30-06, 270 (Blk. 93711)	93712			
C-97322	7mm Rem, 300 Win (Blk. 97321)		97322		
C-27340	EXTRACTOR RIVET		27341		
B-300342-1	EJECTOR	300342			
A-300367-	EJECTOR SPRING	300367			
A-94555	EJECTOR PIN	94555			
B-300330-	BOLT ASSEMBLY PIN	300330			
B-300404-A	FIRING PIN ASSEMBLY	300404			
C-300368-4	BOLT PLUG	300368			
B-300346-	BOLT PLUG INSERT	300346			
C-300418-	TUMBLER	300418			
D-300420-A	TUMBLER BLANK	300420			
C-201224	LOCK PLUNGER (Blk. 201223)	201224			

MF0776

Elizabethtown Research Division

PARTS LIST #YYY

Date: Model 710

Supersedes Previous Model XXX

11/11/99 Bolt Action

Parts List #AAA

Centerfire Rifle R.H.

Sheet 2 Dotted line (- - -)
of 2 indicates same part number

30-06 270

7mm 300
Rem Mag Win Mag

DWG. NO. PART NAME PART NUMBERS

DWG. NO.	PART NAME	PART NUMBERS
FIRING PIN ASSY CONTINUED		
A-201217	LOCK SPRING	201217
A-300427	SPRING RETAINER	300427
C-300334-A	FIRING PIN	300334
C-300335-2	FIRING PIN TIP	300335
C-300336-B	FIRING PIN HEAD	300336
A-300399-D	FIRING PIN SPRING	300399
FRONT SIGHT		
C-15373	30-06, 270 (Blk. C-90393)	94084
B-14659	7mm REM, 300 WIN	94095
B-28510	FRONT SIGHT RAMP (Blk. B-16724)	94657
B-28505	FRONT SIGHT RAMP SCREW (2) (Blk. 90347)	28505
B-103145	REAR SIGHT ASSEMBLY	103145
A-90906	ELEVATION SCREW	90906
C-93905	REAR SIGHT ADJUSTURE (Blk. C-93906)	94333
C-103530	REAR SIGHT BASE (Blk. 94023)	103530
C-93904	REAR SIGHT SLIDE (Blk. C-93907)	94335
B-90904	WINDAGE SCREW (Blk. 91911)	90904
B-28505	REAR SIGHT BASE SCREW (2) (Blk. 90347)	28505
B-305455	STOCK ASSEMBLY COMPLETE	305455
STOCK		
B-15161	FRONT SCREW BUSHING (Blk 91915)	15161
C-97971	GRIP CAP	97971
D-97973	RECOIL PAD	97973
C-97972	RECOIL PAD BACKER	97972
A-98008	RECOIL PAD SCREW (2)	98008
C-300362-4	MAGAZINE LATCH	300362
B-300398-B	LATCH SPRING	300398
B-300371-A	LATCH PIVOT PIN	300371
B-300096	SLING SWIVEL STUD (2)	300096
C-104125	FRONT TAKE DOWN SCREW	104141
C-104125	MIDDLE TAKE DOWN SCREW	104143
B-300425-	REAR TAKE DOWN SCREW	300425
B-305395-	MAGAZINE ASSEMBLY	305395
E-300363-9	MAGAZINE BOX	300363
D-300364-4	MAGAZINE FOLLOWER	300364
D-300365-3	MAGAZINE BOTTOM	300365
C-300405-	MAGAZINE SPRING	300405

MF0777

Elizabethtown Research Division

PARTS LIST #YYY

Date: Model 710

Supersedes Previous Model XXX

11/11/99 Bolt Action

Parts List #AAA

Centerfire Rifle R.H.

Sheet 1 Dotted line (- - -)
 of 2 indicates same part number 30-06 270 7mm 300
 Rem Mag Win Mag

DWG. NO.	PART NAME	PART NUMBERS
----------	-----------	--------------

RAMAC

DOCUMENT ENVELOPE ASSEMBLY

Document Envelope	XXXX	----	----	----
Instruction Book	1649	----	----	----
Product Owners Card	xxxx	----	----	----
Remington Authorized Gunsmith	1426	----	----	----
Safety Booklet	3413	----	----	----
Remington Museum Flyer	3499	----	----	----
Oval Label	3475	----	----	----
	3491	----	----	----

CARTON ASSEMBLY

Box & Envelope Label	993002	----	----	----
(Label To Read "Model 710")				

NOTE: THE ABOVE PARTS ARE FOR PACKAGING ONLY

C-305410-	BARREL ASSEMBLY COMPLETE	305410	305411	305412	305413
C-305400-	BARREL ASSEMBLY	305400	305401	305402	305403
E-305315-11	BARREL	305315	305316	305317	305318
E-300340-8	RECEIVER	300340			
D-300401-A	RECEIVER INSERT ASSEMBLY COMPLETE	300401			
C-300400-	RECEIVER INSERT ASSEMBLY	300400			
1E-300327-17	RECEIVER INSERT	300327			
2E-300327-29					
A-300347-A	THREADED INSERT	300347			
C-300333-5	SIDE PLATE	300333			
A-300328-1	SIDE PLATE PIN (2)	300328			
C-15666	SEAR SAFETY CAM (Blk. C-91921)	15666			
B-300351-	PIVOT PIN (3)	300351			
A-17047	SEAR SPRING	17047			
C-15280	TRIGGER (Blk. C-91922)	15280			
C-19461	TRIGGER CONNECTOR (Blk. C-91921)	19461			
B-17053	TRIGGER SPRING FRONT (Blk. B-91920)	17053			
B-91128	TRIGGER ENGAGEMENT SCREW (Blk. B-91922)	91128			
A-15400	TRIGGER SPRING	15400			
A-300426	TRIGGER STOP SCREW	300426			
D-300408-7	SAFETY	300408			
B-17043	SAFETY PIVOT PIN (Blk. B-91918)	17043			
B-17044	SAFETY SNAP WASHER (Blk. 200042)	17044			
B-300407-1	SAFETY SPRING	300407			
C-300345-2	BOLT STOP	300345			
B-17034	RECEIVER PLUG SCREW (4)	17034			
B-300361-	RECOIL BRACKET	300361			
B-300403-	BOLT BODY ASSEMBLY	300403			
B-300339-5	BOLT BODY	300339			
C-300370-	BOLT HANDLE	300370			
C-300360-	BOLT HANDLE BLANK	300360			
A-300329-2	BOLT HANDLE PIN	300329			
B-305390-2	BOLT HEAD ASSEMBLY	305390	305391		
E-300338-17	BOLT HEAD (30-06, 270)	300338			
C-300416-	BOLT HEAD (7mm Rem, 300 Win)		300416		
	EXTRACTOR				
C-93712	30-06, 270 (Blk. 93711)	93712			
C-97322	7mm Rem, 300 Win (Blk. 97321)		97322		
C-27340	EXTRACTOR RIVET		27341		
B-300342-1	EJECTOR	300342			
A-300367-	EJECTOR SPRING	300367			
A-94555	EJECTOR PIN	94555			
B-300330-	BOLT ASSEMBLY PIN	300330			
B-300404-A	FIRING PIN ASSEMBLY	300404			
C-300368-4	BOLT PLUG	300368			
B-300346-	BOLT PLUG INSERT	300346			
C-300418-	TUMBLER	300418			
D-300420-A	TUMBLER BLANK	300420			
C-201224	LOCK PLUNGER (Blk. 201223)	201224			

MF0778

Elizabethtown Research Division

PARTS LIST #YYY

Date: Model 710

Supersedes Previous Model XXX

11/11/99 Bolt Action

Parts List #AAA

Centerfire Rifle R.H.

Sheet 2 Dotted line (- - -)
 of 2 indicates same part number 30-06 270 7mm 300
 Rem Mag Win Mag

DWG. NO.	PART NAME	PART NUMBERS			
FIRING PIN ASSY CONTINUED					
A-201217	LOCK SPRING	201217	----	----	----
A-300427	SPRING RETAINER	300427	----	----	----
C-300334-A	FIRING PIN	300334	----	----	----
C-300335-2	FIRING PIN TIP	300335	----	----	----
C-300336-B	FIRING PIN HEAD	300336	----	----	----
A-300399-D	FIRING PIN SPRING	300399	----	----	----
FRONT SIGHT					
C-15373	30-06, 270 (Blk. C-90393)	94084	----	----	----
B-14659	7mm REM, 300 WIN			94095	----
B-28510	FRONT SIGHT RAMP (Blk. B-16724)	94657	----	----	----
B-28505	FRONT SIGHT RAMP SCREW (2) (Blk. 90347)	28505	----	----	----
B-103145	REAR SIGHT ASSEMBLY	103145	----	----	----
A-90906	ELEVATION SCREW	90906	----	----	----
C-93905	REAR SIGHT ADJUSTURE (Blk. C-93906)	94333	----	----	----
C-103530	REAR SIGHT BASE (Blk. 94023)	103530	----	----	----
C-93904	REAR SIGHT SLIDE (Blk. C-93907)	94335	----	----	----
B-90904	WINDAGE SCREW (Blk. 91911)	90904	----	----	----
B-28505	REAR SIGHT BASE SCREW (2) (Blk. 90347)	28505	----	----	----
B-305455	STOCK ASSEMBLY COMPLETE	305455	----	----	----
STOCK					
B-15161	FRONT SCREW BUSHING (Blk 91915)	15161	----	----	----
C-97971	GRIP CAP	97971	----	----	----
D-97973	RECOIL PAD	97973	----	----	----
C-97972	RECOIL PAD BACKER	97972	----	----	----
A-98008	RECOIL PAD SCREW (2)	98008	----	----	----
C-300362-4	MAGAZINE LATCH	300362	----	----	----
B-300398-B	LATCH SPRING	300398	----	----	----
B-300371-A	LATCH PIVOT PIN	300371	----	----	----
B-300096	SLING SWIVEL STUD (2)	300096	----	----	----
C-104125	FRONT TAKE DOWN SCREW	104141	----	----	----
C-104125	MIDDLE TAKE DOWN SCREW	104143	----	----	----
B-300425-	REAR TAKE DOWN SCREW	300425	----	----	----
B-305395-	MAGAZINE ASSEMBLY	305395	----	----	----
E-300363-9	MAGAZINE BOX	300363	----	----	----
D-300364-4	MAGAZINE FOLLOWER	300364	----	----	----
D-300365-8	MAGAZINE BOTTOM	300365	----	----	----
C-300405	MAGAZINE SPRING	300405	----	----	----

MF0779

STORAGE LOC


~~300405~~ MAG SPRING ✓
 300398 MAG LATCH SPRING ✓
 300362 MAG LATCH ✓
 15161 FRONT SCREW BUSHING ✓
~~300399~~ FIRING PIN SPRING
 300404 FIRING PIN ASSY ✓
 300330 BOLT ASSY PIN ✓
 94556 EJECTOR PIN ✓
~~300369~~ EJECTOR SPRING
~~BOLT ASSY COMPLETE~~
 300403 BOLT BODY ASSY ✓
 300418 TUMBLER SPRING ✓
 300420 TUMBLER BODY ✓
~~300408~~ TUMBLER SPRING
 300402 SPRING RETAINER ✓

83

MF0780

ADD/USE FROM M700 FOR 710						
PART NBR	DESCRIPTION	QUANTITY ORDERED	DELIVERY DATE	PO #	QUANTITY RECEIVED	BACK- ORDERED
1444	CARTON ASSEMBLY					
15161	FRONT SCREW BUSHING	2,000 4,000	03/08/00 05/15/00	2784 2785	1,700-3/8	300
15400	TRIGGER SPRING	2,000 4,000	03/08/00 05/15/00	2750 2750	2,000-3/8	
15666	SEAR SAFETY CAM	4,000	03/08/00	2728		
15481	TRIGGER STOP SCREW	2,000 4,000	03/15/00 05/15/00	2739 2740	2,000-3/8	
17034	RECEIVER PLUG SCREWS	50,000	02/24/00	2496	25,000-2/2 25,000-3/8	
17043	SAFETY PIVOT PIN	1,000 4,000	03/01/00 05/15/00	2868 2868	1,000-3/8	
17044	SNAP WASHER	2,000 4,000	03/08/00 05/08/00	2741 2742	2,000-3/8	
17047	SEAR SPRING	2,000 4,000	03/08/00 05/15/00	2731 2732	2,000-3/8	
17053	TRIGGER FRONT SCREW	3,500 4,000	03/08/00 05/15/00	2754 2755	3,500-3/8	
19461	TRIGGER CONNECTOR	2,000 4,000	03/08/00 05/08/00	2735 2736	1,000-3/8	1,000
28505	FRONT & REAR SIGHT SCREWS	50,000	01/13/00	2580	25,000-2/9 5,000-3/8	
90904	WINDAGE SCREW	15,000	02/22/00	2645	15,000-2/9	
90906	ELEVATION SCREW	25,000 25,000	02/21/00 07/10/00	2581 2582		
93712	EXTRACTOR	2,000 4,000	03/08/00 05/15/00	2774 2775		
93906	REAR SIGHT ADJUSTURE BLANK	2,000 3,000	MAY JUNE	PMPD PMPD		
93907	REAR SIGHT SLIDE BLANK	2,000 3,000	MAY JUNE	PMPD PMPD		
94023	REAR SIGHT BASE BLANK	2,000 3,000	MAY JUNE	PMPD PMPD		
94084	FRONT SIGHT	2,000 4,000	03/08/00 05/08/00	2743 2744		
94555	EJECTOR PIN	2,000 4,000	03/08/00 05/15/00	2776 2777		
94657	FRONT SIGHT RAMP	2,000 4,000	03/08/00 05/08/00	2745 2746		
97971	GRIP CAP	2,000 5,000	03/08/00 05/08/00	2747 2748		
97973	RECOIL PAD	2,000 4,000	03/08/00 05/08/00	2749 2750		
98008	RECOIL PAD SCREWS	2,000 4,000	03/08/00 05/08/00	2751 2752	2,000-3/8	
201217	LOCK SPRING	1,000 4,000	03/08/00 05/15/00	2753 2753		
201224	LOCK PLUNGER	1,000 4,000	03/15/00 05/08/00	2778 2779		

MF0781



CONFIDENTIAL

MF0782

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

12/09/99

C:\windows\TEMP\Book2.xlsjm710 58,300 597 30,000 710

		710 Costing Model 58,300 597s & 30,000 710s						
PART DESCRIPTION	Part #	Material \$	Run Rate (hrs/pc)	Labor \$	Fixed O.H. \$	Var O.H. \$	Total O.H. \$	Total
Document Envelope Assembly	1721	\$ 0.09		\$ -	\$ -	\$ -	\$ -	\$ 0.09
Document Envelope	1649	0.08		-	-	-	-	0.08
Users manual	3391	0.15		-	-	-	-	0.15
Product Owners Card	1426	0.03		-	-	-	-	0.03
Remington Authorized Gunsmith	3413	0.07		-	-	-	-	0.07
Safety Booklet	3499	0.10		-	-	-	-	0.10
Oval Label	3491	0.01		-	-	-	-	0.01
Carton Assembly	1444	2.05		-	-	-	-	2.05
Box and Envelope Label (710)	993002	0.04		-	-	-	-	0.04
Shelf Talker		0.14		-	-	-	-	0.14
Barrel Assembly Complete	305410		0.0790	0.71	1.08	2.06	3.14	3.85
Barrel Assembly	3305400				-	-	-	-
Barrel	305315	4.80	0.3866	4.09	6.25	11.98	18.15	27.04
Receiver	300340	1.76	0.0055	0.06	0.09	0.17	0.26	2.08
Receiver Insert Assembly Complete	????		0.0530	0.47	0.73	1.38	2.11	2.58
Receiver Insert Assembly	????		0.0050	0.04	0.07	0.13	0.20	0.24
Receiver Insert	300327	0.62		-	-	-	-	0.62
Threaded Insert	300347	0.04		-	-	-	-	0.04
Side Plate	300333	0.09	0.0010	0.01	0.02	0.03	0.05	0.15
Side Plate Pin (2)	300328	0.16	0.0010	0.01	0.02	0.03	0.05	0.22
Sear Safety Cam	15666	0.94		-	-	-	-	0.94
Pivot Pin (3)	300351	0.27		-	-	-	-	0.27
Sear Spring	17047	0.05		-	-	-	-	0.05
Trigger	15280	1.53		-	-	-	-	1.53
Trigger Connector	19461	1.03		-	-	-	-	1.03
Trigger Screw Front	17053	0.07		-	-	-	-	0.07
Trigger Engagement Screw	91128	0.06		-	-	-	-	0.06
Trigger Spring	15400	0.05		-	-	-	-	0.05
Trigger Stop Screw	15481	0.04		-	-	-	-	0.04
Safety	300408	0.23		-	-	-	-	0.23
Safety Detent Spring	300407	0.06		-	-	-	-	0.06
Safety Pivot Pin	300352	0.14		-	-	-	-	0.14
Safety Spring	300343	0.05		-	-	-	-	0.05
Safety Button		0.41	0.0050	0.05	0.08	0.15	0.23	0.70
Safety Plunger		0.07		-	-	-	-	0.07
Safety Key/Cap/Bushing		0.69		-	-	-	-	0.69
Bolt Stop	300345	0.22	0.0010	0.01	0.02	0.03	0.05	0.28
Receiver Plug Screws (4)	17034	0.12		-	-	-	-	0.12
Recoil Bracket	300361	0.19	0.0010	0.01	0.02	0.03	0.05	0.25
Bolt Assembly Complete	????			-	-	-	-	-
Bolt Body Assembly	????		0.0275	0.29	0.45	0.85	1.29	1.59
Bolt Body	300339	0.74	0.0032	0.03	0.05	0.10	0.15	0.92
Bolt Handle	300370		0.0120	0.13	0.19	0.37	0.56	0.69
Bolt Handle Blank	300360	1.63		-	-	-	-	1.63
Bolt Handle Pin	300329	0.10		-	-	-	-	0.10
Bolt Head Assembly	305390		0.0580	0.52	0.79	1.51	2.30	2.82
Bolt Head	300338	1.75	0.0809	0.86	1.31	2.49	3.80	6.40

Page 1

MF0783

Confidential - Subject to Protective Order
BARBER - 5.22.06r0010733
Williams v. Remington

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

12/09/99

C:\windows\TEMP\Book2.xlsjm710 58,300 597 30,000 710

		710 Costing Model 58,300 597s & 30,000 710s						
PART DESCRIPTION	Part #	Material \$	Run Rate (hrs/pc)	Labor \$	Fixed O.H. \$	Var O.H. \$	Total O.H. \$	Total
Extractor	93712	0.77		-	-	-	-	0.77
Ejector	300342	0.11	0.0010	0.01	0.02	0.03	0.05	0.17
Ejector Spring	????	0.02		-	-	-	-	0.02
Ejector Pin	94555	0.04		-	-	-	-	0.04
Bolt Assembly Pin	300330	0.15	0.0010	0.01	0.02	0.03	0.05	0.21
Firing Pin Assembly	????		0.0070	0.06	0.10	0.18	0.28	0.34
Bolt Plug	300368	0.25		-	-	-	-	0.25
Bolt Plug Insert	300346	0.80		-	-	-	-	0.80
Firing Pin	300334	1.19	0.0010	0.01	0.02	0.03	0.05	1.25
Firing Pin Tip	300335	0.33	0.0015	0.02	0.02	0.05	0.07	0.42
Firing Pin Head	300336	1.50	0.0020	0.02	0.03	0.06	0.09	1.62
Firing Pin Spring	????	0.10		-	-	-	-	0.10
Front Sight	94084	0.82		-	-	-	-	0.82
Front Sight Ramp	94657	1.13	0.0020	0.02	0.03	0.06	0.09	1.25
Front Sight Ramp Screws (2)	28505	0.09		-	-	-	-	0.09
Rear Sight Assembly	103146			-	-	-	-	-
Elevation Screw	90906	0.04		-	-	-	-	0.04
Rear Sight Aperture	94333	0.14	0.0030	0.03	0.05	0.09	0.14	0.31
Rear Sight Base	103531	0.97	0.0030	0.03	0.05	0.09	0.14	1.14
Rear Sight Slide	94335	0.47	0.0050	0.05	0.08	0.15	0.23	0.76
Windage Screw	90904	0.02		-	-	-	-	0.02
Rear Sight Base Screw (2)	28505	0.09		-	-	-	-	0.09
Stock Assembly Complete	????		0.0160	0.14	0.22	0.42	0.64	0.78
Stock Assembly	????			-	-	-	-	-
Stock	????	5.38		-	-	-	-	5.38
Front Screw Bushing	15161	0.13		-	-	-	-	0.13
Middle Screw Bushing	????	0.05		-	-	-	-	0.05
Rear Screw Bushing	????	0.05		-	-	-	-	0.05
Grip Cap	97971	0.18		-	-	-	-	0.18
Recoil Pad	97973	1.63		-	-	-	-	1.63
Recoil Pad Screw (2)	98008	0.02		-	-	-	-	0.02
Magazine Latch	300362	0.19		-	-	-	-	0.19
Magazine Latch Spring	????	0.03		-	-	-	-	0.03
Magazine Latch Pin	300371	0.07	0.0010	0.01	0.02	0.03	0.05	0.13
Sling Swivel Stud (2)	300096	0.14		-	-	-	-	0.14
Takedown Screw (2)	????	0.16		-	-	-	-	0.16
Rear Takedown Screw	????	0.08		-	-	-	-	0.08
Magazine Assembly	????		0.0083	0.07	0.11	0.22	0.33	0.40
Magazine Box	300363	2.90	0.0010	0.01	0.01	0.03	0.04	2.95
Magazine Follower	300364	0.26		-	-	-	-	0.26
Magazine Bottom	300365	0.26		-	-	-	-	0.26
Magazine Spring	17028	0.42		-	-	-	-	0.42
Freight on Parts		0.25						0.25
Value Added Cost of:								
Proof/Gallery/Inspect/Pack		1.15	0.1500	1.34	2.05	3.91	5.96	8.45
Total Cost		\$ 43.05	0.9226	\$ 9.15	\$ 13.98	\$ 26.61	\$ 40.59	\$ 92.79

MF0784

Remington Arms Company			M710 Estimate								M710 Complete			Mayfield Plant		
	Proposed	Part #	Print #	Rev #	Material	External Processing	Labor	Fixed	Var	Total	Estimated	White Paper Price	Difference			
PART DESCRIPTION	Process				\$	\$	\$	O.H. \$	O.H. \$	O.H. \$	Price per Part		() Favorable			
Document Envelope Assembly	Purchase	1721	7777		\$ 0.090	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.09	\$ 0.09	\$ -			
Document Envelope	Purchase	1649	1649		\$ 0.080	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.08	\$ 0.08	\$ -			
Instruction Book	Purchase	7777	7777		\$ 0.150	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.15	\$ 0.15	\$ -			
Product Owners Card	Purchase	1426	1426		\$ 0.030	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.03	\$ 0.03	\$ -			
Remington Authorized Gunsmith	Purchase	3413	3413		\$ 0.070	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.07	\$ 0.07	\$ -			
Safety Booklet	Purchase	3499	3499		\$ 0.100	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.10	\$ 0.10	\$ -			
Remington Museum Flyer	Purchase	3475	3475		\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -			
Own Label	Purchase	3491	3491		\$ 0.010	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.01	\$ 0.01	\$ -			
Carton Assembly	Purchase	1444	1444		\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 2.05	\$ (2.05)			
Corrugated Box	Purchase				\$ 0.502	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.50		\$ 0.50			
End	Purchase				\$ 0.690	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.69		\$ 0.69			
					\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -		\$ -			
Box and Envelope Label (710)	Purchase	993002	993002		\$ 0.040	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.04	\$ 0.04	\$ -			
Shelf Talker	Purchase				\$ 0.140	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.14	\$ 0.14	\$ -			
					\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -		\$ -			
Barrel Assembly Complete	Assemble	305410	C-305410	No Rev		\$ -	\$ 0.040	\$ 0.063	\$ 0.116	\$ 0.179	\$ 0.22	\$ 3.85	\$ (3.63)			
Barrel Assembly	Assemble & Machine	305400	C-305400	No Rev		\$ -	\$ -	\$ -	\$ -	\$ -	\$ -		\$ -			
Barrel	Machine	305315	E-305315	11	\$ 5.054	\$ -	\$ 7.765	\$ 5.911	\$ 10.956	\$ 16.867	\$ 25.69	\$ 21.84	\$ (3.85)			
Receiver	Machine	300340	E-300340	19	\$ 1.700	\$ -	\$ 0.886	\$ 1.391	\$ 2.578	\$ 3.969	\$ 6.55	\$ 2.00	\$ 4.55			
Receiver Insert Assembly Complete	Assemble	300401	D-300401	A		\$ -	\$ 0.562	\$ 0.883	\$ 1.636	\$ 2.519	\$ 3.08	\$ 2.63	\$ 0.45			
Receiver Insert Assembly	Ultrasonic Weld	300400	C-300400	No Rev		\$ -	\$ 0.009	\$ 0.014	\$ 0.026	\$ 0.040	\$ 0.05	\$ 0.24	\$ (0.19)			
Receiver Insert	Purchase	300327	E-300327-1-2	(1E)-17 (2E)-29	\$ 0.620	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.62	\$ 0.62	\$ -			
Threaded Insert	Purchase	300347	A-300347	A	\$ 0.036	\$ -	\$ 0.017	\$ 0.017	\$ 0.031	\$ 0.048	\$ 0.08	\$ 0.04	\$ 0.05			
Side Plate	Purchase & Color	300333	C-300333	5	\$ 0.180	\$ -	\$ 0.017	\$ 0.017	\$ 0.031	\$ 0.048	\$ 0.25	\$ 0.15	\$ 0.10			
Side Plate Pin (2)	Purchase & Color	300328	A-300328	1	\$ 0.185	\$ -	\$ 0.011	\$ 0.017	\$ 0.031	\$ 0.047	\$ 0.24	\$ 0.22	\$ 0.02			
Scar Safety Cam	A/U M700	15666	C-15666	24	\$ 0.760	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.76	\$ 0.94	\$ (0.18)			
Pivot Pin (1)	Purchase & Heat Treat	300351	B-300351	No Rev	\$ 0.068	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.07	\$ 0.27	\$ (0.20)			
Scar Spring	A/U M700	17047	A-17047		\$ 0.685	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.82	\$ 0.05	\$ (0.03)			
Trigger	A/U M700	15280	A-15280		\$ 0.375	\$ -	\$ 0.017	\$ 0.017	\$ 0.031	\$ 0.047	\$ 0.44	\$ 1.53	\$ (1.09)			
Trigger Connector	A/U M700	10453	C-10453	2F	\$ 1.506	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 1.51	\$ 1.03	\$ 0.48			
Trigger Screw Front	A/U M700	20053	B-17053	32	\$ 0.040	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.04	\$ 0.07	\$ (0.03)			
Trigger Engagement Screw	A/U M700	300328	A-300328	7	\$ 0.027	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.03	\$ 0.06	\$ (0.03)			
Trigger Spring	A/U M700	10453	A-10453	21	\$ 0.029	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.03	\$ 0.05	\$ (0.02)			
Trigger Stop Screw	Purchase	300328	A-300328	No Rev	\$ 0.042	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.04	\$ 0.04	\$ 0.00			
Safety Arm	Assemble & Heat Treat	300408	D-300408	9	\$ 0.230	\$ -	\$ 0.011	\$ 0.017	\$ 0.031	\$ 0.047	\$ 0.29	\$ 0.23	\$ 0.06			
Safety Pivot Pin	Purchase & Heat Treat	17043	B-17043	1	\$ 0.140	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.14	\$ 0.14	\$ -			
Safety Stopper	Purchase	17044	B-17044	26	\$ 0.025	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.02	\$ 0.06	\$ (0.04)			
Safety Spring	Purchase	300407	B-300407	3	\$ 0.058	\$ -	\$ 0.011	\$ 0.017	\$ 0.031	\$ 0.047	\$ 0.12	\$ 0.05	\$ 0.07			
Bolt Stop	PM/Heat Treat/Color	300345	C-300345	3	\$ 0.219	\$ -	\$ 0.011	\$ 0.017	\$ 0.031	\$ 0.047	\$ 0.28	\$ 0.28	\$ (0.00)			
Receiver Plug Screw (4)	A/U M700	17034	B-17034	34	\$ 0.135	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.14	\$ 0.12	\$ 0.02			
Recall Bracket	Purchase & Color	300361	B-300361	No Rev	\$ 0.123	\$ -	\$ 0.011	\$ 0.017	\$ 0.031	\$ 0.047	\$ 0.18	\$ 0.25	\$ (0.07)			
Bolt Assembly Complete		7777	7777			\$ -	\$ -	\$ -	\$ -	\$ -	\$ -		\$ -			
Bolt Body Assembly	Braze & Finish	300403	D-300403	No Rev		\$ -	\$ -	\$ -	\$ -	\$ -	\$ -		\$ -			
Bolt Body	Machine	300319	D-300319	16	\$ 0.560	\$ -	\$ 0.590	\$ 0.927	\$ 1.718	\$ 2.644	\$ 3.79	\$ 2.51	\$ 1.28			
Bolt Handle	Machine	300370	C-300370	B	\$ 1.630	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 1.63	\$ 0.89	\$ 0.74			
Bolt Handle Blank	Purchase	300360	D-300360	B	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 1.63	\$ (1.63)			
Bolt Handle Pin	Purchase	300329	A-300329	2	\$ 0.140	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.14	\$ 0.10	\$ 0.04			
Bolt Head Assembly	Assemble	305390	B-305390	2		\$ -	\$ 0.136	\$ 0.214	\$ 0.396	\$ 0.610	\$ 0.75	\$ 2.82	\$ (2.07)			
Bolt Head	Machined	300338	E-300338	17	\$ -	\$ 0.600	\$ 0.765	\$ 1.201	\$ 2.225	\$ 3.426	\$ 4.19	\$ 6.40	\$ (2.21)			
Bolt Head Blank	Purchase	300434	D-300434		\$ 1.7500	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 1.75		\$ 1.75			
Extractor	A/U M700	93712	C-93712	2	\$ 0.772	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.77	\$ 0.77	\$ 0.00			
Ejector	Purchase & Color	300342	B-300342	1	\$ 0.110	\$ -	\$ 0.011	\$ 0.017	\$ 0.031	\$ 0.047	\$ 0.17	\$ 0.17	\$ (0.00)			
Ejector Spring	Purchase	300367	A-300367	No Rev	\$ 0.015	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.02	\$ 0.02	\$ (0.00)			
Ejector Pin	A/U M700	94555	A-94555	1	\$ 0.014	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.01	\$ 0.04	\$ (0.03)			
Bolt Assembly Pin	Purchase & Color	300330	H-300330	No Rev	\$ 0.150	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.15	\$ 0.21	\$ (0.06)			
Firing Pin Assembly	Assemble	300404	D-300404	A		\$ -	\$ 0.140	\$ 0.220	\$ 0.407	\$ 0.626	\$ 0.77	\$ 0.34	\$ 0.43			
Pin Plug	Purchase	300368	D-300368	5	\$ 0.215	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.22	\$ 0.25	\$ (0.04)			
Bolt Plug Insert	Purchase	300346	B-300346	No Rev	\$ 0.808	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.81	\$ 0.80	\$ 0.01			
Lock Tumbler	Purchase, H.T., & Color	300418	C-300418	No Rev	\$ 0.626	\$ 0.020	\$ 0.053	\$ 0.083	\$ 0.154	\$ 0.237	\$ 0.92	\$ 0.41	\$ 0.51			
Tumbler Blank	PM/DP	300420	D-300420	A		\$ -	\$ -	\$ -	\$ -	\$ -	\$ -		\$ -			

Confidential

710 Complete 1-20-00

1 of 2

MF0785

Remington Arms Company		M/710 Estimate		M/710 Complete							Mayfield Plans		
PART DESCRIPTION	Proposed	Part #	Print #	Rev #	Material	External Processing	Labor	Fixed	Var	Total	Estimated	White Paper Price	Difference
	Process				\$	\$	\$	O.H \$	O.H \$	O.H \$	Price per Part		() Favorable
Lock Plunger	A/U M/700	201224	C-201224	No Rev	\$ 0.273	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.27	\$ 0.07	\$ 0.20
Lock Spring	A/U M/700	201217	A-201217	No Rev	\$ 0.011	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.01	\$ 0.05	\$ (0.04)
Lock Key Assembly (2 req'd)	A/U M/700	201207	A-201217	No Rev	\$ 0.858	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.90	\$ 0.69	\$ 0.21
Spring Retainer	Purchase	300427	A-300427	No Rev	\$ 0.250	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.25	\$ -	\$ 0.25
Firing Pin	Purchase & Color	300334	C-300334	A	\$ 0.790	\$ -	\$ 0.011	\$ 0.017	\$ 0.031	\$ 0.047	\$ 0.85	\$ 1.25	\$ (0.40)
Firing Pin Tip	Purchase & Heat Treat	300335	B-300335	2	\$ 0.550	\$ -	\$ 0.011	\$ 0.017	\$ 0.031	\$ 0.047	\$ 0.59	\$ 0.42	\$ 0.17
Firing Pin Head	MIM	300336	C-300336	F	\$ 1.500	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 1.50	\$ 1.62	\$ (0.12)
Firing Pin Spring	Purchase	300339	A-300339	D	\$ 0.101	\$ -	\$ 0.032	\$ 0.050	\$ 0.092	\$ 0.142	\$ 0.27	\$ 0.10	\$ 0.17
Front Sight Assembly	A/U M/700	201207			\$ -	\$ -	\$ 0.037	\$ 0.059	\$ 0.109	\$ 0.167	\$ 0.20	\$ -	\$ 0.20
Front Sight	A/U M/700	94084	C-15573	26	\$ 0.807	\$ -	\$ 0.053	\$ 0.083	\$ 0.154	\$ 0.237	\$ 1.10	\$ 0.82	\$ 0.28
Front Sight Ramp	A/U M/700	94657	R-28510	13	\$ 1.188	\$ -	\$ 0.021	\$ 0.033	\$ 0.062	\$ 0.095	\$ 1.30	\$ 1.25	\$ 0.05
Front Sight Ramp Screws (2)	A/U M/700	28505	B-28505	21	\$ 0.080	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.08	\$ 0.09	\$ (0.01)
Rear Sight Assembly	A/U M/700	107145	B-103145	11	\$ -	\$ -	\$ 0.075	\$ 0.117	\$ 0.217	\$ 0.314	\$ 0.41	\$ -	\$ 0.41
Elevation Screw	A/U M/700	90906	A-90906	19	\$ 0.024	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.02	\$ 0.04	\$ (0.02)
Rear Sight Aperture	A/U M/700	97681	C-93905	9	\$ 0.285	\$ -	\$ 0.032	\$ 0.050	\$ 0.092	\$ 0.142	\$ 0.46	\$ 0.31	\$ 0.15
Rear Sight Aperture Blank		93906	C-93906	6	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -
Rear Sight Base	A/U M/700	103531	C-103530	3	\$ 1.017	\$ -	\$ 0.032	\$ 0.050	\$ 0.092	\$ 0.142	\$ 1.19	\$ 1.14	\$ 0.05
Rear Sight Slide	A/U M/700	94335	C-93904	7	\$ 1.200	\$ -	\$ 0.011	\$ 0.017	\$ 0.031	\$ 0.047	\$ 1.26	\$ 0.56	\$ 0.70
Windage Screw	A/U M/700	100026	B-100026	5	\$ 0.191	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.19	\$ 0.10	\$ 0.09
Rear Sight Base Screw (2)	A/U M/700	28505	B-28505	21	\$ 0.047	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.05	\$ 0.09	\$ (0.04)
Stock Assembly Complete	Purchase	305455	D-305455	No Rev	\$ -	\$ -	\$ 0.143	\$ 0.225	\$ 0.417	\$ 0.542	\$ 0.78	\$ 0.78	\$ 0.00
Stock	Purchase	100437	B-100437	No Rev	\$ 5.799	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 5.80	\$ 5.38	\$ 0.42
Front Screw Bushing	A/U M/700	15161	B-15161	77	\$ 0.145	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.15	\$ 0.13	\$ 0.02
Front Screw Bushing Blank		91315	91315	77	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -
Crip Cap	A/U M/700	97971	C-97971	No Rev	\$ 0.180	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.18	\$ 0.18	\$ -
Recoil Pad	A/U M/700	97973	D-97973	26	\$ 1.610	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 1.61	\$ 1.63	\$ (0.02)
Backer Plate	A/U M/700	97972	C-97972	No Rev	\$ 0.230	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.39	\$ -	\$ 0.39
Recoil Pad Screw (2)	A/U M/700	98068	A-98068		\$ 0.090	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.02	\$ 0.02	\$ 0.00
Magazine Latch	Purchase	300362	B-300362		\$ 0.244	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.25	\$ 0.19	\$ 0.06
Magazine Latch Spring	Purchase	300368	B-300368	B	\$ 0.090	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.03	\$ 0.03	\$ (0.00)
Magazine Latch Pin	Purchase & Color	300371	R-300371	A	\$ 0.079	\$ -	\$ 0.011	\$ 0.017	\$ 0.031	\$ 0.047	\$ 0.13	\$ 0.13	\$ (0.00)
Sling Swivel Stud (2)	Purchase	300396	B-300396	4	\$ 0.280	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.28	\$ 0.14	\$ 0.14
Front Takedown Screw	Purchase	100412	C-101125	18	\$ 0.090	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.09	\$ 0.08	\$ 0.01
Front Takedown Screw Blank	Purchase	100412	C-104125	18	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -
Middle Takedown Screw	Purchase	100413	C-104125	18	\$ 0.090	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.09	\$ 0.08	\$ 0.01
Middle Takedown Screw Blank	Purchase	100411	C-104125	18	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -
Rear Takedown Screw	Purchase	300425	C-300425	No Rev	\$ 0.090	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.09	\$ -	\$ 0.09
Magazine Assembly	Assembly	305395	B-305395	No Rev	\$ -	\$ -	\$ 0.074	\$ 0.117	\$ 0.216	\$ 0.333	\$ 0.41	\$ 0.40	\$ 0.01
Magazine Box	Purchase & Color	300363	B-300363	11	\$ 0.600	\$ -	\$ 0.011	\$ 0.017	\$ 0.031	\$ 0.047	\$ 0.66	\$ 2.95	\$ (2.29)
Magazine Follower	Purchase	300364	B-300364	6	\$ 0.134	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.13	\$ 0.26	\$ (0.13)
Magazine Buffer	Purchase	300365	B-300365	9	\$ 0.165	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.17	\$ 0.26	\$ (0.10)
Magazine Spring	A/U M/700	300405	C-300405	No Rev	\$ 0.259	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.26	\$ 0.42	\$ (0.16)
Value Added Cost of: Proof/Gallery/Inspect/Pack					\$ 1.350	\$ -	\$ 1.052	\$ 1.652	\$ 3.061	\$ 4.713	\$ 7.11	\$ 8.45	\$ (1.34)
Total Cost					\$ 41.013	\$ 0.620	\$ 8.644	\$ 13.572	\$ 25.155	\$ 38.727	\$ 89.00	\$ 92.14	\$ (3.14)

MF0786

Remington Arms Company		M710 Estimate				M710 Complete						Mayfield Price		
	Proposed	Part #	Print #	Rev #	Material	External Processing	Labor	Fixed	Var	Total	Estimated	White Paper Price	Difference	
PART DESCRIPTION	Process				\$	\$	\$	O.H.\$	O.H.\$	O.H.\$	Price per Part		() Favorable	
Document Envelope Assembly	Purchase	1721	7777		\$ 0.090	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.09	\$ 0.09	\$ -	
Document Envelope	Purchase	1649	1649		\$ 0.080	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.08	\$ 0.08	\$ -	
Instruction Book	Purchase	7777	7777		\$ 0.150	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.15	\$ 0.15	\$ -	
Product Owners Card	Purchase	1426	1426		\$ 0.030	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.03	\$ 0.03	\$ -	
Remington Authorized Gunsmith	Purchase	1413	1413		\$ 0.070	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.07	\$ 0.07	\$ -	
Safety Hoodlet	Purchase	1499	1499		\$ 0.100	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.10	\$ 0.10	\$ -	
Remington Museum Flyer	Purchase	1475	1475			\$ -	\$ -	\$ -	\$ -	\$ -	\$ -		\$ -	
Oval Label	Purchase	1491	1491		\$ 0.010	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.01	\$ 0.01	\$ -	
Carton Assembly	Purchase	1444	1444			\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 2.05	\$ (2.05)	
Corrugated Box	Purchase				\$ 0.502	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.50		\$ 0.50	
Bed	Purchase				\$ 0.690	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.69		\$ 0.69	
						\$ -	\$ -	\$ -	\$ -	\$ -	\$ -		\$ -	
Box and Envelope Label (710)	Purchase	993002	993002		\$ 0.040	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.04	\$ 0.04	\$ -	
Shelf Talker	Purchase				\$ 0.140	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.14	\$ 0.14	\$ -	
						\$ -	\$ -	\$ -	\$ -	\$ -	\$ -		\$ -	
Barrel Assembly Complete	Assemble	305410	C-305410	No Rev		\$ -	\$ 0.040	\$ 0.074	\$ 0.130	\$ 0.203	\$ 0.24	\$ 3.85	\$ (3.61)	
Barrel Assembly	Assemble & Machine	305400	C-305400	No Rev		\$ -	\$ -	\$ -	\$ -	\$ -	\$ -		\$ -	
Barrel	Machine	305315	E-305315	11	\$ 5.054	\$ -	\$ 3.765	\$ 6.927	\$ 12.198	\$ 19.125	\$ 27.94	\$ 27.04	\$ 0.90	
Receiver	Machine	300340	E-300340	19	\$ 1.700	\$ -	\$ 0.886	\$ 1.610	\$ 2.870	\$ 4.540	\$ 7.09	\$ 2.98	\$ 4.11	
Receiver Insert Assembly Complete	Assemble	300401	D-300401	A		\$ -	\$ 0.562	\$ 1.034	\$ 1.828	\$ 2.856	\$ 5.42	\$ 2.58	\$ 2.84	
Receiver Insert Assembly	Ultrasonic Weld	300400	C-300400	No Rev		\$ -	\$ 0.009	\$ 0.016	\$ 0.029	\$ 0.045	\$ 0.05	\$ 0.24	\$ (0.19)	
Receiver Insert	Purchase	300377	E-300377-1-2	(1E)-17 (2E)-19	\$ 0.620	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.62	\$ 0.62	\$ -	
Threaded Insert	Purchase	300347	A-300347	A	\$ 0.636	\$ -	\$ 0.011	\$ 0.019	\$ 0.034	\$ 0.054	\$ 0.10	\$ 0.04	\$ 0.06	
Side Plate	Purchase & Color	300333	C-300333	5	\$ 0.189	\$ -	\$ 0.011	\$ 0.019	\$ 0.034	\$ 0.054	\$ 0.25	\$ 0.15	\$ 0.10	
Side Plate Pin (2)	Purchase & Color	300328	A-300328	1	\$ 0.186	\$ -	\$ 0.011	\$ 0.019	\$ 0.034	\$ 0.054	\$ 0.25	\$ 0.22	\$ 0.03	
Sole Safety Cam	AU M700	15666	C-15666	24	\$ 0.760	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.76	\$ 0.94	\$ (0.18)	
Pivot Pin (1)	Purchase & Heat Treat	300351	B-300351	No Rev	\$ 0.068	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.07	\$ 0.27	\$ (0.20)	
Sole Spring	AU M700	17047	A-17047		\$ 0.02	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.02	\$ 0.05	\$ (0.03)	
Trigger	AU M700	15280	B-15280	21	\$ 0.13	\$ -	\$ 0.011	\$ 0.019	\$ 0.034	\$ 0.054	\$ 0.44	\$ 1.53	\$ (1.09)	
Trigger Connector	AU M700	15400	C-15400	11	\$ 1.580	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 1.51	\$ 1.03	\$ 0.48	
Trigger Screw Front	AU M700	17053	B-17053	32	\$ 0.019	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.04	\$ 0.07	\$ (0.03)	
Trigger Engagement Screw	AU M700	17128	B-17128	7	\$ 0.027	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.03	\$ 0.06	\$ (0.03)	
Trigger Spring	AU M700	15400	A-15400	11	\$ 0.029	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.03	\$ 0.05	\$ (0.02)	
Trigger Stop Screw	Purchase	300426	A-300426	No Rev	\$ 0.042	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.04	\$ 0.04	\$ -	
Safety Arm	Assemble & Heat Treat	300408	D-300408	9	\$ 0.210	\$ -	\$ 0.011	\$ 0.019	\$ 0.034	\$ 0.054	\$ 0.29	\$ 0.23	\$ 0.06	
Safety Pivot Pin	Purchase & Heat Treat	17043	B-17043	1	\$ 0.140	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.14	\$ 0.14	\$ -	
Slide Washer	Purchase	17044	B-17044	26	\$ 0.025	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.02	\$ 0.06	\$ (0.04)	
Safety Spring	Purchase	300407	B-300407	3	\$ 0.058	\$ -	\$ 0.011	\$ 0.019	\$ 0.034	\$ 0.054	\$ 0.12	\$ 0.05	\$ 0.07	
Bolt Stop	PM/Heat Treat/Color	300345	C-300345	3	\$ 0.219	\$ -	\$ 0.011	\$ 0.019	\$ 0.034	\$ 0.054	\$ 0.28	\$ 0.28	\$ -	
Receiver Plug Screws (4)	AU M700	17034	B-17034	34	\$ 0.135	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.14	\$ 0.12	\$ 0.02	
Recoil Buffer	Purchase & Color	300361	B-300361	No Rev	\$ 0.123	\$ -	\$ 0.011	\$ 0.019	\$ 0.034	\$ 0.054	\$ 0.19	\$ 0.25	\$ (0.06)	
Bolt Assembly Complete	7777	7777	7777	77		\$ -	\$ -	\$ -	\$ -	\$ -	\$ -		\$ -	
Bolt Body Assembly	Braze & Finish	300403	D-300403	No Rev		\$ -	\$ -	\$ -	\$ -	\$ -	\$ -		\$ -	
Bolt Body	Machine	300339	D-300339	16	\$ 0.560	\$ -	\$ 0.590	\$ 1.086	\$ 1.912	\$ 2.998	\$ 4.15	\$ 2.51	\$ 1.64	
Bolt Handle	Machine	300370	C-300370	B	\$ 1.630	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 1.63	\$ 0.69	\$ 0.94	
Bolt Handle Blank	Purchase	300360	D-300360	B		\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 1.63	\$ (1.63)	
Bolt Handle Pin	Purchase	300329	A-300329	2	\$ 0.140	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.14	\$ 0.10	\$ 0.04	
Bolt Head Assembly	Assemble	305390	B-305390	2		\$ -	\$ 0.136	\$ 0.251	\$ 0.441	\$ 0.692	\$ 0.83	\$ 2.82	\$ (1.99)	
Bolt Head	Machined	300338	E-300338	17	\$ -	\$ 0.600	\$ 0.765	\$ 1.407	\$ 2.478	\$ 3.885	\$ 4.65	\$ 6.48	\$ (1.78)	
Bolt Head Blank	Purchase	300334	D-300334		\$ 1.7500	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 1.75		\$ 1.75	
Extractor	AU M700	93712	C-93712	2	\$ 0.772	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.77	\$ 0.77	\$ -	
Ejector	Purchase & Color	300342	B-300342	1	\$ 0.110	\$ -	\$ 0.011	\$ 0.019	\$ 0.034	\$ 0.054	\$ 0.17	\$ 0.17	\$ -	
Ejector Spring	Purchase	300367	A-300367	No Rev	\$ 0.015	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.02	\$ 0.02	\$ -	
Ejector Pin	AU M700	94555	A-94555	1	\$ 0.014	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.01	\$ 0.04	\$ (0.03)	
Bolt Assembly Pin	Purchase & Color	300330	D-300330	No Rev	\$ 0.150	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.15	\$ 0.21	\$ (0.06)	
Firing Pin Assembly	Assemble	300404	B-300404	A		\$ -	\$ 0.140	\$ 0.257	\$ 0.453	\$ 0.710	\$ 0.88	\$ 0.34	\$ 0.51	
Firing Pin	Purchase	300368	D-300368	5	\$ 0.215	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.22	\$ 0.25	\$ (0.04)	
Firing Pin Insert	Purchase	300346	B-300346	No Rev	\$ 0.808	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.81	\$ 0.80	\$ 0.01	
Lock Tumbler	Purchase H.T. & Color	300418	C-300418	No Rev	\$ 0.626	\$ 0.020	\$ 0.053	\$ 0.097	\$ 0.171	\$ 0.269	\$ 0.95	\$ 0.41	\$ 0.54	
Tumbler Blank	PM/PT	300420	D-300420	A		\$ -	\$ -	\$ -	\$ -	\$ -	\$ -		\$ -	

Confidential

710 Complete 120.00

1 of 2

MF0787

Remington Arms Company			M710 Estimate								Mayfield Plan		
	Proposed	Part #	Print #	Rev #	Material	External Processing	Labor	Fixed	Var	Total	Estimated	White Paper Price	Difference
PART DESCRIPTION	Process				\$	\$	\$	O.H \$	O.H \$	O.H \$	Price per Part		() Favorable
Lock Plunger	A/U M700	201224	C-201224	No Rev	\$ 0.273	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.27	\$ 0.07	\$ 0.20
Lock Spring	A/U M700	201217	A-201217	No Rev	\$ 0.011	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.01	\$ 0.05	\$ (0.04)
Lock Key Assembly (2 req'd)	A/U M700	201207	A-201217	No Rev	\$ 0.898	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.90	\$ 0.69	\$ 0.21
Spring Retainer	Purchase	300427	A-300427	No Rev	\$ 0.250	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.25		\$ 0.25
Firing Pin	Purchase & Color	300334	C-300334	A	\$ 0.790	\$ -	\$ 0.011	\$ 0.019	\$ 0.034	\$ 0.054	\$ 0.85	\$ 1.25	\$ (0.40)
Firing Pin Tip	Purchase & Heat Treat	300335	B-300335	2	\$ 0.530	\$ -	\$ 0.011	\$ 0.019	\$ 0.034	\$ 0.054	\$ 0.59	\$ 0.42	\$ 0.17
Firing Pin Head	MM	300336	C-300336	F	\$ 1.500	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 1.50	\$ 1.62	\$ (0.12)
Firing Pin Spring	Purchase	300399	A-300399	D	\$ 0.101	\$ -	\$ 0.032	\$ 0.058	\$ 0.103	\$ 0.161	\$ 0.29	\$ 0.10	\$ 0.19
Front Sight Assembly	A/U M700	201207				\$ -	\$ 0.037	\$ 0.069	\$ 0.121	\$ 0.190	\$ 0.23		\$ 0.23
Front Sight	A/U M700	94084	C-15373	26	\$ 0.807	\$ -	\$ 0.053	\$ 0.097	\$ 0.171	\$ 0.269	\$ 1.13	\$ 0.82	\$ 0.31
Front Sight Ramp	A/U M700	94657	B-28510	73	\$ 1.188	\$ -	\$ 0.021	\$ 0.019	\$ 0.059	\$ 0.107	\$ 1.32	\$ 1.25	\$ 0.07
Front Sight Ramp Screws (2)	A/U M700	28505	B-28505	21	\$ 0.080	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.08	\$ 0.09	\$ (0.01)
Rear Sight Assembly	A/U M700	101145	B-101145	11	\$ -	\$ -	\$ 0.075	\$ 0.137	\$ 0.242	\$ 0.179	\$ 0.45		\$ 0.45
Elevation Screw	A/U M700	90906	A-90906	19	\$ 0.024	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.02	\$ 0.04	\$ (0.02)
Rear Sight Aperture	A/U M700	97681	C-93905	9	\$ 0.285	\$ -	\$ 0.032	\$ 0.038	\$ 0.103	\$ 0.161	\$ 0.48	\$ 0.31	\$ 0.17
Rear Sight Aperture Blank		93906	C-93906	6		\$ -	\$ -	\$ -	\$ -	\$ -			\$ -
Rear Sight Base	A/U M700	101511	C-101530	3	\$ 1.017	\$ -	\$ 0.032	\$ 0.058	\$ 0.103	\$ 0.161	\$ 1.21	\$ 1.14	\$ 0.07
Rear Sight Slide	A/U M700	94335	C-93904	7	\$ 1.200	\$ -	\$ 0.011	\$ 0.019	\$ 0.034	\$ 0.054	\$ 1.26	\$ 0.76	\$ 0.50
Windage Screw	A/U M700	300026	B-300026	5	\$ 0.191	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.19	\$ 0.07	\$ 0.12
Rear Sight Base Screw (2)	A/U M700	28505	B-28505	21	\$ 0.047	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.05	\$ 0.05	\$ (0.00)
Stock Assembly Complete	Purchase	305455	B-305455	No Rev		\$ -	\$ 0.143	\$ 0.263	\$ 0.404	\$ 0.477	\$ 0.87	\$ 0.78	\$ 0.09
Stock	Purchase	300437	E-300437	No Rev	\$ 5.380	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 5.38	\$ 5.38	\$ -
Front Screw Bushing	A/U M700	15161	B-15161	77	\$ 0.145	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.15	\$ 0.13	\$ 0.02
Front Screw Bushing Blank		91915	777		\$ -	\$ -	\$ -	\$ -	\$ -	\$ -			\$ -
Gun Cap	A/U M700	97971	C-97971	No Rev	\$ 0.180	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.18	\$ 0.18	\$ -
Recoil Pad	A/U M700	97973	D-97973	26	\$ 1.610	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 1.61	\$ 1.63	\$ (0.02)
Recoil Plate	A/U M700	97972	C-97972	No Rev	\$ 0.390	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.39		\$ 0.39
Recoil Pad Screw (2)	A/U M700	98008	A-98008	2	\$ 0.042	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.02	\$ 0.02	\$ 0.00
Magazine Latch	Purchase	300362	C-300362		\$ 0.251	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.25	\$ 0.19	\$ 0.06
Magazine Latch Spring	Purchase	300398	B-300398	B	\$ 0.065	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.03	\$ 0.03	\$ (0.00)
Magazine Latch Pin	Purchase & Color	300371	B-300371	A	\$ 0.177	\$ -	\$ 0.011	\$ 0.019	\$ 0.034	\$ 0.054	\$ 0.13	\$ 0.13	\$ 0.00
Sling Swivel Stud (2)	Purchase	300396	B-300396	4	\$ 0.700	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.28	\$ 0.14	\$ 0.14
Front Takedown Screw	Purchase	100425	C-104125	18	\$ 0.090	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.09	\$ 0.08	\$ 0.01
Front Takedown Screw Blank	Purchase	104125	C-104125	18	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -		\$ -
Middle Takedown Screw	Purchase	104125	C-104125	18	\$ 0.090	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.09	\$ 0.08	\$ 0.01
Middle Takedown Screw Blank	Purchase	104141	C-104125	18	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -		\$ -
Rear Takedown Screw	Purchase	300425	C-300425	No Rev	\$ 0.090	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.09		\$ 0.09
Magazine Assembly	Assembly	305395	B-305395	No Rev	\$ -	\$ -	\$ 0.074	\$ 0.137	\$ 0.241	\$ 0.377	\$ 0.45	\$ 0.40	\$ 0.05
Magazine Box	Purchase & Color	300363	B-300363	11	\$ 9.600	\$ -	\$ 0.011	\$ 0.019	\$ 0.034	\$ 0.054	\$ 0.66	\$ 2.95	\$ (2.29)
Magazine Follower	Purchase	300364	B-300364	6	\$ 0.134	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.13	\$ 0.26	\$ (0.13)
Magazine Buffer	Purchase	300365	B-300365	9	\$ 0.165	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.17	\$ 0.26	\$ (0.10)
Magazine Buffer Pin	A/U M700	300405	C-300405	No Rev	\$ 0.259	\$ -	\$ -	\$ -	\$ -	\$ -	\$ 0.26	\$ 0.42	\$ (0.16)
Value Added Cost of: Print/Gallery/Inspect/Pack					\$ 1.350	\$ -	\$ 1.052	\$ 1.936	\$ 3.408	\$ 5.144	\$ 7.75	\$ 8.45	\$ (0.70)
Total Cost					\$ 40.594	\$ 0.620	\$ 8.644	\$ 15.906	\$ 28.008	\$ 43.914	\$ 93.77	\$ 92.14	\$ 1.63

MF0788

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

12/09/99

C:\windows\TEMP\Book2.xls]710 capital by operation

In House Capital

Part Name	Operation	Equipment	Capital Required		Useful Lif	Depreciation	
Barrel	Cut off		\$0				
	Drill	cones	\$9,960	Dec-99	10	996	
	Ream		\$0		10	-	
	Rifle	gages	\$9,800	Feb-00	10	980	
	Wash & Stress Relieve	baskets	\$6,900	Feb-00	10	690	
	Turn	gages	\$10,100	Feb-00	10	1,010	
	Face & Chamber	gages	\$33,300	Apr-00	10	3,330	
	Face & Chamber	machine	\$222,880	Mar-00	10	22,288	
	Cut off and Crown	chuck	\$15,000	Jan-00	10	1,500	
	wash and eddy current test	machine	\$75,000	Mar-00	10	7,500	
	Induction Harden	machine	\$166,000	Mar-00	10	16,600	
	Inspect Hardness	machine	\$12,000	Mar-00	10	1,200	
	Drill and tap sight	fix & gages	\$7,600	Feb-00	10	760	
	Roll mark	fix & gages	\$6,300	Apr-00	10	630	
	Angularity Straighten	fix & gages	\$3,500	Feb-00	10	350	
	Centerless Polish		\$0		10	-	
	Glass Bead Blast	fixtures	\$2,500	Jan-00	10	250	
	Color	racks	\$6,000	Jan-00	10	600	
	Bolt Head	Inspect Purchased Part					
		Blank	gage	\$2,500	Feb-00	10	250
Superabrasive Grind Lugs		fix & gage	\$43,800	Feb-00	10	4,380	
CNC Machine Bolt Face							
Complete		fix & gage	\$174,784	Mar-00	10	17,478	
CNC Machine Cam Cuts							
Ejector Retaining Pin Hole		fix & gage	\$15,000	Mar-00	10	1,500	
CNC Machine Bolt Head							
Retaining Pin Hole		fix & gage	\$15,000	Mar-00	10	1,500	
Punch Form Extractor							
Rotation Notch		fix & gage	\$10,000	Jan-00	10	1,000	
Vendor Heat Treat			\$0		10	-	
Inspect for Hardness			\$0		10	-	
Black Oxide		\$0		10	-		
Bolt Body	Inspect Purchased Part						
	Blank	gage	\$2,000	Jan-00	10	200	
	Machine Cam Cuts	machine	\$0	Feb-00	10	-	
	Assemble Braze Bolt	machine	\$90,000	Mar-00	10	9,000	
	Deplate	tanks	\$9,500	Jan-00	10	950	
	Eddy Current Test		\$0		10	-	
	Glass Bead Blast	fix	\$2,500	Jan-00	10	250	
	Black Oxide		\$0		10	-	
Receiver	Inspect Purchased Part						
	Blank	gage	\$2,500	Jan-00	10	250	
	Machine A-load	machine & CM	\$513,831	Feb-00	10	51,383	
	Machine B-load		\$0	Feb-00	10	-	
	Vibratory tumble deburr		\$0		10	-	
Barrel Assembly	Press Receiver to Barrel	fixture	\$0	Dec-99	Ilion Equip	10	-

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

12/09/99

C:\windows\TEMP\Book2.xls]710 capital by operation
Inspect for straightness gage

\$3,500	Dec-99	10	350
---------	--------	----	-----

**Final
Assembly**

Gallery	100yd range	\$100,000	Dec-99	25	4,000
	snails	\$30,000	Jul-00	25	1,200
	HVAC	\$25,000	Jun-00	10	2,500
	other	\$10,000	Mar-00	25	400
				25	-
		\$100,000	Mar-00	25	4,000
		\$65,000	Jul-00	25	2,600

\$1,801,755**Purchased Parts**

Part #	Part Name	Capital	Tool	Vendor		Payments
300327	Receiver Insert	48,000	Mold	Hanson	Jun-99	5, 9,600
300333	Side Plate	10,000	Stamping Die		Dec-99	5, 2,000
300334	Safety Arm	23,880	Stamping Die	NH Stamping	Dec-99	5, 4,776
300345	Bolt Stop	6,820	PM	Sterling	Dec-99	5, 1,364
300361	Recoil Bracket	2,225	Stamping Die	NH Stamping	Dec-99	5, 445
300360	Bolt Handle Blank	12,800	Invest Cast Die	Fansteel	Dec-99	5, 2,560
300366	Bolt H Braze Shim	0	Use Paste	Lucas Milhaupt	Dec-99	5, -
300368	Bolt Plug	38,088	Mold	Par 4	Dec-99	5, 7,618
300336	Firing pin head	23,000	MIM Mold	Megametal	Dec-99	5, 4,600
300362	Mag Latch	33,480	Mold	Par 4	Dec-99	5, 6,696
300363	Magazine Box	28,000	Mold	Morrissey	Dec-99	5, 5,600
300364	Magazine Follower	33,306	Mold	Par 4	Dec-99	5, 6,660
300365	Magazine Bottom	47,880	Mold	Par 4	Dec-99	5, 9,576
	Stock	150,300	Mold	Par 4	Dec-99	5, 30,060
	Styrofoam Bed	0	Die	Tuscorora		5, -
	PPI	38000				
		\$495,773				

Total	\$2,297,528	253,430
Installation	\$61,000	10, 6,100
	<u>\$2,358,528</u>	<u>259,530</u>

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

12/09/99

C:\windows\TEMP\Book2.xls\Start Up Costs

	8/31/99	9/30/99	10/31/99	11/30/99	12/31/99	Total 1999	1/31/00	2/29/00	3/31/00	4/30/00	5/31/00	6/30/00	7/31/00	Total 2000	Project Total
Direct Labor			3,188.64	4,555.20	3,871.92	11,615.76			7,109.76	8,809.92	10,200.96	6,800.64		32,921.28	44,537.04
From Overhead															
Setters			-	-	-	-	3,625.60	8,565.48	5,349.80	1,767.76		3,070.32	3,535.52	25,914.48	25,914.48
Maintenance			-	-	-	-	2,582.40	5,084.10	5,717.34	4,198.24	3,148.68	4,253.48	2,099.12	27,083.36	27,083.36
EBs			1,849.41	2,642.02	2,245.21	6,737.64	3,600.64	7,916.76	10,542.60	8,570.03	7,742.79	8,192.18	3,268.09	49,833.09	56,570.23
Other Costs															
Travel	124.93		10,000.00			10,124.93									10,124.93
Material for Receiver		2,175.00				2,175.00									2,175.00
Material for Bolt Body			3,000.00			3,000.00									3,000.00
Material for 1,000 Learning Guns (\$43.86/ea)									21,930.00	21,930.00				43,860.00	43,860.00
Material for 60 T&P Guns (\$43.86/ea)										1,315.80	1,315.80			2,631.60	2,631.60
Material for 30 DAT Guns (\$43.86/ea)												1,315.80		1,315.80	1,315.80
15,000 rns of Ammo									600.00	1,200.00	600.00	600.00		3,000.00	3,000.00
Disassembly & Rearrange									6,000.00					6,000.00	6,000.00
Tooling & Inspection		15,265.47	16,250.00	16,250.00	16,250.00	64,015.47									64,015.47
Prototype Parts							8,000.00	8,000.00	8,000.00	8,000.00				32,000.00	32,000.00
Material Handling Purchases											19,333.33	19,333.33	19,333.33	58,000.00	58,000.00
Miscellaneous		5,496.16	9,803.56	9,803.57	9,803.56	34,906.85	286	286	286	286	286	286	286	2,000.00	36,906.85
1999 startup Costs	124.93	22,936.63	44,091.61	33,250.78	32,171.19	132,575.15	18,094.35	29,852.05	65,535.22	56,077.47	42,627.28	43,851.46	28,521.78	284,559.61	417,134.76

MF0791

Description	Items	Part #	Vendor	Lead time	Total Capital	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun	July	Aug
Carton Assembly		1444													
	Carton Dies	0						0		0	0				
	Insert Dies	0			\$19,000			6,333		6,333	6,333				
Box and Envelope Label (710)		993002													
		0													
Barrel Assembly Complete		305410			\$0										
Barrel Assembly		305400			\$0										
Barrel	Machine & gages	305315													
	Cut to length														
	Gundrill Bore														
	Ream Bore	hyd pump			\$6,080	6,080									
	Rifle Bore				\$15,900	7,950		7,950							
	Stress Relieve	baskets			\$7,500		7,000								
	Turn OD	gages			\$5,000		5,000								
	Face and Chamber	gages			\$31,000		15,000	14,000	2,000						
	Face and Chamber	machine			\$189,448	63,149				63,149		63,149			
	Cut off and crown Muzzle	chuck head			\$15,000				15,000						
	Drill and Tap Holes, Mill Slot	fixture&gage			\$7,600			7,600							
	Wash	0			\$0										
	Heat Treat				\$175,000		58,333		58,333	58,333					
	Inspect Hardness				\$15,000				15,000						
	Acid Wash	0			0										
	Centerless Polish	0			0										
	Eddy Current Test				104,500		34,833		34,833	34,833					
	Press Barrel to Receiver				\$11,000										
	Rollmark				\$3,500			6,300							
	Angularity Straighten				3,500										
	Centerless Polish				0										
	Glass Bead Blast				2,500		2,500								
	Black Oxide				6,000		6,000								
Receiver	LT15	300340			\$436,756	145,585				145,585	145,585				
	CMM				\$45,000			22,500		22,500					
	CMM Gage														
	Vibratory Deburr														
Receiver Insert Assembly Complete	Comparator and fixture	300401			\$12,000		2,000	2,000	8,000						
Receiver Insert Assembly	ultrasonic weld fixture	300400			\$4,000			4,000							
Receiver Insert	Hanson Mold	300327			\$48,000			\$48,000							
	PPI Fixture				\$2,500			2,500							
Side Plate	Stamping Die	300333			\$13,000			4,333		4,333	4,333				
	PPI Fixture				\$1,500					1,500					
Sear Safety Cam		15666			\$0										
	PPI Fixture				\$ 3,000.00			1,500			1,500				
Trigger	PM Mold	15280			\$15,225			7,613			7,613				
	PPI Fixture				\$ 3,000.00			1,500		1,500					
Trigger Connector		19461			\$ 3,000.00			1,500		1,500					
Safety Arm	Stamping Die	300408			\$25,552			12,776			12,776				
	PPI Fixture				\$2,400			2,400							
Lock tumbler	MIM Mold	??			\$35,000		17,500			17,500					
Safety Snap Washer	Stamping Die	17044			\$0										
	PPI Fixture				\$2,400			1,200		1,200					
Bolt Stop	PM Die	300345			\$6,820			6,820							
	PPI Fixture	0			\$1,500					1,500					

Description	Items	Part #	Vendor	Lead time	Total Capital	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun	July	Aug
Recoil Bracket	Stamping Die	300361			\$0										
Bolt Assembly Complete		???			\$0										
Bolt Body Assembly	Brazing Machine	300403			\$98,000		32,667		32,667	32,667					
	Deplate Tanks				\$9,500				9,500						
	glass bead blast				\$2,500				2,500						
Bolt Body	Gages at Machining	300339			\$4,500			1,500		3,000					
Bolt Handle	Machining Fixtures & Gages	300370			\$12,500		6,250	6,250							
Bolt Handle Blank	Investment Cast Mold	300360			\$12,575	6,288			6,288						
	PPI Fixture	0			\$2,500		1,200	1,300							
Bolt Head Assembly	Assy Fixture	305390			\$4,100			4,100							
Bolt Head	Edgetek Grind	43800			\$48,900		21,900		21,900						
	Machining Fixtures	174800			\$174,800	69,920			104,880						
	Machine Ejector Retaining				\$15,000		7,500		7,500						
	Machine Retaining Pin Hole				\$15,000		7,500		7,500						
	Punch Form Ejector				\$10,000		5,000		5,000						
Extractor	PPI Fixture	93712			\$3,300				3,300						
Firing Pin Assembly	Assy Fixture	300404			\$4,500		4,500								
Bolt Plug	Plastic Mold	300368			\$38,098	12,596		12,696	12,696						
Bolt Plug Insert	PPI Fixture	300346			\$3,000			1,500		1,500					
Firing Pin Head	MIM Mold	300336			\$37,500		12,500		12,500	12,500					
	PPI Fixture				\$1,500			1,500							
Front Sight Assembly	Assembly Press				\$4,200				4,200						
Front Sight	PM Mold	94084			\$0										
Front Sight Ramp	PM Mold	94657			\$0										
Rear Sight Assembly		103145			\$0										
Rear Sight Aperture	Machining Fixture	97681			\$9,000			4,000	5,000						
Rear Sight Aperture Blank	MIM Mold	93906			\$0										
Rear Sight Base	MIM Mold	103531			\$0										
Rear Sight Slide	MIM Mold	94335			\$0										
Stock Assy															
Stock Assembly	Fixture	???			\$2,800					2,800					
Stock	Plastic Mold	???			\$150,300	50,100		50,100	50,100						
	PPI Fixture	0			\$4,500		4,500								
Front Screw Bushing	Family plastic mold	15161			\$12,000			4,000		4,000	4,000				
Middle Screw Bushing	see front screw bushing	???			\$0										
Rear Screw Bushing	see front screw bushing	???			\$0										
Magazine Latch	Plastic Mold	300362			\$33,480	11,160		11,160	11,160						
	PPI Fixture				\$0										
Magazine Assembly		305395			\$0										
Magazine Box	Stamping Die	300363			\$46,500	15,500		15,500	15,500						
	PPI fixture				\$4,500		2,250		2,250						
Magazine Follower	tic Mold (family w/ bottom)	300364			\$78,786	26,262		26,262	26,262						
	PPI fixture				\$3,000			3,000							
Magazine Bottom	ic Mold (family w/ follower)	300365			\$0										
	PPI fixture														
Magazine Spring	Stamping Die	300405			\$0										
	PPI fixture														

Description	Items	Part #	Vendor	Lease time	Total Capital	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun	July	Aug
Gallery	Design				\$15,000	15,000									
	1st installment				\$100,000		100,000								
	2nd installment				\$140,000			140,000							
	3rd installment				\$45,000				45,000						
	Snails				\$25,000				25,000						
TOTAL					\$2,447,210	440,690	357,433	443,693	543,869	416,235	182,141	63,149	0	0	0

CONFIDENTIAL

83

Team

MF0795

M710 Sept 1999




	Material	Labor	VOH	FOH	Total
% of Total	47.82608696	9.782608696	15.2173913	27.17391304	100
Dollars	44	9	14	25	92

ME0796

M710 vs M597 Sept 1999

Comparison of M710 and M597 Costs



■ M597 % of Total
□ M710 % of Total

	Material	Labor	VOH	FOH
■ M597 % of Total	48.71794872	15.38461538	10.25641026	25.64102564
□ M710 % of Total	47.82608696	9.782608696	15.2173913	27.17391304

83

ME0797

M/710 Estimate									
PART DESCRIPTION	Proposed Process (changes in red)	Part #	Print #	Rev #	Material \$	New Material \$	Rev #	New Part yes only	Status comments
Carton Assembly	Purchase	1444	1444	2					
Corrugated Box	Purchase								
Bed	Purchase								
Document Envelope Assembly	Purchase kevill	????	????						
Document Envelope	Purchase	1649	1649						
Instruction Book	Purchase	????	????						
Product Owners Card	Purchase	1426	1426						
Remington Authorized Gunsmith	Purchase	3413	3413						
Safety Booklet	Purchase	3499	3499						
Remington Museum Flyer	Purchase	3475	3475						
Oval Label	Purchase	3491	3491						
Box and Envelope Label (710)	Purchase	993002	993002						
Barrel Assembly Complete	Assemble	305410	C-305410	No Rev.					
Barrel Assembly	Assemble & Machine	305400	C-305400	No Rev.					
Barrel	Machine	305315	B-305315	5					
Receiver	Purchase	300340	E-300340	6	\$1 760			\$	
Receiver Insert Assembly Complete	Assemble	300401	D-300401	No Rev.					
Receiver Insert Assembly	Ultrasonic Weld	300400	C-300400	No Rev.					
Receiver Insert	Purchase	300327	E-300327-1-2	(1E-300327-23)					
Threaded Insert	Purchase	300347	A-300347	A	\$0.036				
Side Plate	Purchase & Color	300333	C-300333	No Rev.	\$0.090				
Side Plate Pin (2)	Purchase & Color	300328	A-300328	No Rev.	\$0.360				
Sear Safety Cam	AU M/700	15666	C-15666	24	\$0.760				
Pivot Pin (3)	Purchase & Heat Treat	300351	B-300351	No Rev.	\$0.180				
Sear Spring	AU M/700	17047	A-17047	26	\$0.029				
Trigger	AU M/700	15280	C-15280	31	\$0.379				
Trigger Connector	AU M/700	19461	C-19461	21	\$1.506				
Trigger Screw Front	AU M/700	17053	B-17053	32	\$0.040				
Trigger Engagement Screw	AU M/700	91128	B-91128	7	\$0.027				
Trigger Spring	AU M/700	15400	A-15400	11	\$0.029				
Trigger Stop Screw	AU M/700	15481	B-17053	32	\$0.042				
Safety Arm	Assemble & Heat Treat	300408	D-300408	1	\$0.230				
Safety Detent Spring		300407	C-300407	1	\$0.058				
Lock tumbler	Purchase	??	???	??					
Lock Detent	AU M/7	???	???	???					
Safety Pivot Pin	Purchase & Heat Treat	300352	B-300352	1	\$0.140				
Snap Washer		17044	B-17044	26	\$0.025				
Bolt Stop	PM/Heat Treat/Color	300345	C-300345	2	\$0.219				
Receiver Plug Screws (4)	AU M/700	17034	B-17034	34	\$0.135				
Rocott Bracket	Purchase & Color	300361	B-300361	No Rev.	\$0.123				

83

ME0798

M/710 Estimate										
	Proposed Process	Part #	Print #	Rev #	Material \$	New Material \$	Rev #	New Part yes only	Status	comments
PART DESCRIPTION (changes in red)										
Bolt Assembly Complete										
Bolt Body Assembly	Braze & Finish	300403	B-300403	No Rev.						
Bolt Body	Purchase	300330	D-300330	1	\$2 050			\$ 0 17		
Bolt Handle	Bend to Form	300370	C-300370	No Rev.	\$1 630					
Bolt Handle Blank	Purchase	300360	C-300360	No Rev.						
Bolt Handle Pin	Purchase	300329	A-300329	1	\$0 100					
Bolt Head Assembly										
Bolt Head	Machined	300338	B-300338	No Rev.	\$1 750					
Extractor	A/U M/700	93712	C-93712	2	\$0 772					
Ejector	Purchase & Color	300342	B-300342	1	\$0 110					
Ejector Spring	Purchase	300367	A-300367	No Rev.	\$0 015					
Ejector Pin	A/U M/700	94555	A-94555	1	\$0 014					
Bolt Assembly Pin	Purchase & Color	300330	B-300330	No Rev.	\$0 150					
Firing Pin Assembly										
Bolt Plug	Purchase	300368	C-300368	1	\$0 215					
Bolt Plug Insert	Purchase	300346	D-300346	No Rev.	\$0 808					
Firing Pin	Purchase & Color	300334	C-300334	No Rev.	\$1 190					
Firing Pin Tip	Purchase & Heat Treat	300335	B-300335	No Rev.	\$0 230					
Firing Pin Head	MIM	300336	C-300336	No Rev.	\$1 247					
Firing Pin Spring	Purchase	300399	A-300399	No Rev.	\$0 101					
Front Sight Assembly										
Front Sight	A/U M/700	94084	C-15373	26	\$0 786					
Front Sight Ramp	A/U M/700	94657	B-28510	33	\$1 349					
Front Sight Ramp Screws (2)	A/U M/700	28505	B-28505	21	\$0 075					
Rear Sight Assembly										
Elevation Screw	A/U M/700	90906	A-90906	19	\$0 024					
Rear Sight Aperture	A/U M/700	97681	C-93905	9	\$0 140					
Rear Sight Aperture Blank		93906	C-93906	6						
Rear Sight Base	A/U M/700	103531	C-103530	3	\$0 968					
Rear Sight Slide	A/U M/700	94335	C-93904	7	\$1 200					
Windage Screw	A/U M/700	300026	B-300026	5	\$0 199					
Rear Sight Base Screw (2)	A/U M/700	28505	B-28505	21						

83

ME0799

M/710 Estimate									
PART DESCRIPTION	Proposed Process (changes in red)	Part #	Print #	Rev #	Material \$	New Material \$	Rev #	New Part yes only	Status comments
Stock Assembly Complete	Purchase	???	???	??					
Stock Assembly	Purchase	???	???	??					
Stock	Purchase	???	???		\$5.380				
Front Screw Bushing	A/U M/700	15161	B-15161	??					
Front Screw Bushing Blank		91915	??	???					
Middle Screw Bushing	Purchase	???	???	??					
Rear Screw Bushing	Purchase	???	???	??					
Grip Cap	A/U M/700	97971	C-97971	No Rev	\$0.180				
Recoil Pad	A/U M/700	97973	D-97973	26	\$1.610				
Backer Plate		97972	C-97972	No Rev	\$ 0.390				
Recoil Pad Screw (2)	A/U M/700	98008	A-98008	7	\$0.022				
Magazine Latch	Purchase	300362	C-300362	2	\$0.191				
Magazine Latch Spring	Purchase	300398	B-300398	No Rev	\$0.026				
Magazine Latch Pin	Purchase & Color	300371	B-300371	No Rev	\$0.070				
Sling Swivel Stud (2)	Purchase	300096	B-300096	4					
Takedown Screw (2)	Purchase	???	???	???					
Rear Takedown Screw	Purchase	???	???	???					
Magazine Assembly	Assemble	305395	B-305395	No Rev					
Magazine Box	Purchase & Color	300363	B-300363	5	\$2.790				
Magazine Follower	Purchase	300364	B-300364	1	\$0.993				
Magazine Bottom	Purchase	300365	B-300365	No Rev	\$0.405				
Magazine Spring	A/U M/700	300405	C-300405	No Rev					
Value Added Cost of:									
Proof/Gallery/Inspect/Pack					\$0.006	\$ -	\$ -	\$ -	\$ -
			Total Cost		\$35.488	\$ -	\$ -	\$ 0.17	\$ -

83

ME0800

Quoted Parts										
PART DESCRIPTION	Part #	Print #	Rev#	Price/part	Order Qty	Eng. Charge	Vendor Capital	Vendor Gages	PPI Gages	Comments
				\$	M	\$	\$	\$	\$	
Carton Assembly	1444	1444	?						\$ -	
									\$ -	
									\$ -	
Document Envelope Assembly	????	????	?						\$ -	
Document Envelope	1649	1649	?						\$ -	
Instruction Book	????	????	?						\$ -	
Product Owners Card	1426	1426	?						\$ -	
Remington Authorized Gunsmith	3413	3413	?						\$ -	
Safety Booklet	3499	3499	?						\$ -	
Remington Museum Flyer	3475	3475	?						\$ -	
Oval Label	3491	3491	?						\$ -	
									\$ -	
Box and Envelope Label (710)	993002	993002	?						\$ -	
									\$ -	
Barrel Assembly Complete	305410	C-305410	No Rev.						\$ -	
Barrel Assembly	305400	C-305400	No Rev.						\$ -	
Barrel	305315	E-305315	5						\$ -	
Receiver	300340	E-300340	6	\$ 1,760	0				\$ -	Federal Steel--Quote.
Receiver Insert Assembly Complete	300401	D-300401	No Rev.						\$ -	
Receiver Insert Assembly	300400	C-300400	No Rev.						\$ -	
Receiver Insert	300327	E-300327-1-2	(1E)-5 (2E)-23						\$ 5,650.00	
Threaded Insert	300347	A-300347	A	\$ 0.036	20				\$ 200.00	Precision Fasteners
Side Plate	300333	C-300333	No Rev.	\$ 0.090	20				\$ 1,500.00	Historical Data
Side Plate Pin (2)	300328	A-300328	No Rev.	\$ 0.160	60	\$ 225.00			\$ -	Iseli--Quote:
Sear Safety Cam	15666	C-15666	24	\$ 0.760	20		\$ 11,300.00		\$ 3,000.00	Sterling Sintered Tech. Inc.--Quo
Pivot Pin (3)	300351	B-300351	No Rev.	\$ 0.180	60	\$ 450.00			\$ -	Automatic Swiss Corporation--Qu
Sear Spring	17047	A-17047	26	\$ 0.023	20				\$ -	Ilion Quote
Trigger	15280	C-15280	31	\$ 0.377	20		\$ 15,225.00		\$ 3,000.00	Sterling Sintered Tech. Inc.--Quot
Trigger Connector	19461	C-19461	21	\$ 1.51					\$ 3,000.00	
Trigger Screw Front	17053	B-17053	32	\$ 0.040	0 10				\$ 300.00	Fastenal--Quote: 8/19/99
Trigger Engagement Screw	91128	B-91128	7	\$ 0.027	0 10				\$ 300.00	Ilion Quote SAP
Trigger Spring	15400	A-15400	11	\$ 0.029	20				\$ -	Ilion Quote SAP
Trigger Stop Screw	15481	B-17053	32	\$ 0.042	20				\$ 300.00	Fastenal--Quote.
Safety Arm	300408	D-300408	1	\$ 0.230	20		23,552.00		\$ 2,400.00	New Hampshire Stamping--Quote
Safety Detent Spring	300407	C-300407	1	\$ 0.058	20				\$ -	Midstate Spring Inc.--Quote: 9/2
Lock Tumbler	???	???	???						\$ -	
Lock Detent	???	???	???						\$ -	
Safety Pivot Pin	300352	B-300352	1	\$ 0.140	20	\$ 225.00			\$ -	Iseli Company--Quote: 8/25/99
Safety Snap Washer	17044	B-17044	26	\$ 0.025					\$ 120.00	Ilion Quote SAP
Bolt Stop	300345	C-300345	2	\$ 0.219	20		6,826.00		\$ 1,500.00	Sterling Sintered Tech. Inc.--Q
	0	0	0						0	
Receiver Plug Screws (4)	17034	B-17034	34	\$ 0.135					\$ -	Ilion Quote SAP
Recoil Bracket	300361	B-300361	No Rev.	\$ 0.123	20	\$ 550.00			\$ -	Square Stamping Quote Aug. 11,

B3

ME0801

Confidential - SHARPER - 5.22.06P0010751ye Order
Williams v. Remington

Quoted Parts										
PART DESCRIPTION	Part #	Print #	Rev#	Price/part \$	Order Qty M	Eng. Charge \$	Vendor Capital \$	Vendor Gages \$	PPI Gages \$	Comments
Bolt Assembly Complete	????	????	??						\$ -	
Bolt Body Assembly	300403	D-300403	No Rev.						\$ -	
Bolt Body	300339	D-300339	1	\$ 2.050	20				\$ -	Ken-Mar Tools--Quote 8/26/99
	0	0	0						\$ -	
	0	0	0						\$ -	
Bolt Handle	300370	C-300370	No Rev.	\$ 1.630	20		\$12,575.00		\$ -	Fansteel--Quote. 8/12/99
Bolt Handle Blank	300360	C-300360	No Rev.						\$ 2,500.00	
Bolt Handle Pin	300329	A-300329	1	\$ 0.100	20	\$ 450.00			\$ -	Automatic Swiss Corporation--Quo
									\$ -	
Bolt Head Assembly	305390	B-305390	No Rev.						\$ -	
Bolt Head	300338	E-300338	14	\$ 1.750					\$ 120.00	Parker & Harper Mfg Company
Extractor	93712	C-93712	2	\$ 0.72					\$ 3,300.00	Ilion Quote SAP
Ejector	300342	B-300342	1	\$ 0.110	20	\$ 400.00			\$ 3,000.00	Iselis--Quote 8/25/99
Ejector Spring	300367	A-300367	No Rev.	\$ 0.015	20				\$ -	Midstate Spring, Inc.--Quote: 8/2
Ejector Pin	94555	A-94555	1	\$ 0.074	20				\$ -	Ilion Quote SAP
Bolt Assembly Pin	300330	B-300330	No Rev.	\$ 0.150	20	\$ 450.00			\$ -	Automatic Swiss Corporation--Q
Firing Pin Assembly	300404	B-300404	No Rev.						\$ -	
Bolt Plug	300368	C-300368	1	\$ 0.215	20		\$ 36,000.00		\$ 800.00	Kellems & Coe--Quote: 8/17/99
Bolt Plug Insert	300346	B-300346	No Rev.	\$ 0.808	60		\$0.00		\$ 3,000.00	Swiss Precision Machining, Inc.-
Firing Pin	300334	C-300334	No Rev.	\$ 1.190	20	\$ 400.00			\$ 200.00	Iseli--Quote 8/16/99
Firing Pin Tip	300335	B-300335	No Rev.	\$ 0.230	20	\$ 225.00			\$ 3,300.00	Iseli--Quote. 8/16/99
Firing Pin Head	300336	C-300336	No Rev.	\$ 1.247	20		\$ 17,500.00		\$ 1,500.00	Megamet Industries--Quote 9/1
									\$ -	
Firing Pin Spring	300399	A-300399	No Rev.	\$ 0.101	20				\$ -	Midstate Spring--Quote 8/20/99
Front Sight Assembly	0	0	0						\$ -	
Front Sight	94084	C-15373	26	\$ 0.786					\$ -	Ilion Quote SAP
Front Sight Ramp	94657	B-28510	33	\$ 1.188					\$ 400.00	Ilion Quote SAP
Front Sight Ramp Screws (2)	28505	B-28505	21	\$ 0.075					\$ -	Mayfield Quote SAP
Rear Sight Assembly	103145	B-103145	11	\$ 3.719					\$ -	Ilion Quote SAP
Elevation Screw	90906	A-90906	19	\$ 0.024	20				\$ -	Ilion Quote SAP
Rear Sight Aperture	97681	C-93905	9	\$ 0.140	20				\$ -	Ilion Quote
Rear Sight Aperture Blank	93906	C-93906	6						\$ -	
Rear Sight Base	103531	C-103530	3	\$ 0.968	80		\$17,500.00		\$ -	Ilion. Quote
Rear Sight Slide	94335	C-93904	7	\$ 1.200	80		\$17,500.00		\$ -	Megamet Industries--Quote: 9/1
Windage Screw	300026	B-300026	5	\$ 0.191	25	\$ 300.00			\$ -	Swiss Precision Maching Inc.--Q
Rear Sight Base Screw (2)	28505	B-28505	21						\$ -	

43

43

In House Processing									
PART DESCRIPTION	Part #	Print #	Rev #	Material \$	Labor (hrs)	Variable Tools \$	Pre-Op Startup \$	Capital \$	Comments
Carton Assembly	1444	????	0						
Document Envelope Assembly	????	????	0						
Document Envelope	1649	1426	0						
Instruction Book	????	3413	0						
Product Owners Card	1426	3499	0						
Remington Authorized Gunsmith	3413	3475	0						
Safety Booklet	3499	3491	0						
Remington Museum Flyer	3475	0	0						
Oval Label	3491	993002	0						
Box and Envelope Label (710)	993002	C-305410	No Rev.						
		C-305400	No Rev.						
Barrel Assembly Complete	C-305410	E-305315	5						
Barrel Assembly	C-305400	E-300340	6						
Barrel	E-305315	D-300401	No Rev.	\$ 4.800		\$ 2,585.59	\$ 59,098.14	\$ 286,430.00	
Receiver	E-300340	C-300400	No Rev.				\$ -	\$ 563,556.90	
Receiver Insert Assembly Complete	D-300401	E-300327-1-2	(1E)-5 (2E)-23						
Receiver Insert Assembly	C-300400	A-300347	A						
Receiver Insert	E-300327-1-2	C-300333	No Rev.						
Threaded Insert	A-300347	A-300328	No Rev.						
Side Plate	C-300333	C-15666	24						
Side Plate Pin (2)	A-300328	B-300351	No Rev.						
Sear Safety Cam	C-15666	A-17047	26						
Pivot Pin (3)	B-300351	C-15280	31						
Sear Spring	A-17047	C-19461	21						
Trigger	C-15280	B-17053	32						
Trigger Connector	C-19461	B-91128	7						
Trigger Screw Front	B-17053	A-15400	11						
Trigger Engagement Screw	B-91128	B-17053	32						
Trigger Spring	A-15400	D-300408	1						
Trigger Stop Screw	B-17053	C-300407	1						
Safety Arm	D-300408	???	??						
Safety Detent Spring	C-300407	???	???						
Lock tumbler	???	B-300352	1						
Lock Detent	????	B-17044	26						
Safety Pivot Pin	B-300352	C-300345	2						
Snap Washer	B-17044	0	0						
Bolt Stop	C-300345	B-17034	34						
	0	B-300361	No Rev.						
Receiver Plug Screws (4)	B-17034	???	??						
Recoil Bracket	B-300361	D-300403	No Rev.						

83

MF0804

In House Processing									
PART DESCRIPTION	Part #	Print #	Rev#	Material \$	Labor (hrs)	Variable Tools \$	Pre-Op Startup \$	Capital \$	Comments
Bolt Assembly Complete	????	D-300339	1						
Bolt Body Assembly	D-300403	0	0						
Bolt Body	D-300339	0	0			\$ 79.95	\$ 5,403.50	\$ 4,500.00	
	0	C-300370	No Rev.						
	0	C-300360	No Rev.						
Bolt Handle	C-300370	A-300329	1						
Bolt Handle Blank	C-300360	0	0						
Bolt Handle Pin	A-300329	B-305390	No Rev.						
Bolt Head Assembly	B-305390	C-93712	2						
Bolt Head	E-300338	B-300342	1			\$ 0.50	\$ 5,761.38	\$ 316,500.00	
Extractor	C-93712	A-300367	No Rev.						
Ejector	B-300342	A-94555	1						
Ejector Spring	A-300367	B-300330	No Rev.						
Ejector Pin	A-94555	B-300404	No Rev.						
Bolt Assembly Pin	B-300330	C-300368	1						
Firing Pin Assembly	B-300404	B-300346	No Rev.						
Bolt Plug	C-300368	C-300334	No Rev.						
Bolt Plug Insert	B-300346	B-300335	No Rev.						
Firing Pin	C-300334	C-300336	No Rev.						
Firing Pin Tip	300335	No Rev.	0						
Firing Pin Head	C-300336	A-300399	No Rev.						
		0	0						
Firing Pin Spring	A-300399	C-15373	26						
Front Sight Assembly	0	B-28510	33						
Front Sight	C-15373	B-28505	21						
Front Sight Ramp	B-28510	B-103145	11						
Front Sight Ramp Screws (2)	B-28505	A-90906	19						
Rear Sight Assembly	B-103145	C-93905	9						
Elevation Screw	A-90906	C-93906	6						
Rear Sight Aperture	C-93905	C-103530	3						
Rear Sight Aperture Blank	C-93906	C-93904	7						
Rear Sight Base	C-103530	B-300026	5						
Rear Sight Slide	C-93904	B-28505	21						
Windage Screw	B-300026	???	??						
Rear Sight Base Screw (2)	B-28505	???	??						

#305410 - Barrel Assy Complete

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part #	Print #	REV	Material \$	Std. Run Hours	Variable Overhead \$	Preop	Capital	PPI Gages \$	Material Handling	Comments
10	Assemble Sights	Fixture Modifications Press for front sight to front sight base Tooling bench vise wood stand air wrench electric screw driver	305410	000001	05		0.059						
20	Press Receiver Insert Assy Complete into barrel Assy Complete	Fixture with lever arm for pressing					0.02						
Totals						\$ -	0.079	\$ -	\$ -	\$ -	\$ -	\$ -	

Barrel Assembly Complete is defined as BBL REC. and REC INERT ASSY COMPLETE

Time in this operation was defined as assembling sights and receiver scope screws and install receiver insert

Action Estimate the time to assemble the slide assembly to the rear sight base

710 Complete 1

83

MF0807

#305315 - Barrel

Op #	Op #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part #	Print #	REV	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital	PPI Gages \$	Material Handling	Comments
		Material (Blank 94523)		305315	E-305315	1								
10	10	Out to Length					\$ 4,800	0.000000	\$0.12	\$4,140.72	\$0.00			
20	20	Gundrill Bore Dies & Rams						0.054670						
30	30	Rear Bore					n/a	0.025945	\$0.39	\$15,118.95	\$8,080.00			
40	40	Rifle Bore						0.000000						
50	50	Wash & Stress Relieve						0.000413	\$0.00	0	\$7,000.00			Turn O.D. & Inspect
60	60	Turn O.D. & Inspect for Runout Gaging					\$	0.027713	0.072	\$4,993.80	\$5,000.00			
70	70	Cut-off & Crown Muzzle End					\$	0.000000						
		Clamping Chuck					\$	0.011670	\$0.06	\$1,440.58	\$15,000.00			M710 Cutoff and Crown Operation
80	80	Face, Chamber, Machine Hub End, Drill & Tap Takedown Screw Holes, Will Recoil Lug Slot & 100% Inspect						0.080145						
		Gaging Chamber Finish							\$2,585.00	\$33,404.00	\$30,476.00			
		Okuma LB-300 Chamber operation							\$0.00	\$0.00	\$222,880.00			M710 Chamber Operator
90	90	Wash & Magnetix Barrel						0.075900						
100	100	Drill & Tap Sight Screw Holes Gaging						0.000000						
110	110	Induction Heat Treat Hub						0.000000						
120	120	Press Receiver onto Barrel Gaging						0.23370						
130	130	Inspect for Runout & Straighten if Necessary		305015	E-305315	1		0.000000						
140	140	Roll Mark						0.003000						
150	150	Angularly Straighten Muzzle & Inspect Bore						0.000000						
160	160	Centerless Polish						0.004167						
170	170	Glass Bead						0.005500						
180	180	Black Oxide						0.004167						
		TOTALS					\$ 4,800	0.246983	\$2,585.00	\$64,098.14	\$286,430.00	\$0.00	0.00	

Go to the detail pages within this sheet which are all the separate fees used to build this page. The can be found in network neighborhood: mfnlas3engineering/710/barrel

710 Complete 1

83

MF0808

#300340 - Receiver

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity Price/M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI \$	Material Handling	Comments
		Blank Material-1018 DOM	300340	E-300340		1,760	20		0.005500						Federal Steel--Quote
10	Machine Complete											\$ 4,725.00			
20	Vibratory Deburr											\$ 45,000.00			
												\$ 513,831.00			
Total:						\$ 1,760			0	\$		\$ 563,556.00	\$		

CMM Fixture Based on 597 CMM Fixture for the bolt \$4500 and a #6-48 thread gage @225.00
 This estimate assumed an LT 15MY from OKUMA and an automatic operation in house
 An approx 5 min machine cycle time
 max output /year was about 30,000 when coupled with the bolt body
 The receiver consumed about 80% of the machine cycle

Free markets quoted a 30,000 ea 3 year contract at \$219-\$245 combined package of receiver and bolt body
 In house completely burdened was approx \$5.33 for the receiver and \$2.63 for the bolt body

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity Price/M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI \$	Material Handling	Comments
		Free Markets	300340	E-300340	19	\$ 1,760	20		0.005500						Federal Steel--Quote
10	Machine Complete	Inspection Fixture										\$ 1,500.00			
		Inspection Program										\$ 5,000.00			
		Plug gage Chore										\$ 300.00			
		Thread gages										\$ 226.00			
20	Vibratory Deburr yes/no														
Total:						\$ 1,760			0.0055	\$		\$ 10,026.00	\$		

Action Get programs and fixtures for the CMM inspection
 We could have parts as early as 2/15/00
 Do we vibratory deburr??

#300401- Rec Insert Assy Comp

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part #	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
1			300401	300401	A								
10	Demagnetize Metal Components					\$ -	0 000404	\$ -	\$ -				
20	Assemble - Stage 1	Fixturing				\$ -	0 011383	\$ -	\$ -	\$ 1,500.00			
30	Assemble - Stage 2	Fixturing				\$ -	0 025273	\$ -	\$ -	\$ 1,500.00			
40	Adjust on Comparator	Fixturing				\$ -	0 016929	\$ -	\$ -	\$ 5,000.00			
60	Function Check Complete					\$ -	0 006917	\$ -	\$ -				
70	Stamp Identification					\$ -	0 001908	\$ -	\$ -				
Totals						\$ -	0.06	\$ -	\$ -	\$ 8,000.00	\$ -	\$ -	

Set up demagnetizing process
 Staking machine
 Comparator
 Comparator fixtures
 Comparator Screen
 Assembly fixture - and how many

710 Complete 1

83

MF0810

#300327 - Receiver Insert

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Gaging	Programming Fixture Design									\$ 5,650.00		Estimated Quote
	Totals										\$ 5,650.00		

Hanson tool modifications
CMM inspection results-parts shipped 1/28/00 for complete inspection
Delivery of CMM inspection program 2/2/00
Sample of 1000 parts from hanson due after receipt of inspection results on 2/2/00 and completion of any tooling changes

Delivery of CMM??
Parts programmed to measurmax and PPI CMM

fixture begin at PHI and fixture build complete in house

#300347 - Threaded Insert

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity Piece/M	Engineering Charge	Std Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Blank Material - Stamping Gaging (Vendor and Remington)		#300347	A-300347	A	\$ 0.036	20			0.000001			\$ 200.00		Precision Fasteners Estimated Quote
Totals						\$ 0.036	20		0.000001				\$ 200.00		

500 received and 14,5000 returned to vendor 1/26/00
Inspection Completed 1/28/00

710 Complete 1

83

MF0812

#300333 - Side Plate

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity Piece/M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Blank Material - Stamping Gaging (vendor and Remington)		F300333	C-300333	5	0.090	20						\$ 1,500.00		Historical Data Estimated Quote
10	Black Oxide Color								0.000001						
Totals						\$ 0.090	20		0.000001				\$ 1,500.00		

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages		

ME0813

#300328 - Side Plate Pin

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Rev#	Material \$	Quantity Price/M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PFI Gages \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (Vendor and Remington)				\$ 0.080	60.00	\$ 225.00					\$ -		Isch--Quote
10	Blank Oxide Color				\$ -			0.000001	\$ -	\$ -	\$ -	\$ -	\$ -	
Totals					\$ 0.080	60.00	\$ 225.00	0.000001	\$ -	\$ -	\$ -	\$ -	\$ -	

Note: Quoted in C12L14 material
Quoted with .010" max. cornerbreaks unless noted.

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages		

710 Complete 1

BARBER - 5.22.06r0010764

83

MF0814

Confidential - ~~Shane~~ Barber - 5.22.06r0010764 Order
Williams v. Remington

#16886 - Sear Safety Cam

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Price	Rev	Material	Quantity	Engineering	Std. Run	Variable	Preop	Capital	PPI Gages	Material	Comments
	Black Material - PM Parts					\$ 0.40	20								String Sintered Tech. Inc --Quote 8/24/99
	Gaging (vendor and Remington)												\$ 3,000.00		Thon Supplied
	Tooling											\$ 11,300.00			
Totals						\$ 0.268	20		0.000001	\$ -	\$ -	\$ -	\$ 11,300	\$ 3,000	\$ -

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages		

MF0815

#300351 - Prod Pin

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity Piece/M	Engineering Charge	Std Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vendor and Remington)					\$ 0.060	60.00	\$ 450.00					\$ -		Automatic Swiss Corporation--Quote 8/20/99 Estimated Quote
Totals						\$ 0.060	60.00	\$ 450.00 0		\$ -	\$ -	\$ -	\$ -	\$ -	

Note: Quoted in C12L14 material

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages		

MF0816

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Mat.	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Material- Springs					\$ 0.023	20								Billion Quote
	Totals					\$ 0.460	20		0.000000			\$ -			

#15288 - Trigger

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Req #	Material \$	Quantity	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	FPI Gages \$	Material Handling	Comments
	Material-PM Parts Tooling Gages					\$ 0.377	20					\$ 15,225.00	\$ 3,000.00		Sterling Sintered Tech Inc --Quoted 5/03/99 Based on no Serrations on Trigger Estimated Quote
10	Black Oxide Color									0.000001					
Totals						\$ 0.377	20			0.000001		\$ 15,225.00	\$ 3,000.00		

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages		

Sterling part price higher to \$0.50 after requote. NOTE don not useSterling in the Futrue.

#19461 - Trigger Connector

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print#	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Gages					1.51					\$ 3,000.00		Ilion Supplied Estimated Quote
Totals						\$ 1.51				\$ 3,000.00			

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages		

#17053 - Trigger Screw Front

PROCESS OP # DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
Material--Fasteners Gages					\$ 0.040	0.1						\$ 300.00		Fastenal--Quote 8/19/99 Estimated Quote
Totals					\$ 0.040	0.1		0.000000				\$ 300.00		

710 Complete 1

MF0820

#91128 - Trigger Engage Screw

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Material-Fasteners Gages					\$ 0.027	010						\$ 300.00		Ilion Quots SAP Estimated Quote
Totals						\$ 0.027	010		0.000000				\$ 300.00		

710 Complete 1

MF0821

#15400 - Trigger Spring

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part #	Print #	Rev #	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PFI Gages \$	Material Handling	Comments
	Gages					\$ 0.019	20							0	Ilkon Quote SAP
Totals						\$ 0.019	20		0.000000				\$ -		

710 Complete 1

8.3

ME0822

#12481 - Trigger Stop Screw

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev.	Material \$	Quantity	Engineering Charge	Std Run Hours	Variable Overhead \$	Preup \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Material- Screw Gages					\$ 0.042	20						\$ 300.00		Pastenal-Quote Estimated Quote
Totals						\$ 0.042	20		0.000000				\$ 300.00		

710 Complete 1

83

MF0823

#300408 - Safety Arm

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity	Engineering Charge	Std Run Hours	Variable Overhead \$	Preop \$	Capital \$	PFI Gages \$	Material Handling	Comments
	Blank Material- Gaging (Vendor and Reminton)					\$ 0.230	20						\$ 2,400.00		New Hampshire Stamping--Quote 9/28/99
10	Tooling Vendor Heat Treat										\$ 25,552.00				Estimated Quote
20	Black Oxide Color								0.000001						
Totals						\$ 0.230	20		0.000001			\$ 25,552.00	\$ 2,400.00		

Note: Production delivery will take two weeks. 1 week for delivery of first quality acceptance sample.
1 week for delivery of sample approval. 18 weeks total.

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages		

ACTUAL

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity	Engineering Charge	Std Run Hours	Variable Overhead \$	Preop \$	Capital \$	PFI Gages \$	Material Handling	Comments
	Blank Material- Gaging (Vendor and Reminton)					\$ 0.230	20						\$ 2,400.00		New Hampshire Stamping--Quote 9/28/99
10	Tooling Vendor Heat Treat										\$ 25,552.00				Estimated Quote
20	Black Oxide Color								0.000001						
Totals						\$ 0.230	20		0.000001			\$ 25,552.00	\$ 2,400.00		

#30407 - Safety Detent Spring

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print#	Part Rev	Material	Quantity	Engineering Charge	Std Run Hours	Variable Overhead \$	Prep \$	Capital \$	Material Handling	Comments
10	Black Oxide						20		0.000001					Madhava Spring Inc -Quote 9/23/99
Totals														

0.000001

20

\$0.000001

Totals

710 Complete 1

83

MF0825

#300418 - Lock Tumbler

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
10	Wash		B-3004F-B									
20	Black Oxide											
30	Paint											
Totals												

	order date	due date
Tooling ordered		
dot paint not band		

#300420 - Lock Tumbler blank

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print#	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
10	Wash		F-300420	D-300420	C							
20	Black Oxide											
30	Paint											
Totals												

Part not available during estimate

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
ring gages		

#201224 - Look Detent

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part #	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
Totals												

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages		

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material	Quantity Piece/M	Engineering Charge	Std Run Hours	Variable Overhead \$	Preop \$	Capital \$	PFI Gages \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vondor and Remington)					\$ 1.40	20	\$ 225.00					\$ -		Isoli Company--Quote 8/25/99
	Totals					\$ 1.40	20	\$ 225.00	0.000000		\$ -	\$ -		\$ -	

Note. Quoted in C12L14 material
Quoted with .10" max. cornerbreaks unless noted

Tooling ordered
ccmp fixture design
ccmp fix build
ccmp screen
plug gages

order date due date

#17044 - Safety Snap Washer

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part #	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	GAGES					\$ 0.02					\$ 120.00		Ilion Quote SAF Estimated Quote
Totals						\$ 0.02					\$ 120.00		

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages		

#300345 - Bell Stop

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Material \$	Quantity M	Engineering Charges	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	FPI Gages \$	Material Handling	Comments
	Blank Material - PMPD				\$ 0.219	240								Sterling Sentered Tech. Inc. --Quote 8/12/99
	Tools										\$ 6,820.00			Estimated Quote
	Gages											\$ 1,500.00		
10	Vendor Heat Treat													
20	Black Oxide Color							0.003001						
Totals					\$ 0.219	240		0.003001	\$ -	\$ -	\$ 6,820.00	\$ 1,500.00	\$ -	

	order date	due date	
Tooling ordered			
comp fixture design			
comp fix build			
comp screen			
plug gages			

MF0831

#300361 - Reed Bracket

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity Piece/M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Blank Material - Stamping					\$ 0.123	20	\$ 550.00						Square Stamping Quote Aug 11, 99
10	Black Oxide Color								0.000001	\$ -	\$ -	\$ -	\$ -	
	Totals					\$ 0.123	20	\$ 550.00	0.000001	\$ -	\$ -	\$ -	\$ -	

Note: Above quote is to be made from C1008 steel, .187" + or - .003 thickness

Tooling crdard

710 Complete 1

83

MF0832

#305380 - Bolt Body Assembly

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
10	press handle on bolt body	mead press fixture gage				\$ -	0.0051000	\$ -	\$ -	\$ 15,000.00 \$ 1,100.00 \$ 800.00	\$ -	
15	wash both parts	baskets										
20	braze handle on body	braze machine fixture gage				\$ -	0.0065000	\$ -	\$ -	\$ 15,000.00 \$ 1,100.00	\$ -	
30	deplate	material handling tanks				\$ -	0.0000100	\$ -	\$ -		\$ -	
40	magnaflux (obsolete) per Matt G					\$ -	0.0066290	\$ -	\$ -		\$ -	
50	inspect visual					\$ -	0.0000100	\$ -	\$ -		\$ -	
70	glass bead blast	fixture				\$ -	0.0039000	\$ -	\$ -	\$ 1,500.00	\$ -	
80	color	material handling				\$ -	0.0040000	\$ -	\$ -	\$ 2,000.00	\$ -	
Totals						\$ -	0.027549	\$ -	\$ -	\$ 3,500.00	\$ -	

ACTUAL COSTS

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
10	press handle on bolt body	mead press fixture gage				\$ -	0.0051000	\$ -	\$ -	\$ 15,000.00 \$ 1,100.00 \$ 800.00	\$ -	
15	wash both parts	baskets										
20	braze handle on body	braze machine fixture gage				\$ -	0.0065000	\$ -	\$ -	\$ 15,000.00 \$ 1,100.00	\$ -	
30	deplate	material handling tanks				\$ -	0.0000100	\$ -	\$ -		\$ -	
40	magnaflux (obsolete) per Matt G					\$ -	0.0066290	\$ -	\$ -		\$ -	
50	inspect visual					\$ -	0.0000100	\$ -	\$ -		\$ -	
70	glass bead blast	fixture				\$ -	0.0039000	\$ -	\$ -	\$ 1,500.00	\$ -	
80	color	material handling				\$ -	0.0040000	\$ -	\$ -	\$ 2,000.00	\$ -	
Totals						\$ -	0.027549	\$ -	\$ -	\$ 3,500.00	\$ -	

MF0833

#300338 - Ball Body

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part #	Print #	REV	Material \$	Quantity Piece/M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Variable Tool	Preop \$	Capital	Material Handling	Comments
	Blank Material--Machining Gaging (Vendor and Remington)					2 050	20			\$ 0 17					Ken-Mar Tools--Quote 8/26/99
10	Machine Complete from Bar Stock								0.032548			\$5,403.50			
15	Inspect	CMM Fixture Gage CMM Program									\$79.95		\$4,500.00		
	HOT														
TOTALS						\$ 2 050	20		0.032648	\$0 17	\$79 95	\$5,403 50	\$4,500 00	0 00	

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part #	Print #	REV	Material \$	Quantity Piece/M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Variable Tool	Preop \$	Capital	Material Handling	Comments
	Blank Material--Gaging (Vendor and Remington)					\$ 2 530	30								Free Markets
10	Receive complete														
15	Inspect	CMM Fixture Gage CMM Program										\$5,403.50	\$4,500.00		
	HOT														
TOTALS						\$ 2 530	30		0.039960	\$0 00	\$0 00	\$5,403 50	\$4,500 00	0 00	

All Parts FREE Markets

710 Complete 1

83

MF0834

#300370 - Bolt Handle

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity M	Engineering Charges	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
10	Machine Radius in Drill	Tooling Fixture Okum Crown: V				\$ 1,630	20		0.004167	\$ -	\$ -	\$ 12,575.00	\$ -	Fansteel--Quote 8/12/99
Totals						\$ 1,630	20		0.004167	\$0.00	\$0.00	\$12,575.00	\$0.00	

Note: Bolt handle and blank design is not complete. The quote represents drawing number C-300370

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages		

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity M	Engineering Charges	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
10	Machine Radius in Drill	Tooling Fixture Okum Crown V CMM Fixture CMM Program				\$ 1,630	20		0.004167	\$ -	\$ -	\$ 10,000.00	\$ -	Fansteel--Quote 8/12/99
Totals						\$ 1,630	20		0.004167	\$0.00	\$0.00	\$10,000.00	\$0.00	

RADIUS will BE .347 ±.001

FYI

**NORTH AMERICAN
PRECISION CASTING**P O BOX 1407 * 386 LANGSTON CIRCLE * COLUMBUS, MS.
39701

PHONE: 662-245-1155 FAX: 662-245-4897

Fax**TO METTY MORGAN****From: WILLIAM H. SOMERVILLE**

83

Fax: 270 856-4204 **Pages:** 1**Phone:****Date:** May 12, 2000**Re: TOOL STATUS****CC: ALLOY ENG.**☐ Urgent ☒ for Review ☐ Please Comment ☐ Please Reply ☐ Please Recycle

• **Comments:** METTY; PLEASE FIND ATTACHED THE REMINGTON TOOLING STATUS SHEET FOR YOUR FILES. THANKS FOR LETTING US QUOTE THE OTHER TWO PARTS. YOU WILL HAVE THEM MONDAY OR TUESDAY. I AM CERTAIN YOU WOULD RATHER DEAL WITH US ON THESE PARTS THAN WITH BRAND X.

HAVE A NICE WEEKEND.
BILL SOMERVILLE

MF0836

Remington Arms Company, Co., Inc.

C-1044 Vendor Mold & Die Tooling Status Sheet

Mayfield Plant

Customer Metty MORGAN
 Part # D-300360
 Part Name BOLT HANDLE

Enter Task Completion % Below

TASK NAME	START DATE	FINISH DATE	WK 1	WK 2	WK 3	WK 4	WK 5	WK 6	WK 7	WK 8	WK 9	WK 10	WK 11	WK 12	WK 13	WK 14	WK 15	WK 16	WK 17	WK 18	WK 19	WK 20	WK 21
Tool Design																							
Tool Design Review																							
Tool Build	<u>3/28</u>	<u>5/11</u>	<u>0</u>	<u>0</u>	<u>26</u>	<u>20</u>	<u>20</u>	<u>20</u>	<u>20</u>														
Tool Tryout	<u>5/11</u>	<u>5/15</u>	<u>100</u>																				
First Article Approval Run	<u>5/15</u>	<u>6/19</u>																					
First Production Run after First Article Inspection is approved by Remington																							

Special Instructions / Notes: - Remington to receive approval drawings for tool
 - Vendor to supply information listed in sample submission checklist C-1018
 at time of first article sample submission

** Tool put on Hold*

C-1044

Originating Date 2/29/00
 Revision # 0
 Revision Date.

05/12/00 FRI 14:49 FAX 601 245 4697
 BARBER - 5.22.06 0010787

N. AMER. PREC. CASTING

002

MF0837

Confidential - ~~SECRET~~ - 5.22.06 0010787 Order
 Williams v. Remington

#300380 - Bolt Handle Blank

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity M	Engineering Charges	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
10	Machine Radius in Drill	Tooling Fixture Okum Crown V				\$ 1,630	20		0.004167	\$ -	\$ -	\$ 12,575.00	\$ -	Fansteel--Quote 8/12/99
Totals						\$ 1,630	20		0.004167	\$ 0.00	\$ 0.00	\$ 12,575	\$ 0.00	

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages		

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages	Material Handling	Comments
10	Vendor tooling Inspection	Fixture Comparator w/ Screen								\$ 6,800.00		\$ 2,500.00	
Totals						\$ 0.00	0	\$ 0.00	\$ 0.00	\$ 0.00	\$ 2,500.00	\$ 0.00	

#305390 - Bolt Body Assembly

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Prep \$	Capital \$	Material Handling	Comments
10	press handle on bolt body	mead press fixture gage				\$ -	0.0051000	\$ -	\$ -	\$ 15,000.00 \$ 1,100.00 \$ 800.00	\$ -	
15	wash both parts	baskets										
20	brazz handle on body	brazz machine fixture gage				\$ -	0.0065000	\$ -	\$ -	\$ 15,000.00 \$ 1,100.00	\$ -	
30	deplate	material handling tanks					0.0000100	\$ -	\$ -		\$ -	
40	magnaflux (obsolete) per Matt G					\$ -	0.0066250	\$ -	\$ -		\$ -	
50	inspect visual					\$ -	0.0000100	\$ -	\$ -		\$ -	
70	glass bead blast	fixture				\$ -	0.0053000	\$ -	\$ -	\$ 1,500.00	\$ -	
80	color	material handling				\$ -	0.0040000	\$ -	\$ -	\$ 2,000.00	\$ -	
Totals						\$ -	0.027549	\$ -	\$ -	\$ 3,500.00	\$ -	

ACTUAL COSTS

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Prep \$	Capital \$	Material Handling	Comments
10	press handle on bolt body	mead press fixture gage				\$ -	0.0051000	\$ -	\$ -	\$ 15,000.00 \$ 1,100.00 \$ 800.00	\$ -	
15	wash both parts	baskets										
20	brazz handle on body	brazz machine fixture gage				\$ -	0.0065000	\$ -	\$ -	\$ 15,000.00 \$ 1,100.00	\$ -	
30	deplate	material handling tanks				\$ -	0.0000100	\$ -	\$ -		\$ -	
40	magnaflux (obsolete) per Matt G					\$ -	0.0066250	\$ -	\$ -		\$ -	
50	inspect visual					\$ -	0.0000100	\$ -	\$ -		\$ -	
70	glass bead blast	fixture				\$ -	0.0053000	\$ -	\$ -	\$ 1,500.00	\$ -	
80	color	material handling				\$ -	0.0040000	\$ -	\$ -	\$ 2,000.00	\$ -	
Totals						\$ -	0.027549	\$ -	\$ -	\$ 3,500.00	\$ -	

83

ME0839

Confidential - ~~Submittal~~ - 5.22.06#0010789 Order

Williams V. Remington

#300328 - Bot Handle Pin

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Blank Material - Stamping Gaging (Vendor and Remington)					\$ 0.180	20	\$ 450.00						Automic Swiss Corporation--Quote 8/20/99
Totals						\$ 0.180	20	\$ 450.00	0	\$0.00	\$0.00	\$0.00	\$0.00	

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages		

ME0840

#XXXX - Bolt Head Assy

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
10	Assemble Rivetless Extractor					\$ -	0.00692	\$ -	\$ -	\$ -	\$ -	
20	Assemble Ejector <i>LIP-IN HOUSE</i>					\$ -	0.0083	\$ -	\$ -	\$ -	\$ -	
Totals						\$0.00	0.01522	\$0.00	\$0.00	\$0.00	\$0.00	

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages		

EXTRACTOR @ 6/14 - 1900

EXTRACTOR DROP - 6/10/06

#300336 - Bolt Head

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Price	Rev	Material	Std Run Hours	Variable Overhead \$	Prep \$	Capital \$	PFI Gages \$	Material Handling	Comments
	Blank Material					\$ 288.75							
15	Gages Mill Lugs Machine Fixtures Tools Gaging	MX-45 VAE				\$0.00	0.018613935	0.279783	\$2,142	\$154,500	\$ 120.00	\$ -	Parker & Harper Mfg Company Estimated Quote
25	Mazak Fixtures Gaging	New Tombstones/Collets				\$	0.041000	\$ - \$		\$ 60,000.00 \$4,000		\$ -	
56	Rear. Extractor Revol Hole Fixtures					\$	0.0065880	\$ - \$		\$ 1,000.00		\$ -	
57	Com Anti-Rotation Dimple Fixtures					\$	0.0065880	\$ - \$		\$ 1,000.00		\$ -	
60	Ream Egt/Egt Retaining Hole Fixtures					\$0.00 \$0.00	0.0007100	\$ 0.14 \$ 0.08 \$	1,262.43 1,557.00	\$15,000		\$ -	M7:0 Head Ejector Retain Hole M7:0 Bolt Head Retaining Hole and Cam Cuts
58	Rear. & C Sink Extractor Revol Hole Ream Egt Cross Pin Hole Fixtures					\$ -	0.015110	\$ - \$		\$ 1,000.00		\$ -	
70	Deburr & Dimple Fixtures					\$ -	0.015110	\$ \$		\$ 1,000.00		\$ -	
80	Mill Cam Surface on Lugs Machine Fixtures Gaging	CNC Vertical Mill Haas 4th w/ fixturing				\$ -	0.008333	\$ \$		\$ 60,000.00 \$ 15,000.00 \$ 2,000.00		\$ -	
90	Drill Assembly Hole Fixture	Drill Press				\$ -	0.0041000	\$ \$		\$ 1,000.00		\$ -	
100	Rear Assembly Hole Fixture	Drill Press				\$ -	0.002777	\$ \$		\$ 1,000.00		\$ -	
110	Black Oxide					\$0.00	0.001300	\$ \$		\$ 0		\$ -	
Totals						\$ 1.75	0.108156	\$ 0.64 \$	\$ 5,761.38	\$ 316,500.00	\$ 120.00	\$ -	

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages		

FOOTER - DEWITT

Blank DYE -

CMM Fixtures & Inspection -

FORGAGE - (1000) 2/10 -

PLUS GAGES -

ARMED MACHINING - SAMPLE -

1. 10000 0.0000 - BLOOD 1.0000 at 1.0000

710 Complete 1

83

ME0842

#83712 - Extractor

PROCESS OP #	DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Gages					\$ 0.77					\$ 3,300.00		Ilion Quote SAP Estimated Quote
Totals						\$ 0.77	0	\$0.00	\$0.00	\$0.00	\$3,300.00	\$0.00	

	order date	due date
Tooling ordered	2/29	2/29
comp fixture design	2/29	
comp fix build		
comp screen	2/29	
plug gages		

710 Complete 1

BARBER - 5.22.06r0010793

ME0843

Confidential - Subject - 5.22.06r0010793 Order
Williams v. Remington

#300342 - Ejector

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Rev #	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vendor and Remington)				\$ 0.110	20	\$ 400.00					\$ 3,000.00		Isels--Quote. 8/25/99 Estimated Quote
10	Black Oxide Color							0.000001	\$ -	\$ -	\$ -		\$ -	
Totals					\$ 0.110	20	\$ 400.00	0.000001	\$ -	\$ -	\$ -	\$ 3,000.00	\$ -	

Note: Quoted in C12L14 material *Per Change*
Quoted with .10" max. cornerbreaks unless noted

	order date	due date
Tooling ordered	8-7-99	
comp fixture design	8-10-99	
comp fix build		
comp screen	8-16-99	
plug gages		

83

ME0844

#300367- Ejector Spring

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable		Preop \$	Capital \$	Material Handling	Comments
									Overhead \$					
	Blank Material - Screw Machine Gaging (vendor and Remington)		F300367	A-300367	\$ 0.015	20								Midstate Spring, Inc.--Quote: 8/20/99
Totals					\$ 0.015	20		0	\$ -	\$ -	\$ -	\$ -		

Note: Tool charge

Part unknown at time of estimate

Please See

MF0845

#94555 - Ejector Pin

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print#	Rev	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vendor and Remington)					\$ 0.01	20							Then Quote SAP
Totals						\$0.01	20		0	\$ -	\$ -	\$ -	\$ -	

*DPI - ALL
RING CASE*

MF0846

#300330 - Bolt Assy Pin

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print#	Rev	Material \$	Quantity M	Engineering Charge	Std Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vendor and Remington)					\$ 450.150	20	\$ 450.00						Automatic Swiss Corporation--Quote 8/20/99
10	Black Oxide Color					\$			0.000001	\$ -	\$ -	\$ -	\$ -	
Totals						\$ 450.150	20	\$ 450.00	0.000001	\$0.00	\$0.00	\$0.00	\$0.00	

Note: Quoted in C12T,14 material
Quoted with 10" max cornerbreaks unless noted

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages		

#300404 - Firing Pin Assembly

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
10	Assemble Firing Pin Tip to Firing Pin		F300404	B-300404	A	\$ -	0.001109	#VALUE!	#VALUE!		#VALUE!	
20	Assemble Firing Pin Sub Assembly, Main Spring, Bolt Plug & Firing Pin Head					\$ -	0.014515	\$ -	\$ -	\$ 7,500.00	\$ -	
Totals						\$50.00	0.0156238	#VALUE!	#VALUE!	\$7,500.00	#VALUE!	

		order date	due date		
Assemble tip to pin	in house				
Fixture for Assembly Design					
Fixture build					
Assemble the pin assy to spring and head					
Fixture for Assembly Design	in house				
Fixture build					
Assemble the plunger and spring and sonic weld					
Fixture for Assembly Design	in house				
Fixture build					
Welder set-up					

#300366 - Bot Plug

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Material (Plastic) Gaging (Vendor and Remington)					\$ 0.215	20					\$ 36,000.00	\$ 800.00		Kalena & Coe--Quote 8/17/99 Estimated Quote
	What insert Rev does K&C have???														
Totals						\$ 0.215	20		0	\$0.00	\$0.00	\$ 36,000.00	\$ 800.00	\$0.00	

Note: Remington is to supply metal inserts.

	order date	due date			
Tooling ordered	8-22-99				
comp fixture design					
comp fix build					
comp screen					
plug gages					

MF0849

Confidential - SHARPER - 5.22.06r0010799 Order Williams v. Remington

#300346 - Bot Plug Insert

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev.	Material \$	Quantity	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PP1 Gages \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (Vendor and Remington)					0.808	60						\$ 3,000.00		Swiss Precision Machining, Inc. -Quote 8/26/99 Estimated Quote
	What Rev is on order?														
Totals						\$ 0.808	60		0	\$0.00	\$0.00	\$0.00	\$3,000.00	\$0.00	

	order date	due date		
Tooling ordered	8-2-06			
comp fixture design	8-2-06			
comp fix build				
comp screen	8-2-06			
plug gages				

MF0850

#300334 - Firing Pin

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part #	Print #	Rev	Material \$	Quantity M	Engineering Charges	Std Run Hours	Variable Overhead \$	Preop \$	Capital \$	PFI Gages \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vander and Remington)					\$ 1.190	20	\$ 400.00					\$ 200.00		Isels-Quote 8/16/99 Estimated Quote
10	Black Oxide Color					\$			0.000001	\$	\$	\$	\$	\$	
Totals:						\$ 1.190	20	\$ 400.00	0.000001	\$0.00	\$0.00	\$0.00	\$ 200.00	\$0.00	

Note: Quoted in altered drawing (faxed 8-10-99 by Matt Golemboski)
 Quoted in C12L14 material
 Quoted with 10-24 reading 8-32
 Quoted with heat treat and black oxide to be done by Remington
 Quoted with .015" max. cornerbreaks unless noted

	order date	due date
Tooling ordered		
comp fixture design		
comp fix build		
comp screen		
plug gages	2-1	
comp fix build		

DAT - 1215
 T-P - 1214 77

QuickTek859-987-2563

Remington Arms Co

Fax

To: Chuck Ulinski**From:** Matt Golemboski**Fax:** 270-856-3233**Pages:** 2**Phone:** 270-856-4203**Date:** 05/19/00**Re:** Firing Pin and Firing Pin Tip**CC:** Joe Zajk, Jerry Helmer, Matt Morgan

83

☒ **Urgent**☐ **For Review**☐ **Please Comment**☐ **Please Reply**☐ **Please Recycle**

Chuck,

Firing Pin tip F300335 delivered to our plant on 5/18/00 has been approved for production.

Firing Pin F300334 delivered to our plant on 5/18/00 is approved for production under a conditional release. The condition that must be corrected during the production run is the overall length 4.890 +/- .005 is oversized by as much as .012. Please review this dimension during your production.

See attached inspection report.

MF0852

#200335 - Firing Pin Tip

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print#	Rev	Material \$	Quantity M	Engineering Charge	Std Run Hours	Variable Overhead \$	Prep \$	Capital \$	PFI Gages \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vondor and Remington)					\$ 0.230	20	\$ 225.00					\$ 3,300.00		Iseli--Quote 8/16/99 Estimated Quote
10	Black Oxide Color								0.000001	\$ -	\$ -	\$ -		\$ -	
Totals						\$ 0.230		\$ 225.00	0.000001	\$0.00	\$0.00	\$0.00	\$3,300.00	\$0.00	

Note: Quoted in altered drawing (faxed 8-10-99 by Matt Golemboski)
Quoted with 10-24 reading 8-32
Quoted with 143 +/- .002 diameter reading 141 +/- diameter
Quoted with heat treat and black oxide to be done by Remington
Quoted with .015" max cut-off nub on threaded end

	order date	due date		
Tooling ordered				
comp fixture design				
comp fix build				
comp screen	ADONE			
plug gages				

12.14?
Quick fix - samples.

#300336 - Firing Pin Head

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material	Quantity	Engineering Charge	Std Run Hours	Variable Overhead \$	Preop \$	Capital \$	PFI Gages \$	Material Handling	Comments
10	Blank Material - MIM Gages MIM process part	mold furnace setters	R300336	C-300336	F	1.500	20						\$ 1,500.00		Megamet Industries--Quote 9/13/99 Estimated Quote
20	Electroless Nickel Plate Has been dropped					\$ (0.263)						\$ 15,000.00 \$ 2,500.00			
Totals						\$ 1.247	20		0	\$ -	\$0.00	\$17,500	\$ 1,500.00	\$0.00	

	order date	due date		
Tooling ordered				
comp fixture design		7.1.00		
comp fx build	6.1.00			
comp screen		3.1.00		
plug gages <i>F#1022.2.0</i>				

ME0854

#300399- Firing Pin Spring

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material	Quantity	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vendor and Remington)		F300399	A-300399	D	\$ 0.001	20							Midstate Spring--Quote 8/20/99
10	Black Oxide Color					\$			0.000001	\$ -	\$ -	\$ -	\$ -	
Totals						\$ 0.001	20		0.000001	\$0.00	\$0.00	\$0.00	\$0.00	

Sample received for dat on _____

WHE- GALVANIZED?

Any need to BLACK OXIDE??

Q. 1st Sample - SPECIAL -

#- Front Sight Assy

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vendor and Remington)		F94048	C-15373		\$ 0.30						
10	Assem Front sight to front sight ramp											
		Totals				\$0.30	0	\$0.00	\$0.00	\$0.00	\$0.00	

Press covered in the barrel assembly process.

From F. R. Mc - H. F. J. R.

710 Complete 1

83

MF0856

#94084 - Front Sight

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vendor and Remington)		94084 C-15323			\$ 0.79						Ilion Quote SAP
			94095									
10	Black Oxide Color					\$	0.000001	\$ -	\$ -	\$ -	\$ -	
	Paint front dot	not in estimate										
Totals						\$0.79	0.000001	\$0.00	\$0.00	\$0.00	\$0.00	

NOTE two part numbers: regular and magnum

PPlinsection???

GET SAP blank price and our cost to finish and paint

#94657 - Front Sight Ramp

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print#	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vendor and Remington)					\$ 1.19					\$ 400.00		Ilion Quote SAP Estimated Quote
10	Black Oxide Color						0.000001	\$	\$	\$		\$	
Totals						\$1.19	0.000001	\$0.00	\$0.00	\$0.00	\$400.00	\$0.00	

Estimate the machining cycle based on the Ilion process and SAP values Big oppuruntiy with the Crown 4018 w/p pallet changer

PPI inspections???

83

ME0858

Confidential - ~~Submittal~~ - 5.22.06/0010808 Order
Williams v. Remington

#28505 - F Sight Ramp Screws

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Unit #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vendor and Remington)					\$ 0.04						Mayfield Quote SAP
	Totals					\$0.04	0	\$0.00	\$0.00	\$0.00	\$0.00	

710 Complete 1

MF0859

#103145 - Rear Sight Assembly

PROCESS OP #	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vendor and Remington)	F103145	B-103145		\$ 3.72						Ilion Quote SAP
Totals					\$3.72	0	\$0.00	\$0.00	\$0.00	\$0.00	

NOTE estimated as a 103146 and parts list is a 103145

#305455 - Stock Assy. Complete

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part #	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vendor and Remington)					\$ 0.30						
10	Assemble butt plate to stock											
Totals						\$0.30	0	\$0.00	\$0.00	\$0.00	\$0.00	

710 Complete 1

B3

MF0861

#300347 - Stock

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Prep \$	Capital \$	PFI Gages \$	Material Handling	Comments
	Material-Plastic Gaging (vendor and Remington)		F300347	E-300347		\$ 5.38	20						\$ 4,500.00		Par 4 Plastics, Inc.
10	Cavity Mold	New Tooling										\$ 150,300.00			
Totals						\$5.38	20		0	\$0.00	\$0.00	\$150,300.00	\$4,500.00	\$0.00	

Note: Divider sleeves for the stock have been amortized over the first years production at a cost of \$.006 per sleeve

Files to Par 4
CMM Fixture
CMM Program

date ordered date due

ORDER BY END WEEK - 87000

Drilling fixture to be ordered by 2/20/00 after the gun price is evaluated to determine whether or not to amortize the drilling fixture

Press for con. inserts

✓ CMM Program & Fix
Sack mod. ??

#15161 - Front Screw Bushing

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print#	Rev	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Material-screw machine Gaging (vender and Remington)						20							
10	Cavity Mold	New Tooling												
Totals						\$0.00	190		0	\$0.00	\$0.00	\$0.00	\$0.00	

Ilion part - verify dmsions on inspection
Estimated as a plastic part

710 Complete 1

83

MF0863

#97971 - Grip Cap

OF #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material	Quantity	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Material-Plastic Gaging (vendor and Remington)					\$ 0.18	20							Elon Quote SAP
10	Cavity Mold Iton provided													
Totals						\$0.18	20		0	\$0.00	\$0.00	\$0.00	\$0.00	

710 Complete 1

ME0864

CMM Program and Fixture
PPI inspection gages
Does this fit to the new stock
need samples (50 Pcs) ship ASAP for dimensional layout. Forward info to Keeney for match to model.

CMM Program and Fixture
PPI inspection gages
 Does this fit to the new stock
 need samples (50 Pcs) ship A

310 Complete 1

MF0865

#97972 - Backer Plate

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PFI Gages \$	Material Handling	Comments
	Material-Plastic Gaging (vendor and Remington)					\$ 0.39									Iron Quote SAP Estimated Quote
Totals						\$0.39			0	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	

710 Complete 1

MF0866

#30035 - Repro Pad Stamp

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part #	Print #	Material	Quantity	Engineering Charge	Std. Run Hours	Variable Overhead \$	Fixed \$	Material Handling	Comments
	Material-Optic					20						
	Coating (vulcan and Remington)					0.01						
	Blank Part											
Totals												
						20		0	\$0.00	\$0.00	\$0.00	

Printed--Quote

710 Complete 1

MF0867

300562 - Magazine Latch

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Material-Plaste Gauging (Vendor and Remington)					\$ 0.131	20							Kellems & Coe-Quote 8/17/99
10	Cavity Mold	New Tooling										\$ 39,000.00		
Totals						\$ 2.62	20		0	\$0.00	\$0.00	\$39,000.00	\$0.00	

	order date	due date	
Toling			
Comp Screen			
Comp Fixture			
Design of the screen and fixture			

710 Complete 1

BARBER - 5.22.06r0010818

MF0868

Confidential - Subject - 5.22.06r0010818 Order
Williams v. Remington

#300396 - Magazine Latch Spring

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Material-Plastic Gaging (vendor and Remington)		P300398	B-300398	B	\$ 0.026	20							Industrial Spring-Quote 8/21/99
Totals						\$ 0.026	20		0	\$0.00	\$0.00	\$0.00	\$0.00	

	order date	due date	
tooling			
comp screen			
prototypes??			
Critical path due to the function of the box relying on this par and latch.			

#300425 - Rear Takedown Screw

PROCESS OP #	DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vendor and Remington)		F300425	B-300425		\$ 0.08					\$ 200.00		Estimated Quote
	Parts Delivered on ???												
	Totals					\$0.08	0	\$0.00	\$0.00	\$0.00	\$200.00	\$0.00	

710 Complete 1

83

MF0870

#104125- Takedown Screws (2)

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (Vendor and Remington) blank # is 104141 Ibon A/U		F104125	C-104125		\$ 0.30					\$ 200.00		Estimated Quote
Totals						\$0.30	0	\$0.00	\$0.00	\$0.00	\$200.00	\$0.00	

710 Complete 1

MF0871

#300371 - Mag Latch Pivot Pin

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev.	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vendor and Remington)					\$ 0.070	20	\$ 225.00						Isel.-Quote: 8/25/99
10	Black Oxide Color								0.000001	\$ -	\$ -	\$ -	\$ -	
Totals						\$ 0.070	20	\$ 225.00	0.000001	\$0.00	\$0.00	\$0.00	\$0.00	

Note: Quoted in C12L14 material
Quoted with .015" max. cornerbreaks unless noted

MF0872

#94996 - Sling Swivel Stud

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Blank Material - Screw Machine Gaging (vendor and Remington)		F94996									
	revised was 300096 now 94996 same as 597											
	Totals					\$0.00	0	\$0.00	\$0.00	\$0.00	\$0.00	

710 Complete 1

ME0873

#305395 - Magazine Assy

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
10	Assemble Magazine box Esimated in house		305395	B-305395		\$ -	0.0083	\$ -	\$ -	\$ -	\$ -	
Totals						\$ -	0.0083	\$ -	\$ -	\$ -	\$ -	

Options lie at Par 4 or Brainin also

Inspection procedure??

710 Complete 1

MF0874

#300363 - Magazine Box

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Blank Material - Stamping Gaging (vendor and Remington)		F300363	E-300363	11	\$ 2,790	20						\$ 4,500.00		Historical Data Used Estimated Quote
10	Black Oxide Color								0.000001	\$ -	\$ -	\$ -		\$ -	
Totals						\$ 2,790.00	20		0.000001	\$ -	\$ -	\$ -	\$ 4,500.00	\$ -	

tooling prototype
 tooling production
 CMM fixture design
 CMM fixture build
 CMM program

order date
 due date

\$12,500 taken by Etown we take the \$13.00 + 10% for all parts

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Blank Material - Stamping Gaging (vendor and Remington)		F300363	E-300363	11	\$ 1,000	20					\$ 79,000.00	\$ 4,500.00		Historical Data Used Estimated Quote
10	Black Oxide Color					\$ -			0.000001	\$ -	\$ -	\$ -		\$ -	
Totals						\$ 1,000.00	20		0.000001	\$ -	\$ -	\$ 79,000.00	\$ 4,500.00	\$ -	

710 Complete 1

ME0875

#300363 - Magazine Follower

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print#	Rev	Material \$	Quantity M	Engineering Charge	Std Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Blank Material - Poly prop Gaging (vender and Remington) Tooling		F300364	D-300364	11	\$ 0.002	20					\$ 78,786.00	\$ 3,000.00		Par 4 Plastic, Inc --Quote 8/27/99 Estimated Quote
Totals						\$ 0.004	20		0.000000	\$ -	\$ -	\$ 78,786.00	\$ 3,000.00	\$ -	

PAR 5 Family fold with the box bottom

Original material was PA66 nylon with glass
changed to poly prop shrink rates vary similar to PA66

Comp screen design
Comp fixture design
comp fixture build

order date

due date

710 Complete 1

83

MF0876

#300365 - Magazine Bottom

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Quantity M	Engineering Charge	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
	Blank Material - Poly prop Gaging (Vendor and Remington) Tooling		F300365	D-300365	9	\$ 0.105	1							Par 4 Plastics, Inc - Quote 8/27/99
Totals						\$ 0.105	1		0.000000	\$ -	\$ -	\$ -	\$ -	

Inspector Procedure

Artwork define on 1/25/00 R&D to have drawing available

710 Complete 1

B3

MF0877

#17028 - Magazine Spring

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	PPI Gages \$	Material Handling	Comments
	Blank Material - Stamping Gaging (vondor and Remington) Tooling					\$ 2.79				\$ 39,710.00	\$ 3,000.00		Estimated Quote
	Totals					\$ 2.79	0.000000	\$ -	\$ -	\$ 39,710.00	\$ 3,000.00	\$ -	

tooling must get off center

comp screen design

Prototypes???

Heat treat in lilon is on racks lying down Need samples to cost

Samles are SAKOs Can we buy their spring??

710 Complete 1

MF0878

50

Have part quoted and order 500 parts on March 1st any receiver changes will appear by then.

M710 - Assembly, Gallery, Pack

OP #	PROCESS DESCRIPTION	MACHINE DESCRIPTION	Part#	Print #	Rev	Material \$	Std. Run Hours	Variable Overhead \$	Preop \$	Capital \$	Material Handling	Comments
10	Proof Test					\$ 1.25	0.016046	\$ -	\$ -	\$ -	\$ -	
20	Test & Target (10%)	(5x\$ 15)*10%				\$ 0.10	0.031759	\$ -	\$ -	\$ -	\$ -	
30	Inspect Heading & Sear Lift					\$ -	0.019630	\$ -	\$ -	\$ -	\$ -	
40	Inspect for Live AMMO					\$ -	0.004270	\$ -	\$ -	\$ -	\$ -	
50	Final Inspection					\$ -	0.022370	\$ -	\$ -	\$ -	\$ -	
60	Assemble Rear Swivel Screw					\$ -	0.004315	\$ -	\$ -	\$ -	\$ -	
65	Laser Engrave						0.000100					
70	Pack	printer bench vise computer and lines				-	0.019043	\$ -	\$ -	\$ -	\$ -	
Totals						\$ 1.35	0.117533	\$0.00	\$0.00	\$ -	\$0.00	

order date

due date

Galery and build progress
Sanis

710 Complete 1

83

ME0880

Confidential - ~~BARBER - 5.22.06r0010830~~ Order

Williams V. Remington

CONFIDENTIAL 83

MF0881

Feature #	Feature Name	X Actual	X Std. Dev	X Nominal	X Tolerance	X Deviation	Y Actual	Y Std. Dev.	Y Nominal	Y Tolerance	Y Deviation	Dis. Actual	Std. Dev	Nominal	Tolerance	Deviation
37	D-Datum Hole - from ABC	0.8512	0.0003	0.850	+/- 0.003	0.0012	-0.6225	0.0003	-0.621	+/- 0.003	-0.0015	0.1222	0.0001	0.122	+/- 0.0015	0.0002
38	Rear Sear Hole - from DC	-1.4263	0.0001	-1.428	+/- 0.003	0.0017	0.0048	0.0002	0.000	+/- 0.003	0.0048	0.1224	0.0000	0.122	+/- 0.0015	0.0004
39	Engagement View Hole - from DC	-0.8861	0.0001	-0.887	+/- 0.005	0.0009	-0.1809	0.0002	-0.183	+/- 0.005	0.0021	0.1292	0.0001	0.127	+/- 0.005	0.0022
40	Safety Pivot Pin Hole - from DC	-1.3077	0.0001	-1.306	+/- 0.002	0.0017	-0.6457	0.0002	-0.650	+/- 0.002	0.0043	0.1244	0.0000	0.122	+/- 0.0015	0.0024
41	Trigger Pivot Pin Hole - from DC	-0.8418	0.0002	-0.840	+/- 0.002	0.0018	-1.2369	0.0002	-1.240	+/- 0.002	0.0031	0.1236	0.0001	0.122	+/- 0.0015	0.0016
56	Front Rivet Hole - from DC	-0.2988	0.0003	-0.297	+/- 0.002	0.0018	-1.1240	0.0003	-1.128	+/- 0.002	0.0040	0.0973	0.0001	0.097	+/- 0.0015	0.0003
58	Rear Rivet Hole - from DC	-1.2319	0.0004	-1.259	+/- 0.002	0.0029	-1.1847	0.0004	-1.191	+/- 0.002	0.0063	0.0973	0.0001	0.097	+/- 0.0015	0.0003

Feature #	Feature Name	Resulting True Position	Model Drawing True Position (RFS)
37	D-Datum Hole - from ABC	0.0038	0.006
38	Rear Sear Hole - from DC	0.0102	0.006
39	Engagement View Hole - from DC	0.0046	0.010
40	Safety Pivot Pin Hole - from DC	0.0092	0.004
41	Trigger Pivot Pin Hole - from DC	0.0072	0.004
56	Front Rivet Hole - from DC	0.0088	0.004
58	Rear Rivet Hole - from DC	0.0139	0.004

Feature #	Feature Name	X Actual	X Std. Dev.	X Nominal	X Tolerance	X Deviation	Y Actual	Y Std. Dev.	Y Nominal	Y Tolerance	Y Deviation	Dia. Actual	Std. Dev.	Nominal	Tolerance	Deviation
37	D-Datum Hole - from ABC	0.8498	0.0003	0.850	+/- .003	-0.0002	-0.6220	0.0004	-0.621	+/- .003	-0.0010	0.1257	0.0000	0.122	+/- .0015	0.0037
38	Rear Sear Hole - from DC	-1.4252	0.0001	-1.428	+/- .003	0.0028	0.0169	0.0004	0.000	+/- .003	0.0169	0.1258	0.0000	0.122	+/- .0015	0.0038
39	Engagement View Hole - from DC	-0.8660	0.0001	-0.867	+/- .005	-0.0010	-0.1804	0.0002	-0.183	+/- .005	0.0026	0.1292	0.0000	0.127	+/- .005	0.0022
40	Safety Pivot Pin Hole - from DC	-1.3069	0.0001	-1.306	+/- .002	-0.0002	-0.6453	0.0002	-0.650	+/- .002	0.0047	0.1261	0.0000	0.122	+/- .0015	0.0041
41	Trigger Pivot Pin Hole - from DC	-0.8370	0.0004	-0.840	+/- .002	0.0039	-1.2344	0.0004	-1.240	+/- .002	0.0056	0.1257	0.0001	0.122	+/- .0015	0.0037
56	Front Rivet Hole - from DC	-0.2988	0.0002	-0.297	+/- .002	-0.0018	-1.1224	0.0003	-1.128	+/- .002	0.0056	0.1002	0.0000	0.097	+/- .0015	0.0032
58	Rear Rivet Hole - from DC	-1.2612	0.0004	-1.259	+/- .002	-0.0022	-1.1838	0.0004	-1.191	+/- .002	0.0071	0.1001	0.0001	0.097	+/- .0015	0.0031

Feature #	Feature Name	Resulting True Position	Model Drawing True Position (RFS)
37	D-Datum Hole - from ABC	0.0020	0.006
38	Rear Sear Hole - from DC	0.0343	0.006
39	Engagement View Hole - from DC	0.0056	0.010
40	Safety Pivot Pin Hole - from DC	0.0096	0.004
41	Trigger Pivot Pin Hole - from DC	0.0127	0.004
56	Front Rivet Hole - from DC	0.0118	0.004
58	Rear Rivet Hole - from DC	0.0149	0.004

Receiver Insert 200327**Analysis of Hanson 200 pc. Capability run - 64 second IQC process w/ chilled core**

All actual data is the mean & Std. Deviation of 25 pcs. out of the 200 pcs. run

Data was collected using Giddings & Lewis Discovery D-8 CMM with MeasureMax software and analyzed using Giddings & Lewis Real-Time Statistics Monitor software

All parts were run by same operator

Part located on:

M710 Turned Barrels

1/10 Groov	Bore	3/10 Groov	Bore
1. .3095	.3015	1. .3094	.3015
2. .30955	.30155	2. .3093	.3016
3. .3091	.3015	3. .3092	.3015
4. .3094	.3016	4. .3092	.30125
5. .3089	.3012	5. .3092	.3014
6. .3096	.3013	6. .3088	.3013
7. .3092	.30145	7. .3088	.3012
8. .3095	.3016	8. .30925	.3013
9. .3095	.3015	9. .3094	.3013
10. .3096	.3014	10. .3096	.3013

2/10 Groov	Bore	4/10 Groov	Bore
1. .3086	.3013	1. .3085	.3005
2. .3086	.3010	2. .3086	.3012
3. .3087	.3013	3. .3086	.3012
4. .30855	.30125	4. .3084	.3012
5. .3085	.30125	5. .3086	.3009
6. .3087	.3012	6. .3086	.3013
7. .3086	.3011	7. .3086	.3012
8. .3086	.3013	8. .3085	.30105
9. .3095	.3015	9. .3086	.3012
10. .3090	.3015	10. .3087	.3013

MF0884

5/10 Groov	Bore	6/10 Groov	Bore
1. .3085	.3011	1. .3085	.3010
2. .3085	.3012	2. .3085	.3011
3. .3086	.3012	3. .3085	.3012
4. .30855	.30125	4. .30845	.30115
5. .3086	.3012	5. .3084	.3010
6. .3086	.3013	6. .3085	.30105
7. .3086	.30105	7. .3085	.30125
8. .3086	.3011	8. .30845	.3011
9. .3086	.30105	9. .3084	.30105
10. .3087	.3010	10. .3086	.30125

CONFIDENTIAL

MF0885

Remington Arms Company, Inc

CONFIDENTIAL

Research and Development Technology Center
Elizabethtown, Kentucky

June 7, 2000

To: Joe Zajk
From: Marlin Jiranek

Cc: D. Danner, M. Keeney

RE: MPIF FC 0508-60 MATERIAL AND HEAT TREATMENT**SUMMARY**

A sample of five M/710 bolt stops was delivered to the Elizabethtown facility for microhardness analysis. The parts were manufactured by Sterling Sintered company from MPIF FC 0508-60. The heat treatment on the print calls out a Carburize at 0.7% carbon potential and a final part hardness of HR15n 88-92. The hardness readings which were obtained upon inspection at the Hickory manufacturing plant were HR15n 80-83.

The MPIF FC 0508-60 material (which corresponds to Remington P.M. 4058) is nominally 5% Cu, 0.75% C, and the balance Fe. This material is NOT intended to be case hardened. This particular material is intended to be used in the as-sintered condition and provide good wear resistance and moderate toughness. This material inherently contains a large amount of porosity (up to 15%) in it's sintered state, but can be quench and tempered to increase the sintered apparent hardness level to HRC mid-40's. Microhardness measurements are typically not achievable due to the large amount of porosity in the material.

RECOMMENDATION

This material is most likely acceptable to be used for this component. Alternatives can be provided if required. The print should have the heat treat and the hardness sections altered to reflect the actual processing and should read as follows:

Material: P.M. 4058 or MPIF FC 0508-60
Heat Treat: Oil Quench & Temper or Carburize (0.7% C.P.)
Hardness: HRC 42-48 Apparent
Color: Black Oxide

The heat treatment, based on the carbon content of the material, can be run in either of the two processes. The standard quench and temper treatment will provide the same part as the carburized part. The carburizing atmosphere would simply provide a protective atmosphere for the component at temperature, but is really unnecessary if its cost is greater than the standard quench and temper processing.

The last potential issue is the colorability of the Fe/Cu material. The material will have undissolved Cu in the matrix (see figures in procedure section) and may not color well with the black oxide. Some sample parts will have to be run on a trial basis to determine if the coloration is acceptable.

Marlin R. Jiranek, II
Research Engineer

Page 1 of 3

MF0886

PROCEDURE / RESULTS

To characterize the material specimens which were sent for evaluation, all five specimens were first measured for hardness using the HR15n scale. One of the specimens was then sectioned, mounted in bakelite, and polished to an 0.05mm finish for microstructural evaluation. Three of the remaining samples were measured for density per ASTM Specification 311-93. Additionally, all four of the specimens were measured for hardness using the HRc scale.

Hardness / Density Results

The hardness and density measurement results are presented in Table 1. Note that the specification hardness is for case hardening components and is not applicable for this material, as all of the parts are out of specification tolerance per the print.

MATERIAL DATA									
M710 BOLT STOP - MPIF EC-0508-60									
Hardness						Density (ASTM B311-93)			
	Specification	Parts				Test Block	Specification	Parts (g/cc)	
		1	2	3	4	5		2	3
HR15n	88 - 92	86.0	84.3	85.4	83.0	85.6	89.2 +/- 1.6	6.82	6.76
HRc	---	46.6	46.5	48.3	43.9	---	---	6.76	6.75

Table 1. Hardness and density results obtained from the samples provided for analysis.

The hardness of the material is actually in the mid-40's (HRc scale) which would most likely provide sufficient strength for the application. Other materials could be substituted for this material to provide equivalent or increased strength and toughness. These materials include some of the Fe/Cu (FC Series), Fe/Ni (FN Series), low alloy steels (FL Series), and the sinter-hardened materials (FLC Series).

The density of the components was slightly lower than the print. However, the MPIF standard lists the 6.8 g/cc density value as a "typical" value. Individual supplier material may differ from this value to some degree. For this reason, these numbers are acceptable from an incoming inspection perspective.

Microstructure

As expected, the microstructure of the component contains approximately 16% porosity and regions of pure Cu in the steel matrix. This is expected of steel material with greater than about 2% Cu additions. Figures 1, 2, and 3 present images of the microstructure at 50, 200, and 500X magnification. These images illustrate the amount of porosity in the material and present the microstructure of the material. The microstructure is what is expected of a quench and tempered high carbon steel material.




Figure 1. Unetched image of MPIF FC 0508-60 material, illustrating the amount of porosity in the part. Magnification approximately 50X.




Figure 2. Unetched microstructure of the material showing the undissolved Cu present in the matrix. Magnification approximately 200X.




Figure 3. Etched (2% Nital) microstructure, showing undissolved Cu in a tempered martensite matrix. Magnification approximately 500X.

Marlin R. Jiranek, II
Research Engineer

Page 3 of 3

MF0888

SHOOT - JESSE
 SHOT FROM BENCH
 SCOPE- LEUPOLD 36 POWER
 DATE- 10-1-99 THRU - 10-14-99

MODEL 710 BO ACTION RIFLE
 100 YARD ACCURACY

PROJECT 1095
 TLR 9256E

MODEL 710 ACCURACY EVALUATION

GUN	SERIAL#	AMMO	GROUP#1	GROUP#2	GROUP#3	GROUP#4	GROUP#5	AVERAGE
1	XC1064	REM R30062 150GR	0.999	0.864	1.373	1.709	1.502	1.2894
		LOT# C12UC9113						
30.06		REM R30064 180GR	1.775	2.02	1.577	0.701	1.496	1.5138
		LOT# C03SC1326			AVERAGE BOTH AMMO TYPES -			1.4016
GUN	SERIAL#	AMMO	GROUP#1	GROUP#2	GROUP#3	GROUP#4	GROUP#5	AVERAGE
2	XC1066	REM R30062 150GR	1.594	1.022	1.091	0.802	1.078	1.1174
		LOT# C12UC9113						
30.06		REM R30064 180GR	2.086	1.277	1.924	1.304	1.354	1.589
		LOT# C03SC1326			AVERAGE BOTH AMMO TYPES -			1.3532
GUN	SERIAL#	AMMO	GROUP#1	GROUP#2	GROUP#3	GROUP#4	GROUP#5	AVERAGE
3	XC1067	REM R30062 150GR	1.615	1.929	1.966	1.02	2.651	1.8362
		LOT# C12UC9113						
30.06		REM R30064 180GR	0.769	1.268	1.997	2.35	0.995	1.4758
		LOT# C03SC1326			AVERAGE BOTH AMMO TYPES -			1.656
GUN	SERIAL#	AMMO	GROUP#1	GROUP#2	GROUP#3	GROUP#4	GROUP#5	AVERAGE
4	XC1068	REM R30062 150GR	1.055	0.887	1.355	1.303	1.204	1.1608
		LOT# C12UC9113						
30.06		REM R30064 180GR	1.393	1.296	1.867	1.349	1.034	1.3878
		LOT# C03SC1326			AVERAGE BOTH AMMO TYPES -			1.2743
GUN	SERIAL#	AMMO	GROUP#1	GROUP#2	GROUP#3	GROUP#4	GROUP#5	AVERAGE
5	XC1069	REM R30062 150GR	1.32	1.155	1.634	2.021	1.831	1.5922
		LOT# C12UC9113						
30.06		REM R30064 180GR	1.381	2.07	1.313	1.08	1.168	1.4024
		LOT# C03SC1326			AVERAGE BOTH AMMO TYPES -			1.4973

BARBER - 5.22.06r0010839

83

MF0889

Confidential - Subject - 5.22.06r0010839 Order Williams v. Remington

SHOOT - JESSE
 SHOT FROM BENCH
 SCOPE- LEUPOLD 36 POWER
 DATE- 10-1-99 THRU - 10-14-99

MODEL 710 BOLT ACTION RIFLE
 100 YARD ACCURACY

PROJECT: 1095
 TLK 9256E

GUN	SERIAL#	AMMO	GROUP#1	GROUP#2	GROUP#3	GROUP#4	GROUP#5	AVERAGE
6	XC1070	REM R30062 150GR LOT# C12UC9113	0.916	1.591	1.423	1.495	1.413	1.3676
30.06		REM R30064 180GR LOT# C03SC1326	1.146	1.305	1.605	0.971	1.461	1.2976
			AVERAGE BOTH AMMO TYPES -					1.3326
GUN	SERIAL#	AMMO	GROUP#1	GROUP#2	GROUP#3	GROUP#4	GROUP#5	AVERAGE
7	XC1071	REM R30062 150GR LOT# C12UC9113	1.35	1.343	1.662	1.482	1.479	1.4632
30.06		REM R30064 180GR LOT# C03SC1326	1.292	0.888	1.587	1.659	1.214	1.328
			AVERAGE BOTH AMMO TYPES -					1.3956
GUN	SERIAL#	AMMO	GROUP#1	GROUP#2	GROUP#3	GROUP#4	GROUP#5	AVERAGE
8	XC1074	REM R30062 150GR LOT# C12UC9113	1.195	1.553	1.477	1.52	1.116	1.3742
30.06		REM R30064 180GR LOT# C03SC1326	1.378	1.058	1.436	1.438	0.872	1.2364
			AVERAGE BOTH AMMO TYPES -					1.3053
GUN	SERIAL#	AMMO	GROUP#1	GROUP#2	GROUP#3	GROUP#4	GROUP#5	AVERAGE
9	XC1075	REM R30062 150GR LOT# C12UC9113	1.513	1.041	1.257	1.216	1.211	1.2476
30.06		REM R30064 180GR LOT# C03SC1326	1.361	0.981	1.858	2.134	0.943	1.4554
			AVERAGE BOTH AMMO TYPES -					1.3515
GUN	SERIAL#	AMMO	GROUP#1	GROUP#2	GROUP#3	GROUP#4	GROUP#5	AVERAGE
10	XC1077	REM R30062 150GR LOT# C12UC9113	0.746	1.449	1.443	1.598	1.333	1.3138
30.06		REM R30064 180GR LOT# C03SC1326	1.362	1.464	1.018	1.272	1.679	1.359
			AVERAGE BOTH AMMO TYPES -					1.3364
GUN	SERIAL#	AMMO	GROUP#1	GROUP#2	GROUP#3	GROUP#4	GROUP#5	AVERAGE
11	XC1078	REM R30062 150GR LOT# C12UC9113	1.805	1.479	2.025	2.103	1.483	1.779
30.06		REM R30064 180GR LOT# C03SC1326	1.51	2.694	2.297	1.857	1.133	1.8982
			AVERAGE BOTH AMMO TYPES -					1.8386

BARBER - 5.22.06/0010840

83

ME0890

Confidential - Subject - 522060600640
 Order
 Williams v. Remington

SHOOT - JESSE
SHOT FROM BENCH
SCOPE- LEUPOLD 36 POWER
DATE- 10-1-99 THRU - 10-14-99

MODEL 710 BC ACTION RIFLE
100 YARD ACCURACY

PROJECT 11095
TLR 9256E

GUN	SERIAL#	AMMO	GROUP#1	GROUP#2	GROUP#3	GROUP#4	GROUP#5	AVERAGE
12	XC1080	REM R30062 150GR	1.376	1.331	1.3	1.611	1.51	1.4256
		LOT# C12UC9113						
30.06		REM R30064 180GR	1.335	1.491	1.4	1.181	1.345	1.3504
		LOT# C03SC1326						
AVERAGE BOTH AMMO TYPES -								1.388
AVERAGE GROUP SIZE ALL GUNS R30062 150GR - 1.413								
AVERAGE GROUP SIZE ALL GUNS R30064 180GR - 1.441								
THOROUGHLY CLEANED GUNS BEFORE SHOOTING GROUPS AND BETWEEN AMMO TYPES.								
SWABBED BORE WITH ONE COTTON PATCH WITH HOPPIES SOLVENT FOLLOWED BY FOUR DRY COTTON PATCHES AFTER EACH FIVE SHOT GROUP.								
COOLED GUN AFTER EACH FIVE SHOT GROUP.								
SHOT ONE FOULING SHOT PRIOR TO SHOOTING EACH GROUP.								

BARBER - 5.22.06r0010841

83

MF0891

Confidential - Subject - 5.22.06r0010841
Shirley Williams v. Remington

Golemboski, Matt R.

From: Keeney, Mike
Sent: Friday, May 19, 2000 10:43 AM
To: Zajk, Joseph J; Golemboski, Matt R.
Subject: 710 Magazine Box Tab dimensions

Guys,
the tab locations on the latest drawing (rev. 15) are incorrect. The dimensions should be 1.648 +/- .005 in the rear and 1.524 +/- .005 in the front. Drawing will be updated and forwarded to you.

Sorry
Mike

CONFIDENTIAL 83

Model 710 Receiver Insert Non-DAT Testing**Brian Rages****5/16/005/16/00****PURPOSE**

The purpose of this test was to examine the robustness of the Remington Model 710 receiver insert during conditions of extreme abuse. The first test evaluated the tendency of the receiver insert to deform when placed in a high-temperature, high-humidity environment. The second test evaluated deformation over 10,000+ cycles of sear loading.

CONCLUSIONS

No significant longevity deficiencies were found. The ANSYS model showed stresses well below the limits of the material used in the receiver insert. The creep test revealed no significant movement of the firing pin head once the fixture reached the temperature of its chamber. The first receiver insert fatigue test showed an unexpected increase in firing pin head protrusion as the number of cycles on the insert increased. This was attributed to error caused by an inconsistent measurement technique. In the second fatigue test, care was taken to align the firing pin head before measuring. During this retest, all measurements fell within a 0.005 inch wide band. When the test was concluded, none of the gun's components showed extreme wear.

PROCEDURE

ANSYS analysis. An analysis was performed in ANSYS to determine stress levels in the receiver insert. In this analysis, it was assumed that the steel side plate and the steel pins in the plate did not deform significantly relative to the plastic receiver insert. Three steps were used in the analysis.

First, a simplified ANSYS model of the receiver insert was created. It was meshed and a stress was placed on one of the holes in the receiver insert that mated with the metal side plate. The result of this analysis was used to determine stiffness, both vertically and horizontally, for that hole. The analysis was then repeated for all the holes in the receiver insert that mated with the side plate.

An ADAMS model of the side plate was created. The holes were attached to springs whose stiffness values had been derived from the ANSYS analysis. The plate was loaded with a force equivalent to the force of the firing pin head on the sear. When the analysis was run, the plate quickly achieved equilibrium. The forces at each hole were taken from this analysis.

The ANSYS model was loaded using the forces from the ADAMS analysis. At each hole where a load was applied, the nodes in the area where loads were applied were constrained to move together. The analysis was solved using the ANSYS PCG solver.

Creep test fixture. The creep test fixture was constructed from a 710 receiver fitted to a barrel that had been cut off just beyond the chamber. The gun was fitted with a standard 710 action in which the firing pin tip had been replaced with a threaded rod long enough to protrude from the barrel. A five inch long die spring with a spring constant of 45 lbs/in was slipped over the threaded rod, and a washer and nut were used to compress the spring to 3.89 inches. The resultant load was 50 pounds, roughly twice the standard load. The complete creep fixture may be seen in Figure 1.




Figure 1. Creep Test Fixture.

The flat front of the receiver was placed upon a granite table and the distance from the back face of the receiver to the back face of the firing pin head was measured. Figure 2 shows the setup used to measure firing pin protrusion. Figure 3 shows the two locations used for measurement.



Figure 2. Height gauge used to measure firing pin protrusion (fatigue fixture shown)




Figure 3. Closeup of measured area.

The entire fixture was placed in a humidity chamber set for 200° F and 90% relative humidity. At that temperature, the chamber was only able to achieve a relative humidity of around 70%. After the fixture had been in the humidity chamber for three hours, the firing pin head protrusion was measured again. It was then measured twice daily for ten days.

Fatigue fixture. The fatigue fixture was similar to the creep test fixture. It also was constructed from a 710 receiver and parts with a shortened barrel. A threaded rod was turned down and screwed in place of the firing pin tip. A 45 lb/in spring was used to apply 50 pounds of preload as in the creep fixture. A 1 ¼" bore air cylinder was used to press cyclically on the threaded rod, lifting the firing pin head off the sear and letting it drop again. The fatigue test fixture may be seen in Figure 4.




Figure 4. Fatigue Test Fixture.

Like the creep test fixture, the distance from the back face of the receiver to the back face of the firing pin head was measured with a height gauge. The firing pin head protrusion was measured before beginning the fatigue test. It was then measured every 1,000 cycles until 10,000 cycles were performed. The assembly was then disassembled and checked for wear and looseness. The receiver was reassembled with a different action and receiver insert and the test was performed again. This time, care was taken to rotate the firing pin until the firing pin head had seated completely before taking the measurement, something that had not been done during the first test. Seating the firing pin head each time caused the measurements to be more consistent. 10,000 cycles were placed on the new receiver insert, measuring every 1,000 cycles. Then, another 20,000 cycles were placed on the receiver insert and the firing pin head protrusion was measured again. The fixture was disassembled and the receiver insert and fire control parts were checked for wear.

RESULTS

ANSYS analysis. The results from the ANSYS analysis may be seen in Figure 5. The loading in the ANSYS model was based on a constant firing pin spring force of 25.5 pounds. Considerably higher stresses could be expected to occur in the fatigue test from the peak load developed due to the impact between the firing pin and sear when the firing pin was allowed to drop back into place between cycles. Under static loading, peak stress occurred at the back end of the receiver insert and at the sear pin hole. Stresses there

were calculated to be around 1,400 psi, with a strain of 0.2%. The failure criteria for the material are 9,000 psi or 2.4%, whichever comes first.




Figure 5. Von Mises stress distribution through receiver insert. (stress in psi)

Creep test. Figure 6 contains a graph of firing pin protrusion measured during the duration of the creep test. The firing pin protrusion dropped from 0.691 inches to 0.682 inches after the fixture had been in the chamber three hours. After that, the measurements fluctuated in a band between 0.684 inches and 0.6815 inches.




Figure 6. Firing pin protrusion over creep test duration.

Fatigue test. Figure 7 contains a graph of firing pin head protrusion over the duration of the test. In the first test, firing pin head protrusion rose over time. It climbed slowly until 5000 cycles, where it jumped 0.013 inches before leveling off. In the second test, care was taken to rotate the firing pin head back into the same alignment each time the measurement was taken. It turned out to be more consistent, with a low value of 0.693 and a high value of 0.6985 occurring early in the test. After 10,000 cycles had been put on the receiver insert, the fixture was cycled 20,000 more times. The firing pin head protrusion was then measured to be 0.6975 inches.




Figure 7. Firing pin protrusion over fatigue test duration.

Golemboski, Matt R.

From: Keeney, Mike
Sent: Tuesday, February 15, 2000 8:40 AM
To: Golemboski, Matt R.; Zajk, Joseph J
Cc: Diaz, Danny
Subject: 710.xls

Matt/Joe,

Attached is a spreadsheet indicating 710 performance data for the two guns that completed testing last week. There are two malfunction types common to both guns, stem low and misfires.

Misfires -- I had previously designed and prototyped higher energy firing pin springs as backup for the primary spring. I have installed a higher energy spring in both of the test guns and will have Jesse reshoot the test. Copper crusher indents averaged .018" with the new springs, versus approx. .016" with the old springs. I measured the old springs when removed from the test guns, the free length varied .04" between the two and were up to .06" shorter than the spec. Not sure if this was due to "setting" of the springs or the protos varied in free length originally. My plans are to enter DAT with the production sample springs that you have already received. If we see misfire problems during DAT, we will order the higher energy springs for part B testing. Firing pin energy and bolt lift forces are the two items that I am trying to balance, thus the desire to stay away from the higher energy spring.

Stem Low -- When we incorporated the .02" radius on the bottom side of the feed lips for the production box, the feed lip width increased from .417 to .434. The test boxes were at .417". I have opened the test box feed lips to .434 for the retest. Hopefully this will allow the rounds to sit high enough to eliminate the stem low malfunction.

Please review and let me know if you have questions,
Thanks
Mike



710.xls

DATE - 2-7-00 THRU 2-11-00
SHOOTER - JESSE

PROJECT# 241095
TLW 9256C

MODEL 710 FUNCTION / ENDURANCE TEST.

GUN	AMMO	ROUNDS	MALFUNCTIONS	
			STEM LOW	MISFIRE
XC 1071	R30064	300	31	
	R30061	100	1	1
	R3006B	400	7	1
	R30065	700	6	1
	R30063	500	0	0
	TOTAL	2000	45	3

NOTE: HEAD SPACE AT START OF TEST +.003

NOTE: HEAD SPACE AT END OF TEST +.004

NOTE: GUN FUNCTION WAS SMOOTH EXCEPT FOR AMMO - R30064

GUN	AMMO	ROUNDS	MALFUNCTIONS	
			STEM LOW	MISFIRE
XC 1075	R30064	340	15	
	R30061	580		1
	R3006B	480	9	
	R30065	200		
	R30063	400		1
	TOTAL	2000	24	2

NOTE: (528 RDS.) BROKEN FIRING PIN HEAD. REPLACED WITH KNOW OTHER PROBLEMS.

HEAD SPACE AT START OF TEST +.003

HEAD SPACE AT END OF TEST +.005

NOTE: GUN FUNCTION WAS SMOOTH EXCEPT FOR AMMO - R30064

MF0899

Remington Arms Company, Inc.
January 27, 2000

CONFIDENTIAL

Research and Development Technology Center
Elizabethtown, Kentucky

M/710 Cosmetic Review

January 26, 2000

Attendance via Conference Call: D. Diaz, M. Golemboski, A. Russo,
D. Kohler, M. Keeney

The following is an item by item summary of the discussions:

Synthetic Material Color Selection:

The stock, magazine box bottom and magazine follower are the three components in question. In an attempt to differentiate the M/710 from other synthetic stocked guns, the stock color will be gray. To correspond with the stock, the box bottom will also be the same gray and since the box bottom and follower components will be molded in the same tool, the follower will also be the same gray. This will allow for the same material to be used in the molding of all three components, thus the color match should be perfect. R&D has provided a M/597 stock molded in the proposed gray color. Marketing is to determine whether the color match is correct.

We were shipped two variances of gray stocks, one was a light gray and one resembled a slate-gray. When you put a blued barreled action on the slate-gray, it makes the stock almost look black. Considering that the M/710 stock will be larger than the M/597 stock, the light gray stock will be too pronounced in the larger model. We would like to see a sample of a stock that is in between the light gray and the slate-gray. We feel that this will be the optimum color.

Stock Texture:

The M/710 stock texture will be the exact texture provided on one half of the M/597 color sample stock submitted to Marketing, similar to the M/7 texture as well. The texture specification is "Modified MT 11160".

This works!

Box Bottom Artwork:

The box bottom will have "Remington" oriented vertically along the full length of the box bottom. There will be a recessed and textured rectangular area enclosing raised "Remington" lettering. The font will match the 2000 price list font, sized accordingly to fit the box bottom. A reveal line will be added at the intersection of lettering insert and the main body of the molding tool to cover potential mismatch of the insert and tool. This will work, however:

Need to consider some texturing on the externally exposed sides of the magazine box, as well as, tapering of the stock in toward the magazine where the relief cuts are located. This will naturally draw one's fingers (especially with gloves on - we tested this) inward to the sides of the textured magazine box and cause the individual to grasp the textured

Michael D. Keeney
Staff Engineer

Page 1 of 3: CONFIDENTIAL

MF0900

Remington Arms Company, Inc.
January 27, 2000

CONFIDENTIAL

Research and Development Technology Center
Elizabethtown, Kentucky

sides with their thumb, middle, ring and little finger while depressing the release with their pointer finger.

On a similar note to the raised lettered 'Remington', can we have a molded "R" on the grip cap? This should be similar to the magazine box bottom with a recessed area and raised "R". Also, the grip cap has a sharp edge and should be a little more tapered to the flat bottom.

Barrel Markings:

Will follow the exact layout and fonts of the M/700 with the exception of "Made in Mayfield KY". OK

Receiver Markings:

Will follow the exact layout and fonts of the M/700 with the exception of "710" in place of "700". After looking at the receiver, there is quite a bit more room. We can use the same style fonts but, we can enlarge the size by 2 - 4 (if is currently a 10, we could make it a 12 or 14). Additionally, the layout on the M/700 is very close to the receiver/stock line. This could be moved up slightly so that "Model 710" does not appear to be partially covered by the stock.

Bolt Handle Knurl:

The bolt handle will have two circular knurled regions, one on the top and one on the bottom of the ball. The knurl pitch will be the same as the M/700 bolt handle.

OK

Marketing Questions

Can the magazine for the 710 come apart for cleaning purposes?

What is the degree of angle that the bolt must travel to go from engaged to disengage (for instance, a Browning A-Bolt's bolt travel is 60 degrees)? Please keep in mind that this gun will also be used with a scope. If the bolt travel is too outwardly canted from the stock and travels too much, it will interfere with the shooter cycling rounds with a mounted scope. The shooter should be able to cycle rounds while looking through a mounted scope with no interference from the motion of the bolt.

Is the entire bolt going to be blued? If so, what type of wear will occur on the bolt and it's bluing from riding in the plastic guides? What kind of wear and/or life (# of rounds) can be expected from the plastic guide rails? Are the guide rails replaceable? By a RARC or by a consumer?

Michael D. Keeney
Staff Engineer

Page 2 of 3: 5.22.06r0010851

MF0901

Remington Arms Company, Inc.
January 27, 2000

CONFIDENTIAL

Research and Development Technology Center
Elizabethtown, Kentucky

Also on the bolt, if an individual want to disassemble it, will they need a special tool?
I've also noticed that there isn't a cocking indicator on the bolt. One can't tell if there's a
live round in the chamber or if the gun has been fired. This is a safety concern. Your
thoughts on this would be appreciated.

Trigger: will the trigger itself be blued or chrome? Will it be adjustable?

Same question on the safety, blued or chrome? Can we use a safety similar to the top part
of a M/700 that your thumb comes into contact with when moving into fire or safe
positions.

Scope rails: will we be able to supply a base in the first year that we introduce the M/710?
Is this something that we need to help the accessories group develop? We need to have
one.

On the bottom of the gun there are three screws. Two have the same Allen head and one
is different. Can we have all three the same so that only one Allen wrench or bit would
be needed? If they were all interchangeable that would be great if that is not possible due
to threads or lengths, let's at least make the head use the same Allen wrench.

Lastly, let's talk about the LOP for the stock. If we made the stock to have a 13 1/2" LOP
(minus the thickness of the recoil pad) then from that mold would we be able to make a
youth stock? However, if we made the stock in the mold so that we could outfit it with a
recoil pad for either an adult (greater thickness of recoil pad and/ or a spacer) or a recoil
pad for a smaller framed individual (a youth or a female), we would have much more
flexibility in making alterations. Additionally, we wouldn't use as much material in
making the stock and hopefully would obtain cost savings. Again, your thoughts are more
than welcome in addressing this and all of the above topics.

Please let me know at your earliest convenience.

Thanks,

Drew

Michael D. Keeney
Staff Engineer

Page 3 of 3

MF0902

Remington Arms Company, Inc.
January 27, 2000

CONFIDENTIAL

Research and Development Technology Center
Elizabethtown, Kentucky

M/710 Cosmetic Review

January 26, 2000

Attendance via Conference Call: D. Diaz, M. Golemboski, A. Russo,
D. Kohler, M. Keeney

The following is an item by item summary of the discussions:

Synthetic Material Color Selection:

The stock, magazine box bottom and magazine follower are the three components in question. In an attempt to differentiate the M/710 from other synthetic stocked guns, the stock color will be gray. To correspond with the stock, the box bottom will also be the same gray and since the box bottom and follower components will be molded in the same tool, the follower will also be the same gray. This will allow for the same material to be used in the molding of all three components, thus the color match should be perfect. R&D has provided a M/597 stock molded in the proposed gray color. Marketing is to determine whether the color match is correct.

Stock Texture:

The M/710 stock texture will be the exact texture provided on one half of the M/597 color sample stock submitted to Marketing, similar to the M/7 texture as well. The texture specification is "Modified MT 11160".

Box Bottom Artwork:

The box bottom will have "Remington" oriented vertically along the full length of the box bottom. There will be a recessed and textured rectangular area enclosing raised "Remington" lettering. The font will match the 2000 price list font, sized accordingly to fit the box bottom. A reveal line will be added at the intersection of lettering insert and the main body of the molding tool to cover potential mismatch of the insert and tool.

Barrel Markings:

Will follow the exact layout and fonts of the M/700 with the exception of "Made in Mayfield KY".

Receiver Markings:

Will follow the exact layout and fonts of the M/700 with the exception of "710" in place of "700".

Bolt Handle Knurl:

The bolt handle will have two circular knurled regions, one on the top and one on the bottom of the ball. The knurl pitch will be the same as the M/700 bolt handle.

Michael D. Keeney
Staff Engineer

Page 1 of 1

Cosmetic Issues Results 01-26

MF0903

Confidential - Subject to Protective Order
BARBER - 5.22.06r0010853
Williams v. Remington

Golemboski, Matt R.

From: Jiranek, Marlin R.
Sent: Friday, January 21, 2000 1:03 PM
To: Keeney, Mike
Cc: Golemboski, Matt R.; Zajk, Joseph J; Danner, Dale; Urbon, James E
Subject: M/710 Issues

After the meeting, here are the things I committed to do:

- 1.) Material spec for the M/710 barrel steel
 Will be training Jim Urbon on writing the specifications and this will be his first one. This should be completed by Jan 28.
- 2.) Material Spec and Material Code database for use of all specs and codes from Mayfield to be set up on the server.
 Working on the plan. Will need a format for the material codes from Joe Zajk and E-mail copies of all codes and specs that Mayfield is currently using. Also, I need a copy of the Excel sheet currently being used to log design or drawing changes (which we talked about Matt). (THIS IS THE REQUEST FOR THAT INFORMATION)
- 3.) Recoil Bracket - use of 1008 material rather than the 1010-1020 material specified
 OK, figure on a 2-5% decrease in mechanical properties across the board, with the exception of a 2-5% increase in ductility.
- 4.) Inspection criteria for material specifications - what should be done
 Working on it. Will have something for you by Jan 26.
- 5.) Mechanical property comparison of switching from 1215 to 12L14 material for the firing pin body
 OK, the leaded (0.15% - 0.35% Pb) steels (10XX, 11XX and 12XX) can be used across the board as a substitution for the standard material. There is little or no effect on the mechanical and fatigue properties of the material and the machinability and surface finish quality go up significantly. The material typically costs about 5-10% more, but can be cost effective due to the higher speeds the machining can be done at. There will not be any cost advantages if the machine tools are already being operated at maximum speed. This should probably be looked at across the board for parts requiring alot of machining (parts requiring >10% by weight machining removal).
- 6.) Firing pin head - FEA of torsional loading on MIM (either 46XX series heat treated or Fe2%Ni unheat treated) part and subsequent failure examination of the material (Instron Testing)
 Passed on the FEA assignment to H. Davidson and B. Rages. They should have some results in a couple of weeks. Currently looking into getting some MIM material samples and designing a fixture for the testing portion of the process. The fixture design should be complete by end of January.
- 7.) Magazine Spring Heat Treatment for the stamping vendors - they are afraid that the spring will return to the straight condition during the heat cycle.
 The springs done in Ilion are done in this manner without any real distortion issues: Basically, form the material for the raw strip (usually spheritized 1070 or 1090 or something) and then heat treat. Heat treatment should be Austemper and the springs should be laid flat in baskets. Final part hardness should be HRc 47-52 or equivalent. They will not straighten out, they are not shape memory alloy.

If anyone has any questions, please let me know.

Marlin.

Marlin R. Jiranek, II
 Research Engineer
Remington Arms Company, Inc.
 Phone: (270) 769-7645
 FAX: (270) 737-9576
 E-mail: jiranekmr@etown.remington.com

Golemboski, Matt R.

From: Zajk, Joseph J
Sent: Sunday, January 16, 2000 5:37 PM
To: Keeney, Mike
Cc: Golemboski, Matt R.
Subject: 710 Safety

Importance: High

Mike,

Who in Marketing needs to give the blessing to the 710 safety arm? Right now that part is rapidly becoming the constraint in making our end of May/beginning of June T&P schedule. The lead time is 18-20 wks for delivery of first production parts.

Let me know who we need to talk to in order to try to put some pressure on them from our end.

Joe Z.

CONFIDENTIAL 83

M/710 Weekly Progress Report – Week ending 1/14/00

	Actual	Budget
Capital Dollars Spent (Total Project)		\$2,350,000
Capital Dollars Committed Dollars (Total Project)	\$559,594	
Pre-op Dollars Spent (Total Project)		\$414,000
Capital Dollars Spent (month to date)		
Capital Dollars Committed Dollars (month to date)	\$121,750	
Pre-op Dollars Spent (month to date)		
T&P Date (estimated build completion date)	6/9/00	5/30/00
Product Price	\$93.33	\$92.79

- Product price as of information at close of business 1/14/00. Price includes \$42 for 1st year amortization of Par 4 drilling fixture.
- T&P date pushed out as a result of delay in getting safety arm tool ordered. Current lead time 18-20 wks, which puts us in the end of May for part delivery. Delay is Marketing. Safety arm is currently the constraint.
- Capital does not include Welduction Induction Hardening Machine, as P.O. was not issued on Friday.

MF0906

Golemboski, Matt R.

From: Zajk, Joseph J
Sent: Sunday, January 16, 2000 5:33 PM
To: Golemboski, Matt R.
Subject: M/710 Weekly Progress Report



710 Progress Report -
Week End..

CONFIDENTIAL 83

Golemboski, Matt R.

From: Zajk, Joseph J
Sent: Saturday, January 15, 2000 3:20 PM
To: Cook, Todd D.
Cc: Keeney, Mike; Golemboski, Matt R.
Subject: 710 Stock Issues

Importance: High

Sam Todd talked with me late yesterday afternoon concerning a couple of issues with the 710 stock. They are:

- **The changes in the magazine box area:** According to Sam Todd, Quality Tool still needs the updated electronic files for the changes outlined last week by you and Mike. They need the updated IGES files no later than the end of Tuesday in order to keep on track.
- **Magazine Latch Pin Retainer Core:** According to Sam, the folks at Quality Tool believe there will be a problem with the undercut or "wrap" that retains the mag latch pin as its currently modeled. They think there's too much undercut and they will deform material when the core pulls. Sam left me a drawing from Quality Tool that sort of shows what they mean. I'll fax it to you so you can take a look at it.

Both of these issues have to be addressed promptly in order to make sure the tool build progress stays on track. Please find out what you can as quickly as possible. Let me know if I can be of any assistance.

Joe Z.

CONFIDENTIAL 83

Confidential

Remington Arms Co.

Memo

To: 710 team
From: Matt Golemboski
CC: Joe Zajk
Date: 12/10/99
Re: M/710 Meeting

I would like to hold a 1:00pm meeting on Dec.10. Be prepared to discuss the following items:

	Topic	Completion Date	Delivery Date
Barrels:	Is material ordered through Ilion Heat Treat Schedule	12/16/99	
Bolt Head	Machining Schedule Grinding Schedule	12/16/99 12/31/99	
Bolt Handle	Finished Print Order Tool		
Bolt Plug	Order Tool	12/14/99	3-20-2000
Firing Pin Head	Order Block of Material Order Tool	12/20/99 1/25/99	
F. Screw Bush	Material Samples		
Magazine Latch	Material Cancel Par 4 PO	12/10/99	
Magazine Box	Order 500 at \$13.17 each Mayfield Cost Etown pay \$12,500 tooling charge	12/13/99	10/99
Range	Design PO and Start Expected Design Completion	12/10/99 1/31/99	1/20/99
Ultra Sonic Welder	Shipment from Ilion	12/1/99	

Confidential

Remington Arms Co.

To: Mike Keeney; D. Diaz

From: Matt Golemboski

CC: Joe Zajk

Re: M/710 Vendor Tooling

Date: 12/10/99

M/710 RELEASE OF CAPITAL TOOL BUILD

We are at the point some tooling must be ordered to maintain schedules. Below is a list of the tooling and what the current state of the design, and preferred vendor name and contact. Some of the parts do not have a firmed design. Tool build can not begin until the design is completed. I would suggest R&D and Mayfield jointly contact the preferred vendor for each part, in order to keep cost controlled during the final during the finalization of the design.

Trigger C-15280

Vendor: Sterling Sintered

Contact: John Bartrum

Phone: 860-379-2753

The best casting to date does not include the serrations on the finger radius of the trigger. A print must be generated to order tooling. Once the drawing is issues tool build will begin immediately.

Safety D-300408

Vendor: New Hampshire Stamping

Contact: John Maffco

Phone: 603-641-1234

The texture on the top of the part has not yet been defined per marketing request.

Bolt Stop D-300345

Vendor Sterling Sintered

Contact: John Bartrum

Phone: 860-379-2753

Assume design is complete, with the exception of material change to MPIF standards. Tool will be released for build by 12/20/99. Impact of design change will be a scrapped tool.

Confidential

Remington Arms Co.

Bolt Handle Blank C-300360

Vendor: North American Precision Casting

Contact: William Sommerville

Phone: 662-245-1155

Design requires knurling as per marketing request. Print should define parting line location and acceptable size notes, as well.

Bolt Plug C-300368

Vendor: Kellums and Coe

Contact: Kenny Ulrich

Phone: 812-283-4435

Design is complete. Texturing not specified, assume EDM finish. PO to be issued by 12/15/99.

Tumbler Blank D-300420

Vendor: PMPd

Contact: Matt Marley

Design is complete and ready to issue to tool build. Will be issued by 12/31/99.

Firing Pin Head C-300336

Vendor: Megamet Industries

Contact: Jim Mullineaux

Phone: 314-739-4499

MIM Blocks for DAT testing are being made. Paramatech will not quote on lower volume, 20,000 units. The lead-time prohibits waiting until February for testing. With a material change to MPF standards, Mayfield will then assume design is complete and will start tooling by 1/10/00.

Stock Dwg-xxxxxx

Vendor: Par 4

Contact: Sam Todd

Phone: 502-965-9141

Tool has been issued for build. Model to be revised by 12/10/99 for new coring to accommodated the M/700 grip cap. Method of attachment has will be press fit at molding time of the stock. The assumption is no alteration of the grip cap will be required for this fit.

Confidential

Remington Arms Co.

Magazine Latch C-300362

Vendor: Par 4

Contact: Sam Todd

Phone: 502-965-9141

Tool issued and canceled. Design on hold to convert to metal part. Powder metal option with Sterling Sintered was a quote. Suggested a die cast or investment cast or MIM. PM is an option but print must be made specific for PM.

Magazine Box E-300363

Vendor: Brainin

Contact: Richard Lee

Phone: 513-874-5486

Prototypes to be Released 12/10/99, 500 piece lot, DAT and T&P run. Upon first week of DAT testing the Production too will be released for build.

Magazine Follower D-300364 and Magazine Bottom D-300365

Vendor: Par 4

Contact: Sam Todd

Color not yet approved by marketing. Material must be common to both on the family mold. Follower is complete. The box bottom is not defined for artwork. This will impact the insert sizing. Design and build to be released by 12/10/99. Build will be conditional of artwork approval on the magazine bottom.

Magazine Spring C-300405

Vendor: Brainin

Contact: Richard Lee

Phone: 513-874-5486

Design is complete. PO will be issued by 12/31/99.

Confidential

Remington Arms Co.

Memo

To: 710 team
From: Matt Golemboski
CC: Joe Zajk
Date: 12/06/99
Re: M/710 Magazine Latch Tool

The M/710 magazine latch tool was approved for build on 12/2/99. The tool will be purchased through Par 4 with an 16-week lead-time to the completion of the tool. Sam Todd assured me the press time will be available and the lapse between the tool build completion and sampling will be within 2-3 days afterward. Piece price of \$0.245 each for 20,000 and \$31,806 for the tool. No texturing is required on the part.

No guarantee on the parting lines was given.

As of 12/6/99, Mayfield will quote the part as a Powder Metal part through Sterling Sintered. Joe has overnighed the drawings and specs to look at the possibility of a powder metal part with material the same as the 597 latch for non-heat treated and same as the barrel clamp for heat treated options. This will require Sterling to complete a secondary drill operation. The powder metal option is being pursued in case the plastic latch wears quickly, a concern brought forward by Mike Keeney on 12/6/99.

The Par 4 will be put on hold on 12/13/99 if we do not have a decision from Sterling by this time. Mett will notify Sam Todd of Par 4 to inform him of a potential changes and we will have the PO held until 12/13/99.

Assembly cost of the latch and spring to the stock will be quoted at a later date.

MF0913

Elizabethtown Research Division

PARTS LIST #YYY

Date: **Model 710**

Supersedes Previous Model XXX

12/02/99 **Bolt Action**

Parts List #AAA

Centerfire Rifle R.H.

Sheet 1 Dotted line (- - -)
 of 2 indicates same part number 30-06 270 7mm 300
 Rem Mag Win Mag

DWG. NO.	PART NAME	PART NUMBERS
----------	-----------	--------------

RAMAC #**DOCUMENT ENVELOPE ASSEMBLY**

Document Envelope	XXXX	----	----	----
Instruction Book	1649	----	----	----
Product Owners Card	XXXX	----	----	----
Remington Authorized Gunsmith	1426	----	----	----
Safety Booklet	3413	----	----	----
Remington Museum Flyer	3499	----	----	----
Oval Label	3475	----	----	----
	3491	----	----	----

CARTON ASSEMBLY

Box & Envelope Label	993002	----	----	----
(Label To Read "Model 710")				

NOTE: THE ABOVE PARTS ARE FOR PACKAGING ONLY

C-305410-	BARREL ASSEMBLY COMPLETE	305410	305411	305412	305413
C-305400-	BARREL ASSEMBLY	305400	305401	305402	305403
E-305315-11	BARREL	305315	305316	305317	305318
E-300340-8	RECEIVER	300340			
D-300401-A	RECEIVER INSERT ASSEMBLY COMPLETE	300401			
C-300400-	RECEIVER INSERT ASSEMBLY	300400			
1E-300327-17	RECEIVER INSERT	300327			
2E-300327-29					
A-300347-A	THREADED INSERT	300347			
C-300333-5	SIDE PLATE	300333			
A-300328-1	SIDE PLATE PIN (2)	300328			
C-15666	SEAR SAFETY CAM (Blk. 91921)	15666			
B-300351-	PIVOT PIN (3)	300351			
A-17047	SEAR SPRING	17047			
C-15280	TRIGGER (Blk. C-91912)	15280			
C-19461	TRIGGER CONNECTOR (Blk. C-91922)	19461			
B-17053	TRIGGER SCREW FRONT (Blk. B-91920)	17053			
B-91128	TRIGGER ENGAGEMENT SCREW (Blk. B-91922)	91128			
A-15400	TRIGGER SPRING	15400			
A-300426	TRIGGER STOP SCREW	300426			
D-300408-7	SAFETY	300408			
B-17043	SAFETY PIVOT PIN (Blk. B-91918)	17043			
B-17044	SAFETY SNAP WASHER (Blk. 200042)	17044			
B-300407-1	SAFETY SPRING	300407			
C-300345-8	BOLT STOP	300345			
B-17034	RECEIVER PLUG SCREW (4)	17034			
B-300361-	RECOIL BRACKET	300361			
B-300403-	BOLT BODY ASSEMBLY	300403			
C-300339-5	BOLT BODY	300339			
C-300370-	BOLT HANDLE	300370			
C-300360-	BOLT HANDLE BLANK	300360			
A-300329-2	BOLT HANDLE PIN	300329			
B-305390-2	BOLT HEAD ASSEMBLY	305390	305391		
E-300338-17	BOLT HEAD (30-06, 270)	300338			
C-300416-	BOLT HEAD (7mm Rem, 300 Win)		300416		
D-300424-	BOLT HEAD BLANK	300424			
C-93712	EXTRACTOR				
C-97322	30-06, 270 (Blk. 93711)	93712			
C-27340	7mm Rem, 300 Win (Blk. 97321)		97322		
B-300342-1	EXTRACTOR RIVET		27341		
A-300367-	EJECTOR	300342			
A-94555	EJECTOR SPRING	300367			
B-300330-	EJECTOR PIN	94555			
B-300404-A	BOLT ASSEMBLY PIN	300330			
C-300368-4	FIRING PIN ASSEMBLY	300404			
B-300346-	BOLT PLUG	300368			
B-300418-	BOLT PLUG INSERT	300346			
D-300420-A	TUMBLER	300418			
	TUMBLER BLANK	300420			

MF0914

Elizabethtown Research Division

PARTS LIST #YYY

Date: Model 710

Supersedes Previous Model XXX

12/02/99 Bolt Action

Parts List #AAA

Centerfire Rifle R.H.

Sheet 2 Dotted line (- - -)
 of 2 indicates same part number

30-06 270 7mm 300
 Rem Mag Win Mag

DWG. NO.	PART NAME	PART NUMBERS			
C-201224	LOCK PLUNGER (Blk. 201223)	201224	----	----	----
	FIRING PIN ASSY CONTINUED				
A-201217	LOCK SPRING	201217	----	----	----
A-300427	SPRING RETAINER	300427	----	----	----
C-300334-A	FIRING PIN	300334	----	----	----
C-300335-2	FIRING PIN TIP	300335	----	----	----
C-300336-B	FIRING PIN HEAD	300336	----	----	----
A-300399-D	FIRING PIN SPRING	300399	----	----	----
	FRONT SIGHT				
C-15373	30-06, 270 (Blk. C-90393)	94084	----	----	----
B-14659	7mm REM, 300 WIN			94095	----
B-28510	FRONT SIGHT RAMP (Blk. B-16724)	94657	----	----	----
B-28505	FRONT SIGHT RAMP SCREW (2) (Blk. 90347)	28505	----	----	----
B-103145	REAR SIGHT ASSEMBLY	103145	----	----	----
A-90906	ELEVATION SCREW	90906	----	----	----
C-93905	REAR SIGHT ADJUSTURE (Blk. C-93906)	94333	----	----	----
C-103530	REAR SIGHT BASE (Blk. 94023)	103530	----	----	----
C-93904	REAR SIGHT SLIDE (Blk. C-93907)	94335	----	----	----
B-90904	WINDAGE SCREW (Blk. 91911)	90904	----	----	----
B-28505	REAR SIGHT BASE SCREW (2) (Blk. 90347)	28505	----	----	----
B-305455	STOCK ASSEMBLY COMPLETE	305455	----	----	----
	STOCK				
B-15161	FRONT SCREW BUSHING (Blk 91915)	15161	----	----	----
C-97971	GRIP CAP	97971	----	----	----
D-97973	RECOIL PAD	97973	----	----	----
C-97972	RECOIL PAD BACKER	97972	----	----	----
A-98008	RECOIL PAD SCREW (2)	98008	----	----	----
C-300362-4	MAGAZINE LATCH	300362	----	----	----
B-300398-B	LATCH SPRING	300398	----	----	----
B-300371-A	LATCH PIVOT PIN	300371	----	----	----
B-300096	SLING SWIVEL STUD (2)	300096	----	----	----
C-104125	FRONT TAKE DOWN SCREW (Blk. 104141)	104131	----	----	----
C-104125	MIDDLE TAKE DOWN SCREW (Blk. 104143)	104133	----	----	----
B-300425-	REAR TAKE DOWN SCREW	300425	----	----	----
B-305395-	MAGAZINE ASSEMBLY	305395	----	----	----
E-300363-9	MAGAZINE BOX	300363	----	----	----
D-300364-4	MAGAZINE FOLLOWER	300364	----	----	----
D-300365-8	MAGAZINE BOTTOM	300365	----	----	----
C-300405-	MAGAZINE SPRING	300405	----	----	----

MF0915

Golemboski, Matt R.

From: Zajk, Joseph J
 Sent: Monday, December 06, 1999 6:55 PM
 To: Cook, Todd D.
 Cc: Diaz, Danny; Keeney, Mike; Golemboski, Matt R.
 Subject: RE: Model 710 Core Issues

Importance: High

Todd,

Here's a quick summary about what we discussed today and the paths we're pursuing:

- Options 1 & 2 are not viable options
- We will investigate options 3 & 4; in particular we need to see if a 700 grip cap, modified to fit in a 710, will still satisfy the requirements for the 700 stock

We are going to do some experimenting and investigation into the option 3 grip cap modification to see if its viable. If so, we will then need to weight the cost of modifying an existing tool vs. building a whole new one. This will require input from Mayfield, E'town and Ilion as to its viability. If you have any insight as to whether this is a good idea, please let me know.

In conclusion, as it stands now, we are only pursuing those options that give us the optimal coring for the 710 stock, with an emphasis on trying to find a modified 700 grip cap geometry that satisfies both 700 & 710 stocks in order to limit the amount of unplanned capital required. Any info on Ilion's grip cap/stock assembly process that you can offer will be of great help, as Ilion's knowledge base might be temporarily somewhat degraded now that Jeff Swanson is no longer with Remington. We will be attempting to gather as much information as we can from Ilion as well.

Joe Z.

-----Original Message-----

From: Cook, Todd D.
 Sent: Friday, December 03, 1999 3:54 PM
 To: Zajk, Joseph J
 Cc: Diaz, Danny; Keeney, Mike
 Subject: Model 710 Core Issues

Joe,

I know that you will be talking about these issues next week early, but I wanted to give you a heads up on the Model 710 core issue. We still have the potential problem of a thin steel condition with the coring as designed. The issue falls out to a number of choices:

1. Use the current grip cap and have a steel condition that is not ideal. (The thin area in the mold may occasionally have to be repaired).
2. Use the current grip cap and fix the thin steel condition leading to bad sink problems and part distortion in the grip area. No core would be left in the area where your right hand would grip (for a right handed shooter).
3. Use the current grip cap, but sand off part of it so that both the sink and the thin steel condition in the grip area can be eliminated. (The same thing may be able to be accomplished with a new core or core modification in the existing grip cap mold for slightly more \$ but not as much as new grip cap mold)
4. Build a new mold for a grip cap that is idealized for this application, which reduces the piece cost, but drives up the capital needs.

None of these options is ideal, but I feel certain that with some discussion you can arrive at the one that makes the most sense for your current needs. My advice is option 3 to get started and not cause extra expense. It also seems to be more durable and better for cooling. There are other advantages to the current lay out as well like minimizing sink from the screw bosses for the recoil pad. In short, I think option three is best. You may be able to see issues with it, though. I am sending you some pictures (Mike will bring them) that show the cores for these options. They are labeled for the options from this E-mail. Hopefully, they will help you see what I was up against. Anyway, if you guys need more info, I will do whatever I can.

Todd

CONFIDENTIAL

83

100-106-CHARTS

MF0917

Remington Arms Company, Inc
 Mayfield Plant
 22 Rifle Trail
 P O Box 99
 Hickory, KY 42051
 Phone: (270) 856-4200
 Fax (270) 856-3233

Remington.

Fax

To: MIKE LOONEY From: MATT G.
 Fax: _____ Pages: 2
 Phone: _____ Date: 5/22/06
 Re: _____ CC: _____

☐ Urgent ☐ For Review ☐ Please Comment ☐ Please Reply ☐ Please Recycle

• Comments:

PLEASE REVIEW
 I AM LISTING REVERSED SERIAL
 COUNTERS & THOUGHT THIS MAY LOOK
 BEST BUT IS THE MOST DIFFICULT TO
 MAKE - SMYIS INC. CALL ME

Matt

MF0918

Remington Arms Company, Inc.
 Mayfield Plant
 22 Rifle Trail
 P O Box 99
 Hickory, KY 42051
 Phone: (270) 856-4200
 Fax: (270) 856-3233

Remington.

Fax

To: GORDON DILL From: MATT GOLEMBOSKI
 Fax: 662 245 155 4/6/97 Pages: 5
 Phone: _____ Date: 6/10/00
 Re: _____ CC: _____


☒ Urgent ☐ For Review ☐ Please Comment ☐ Please Reply ☐ Please Recycle


• Comments:

ATTACHED PLEASE FIND YOUR ORIGINAL
 SKETCH TO ME WITH .015 WIDTH CONSTANT &
 DEPTH CHANGING AROUND THE RADIUS. ALSO, FIND OUR
 MODEL OF THE SAME - DATA.


MF0919

Confidential - Subject to Protective Order
BARBER - 5.22.06/0010870
Williams v. Remington





MF0921



MF0922



CONFIDENTIAL 83

MF0923



Remington Arms Co., Inc.
R&D Technical Center
315 W. Ring Road
Elizabethtown, KY 42701

Phone: 270-769-7600
Fax: 270-737-9576

Date: 6/5/00

No. of pages including cover sheet: 2.

Please note our new area code.

TO:

From:

Max G.

Mike R.

Phone

Fax Phone

CC:

Phone

Fax Phone

REMARKS:

☐ Urgent

☐ For your review

☐ Reply ASAP

☐ Please comment

*6/7/00 BOB HARVEY KNOWLEDGE - I WILL COPY EXACTLY FOR M/710.
FORWARDED TO THE CASTING, VENDOR.*

Mike

--The information contained in this FAX is confidential and/or privileged. The FAX is intended to be reviewed initially by only the individual named above. If the reader of this transmittal page is not the intended recipient or a representative, you are hereby notified that any review, dissemination or copying of this FAX or information contained herein is prohibited. If you have received this FAX in error, please immediately notify the sender or salesperson and return this FAX to the sender at the above address. Thank you.

MF0924

Confidential - Subject to Protective Order
BARBER - 5.22.06 0010874
Williams v. Remington

Remington Arms Company, Inc
 Mayfield Plant
 22 Rifle Trail
 P O Box 99
 Hickory, KY 42051
 Phone: (270) 856-4200
 Fax: (270) 856-3233

Remington.

Fax

To: Bill Somerville From: Matt Golemboski
 Fax: _____ Pages: 2
 Phone: _____ Date: _____ 83
 Re: _____ CC: _____
☐ Urgent ☐ For Review ☐ Please Comment ☐ Please Reply ☐ Please Recycle

• Comments:

ATTACHED THE PHOTO OF THE KNIFE
 IT WILL BE SHIPPED OVER A .640 DIAMETER
 RAIL IN THE HANDLE. PLEASE SEND A
 NOTE FOR THE REVISION. THANKS

Matt

MF0925

1. TOLERANCE DIMENSIONS SHALL BE TO THE FOLLOWING UNLESS OTHERWISE NOTED:

1. DIMENSIONS ON DECIMAL DIMENSIONS ARE TO BE: (1) - TOLERANCE $\pm .015$ (2) - TOLERANCE $\pm .010$ (3) - TOLERANCE $\pm .005$

2. DIMENSIONS ON FRACTIONAL DIMENSIONS $\pm .004$

3. ANGULAR DIMENSIONS $\pm .00^\circ$ 30'

4. DIMENSIONS ARE DECIGRATED BY ROOT MEAN SQUARE (RMS) SURFRO-TOUCH SMOOTHNESS (S) MEASURING THE PRAISE MANUFACTURED TO THE CLOSEST DIMENSION SPECIFIED.

5. DIMENSIONS TO BE $\pm .000$ ON DESIGN

REPAIRS TO BE DONE BY REMINGTON

HARDNESS - B-8-95


COLOR - RESTORED

LEAF TRAIL - ANADDED

GENERAL - WASH C 105C

1. ADDED

2. Added Use




SECTION B-B

VENIDORS USE ONLY

NO. KHL 1243. THE SUPPLIED

-100 KAD, LEF.

2. 2




DETAIL OF CHECKERING — 10X

MF0926



The Hanson Group, Ltd.

A United Plastics Group Company



Fax Cover Sheet
(www.hansonltd.com)

Date: 4/4/00

2 Pages (including cover)

To: Joe Zajak

From: John Rego

Company: Remington Arms

Fax: 271-856-3233

Phone:

Please return fax transmission to:

- ☐ Corporate (413) 589-7552
☒ Tooling (413) 589-0761
☐ Molding (413) 547-6167

☐ URGENT

☐ FOR REVIEW

☐ F.Y.I. ONLY


☐ PLEASE REPLY

Comments:

P.O. Box 789 • Ludlow, MA 01056-0789 • (413) 589-0534

MF0927

Confidential - Subject to Protective Order
BARBER - 5.22.06r0010877
Williams v. Remington



QUOTATION NO 990118-2010-15
DATE April 4, 2000
TERMS Net 30 Days

TO Mr. Jim McCollum
REMINGTON ARMS CO., INC.
315 West Ring Road
Elizabethtown, KY 42701-9318

REFERENCE: **Receiver Insert, #1E-3000327**

We are pleased to quote you as follows:

Mold 9,000 parts in Black Nylon 66 RTP299X82691GF using customer supplied single cavity tool with IQC process control @64 second cycle time:

\$3,380.43/M

Mold 9,000 parts in Black Nylon 66 RTP299X82691GF using customer supplied single cavity tool with IQC process control @ 74 second cycle time:

\$3,756.60/M

Mold 9,000 parts in Black Nylon 66 RTP299X82691GF using customer supplied single cavity tool with IQC process control @ 84 second cycle time:

\$4,132.77/M

- Quote is based on minimum run of 1,500 units.
- Molding prices are based on current raw material costs. Changes in raw material costs may affect molding prices.
- Quoted prices are based on supplied quantities. Changes in quantities will affect prices.
- FOB Ludlow, MA Freight Collect

cc: Joc Zajk, 270-856-3233
T (270) 769-7600
F (270) 737-9576

We await your reply and assure you of our best attention and services at all times.

(Quote valid for 30 days.)

Subject to the terms and conditions on the reverse side hereof.

Eugene Tabarovsky
Corporate Engineering Manager

CLIENT COPY

F03.005SQ

Rev. Level B

Revised: 01/26/99

MF0928

Golemboski, Matt R.

From: Morgan, Metty E.
Sent: Tuesday, March 14, 2000 9:38 AM
To: Zajk, Joseph J
Cc: Golemboski, Matt R.; Chamblee, Danny
Subject: Master Data for 710 Steel

03/14/2000

Joe,

Someone needs to enter the master data for the 710 Steel. I believe the part number is F300447 per parts list.
Information as follows:

24" per barrel
Wt. per barrel is 8.8175# ea.
12ft 6" bar weighs 55#
9000 710 guns will require around 82,000 # of this steel, I will order in 20,000# increments with the first delivery in late June.
Cost for steel is \$ 62.00 per 100 pounds (cwt.)

I believe there is a conversion area somewhere in the master data, (Danny knows where) We will need to put the # to ft. conversion in there. The 1137 steel is set-up per ft., but is ordered per #, and the SAP system converts it. We should probably set the 710 steel up the same way. I will place the PO for the steel as soon as you have completed this task.

Thanks,
Mett

Golemboski, Matt R.

From: Zajk, Joseph J
Sent: Wednesday, March 15, 2000 4:53 PM
To: Keeney, Mike
Cc: Golemboski, Matt R.; Diaz, Danny
Subject: 710 Firing Pin/Firing Pin Tip

Mike,

After some discussions here we were wondering if there might be some way to avoid having an assembly dimension for the firing pin tip/firing pin. We were thinking about the following possibilities

- Could the firing pin tip be modified slightly in the back to give a larger shoulder to bear on the firing pin (and the firing pin c'bore adjusted accordingly)? Could this increased diameter of the firing pin at the back be swept so that the increased diameter remains contained inside the firing pin c'bore so we don't have to worry about tolerance stack and potential interference with the firing pin hole in the back of the bolt head?
- Another possibility might be to shrink the thread down one size (say #5-40) to give more bearing surface on the shoulder.

I know there's not a lot of room to work with. Let me know what you think.

Thanks,

Joe Z.

CONFIDENTIAL 83

Golemboski, Matt R.

From: Keeney, Mike
Sent: Wednesday, March 15, 2000 12:36 PM
To: Morgan, Metty E.
Cc: Diaz, Danny; Golemboski, Matt R.; Zajk, Joseph J
Subject: 710 firing pin springs

Mett,
I received the rush order firing pin springs from Industrial, inspected the lengths and force values and they were right on.
Jeff Wade forwarded the shipper to you so that you could receive them into SAP.

Thanks
Mike

CONFIDENTIAL 83

Golemboski, Matt R.

From: Keeney, Mike
Sent: Wednesday, March 15, 2000 12:33 PM
To: Zajk, Joseph J
Cc: Diaz, Danny; Golemboski, Matt R.
Subject: M/710 Firing pin assembly

Joe,

After assembling the firing pins this morning, I measured from the shoulder to the end of the tip to verify the tips were seated completely. Model drawing tolerance is 1.167 to 1.183 for the assembly. My measurements were 1.158 to 1.168. I measured the extra firing pin tips (1.275) and they were within tolerance. When I attempted to measure the firing pin pocket depth it became apparent to me that the shelf that the tips are supposed to stop against is very small. I believe that under torque, the tips actually deform the shelf causing the shorter than m/d dimension. Would you review your measurements for the .100 +/- .003 pocket depth and double check some of the other parts to verify their position? If your measurements are OK, we will specify an assembled dimension for the firing pin tip to shoulder length. If the pockets are deep, we will adjust the M/D to match the parts. Please advise me of your findings. The parts will be used for DAT with drawing changes to follow based on your information.

Thanks
Mike

CONFIDENTIAL 83

Golemboski, Matt R.

From: Zajk, Joseph J
Sent: Friday, March 17, 2000 10:17 AM
To: Morgan, Metty E.
Cc: Golemboski, Matt R.
Subject: Bolt Handle Blank

Gordon Dill at NAPC was mistaken as far as parting line; he was looking at something on the finish bolt handle drawing. There are a couple of minor things he suggested, like removing the suggested parting line completely and just state that there is to be a .01 max. witness at the parting line (the knurl will define where the parting line has to be) that I will talk with Mike about, but no show stoppers like he first said.

Joe Z.

CONFIDENTIAL 83

Golemboski, Matt R.

From: Keeney, Mike
Sent: Friday, March 17, 2000 8:42 AM
To: Zajk, Joseph J
Cc: Golemboski, Matt R.; Morgan, Metty E.
Subject: 710 Safety Samples

Joe,
I received three safety samples from Square yesterday. Square further developed their tooling to produce more consistent contour and surface finish while eliminating the sharp burr. I spoke with Dan this morning and instructed him to proceed with this contour and to provide firm numbers for a secondary operation. Based on Marketing input, we need to coin the outside edge of the button and add serrations across the button. I asked for a .02 to .03 Radius on the top edge and serrations across the surface. Dan will provide an estimate and drawing details based on their capability.

Mike

CONFIDENTIAL 83

Golemboski, Matt R.

From: Keeney, Mike
Sent: Thursday, March 09, 2000 3:34 PM
To: Zajk, Joseph J
Cc: Golemboski, Matt R.; Morgan, Metty E.; Diaz, Danny
Subject: 710 Safety Design

I spoke with Dan Hart this afternoon regarding the samples that I had received. The concave or "hump" geometry will be acceptable but there was a sharp burr generated along the outside edge of the button. Dan believes that the production parts will not have as extreme of a burr due to production die clearances and die roll of the blanked edges. Based on our discussion and his understanding of the burr issue, I instructed Dan to proceed with the production tool to the geometry of the concave button surface. He will make a back up set of blank punches to allow us to revert back to a flat button geometry if required. Once we have production samples to evaluate relative to burrs, we will have three options: 1. Accept the parts as produced, 2. Revert back to the flat button surface, or 3. Add a secondary coin operation to compress the burr and possibly add serrations to the top surface. Options 1&2 will not affect piece price, option 3 will add approximately \$.08-.10/piece and additional tooling expense to build the coining punch and die. All three options will incorporate an additional .05" to the width of the button (.805 dimension to .855) and change the corner radii from .08 R to .150 R.

I have filed the burr off on one sample and will show it to all next tuesday in Madison. I will ship a couple of the samples to you tomorrow.

Mike

CONFIDENTIAL

Golemboski, Matt R.

From: Zajk, Joseph J
Sent: Thursday, March 09, 2000 12:47 PM
To: Keeney, Mike
Cc: Golemboski, Matt R.; Diaz, Danny
Subject: Revised trigger for 710

Mike,

Per our conference call yesterday Mayfield is doing the following concerning the 710 trigger:

- Suspending tool build of the 710 trigger C-300435 pending a decision by Danny Diaz & Legal as to whether the new 700 trigger should be adopted for the 710. Please note that the tool design by Sterling Sintered for C-300435 Rev. C is complete.
- Evaluating what needs to be done from a manufacturing standpoint to machine the new MIM trigger blank D-201342 to the specifications shown on the finished trigger drawing D-109835. We currently plan to machine the blank here.

I received the prints for the new 700 trigger today. Thank you.

Also, in regards to the chamber, we concur with your recommendations and will proceed accordingly.

Please let me know if you have any questions or comments.

Joe Z.

CONFIDENTIAL

Golemboski, Matt R.

From: Guiliano, Gerald P.
Sent: Thursday, March 09, 2000 12:49 PM
To: Golemboski, Matt R.
Cc: Bedore, Edward D.; Colley, Amber
Subject: FW: m710 scope rails

Please provide us with as much information about the scope rail and clip as possible. We will need cost, size, weight, lead time and minimum order runs. I have spoke with Al Russo about a number of 5,000 units on a scope rail but quantities on the clip. The 5,000 may be to steep for accessories to start (not having any information or history on the product) but we can discuss. We will need the raw material number and any other information you can provide. Thanks.

-----Original Message-----

From: Bedore, Edward D.
Sent: Monday, February 28, 2000 11:35 AM
To: Guiliano, Gerald P.
Subject: FW: m710 scope rails

LETS DISCUSS THIS ASAP.

-----Original Message-----

From: Russo, Alfred D.
Sent: Tuesday, February 15, 2000 1:41 PM
To: Bedore, Edward D.
Cc: Guiliano, Gerald P.
Subject: FW: m710 scope rails

Ed we are planning to build 7,000 guns in 2000 and 30,000 in 2001. My vote would be 2500 and 7000 for starters. Your call AL

-----Original Message-----

From: Golemboski, Matt R.
Sent: Tuesday, February 15, 2000 11:44 AM
To: Guiliano, Gerald P.
Cc: Russo, Alfred D.; Bedore, Edward D.
Subject: m710 scope rails

We have design a scope rail very similar to the M/587 rail for the M710. This is usually a long lead time item (14 weeks). We can order some any time. I would just like for someone to give a quantity by the March 31, 2000. This will give us plenty of time to order them and have some ready for sales events etc. in the fall.

Matt Golemboski

Golemboski, Matt R.

From: Keeney, Mike
Sent: Tuesday, March 07, 2000 8:17 AM
To: Morgan, Metty E.
Cc: Golemboski, Matt R.
Subject: firing pin spring 300399 rev. E

Mett,
I have faxed the new firing pin spring drawing to your attention, A-300399 Rev. E. Please copy and replace 300399 Rev. D in drawing files. Also check delivery of a 15 piece minimum sample by 3/14/00.

thanks
Mike

CONFIDENTIAL 83

Golemboski, Matt R.

From: Keeney, Mike
Sent: Wednesday, March 08, 2000 9:00 AM
To: Golemboski, Matt R.; Zajk, Joseph J
Cc: Morgan, Metty E.; Diaz, Danny
Subject: M/700 Trigger redesign

Guys,
received a copy of the new M/700 blank and finished drawings from David. There changes are significant, it is no longer a powder metal part instead it has become a MIM part. Since it is MIM the serrations should not be a cost issue, I would suggest that you discuss the procurement of this part with Ilion. I will forward a set of drawings for your review. The M/710 will incorporate the changes as designed by David.

Mike

CONFIDENTIAL 83

Golemboski, Matt R.

From: Keeney, Mike
Sent: Thursday, March 09, 2000 3:34 PM
To: Zajk, Joseph J
Cc: Golemboski, Matt R.; Morgan, Metty E.; Diaz, Danny
Subject: 710 Safety Design

I spoke with Dan Hart this afternoon regarding the samples that I had received. The concave or "hump" geometry will be acceptable but there was a sharp burr generated along the outside edge of the button. Dan believes that the production parts will not have as extreme of a burr due to production die clearances and die roll of the blanked edges. Based on our discussion and his understanding of the burr issue, I instructed Dan to proceed with the production tool to the geometry of the concave button surface. He will make a back up set of blank punches to allow us to revert back to a flat button geometry if required. Once we have production samples to evaluate relative to burrs, we will have three options: 1. Accept the parts as produced, 2. Revert back to the flat button surface, or 3. Add a secondary coin operation to compress the burr and possibly add serrations to the top surface. Options 1&2 will not affect piece price, option 3 will add approximately \$.08-.10/piece and additional tooling expense to build the coining punch and die. All three options will incorporate an additional .05" to the width of the button (.805 dimension to .855) and change the corner radii from .08 R to .150 R.

I have filed the burr off on one sample and will show it to all next tuesday in Madison. I will ship a couple of the samples to you tomorrow.

Mike

CONFIDENTIAL

Golemboski, Matt R.

From: Zajk, Joseph J
Sent: Thursday, April 20, 2000 2:52 PM
To: Keeney, Mike
Cc: Morgan, Metty E.; Golemboski, Matt R.; Helmer, Gerald A.
Subject: RE: Retaining Cap

If you don't see a problem from a design standpoint in shortening the plunger stud then let's do it and add whatever you can for a stud to the bottom of the retaining cap. That means it will be a different plunger from the 700 and we'll need to get new prints of both the new plunger and the new retaining cap ASAP so we can get them quoted and on order. Send the drawings to Jerry's attention; I'll be at machine runoffs most of next week.

Joe Z.

-----Original Message-----

From: Keeney, Mike
Sent: Thursday, April 20, 2000 2:39 PM
To: Zajk, Joseph J
Subject: RE: Retaining Cap

In the current state we could not add a tab to the retainer. The plunger stud height is .094", the working height at the second load point is .127" so that only leaves us .033" clearance at nominal conditions. If we need to add a stud to the retainer we will need to shorten the stud on the plunger. Let me know if that is possible and if so, I will change the two parts.

Mike

-----Original Message-----

From: Zajk, Joseph J
Sent: Friday, April 14, 2000 4:10 PM
To: Keeney, Mike
Subject: Retaining Cap
Importance: High

Is it possible to put a small dimple or stud on the underside of the retaining cap for the bolt plug assembly? This is a recommendation from the ultrasonic welding people to help retain the spring while the cap is being welded in place. I don't know if there's room with the plunger.

If we can do that they think we can ultrasonically weld the cap on without too much difficulty.

Let me know what you think.

Joe Z.

Remington Arms Company, Inc.
September 9, 1999

CONFIDENTIAL

Research and Development Technology Center
Elizabethtown, Kentucky

To: Rich Kosko, The Hanson Group
Date: Sept. 9, 1999

cc: D. Diaz, J. McCollum,
M. Golemboski

Topic: Remington Receiver Insert, Pt. #300327

Rich,

Please find enclosed drawings 1E & 2E-300327. Please review and quote tool alterations per revisions no. 28 and 29 of drawing 2E-300327. The alterations are to be completed prior to the next sampling of the tool. Direct your quote to Jim McCollum, purchasing manager Elizabethtown facility.

Other tool alterations required (at no charge to Remington) are to include resizing of the four .122 +/- .0015 diameter holes and the two .097 +/- .0015 diameter holes as highlighted on drawing 2E-300327. In house inspections indicate the .122 diameter holes are .1245 and the .097 diameter holes are .100. Please resize the core pins to produce mean model drawing hole diameters.

Please call me to discuss if you have any questions or concerns.

Sincerely

Michael D. Keeney
Remington Arms Co., Inc.

Michael D. Keeney
Staff Engineer

Page 1 of 1

hanson 9-9-99

MF0942

Confidential - Subject to Protective Order
BARBER - 5.22.06r0010892
Williams v. Remington

Golemboski, Matt R.

From: Zajk, Joseph J
Sent: Tuesday, March 28, 2000 9:12 AM
To: RKoskohgl@aol.com
Cc: Golemboski, Matt R.; Keeney, Mike; JJREGOHGL1@aol.com; Vicmorando@aol.com
Subject: RE: Receiver Insert Meeting Minutes



Receiver Insert
Meeting Notes ...

Rich,

In general your minutes look OK. The only discrepancy I have is with the flash on details #35 & 36. I have the flash height as being within the model drawing specs for the entire surface.

Here is my write-up of my notes for you to review as well. I kept it in the general format of the agenda I created for us to use last Thursday, and inserted the answers & conclusions immediately following each bullet point. Please review and let me know if Hanson is in agreement or if I mis-stated or omitted something.

Best regards,

Joe Zajk
Engineering Manager

-----Original Message-----

From: RKoskohgl@aol.com [mailto:RKoskohgl@aol.com]
Sent: Monday, March 27, 2000 3:20 PM
To: zajkj@remington.com
Cc: Golembosmr@remington.com; keeneymd@etown.remington.com; JJREGOHGL1@aol.com; Vicmorando@aol.com
Subject: Receiver Insert Meeting Minutes

Joe

Please review my attached minutes and let me know if I may have missed anything during our discussion. Could you please check into the purchase order to cover the work necessary to grind down the 4 firing pins which Mike has requested.

We have completed the necessary changes and are scheduling the run for tomorrow, 3/28/00. I will overnight the parts to your attention as they become available.

Thanks in advance for your assistance in the measurement techniques and to provide us with a "win -- win" situation for both companies.

Rich Kosko
Program Manager

Receiver Insert 300327 Meeting Notes

Meeting Date: 3/23/00
 Attendees: Joe Zajk – Remington Arms
 Rich Kosko – Hanson Group
 Frank Fasano – Hanson Group

Reason: To discuss the path forward on the Remington receiver insert program, P/N 300327

Five general topics were covered during the meeting between Hanson & Remington on Thursday, 3/23/00. These topics were:

1. Decide on conventional molding vs. IQC molding process for receiver insert.
2. Discuss and come to an agreement on inspection methods for receiver insert.
3. Review dimensional layout
4. Discuss Lot traceability requirements.
5. Gage Repeatability & Reproducibility

A more detailed list of the topic detail and the decisions mutually agreed upon by Remington & Hanson are given below. The topic detail is given in bold italics, and the decision is given below it in normal type:

Topics

1. ***Decide on conventional & IQC processes for receiver insert***
 - ***Using dimensional layouts determine best process for running receiver insert. This will be determined through analysis of feature positions between the two processes and determine which is the more accurate of the two processes.***

Based on sample parts run by Hanson on 3/22, it was determined that the IQC process was most dimensionally stable. This was determined by measuring key features on five pieces each of the conventional & IQC process. After several process iterations it was decided to use a chiller to circulate 55°F water through the long core (cores out receiver ID and tang) and to extend the cooling time in the press by 10 seconds. This yielded a cycle time of approximately 64 seconds, 10 seconds longer than the baseline IQC process used in Michigan. This resulted in a reduction of part warping by approximately 38% from the baseline IQC process and approximately 50% from the conventional process.

MF0944

- **Once process is determined run off sufficient parts to determine process stability. Remington requests copies of process parameters for final settings used for process stability run. Remington proposes the following process stability test:**
 - **Using "final parameters", run 50 pcs. to warm up mold. Discard those parts.**
 - **Mold a 600-piece run. From the start of the run pull & mark the following pieces: 1, 2, 3, 51, 52, 53, 101, 102, 103, 151, 152, 153, 201, 202, 203, 251, 252, 253, 301, 302, 303, 351, 352, 353, 401, 402, 403, 451, 452, 453, 501, 502, 503, 551, 552, 553, 598, 599, 600. This will form thirteen data points for an x-bar chart (subgroup n=3) for each feature on the receiver insert. These samples will be shipped to Remington Arms. The parts will then be inspected via CMM by the mutually agreed upon inspection method discussed in section 2 below. NOTE: Remington's CMM software has the capability to automatically create x-bar charts for all features inspected.**

It is desired that Hanson grinds the Bolt Stop core pin to match model drawing and grind .0015" off the diameter of the four pins currently used for the four .1220 fire control pins prior to starting the process stability run listed above.

Hanson agreed to run the capability test as stated above. Run was to begin on 3/27, after the pins were ground down. Parts will be numbered and sent to Remington for analysis. Hanson will keep an additional 50 pieces to conduct their own capability analysis in order to correlate to Remington's analysis of data. Measurement will be by the agreed upon method listed in Topic 2, below.

2. Discuss and come to an agreement on inspection methods for receiver insert

- **Propose using .699 diameter rod of sufficient length to locate part along entire surface of the A-datum diameter and incorporate this into general CMM fixture design D-K-10400.**

Remington and Hanson both agree to this method.

- **Propose establishing a datum target on the shooter's LH side B-datum surface due to its dimensional stability and incorporating this B-Datum target on CMM inspection fixture D-K-10400.**

Remington and Hanson both agree to this pending approval of Remington's R&D's facility.

MF0945

- **Remington to build and supply Hanson copy of all special gaging & fixtures (including prints) it will use during the inspection process.**

Agreed upon by both parties. This is normal procedure for Remington where special fixturing is involved.

- **Remington to supply Hanson with plug gage information sheets for plug gages Remington plans to use during its inspection process so Hanson can order duplicate plug gages.**

Agreed upon by both parties. Remington left copies of all standard plug gages so Hanson can order the same plugs to the same wear allowance, gage tolerance class, etc.

- **Discuss & come to agreement on critical and in-process dimensions**

Critical and in-process dimensions agreed upon based on fax from Joe Zajk of Remington to Rich Kosko of Hanson dated 3/16/00. Terminology of "critical" vs. "in-process" mutually agreed upon. Critical dimensions are checked at first and last article inspection. In-process dimensions are checked at regular intervals during run. Due to the special nature of this part the distinction between critical and in-process dimensions overlap. Therefore, Hanson has agreed to use their programmable Micro-View to check all critical dimensions (fire control holes & other dimensions listed in fax) as part of their in-process checks as well as for first and last article inspection.

Additionally, several visual issues were discussed. They consisted of the following:

- Flash: Critical areas for flash were pointed out and defined. On the inner surface of the fire control sideplate, ejector pin flash had to remain within the .175 +.003/-.001 model drawing tolerance (inspection #35 & 36). On the bosses surrounding the rivet holes (#57 & 59), flash had to remain below the surrounding .250 surface in order to allow sideplate to sit flush on the .250 spacer surfaces.
- Step Gate: Hanson agreed to investigate the fit of step gate on bottom of part immediately forward of the sideplate in order to improve shutoff and matchup in order to reduce flash in that area.
- Acceptable Parting Line Flash: Hanson to supply Remington with standard parting line flash and witness sizes for non-critical areas so Remington can review. Hanson asks that Remington locate text defining parting line flash and witness on prints once the size is agreed upon.

MF0946

- Mismatch on Tang: Hanson to investigate and correct pronounced visual mismatch on top LH side of the 20 degree tang cut. Mismatch appears to be an oversight from a previous tool revision in which the tang surface was modified.
- Core pin for Press Insert Hole: During the dimensional layout review it was noticed that the GO/NOGO plug gage Remington supplied would not go down the GO depth notch on the .370 deep hole on the rear boss where the pressed insert would be ultrasonically welded in. At first glance it appears that the core pin might be damaged on the edge. Hanson will investigate and repair as necessary.

3. Review dimensional layout

Dimensional layout for IQC and conventional parts were reviewed. Remington supplied various plug gages to assist in the dimensional layout of the parts. This assisted in coming to final determination of process used in Topic 1 and in gaging method in Topic 2.

4. Discuss Lot traceability requirements

• Review Remington's draft of lot traceability requirements

A draft copy of Remington's draft lot traceability requirements was supplied to Hanson. Hanson agrees to comply with the requirements. In addition, Hanson will keep all in-process and critical dimension inspections, material certifications, etc. for each lot for a minimum of two years. Hanson would notify Remington when it plans to dispose of such records so Remington has the option of obtaining this documentation for its own records.

Hanson & Remington also discussed possible ways of easily identifying parts from various lots. As there will most likely be a small number of runs per year, it may be possible to vapor hone an identification mark on a non-critical surface of the receiver insert that both Remington and Hanson can use for quick identification of lot vintage. This mark would change from run to run and be tied back to the lot number. One suggestion was to use Remington's date code system it uses for assembly; others include symbology used by other manufacturers. Remington will supply Hanson with its date code system for review. Hanson to submit to Remington possible other symbology to review. The mutually agreed upon symbology would most likely be placed on the shooters LH side of the part immediately under the rear tang surface.

MF0947

5. Gage R&R

Remington and Hanson agreed upon Gage R&R method for determining the repeatability and reproducibility of the various inspection gages.

CONFIDENTIAL 83

MF0948

Meeting Minutes

Meeting Date: 02/22-23/2000

Place: Michigan Room

Present: Joe Zajk, Frank Fasano

CC. Matt Golemboski, Mike Keeney, Glenn Hanson, John Rego, Vic Morando, Eugene Tabarovsky, Robert Rousseau, Betty White

Subject: Remington Receiver Insert

Items discussed:

Collectively we have decided to produce parts using the "IQC" technology with a 64 sec cycle and placing the long core on a separate chiller. Preliminary results showed that this direction would yield the most favorable results in processing this particular component.

Joe spoke of lot trace ability to this part, some of the ideas we brainstormed were to place changeable date code wheel in the mold, prick punching an ejector pin, vapor hone a rectangular area on the rear of the Receiver every time a new order is received, or whatever else we may place on the side of the Receiver which will not interfere with its performance.

We also will supply dimensional reports from each factory order release and material certification from each run. First and last shots from the mold will also be sent to Remington.

Identify the same measurement technique to be used by both Remington and Hanson in measuring the Receiver during the 600 pc run.

Joe will provide us with an x-bar chart and Excel spreadsheet layout on measurements taken from the run next week.

Mike Keeney has requested that 4 pins in the firing pin location be turned down by .0015" from the present steel condition. A quote has been provided for this change, at the same time we will change the Bolt stop core pin to the .290 +/- .005 dimension.

Capability study will be done with 50 pcs from the next scheduled run on 3/28/00.

Ejector pin flash on detail #35 and #36 should not exceed +.003 / -.000

Detail #57 and #59 should have no flash above the .250 surfaces as referenced on detail #49

Joe and Mike Keeney will establish and provide target-measuring areas for the quality department

PO Box 789 • State Street • Ludlow • MA 01056-0384 • Tel: 413-589-0534 • Fax 413-589-0761

MF0949

We will e-mail (go / no-go) gage drawings of the Mickey Mouse ears to Joe for his comparison

Joe said Remington would build and provide us with a set of gages and fixtures to measure the Insert during the inspection process

We have accepted Joe's critical dimension inspection and in-process sheet except for the .559 dimensions, which requires additional thought on how the part needs to be positioned to be measured.

I will speak to our plant manager on the amount of inventory Hanson will be willing to keep during production releases. We would ideally like to produce Remington's entire order for the year in one factory run and ship the product when complete.

Frank will have one of his quality technicians write an inspection program for the automatic Micro-vue machine and establish a confidence level in the parts being measured consistently.

Frank will instruct his lab technician to perform a Gage R&R study early next week in preparation of the 600 piece pilot run.

Joe has requested when we run the process on 3/28/00, to remove and label inserts as per his instructions listed on meeting agenda. These parts will assist the inspection team to detect any process variation.

CONFIDENTIAL

PO Box 789 • State Street • Ludlow • MA 01056-0384 • Tel: 413-589-0534 • Fax 413-589-0761

MF0950

Rich Kosko

Program Manager

CONFIDENTIAL 83

PO Box 789 • State Street • Ludlow • MA 01056-0384 • Tel: 413-589-0534 • Fax 413-589-0761

MF0951

Golemboski, Matt R.

From: Cook, Todd D.
Sent: Monday, January 17, 2000 10:01 AM
To: Golemboski, Matt R.
Cc: Keeney, Mike; Zajk, Joseph J
Subject: RE: M/710 Stock Issues

Matt,

Thanks for the note. We will see you Wednesday.

The CAD Group and I are working on a request from Quality Tooling to get a trimmed surface model of the complete stock--if it's easy, it will be done by then. If not, we may be working on it until the end of the week. They did not have to have the trimmed surface model, so it's a "nice to have" at this point, but we are working on it with an eye on your future need for the data (ala DeRobertis, etc on M/597) Apparently, Quality is okay with all the other dimensions on the new models we sent, except for the under cut on the magazine latch pivot. There will need to be some undercut, but we will have to resolve with them, Mike, and you how much undercut. At this point, my opinion is that 0.007 - 0.010" per side will pull without damage. This is much less than what's called for in the CAD model. It may not be enough, if the part has to stay there for the life of the product, though. More Wednesday.

Todd

From: Golemboski, Matt R.
Sent: Monday, January 17, 2000 10:25 AM
To: Cook, Todd D.
Subject: keeney

Keeney is not going here today. I will be in E'town on Wednesday to discuss design issues on 710.

Matt Golemboski

Golemboski, Matt R.

From: Cook, Todd D.
Sent: Thursday, January 20, 2000 3:23 PM
To: Gary Hillyard (Quality Tool)
Cc: Golemboski, Matt R.; Zajk, Joseph J; Keeney, Mike
Subject: 710 Stock Revision: The recoil lug rear wall moves forward 0.013" to accommodate thinner lug material


Gary,

I shipped you floppies, similar to Tuesday's effort, via UPS that contain the file TEST7103.ZIP, a zip archive of the IGES file you need to have with the latest revision. The only change from the files you got Wednesday should be that the recoil lug pocket (it's a slot 0.192" wide just behind the forward screw hole) rear wall moved forward by 0.013". We will fax a sketch over to make it easier to see in the model. That's the only change I have, but as we discussed, if I hear of another, I will let you know immediately.

This E-mail is cc'd to the manufacturing group (Matt and Joe) and the design engineer (Mike) so they will know what you do. Thanks again.

Todd

CONFIDENTIAL 83



QUOTATION NO. 990118-2010-13
DATE March 13, 2000
TERMS Net 30 Days

TO
Mr. Matt Golemboski
REMINGTON ARMS CO., INC.
22 Rifle Trail, PO Box 99
Hickory, KY 42051

REFERENCE: **Receiver Insert**

We are pleased to quote you as follows:

Mold 1000 parts using the Hanson I.Q.C. process:

Mold 500 parts using regular injection molding methods (If it is determined early in this test that the regular injection molding process is not feasible, this test will be cancelled).

These molding runs will be used to establish a stable process and to determine dimensional capability of this process.

We will also use this production run to determine the correct inspection process used on these parts. This will include a R&R study of the gauge currently owned by Remington. Any costs required to revise the existing gauge or to build new gauges are not included in this quotation. Our ultimate goal is to have an inspection measurement technique that is repeatable at both Remington and The Hanson Group.

It is a requirement that Remington provide suitable Engineering and Quality support personnel to be present at the mold trials, in Ludlow MA. These trials are expected to be during the later part of the week of March 20th.

T (502) 856-4203

F (502) 856-3233

We await your reply and assure you of our best attention and services at all times.


(Quote valid for 30 days.)

Subject to the terms and conditions on the reverse side hereof.

\$ 5,000.00

83

CLIENT COPY


Eugene Tabarovsky
Corporate Engineering Manager

F03.005SQ

Rev. Level B

Revised: 01/26/99

MF0954

TERMS AND CONDITIONS OF SALE

These terms and conditions of sale shall govern the sale of goods sold on credit by the Seller and the Purchaser for the goods described herein ("goods") as such description may be modified from time to time in writing by the Seller and the Purchaser and no part of the terms of sale, conditions, notices or agreements between them as to the subject matter hereof. The terms of sale shall be in full and complete satisfaction of the Seller's obligations to the Purchaser.

1. **ACCEPTANCE.** The Purchaser shall be deemed to have accepted the terms and conditions of sale upon the delivery to the Purchaser of a copy of the terms and conditions of sale as set forth by the Seller at the time of delivery. The Purchaser shall not be bound by any conditions of sale which are not set forth in the terms and conditions of sale as set forth by the Seller at the time of delivery. Any terms or conditions of sale which are not set forth in the terms and conditions of sale as set forth by the Seller at the time of delivery, whether printed on the goods, or on any other document of the Purchaser, whenever received, which are inconsistent with the terms and conditions of sale as set forth by the Seller at the time of delivery, shall not be binding on the Seller and shall not be part of the agreement for the sale or shipment of the goods, notwithstanding any provision to the contrary in any document of the Purchaser. If the Purchaser has not otherwise agreed to be bound by the terms of sale hereof, then the Purchaser's acceptance of the goods shall constitute its agreement to be so bound. The Purchaser's orders are accepted by the Seller only when acknowledged by the Seller's general office. The Seller may at any time correct stenographic and clerical errors in documents and materials executed by the Seller in connection with the sale of the goods.

2. **WAIVER OF MODIFICATION.** No waiver, alteration or modification of any of the provisions hereof shall be binding on the Seller unless made in writing and signed or on behalf of the Seller by a duly authorized officer. The waiver by the Seller of any breach by the Purchaser of any provision hereof shall not constitute a waiver of any subsequent or continuing breach by the Purchaser of such provision or any other provision. Any such alteration or modification may result, among other things, in rescheduling of production and delivery and in the obligation of the Purchaser to reimburse the Seller for raw material and work-in-process previously ordered and for handling and other charges incurred by Seller, all as required by the Seller.

3. **PRICE.** Unless otherwise specified herein, the prices and charges for goods shall be as set forth herein. Unless otherwise specified herein, prices do not include any federal, state or local taxes and other charges, whether presently existing or imposed in the future. The Purchaser shall reimburse the Seller upon demand for all taxes and other charges including, without limitation, sales and use taxes, excises or other charges, except excises in the nature of an income tax, which the Seller may be required to pay to any government, federal, state, county or local, or other person upon the sale, production or transportation of the goods. Unless otherwise specified herein, the prices quoted herein do not include testing or inspection of the goods. Where the Purchaser requires tests or inspection not regularly provided by the Seller, the Purchaser shall reimburse the Seller for the additional costs of or the Seller's charges for such tests and inspection.

4. **PAYMENT.** Prices for materials delivered under any order are payable only in United States Dollars at the Seller's plant. Unless otherwise specified herein, where credit is given to the Purchaser, payment is due within thirty (30) days from the earlier of the invoice date or date of delivery. Whether any credit shall be granted to the Purchaser in any instance shall be within the sole discretion of the Seller. Each shipment made on any order shall be considered a separate sale and if payment is not received therefor within the period specified herein, the Seller may bring a separate suit to recover the contract price of each such shipment. The Seller may from time to time require different terms of payment, whether or not terms are specified herein, including, without limitation, cash on or prior to delivery. Whenever it reasonably appears to the Seller that the Purchaser's financial condition has changed or become unsatisfactory to the Seller, the Seller may demand adequate assurances from the Purchaser of its performance. If the Purchaser fails to pay any amounts due hereunder, or if within the period specified in such demand the Purchaser fails to give assurance of its ability to pay which the Seller deems adequate, the Seller may, at its option, and in addition to all remedies available to the Seller, treat such failure or refusal as a repudiation of the portion of the order which has not been fully performed and accordingly suspend or stop performance hereunder. The Purchaser shall be liable to the Seller for interest at the rate of one and one-half percent (1 1/2%) per month (or such lesser rate as may be the maximum lawful rate from time to time) on all overdue amounts.

5. **SECURITY INTERESTS.** To secure the purchase price and all amounts expended by the Seller to collect the purchase price and protect the goods, the Purchaser hereby grants a security interest in the goods to the Seller. The Purchaser hereby irrevocably appoints the Seller its attorney-in-fact coupled with an interest to execute all the U.C.C. financing statements to perfect the Seller's security interest in the goods. If the Purchaser does not timely pay for the goods, the Seller shall have an and may exercise all of the rights of a secured party under the Uniform Commercial Code and the Purchaser shall be liable for the purchase price, plus the Seller's expenses in connection with enforcing its rights hereunder, including legal fees and court costs.

6. **DELAYS AND FORCE MAJEURE.** Any date of delivery or shipment indicated herein is the Seller's best estimate of the approximate date when the goods will be ready for shipment. The Seller shall not be liable for damages or any nature resulting from delay for or failure of performance caused by accident, strike or other labor difficulty, labor shortage, fire, explosion, flood, earthquake or adverse weather conditions; delay in transportation or lack of transportation facilities; federal, state, county or local government or governmental agency laws, rules, regulations, orders, proclamations, or decrees; shortage of fuel, power, materials or supplies; or any cause beyond the control of the Seller. In case of any delay so caused, the Seller shall have such additional time within which to perform as may be reasonably necessary under the circumstances, and shall have the right to apportion its materials or production among its customers in such manner as it may consider to be equitable.

7. **SHIPMENT, DELIVERY AND RISK OF LOSS.** Unless otherwise specified herein, delivery shall be F.O.B. the Seller's plant at Ludlow, Massachusetts. The risk of loss shall not be by contract of either party that may constitute a default or breach hereunder. If the Purchaser specifies a carrier and that carrier fails or refuses to accept delivery when tendered, the Seller shall store the goods for the Purchaser at the Purchaser's risk and expense, but the purchase price shall be payable as if delivery occurred at the time of tender.

8. **WARRANTY.** The Seller warrants that the goods to be supplied to the Purchaser will conform to the description or specifications on the face hereof. SUCH WARRANTY IS IN LIEU OF ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. ALL OTHER IMPLIED WARRANTIES AND ANY LOSS NOT BASED UPON THE CONTRACT ARE HEREBY DISCLAIMED AND EXCLUDED BY THIS AGREEMENT. All warranty claims of any nature are barred if the goods have been altered, damaged, or in any way physically changed by the Purchaser, or subjected by the Purchaser to abuse, misuse, negligence or accident, or if the Purchaser fails to perform any of its duties set forth herein. All warranty claims of any nature are barred unless made by the Purchaser in a writing received by the Seller within ten (10) days after the Purchaser's receipt of the goods for defects that are not latent and within ninety (90) days after the Purchaser's receipt of the goods for latent defects.

9. **DAMAGES.** The liability of the Seller to the Purchaser's exclusive remedy, whether in contract or in tort, hereunder or any warranty applicable to the goods, are limited to the repair or replacement, at the Seller's option, of any defective part of the goods or the refund by the Seller of the purchase price for the goods in respect of which damages are claimed following the receipt by the Seller of such goods. In any event, liability of the Seller for damages hereunder shall not exceed the purchase price of the goods in respect of which damages are claimed. Goods may not be returned to the Seller without the Seller's prior permission, and then only in the manner described by the Seller. THE REMEDY HEREBY PROVIDED SHALL BE THE EXCLUSIVE AND SOLE REMEDY OF THE PURCHASER. IN NO EVENT SHALL THE SELLER BE LIABLE FOR ANY INDIRECT, PUNITIVE, INCIDENTAL OR CONSEQUENTIAL DAMAGES OR SPECIAL DAMAGES, REGARDLESS OF WHETHER A CLAIM FOR SUCH DAMAGES IS BASED ON WARRANTY, CONTRACT, NEGLIGENCE OR OTHERWISE.

10. **PATENTS, TRADEMARKS.** Whenever goods make use of protected information, including, without limitation, any patent, design, copyright, trademark, trade name or trade secret provided by the Purchaser, the Purchaser warrants that it has the right to use such protected information and shall defend and indemnify the Seller against all damages, claims and losses resulting from infringement or alleged infringement of such protected information.

11. **OWNERSHIP AND DISPOSITION OF HOBS, JIGS, TOOLS, PRINTS AND TRACINGS.** All hobs, jigs, tools, patterns, prints and tracings required to build any goods ordered by the Purchaser are property of the Seller unless supplied by the Purchaser or unless otherwise specified in writing by the Seller. The Seller need not return the Purchaser's hobs, patterns and tracings in their then existing condition, only if so specified in writing by the Purchaser. Unless otherwise specified in writing by the Purchaser, six months from the date of shipment of the goods the Seller may dispose of, without liability, the Purchaser's prints submitted for quotation, patterns, and tracings and special hobs, jigs, tools and designs used in the manufacture of the goods.

12. **CANCELLATION BY PURCHASER.** In addition to all other remedies available to the Seller, the Purchaser shall be liable for any loss suffered by the Seller resulting from the Purchaser's cancellation of any order, including, without limitation, loss of the Seller's profits. If delivery does not occur within the time specified, the Purchaser's order shall remain in effect until completed or specifically cancelled by the Purchaser by a writing received by the Seller.

13. **ARBITRATION.** Any controversy arising out of or relating hereto, including any modification or amendment hereof, shall be settled by arbitration in the City of Springfield, Massachusetts in accordance with the Rules then obtaining of the American Arbitration Association. The parties agree that the arbitrators sitting in any such controversy shall have no power to alter or modify any express provision hereof or to render an award which by its terms effects any such alteration or modification. The parties consent to the jurisdiction of the courts of the Commonwealth of Massachusetts and of the United States District Court of Massachusetts for all purposes in connection with said arbitration. The parties further consent that any process or notice of motion or other application to any of said courts or a judge thereof, or any notice in connection with any arbitration hereunder, may be served inside or outside the Commonwealth of Massachusetts by registered or certified mail, return receipt requested, or by personal service provided a reasonable time for appearance is allowed, or in such other manner as may be permissible under the rules of said court.

14. **LIMITATION OF RIGHT TO ARBITRATE.** Any claim by the Purchaser of any kind, nature or description, barred and waived unless Purchaser institutes arbitration proceedings within six months after giving notice of such claim as provided herein. The failure to institute arbitration proceedings within this period shall constitute an absolute bar to a claimant's right to any other proceedings by the Purchaser and a waiver of all claims on the Purchaser's part.

15. **ASSIGNMENT.** No right of the Purchaser hereunder or arising out of this agreement may be assigned without the express written consent of the Seller and any assignment in violation of this agreement without the express written consent of the Seller shall be void.

16. **SEVERABILITY.** If any provision hereof is, becomes or is found by a court of competent jurisdiction to be at any time and under any law, rule or regulation, unenforceable or invalid, no other provision hereof shall be affected thereby, and the remaining provisions hereof shall continue in full force and effect as if such unenforceable or invalid provision had not been a part hereof.

17. **JURISDICTION.** Massachusetts law shall govern the making, construction and enforcement hereof.

MF0955



The Hanson Group, Ltd.

P.O. Box 789
Ludlow, MA 01056-0789
PHONE: (413) 589-0534
FAX: (413) 589-0761

QUOTATION NO. 990118-2010-11

DATE February 28, 2000

TERMS Net 30 Days

TO Mr. Jim McCollum
REMINGTON ARMS CO., INC.
315 West Ring Road
Elizabethtown, KY 42701-9318

3/1 : call 10:30 AM

REFERENCE: **Receiver Insert, HGL Job#9990204, 1000 Piece Run**

We are pleased to quote you as follows:

Mold 1,000 parts in RTP 299 x 83002 in single cavity mold with IQC process:

\$ 4,553.45 ⁸³

- Parts to be molded in IQC development tech center in MI. Please allow sufficient time to schedule this job into the lab.
- F.O.B. Ludlow, MA, Freight Collect
- Molding prices are based on current raw material costs. Changes in raw material costs may affect molding prices.
- Quoted prices are based on supplied quantities. Changes in quantities will affect prices.

cc: Joe Zajk, Remington
Mike Keeney, Remington

T (270) 769-7600
F (270) 737-9576


*Refused
B1 990118-2910-13*

We await your reply and assure you of our best attention and services at all times.

(Quote valid for 30 days.)

Subject to the terms and conditions on the reverse side hereof.

CLIENT COPY


Roman H. Suski
Estimating Coordinator

F03.005SQ

Rev. Level B

Revised: 01/26/99

MF0956

**The Hanson Group, Ltd.**

A United Plastics Group Company

Fax Cover Sheet
(www.hansonltd.com)

Date:

2/28/00

2 Pages (including cover)

83

To:

Joe Zajk

From:

John Rego

Company:

Remington

Fax:

270-856-3233

Phone:

Please return fax transmission to:

- ☐ Corporate (413) 589-7552
☒ Tooling (413) 589-0761
☒ Molding (413) 547-6167

☐ URGENT☐ FOR REVIEW☐ F.Y.I. ONLY☐ PLEASE REPLY

Comments:

P.O. Box 789 • Ludlow, MA 01056-0789 • (413) 589-0534

MF0957

Confidential - Subject to Protective Order
BARBER - 5.22.06r0010907
Williams v. Remington

Golemboski, Matt R.

From: Keeney, Mike
Sent: Wednesday, March 01, 2000 2:27 PM
To: Golemboski, Matt R.; Zajk, Joseph J
Cc: Diaz, Danny
Subject: 710 Safety Button

Guys,
I have spoken with Paul Holmberg and Al Russo relative to the cosmetic 710 sample. With the ISS bolt plug, the safety button geometry is not the most desired feature of the rifle. They have asked that we look at reducing the sharpness of the geometry. Based on the thickness of the part, I'm not sure if we can obtain a more rounded or domed top surface. I would like to talk to Square regarding possibilities. I do not want to contact square without informing you of the issues. Would you like to do a conference call with Square to discuss?

Mike

CONFIDENTIAL 83

Brainin

ISO 9001

Deer Park Die & Stamping Division

Fairfield

QUOTATION

December 14, 1999

Remington Arms Company, Inc.
 22 Rifle Trail
 PO Box 99
 Hickory, Ky 42051

Attn: Matt Golembowski

Ref: Part # E-300363 rev. 9 with radius on edge at section B-B

We are pleased to submit the following quotation for your consideration.

TOOLING COST

Design and build progressive die to stamp part complete \$83,000.00

PRODUCTION COST PER/M**Quantities:**

	Price/M
20/M.....	\$600.36/M
40/M.....	\$511.61/M
60/M.....	\$476.20/M

Notes: Quote based on running part in quarterly production runs.

Parts will be bulk packed in Deer Park boxes on a skid.

Material quoted is a 1010/1020 Cold Rolled Steel.

Parts are to be produced by stamping in a progressive die and welding the overlap.

Tooling cost includes cost for welding fixture.

Quote Modified to allow for additional station in die to coin .020 radius edge at B-B.

Inspection: Production parts to be sample inspected per Deer Park's internal procedure when no other standard is specified by the client.

Delivery: Tooling, 14-16 weeks. Production, 4-6 weeks upon receipt of raw material.


Terms: Tooling, 1/3 at PO, 1/3 at sample submission, 1/3 at customer approval.

Terms: Production, Net 30 days.

FOB: Deer Park

Thank you for considering Deer Park Die & Stamping, an ISO 9001 certified firm, as your supplier.

Best Regards,



Jerry Rossman, Sales Engineer



Carl Dearman, Engineering Manager

Cc: Mike Keeney, Remington Arms Company, Inc.

Brainin

ISO 9001

Deer Park Die & Stamping Division

Fairfield

QUOTATION

December 14, 1999

Remington Arms Company, Inc.
22 Rifle Trail
PO Box 99
Hickory, Ky 42051

Attn: Matt Golembowski

Ref: Part # E-300363 rev. 9 with radius on edge at section B-B

We are pleased to submit the following quotation for your consideration.

TOOLING COST

Design and build progressive die to stamp part complete\$83,000.00

PRODUCTION COST PER/M

Quantities:	Price/M
20/M.....	\$600.36/M
40/M.....	\$511.61/M
60/M.....	\$476.20/M

Notes: Quote based on running part in quarterly production runs.

Parts will be bulk packed in Deer Park boxes on a skid.

Material quoted is a 1010/1020 Cold Rolled Steel.

Parts are to be produced by stamping in a progressive die and welding the overlap.

Tooling cost includes cost for welding fixture.

Quote Modified to allow for additional station in die to coin .020 radius edge at B-B.

Inspection: Production parts to be sample inspected per Deer Park's internal procedure when no other standard is specified by the client.

Delivery: Tooling, 14-16 weeks. Production, 4-6 weeks upon receipt of raw material.


Terms: Tooling, 1/3 at PO, 1/3 at sample submission, 1/3 at customer approval.

Terms: Production, Net 30 days.

FOB: Deer Park

Thank you for considering Deer Park Die & Stamping, an ISO 9001 certified firm, as your supplier.

Best Regards,



Jerry Rossman, Sales Engineer



Carl Dearman, Engineering Manager

Cc: Mike Keeney, Remington Arms Company, Inc.

MF0960

Brainin

Deer Park Die & Stamping Division

Fairfield

To: Remington Arms
Matt Golemboski
FAX: 270-856-3233

From: Brainin
Rich Lee

Date: 3-01-2000
Number of Pages: 2
Phone: (513) 874-9760
Fax: (513) 874-9764

Remarks:

— URGENT ☒ FOR YOUR REVIEW — REPLY ASAP — PLEASE COMMENT

PART E-300363 REV. 9

PLEASE FIND COPY OF QUOTE DATED 12/14/99. STILL
A VALID QUOTE.

Regards,

Rich

MF0961

Golemboski, Matt R.

From: Rossman, Jerry [jrossman@brainin.com]
Sent: Monday, January 31, 2000 10:13 AM
To: 'Golemboski, Matt R.'
Cc: Dearman, Carl
Subject: RE: Magazine Box

Matt-

Delivery date on the prototype is scheduled for March 9th, 2000. We could afford to give you some time to evaluate the prototypes but it couldn't be more than a few days before a PO is cut for production. After that you will have a couple days in which we could do some minor modifications to the production tool before it would impact the final delivery date.

Jerry Rossman

-----Original Message-----

From: Golemboski, Matt R. [mailto:golembosmr@remington.com]
Sent: Thursday, January 27, 2000 5:10 PM
To: jrossman@brainin.com
Subject: Magazine Box

What is the expected delivery date on the prototype samples? Will this occur before the drop dead date?

Matt Golemboski

CONFIDENTIAL 83

Golemboski, Matt R.

From: Morgan, Metty E.
Sent: Monday, January 24, 2000 2:28 PM
To: Keeney, Mike
Cc: Golemboski, Matt R.
Subject: 710 Safety Arm

01/24/2000

Mike,

Dan Hart at Square Stamping can be reached at 315-896-2641.

The scenario goes: Square has quoted the best tooling cost by some \$4500.00. vs. the other quoters., however, his piece price is highest. .23 cents vs .88 cents which I have just today gotten him down to .68 cents.

He says he has three issues with the design. 1.) no hole to check the cam surface.

2.) hole size

3.) tighter die clearance. shouldn't be much die break there.
needs to be straight as possible.

He said our 710 safety has a form that is not on the 700 design. He is charging .285 ea. for that to Ilion. I could use some help here. Dan is very familiar with the 700 safety. He is confident that we will have trouble with a new vendor at .23 cents each. He is willing to drop the cost on other 710 parts if necessary, but says as this design is now there is no way he can move further. Please call him and see what you can do.

Thanks Mike,
Mett @ Mayfield



FACSIMILE COVER PAGE

Date: 1/27/00
Time: 9:03:02
Page: 1

To: Matt Golembowski
Company: Remington
Fax #: 270-737-9576

From: Jerry Rossman
Company: Brainin - Deer Park Die & Stamping Div.
Address: 4348 LeSaint Court
Fairfield, OH 45014
Fax #: 513-874-9764
Voice #: 513-874-9760

Message:

Matt-

Sorry it has taken so long to get back to you. Things have been hectic here in the office, we just got a new Network server and have been in the process of debugging. Good news is we have e-mail. My e-mail address is jrossman@brainin.com.

Anyways, Rich relayed to us you would like a drop dead date for production tooling to receive a June 30th PPAP submission date. That being the case, a purchase order should be placed by March 10, 2000. That gives us our full standard lead time. If you place the PO any later, we may have to come back with expediting charges to cover our overtime commitments. If you have any questions, please do not hesitate to call.

Regards,

Jerry Rossman

P.s. We received our QS 9000 certification on Jan. 12, 2000.

MF0964

1-12-99

METT,

WE ARE GOING TO PROTOTYPE A TOOL
AT BRAININ THEN BUILD A PRODUCTION TOOL.
PLEASE CREATE A P.O. FOR \$12,500 FOR PROTOTYPE
TOOLING. CALL JOHN CARRY @ E'TOWN FOR A CHARGE #.
E'TOWN WILL PAY FOR THE PROTOTYPE TOOL &
WE WILL PAY FOR THE PARTS. I WANT 500 PC 83
AT \$13.17 EA. (TOTAL \$6585).

DO NOT WORRY TOO MUCH ABOUT THE TEXT BECAUSE
IT IS NOT THE PERMANENT TOOL. PAYMENT
WILL BE SUBJECT TO FIRST ARTICLE APPROVAL.

DO NOT REFERENCE THE PRODUCTION TOOL AT THIS POINT.
I AM GOING TO DISCUSS THIS WITH THEM AFTER
THEY RECEIVE THIS P.O.

THANKS

MATT

MF0965

Brainin

Deer Park Die & Stamping Division

Fairfield

To: Remington Arms

Matt Golembuski

FAX: 270-856-3233

From: Brainin

Rich Lee

Date: 3-01-2000

Number of Pages: 2

Phone: (513) 874-9760

Fax: (513) 874-9764

Remarks:

83

— URGENT ☒ FOR YOUR REVIEW — REPLY ASAP ☒ PLEASE COMMENT

Matt,

Please find the latest program chart for the prototypes. Things seem to be in great shape at the present, and parts should be in your hands by 3-13 or possibly sooner.

Do you wish to have any parts sent overnight to your attention, separate from the 500 lot? I will be in Detroit for the SAE Show all next week while these are being completed, so if there are any special needs, please contact Jerry Rossman. Please keep in mind the 3-10 target date to release the production tool program for a 6-30 PPAP.

We will be somewhat flexible and realize you may need a little time to evaluate the part design, but would appreciate as much lead-time as possible. You might want to start your paperwork. We appreciate this opportunity to be of service and value Remington's continued patronage highly.

Best Regards,

Rich Lee

Rich

MF0966



Deer Park Die & Stamping Division

3-01-2000

Fairfield

Deer Park Die & Stamping
Tooling Status ReportCustomer: Remington ArmsPart Number: E-300363Part Name: Mag. Box

Enter Task Completion % Below

Task Name	Duration	Start Date	Finish Date	Wk 1	Wk 2	Wk 3	Wk 4	Wk 5	Wk 6	Wk 7	Wk 8	Wk 9	Wk 10	Wk 11	Wk 12	Wk 13	Wk 14	Wk 15	Wk 16
SO#																			
strip layout		1-17-00	1-21-00	100%															
cross sections		1-24-00	1-27-00		100%														
design complete		1-27-00	2-9-00			100%													
steels received		2-9-00	2-11-00				100%												
components soft machined		2-1-00	2-25-00			10%	25%	55%	100%										
dieset machined		1-28-00	2-23-00						100%										
complete HT & ground		2-9-00	2-25-00				10%	60%	100%										
tryout mtl received		2-9-00	2-17-00					100%											
wire edm & jig complete		2-14-00	2-29-00					60%	100%										
fitting / assembly		2-28-00	3-3-00						100%										
tryout complete		2-28-00	3-8-00							50%									
samples made		3-8-00	3-18-00																
ISIR shipped			3-18-00																

Special Instructions / Notes:

The above Time Line covers both dies
 1st Die has 3 stations. This Die will be ready for tryout 2-25-00
 2nd Die has 4 stations
 While we try out 1st Die the 2nd Die will be fitted and assembled. We will then
 be able to continue the job through the last 4 stations.
 tryout material is in house and we have the first 10 prototype flat
 blanks cut and ready to run through the 1st Die on 2-25-00.

Form #23-1 Rev. 2 9/27/99

3-1-00 Dies are finished. we are now developing blank shape.
 spot welder tips are due in 3-2-00

83

BARBER - 5.22.06P0010917

03/01/00 12:11 DEER PARK DIE & STAMPING INC - 502 856 3233

NO. 688 P002/002

Confidential - Subject - 522P0010917 Order

Williams V. Remington

ME0967

ME09668

02/22/00 16:24 DEER PARK DIE & STAMPING INC → 502 856 3233

NO.465 P001/001

DEER PARK DIE & STAMPING DIVISION

Fairfield

Deer Park Die & Stamping
Tooling Status Report

Customer: Remington Arms

Part Number: E-300363

Part Name: Mag. Box

1-17 Thru 1-21
1-24 Thru 1-28
1-31 Thru 2-4
2-7 Thru 2-11
2-14 Thru 2-18
2-21 Thru 2-25
2-28 Thru 3-3
3-6 Thru 3-10

Enter Task Completion % Below

Task Name	Duration	Start Date	Finish Date	WK 1	WK 2	WK 3	WK 4	WK 5	WK 6	WK 7	WK 8	WK 9	WK 10	WK 11	WK 12
SO #															
strip layout		1-17-00	1-21-00	100%											
cross sections		1-24-00	1-27-00		100%										
design complete		1-27-00	2-9-00			100%									
steels received		2-8-00	2-11-00				100%								
components soft machined		2-1-00	2-25-00			10%	25%	55%							
die set machined		1-28-00	2-23-00						100%						
complete HT & ground		2-8-00	2-25-00				10%	60%							
tryout mtl received		2-9-00	2-17-00					100%							
wire edm & jig complete		2-14-00	2-29-00					60%							
fitting / assemble		2-28-00	3-3-00												
tryout complete		2-28-00	3-8-00												
samples made		3-8-00	3-10-00												
ISIR shipped			3-10-00												

Special Instructions / Notes:

The above Time Line covers Both dies
1st Die has 3 stations. This Die will be ready for Tryout 2-25-00
2nd Die has 4 stations
While we try out 1st Die the 2nd Die will be fitted and assembled. We will then
be able to continue the part through the last 4 stations.
Tryout Material is in house and we hope the first 10 Prototype Flat
blanks cut and ready to run through the 1st Die on 2-25-00.

Form # 23-1 Rev. 2 9/27/99

Date: 2/22	From: Jerry Rossman
Post-it® Fax Note 7671	To: MATT COLEMAN 300-441
	Co: Remington Arms
	Phone #
	Fax # 502-856-3233

BARBER - 5.22.06/0010918



ISO 9001

Deer Park Die & Stamping Division

Fairfield

QUOTATION

December 9, 1999

Remington Arms Company, Inc.
22 Rifle Trail
PO Box 99
Hickory, Ky 42051

Attn: Metty Morgan
Ref: Part # E-300363 rev. 9, Prototypes

We are pleased to submit the following quotation for your consideration.

TOOLING COST

Design and build secondary "soft" tooling to stamp laser-cut parts \$12,500.00

PRODUCTION COST

Quantities:	Price:
10 pcs.	\$188.87 each
100 pcs.	\$ 26.23 each
500 pcs.	\$ 13.17 each
1000 pcs.	\$ 11.83 each

Notes: Prototype parts are to be manufactured on tooling not intended for production runs.

Parts will be bulk packed in Deer Park boxes on a skid.

Material quoted is a 1010/1020 Cold Rolled Steel.

Inspection: Production parts to be sample inspected per Deer Park's internal procedure when no other standard is specified by the client.

Delivery: Tooling, 8 weeks. Production, 2-4 weeks upon receipt of raw material.


Terms: Tooling, 1/3 at PO, 1/3 at sample submission, 1/3 at customer approval.

Terms: Production, Net 30 days.

FOB: Deer Park

Thank you for considering Deer Park Die & Stamping, an ISO 9001 certified firm, as your supplier.

Best Regards,


Jerry Rossman, Sales Engineer


Edward J. Kreuzer, Vice President/General Manager
Copy: Matt Golemboski, Mike Keeney

Golemboski, Matt R.

From: Keeney, Mike
Sent: Tuesday, December 14, 1999 9:35 AM
To: Golemboski, Matt R.; Zajk, Joseph J
Cc: Diaz, Danny
Subject: Couple of things

Matt/Joe,

I spoke with Jerry Rossman at Brainen regarding the feedlip coining suggestion of Metgar. I faxed a marked copy of section B-B to Jerry also. I have asked him to look at a .010 to .020 radius on the underside of the feedlips. He said they could accomplish it by adding another step to their progression and that it would only increase tool costs, not affect piece price. I asked him to review it with their tool guys, send a quote to you, and then based on the cost we would alter the drawing. Look for an updated quote from them in the next week or so.

I also spoke with John Bartrum at Sterling regarding the PM latch issue. It pretty much boils down to a secondary operation to either drill the hole or machine the spring pocket depending on press direction. I can work on the redesign if you are interested in a secondary operation. Let me know if you want to pursue that.

I also spoke with Travis Ayers at Parmatech, they were going to mold boxes last night. If they could fill the tool and obtain green parts, they would have sintered parts in a week. I told him to keep us updated and that as soon as they have processed parts to review, a group of us would be out to discuss path forward. I emphasized the timing. He mentioned his main concern is holding the $\pm .002$ tolerances if they get that far. By no means is it a guarantee. Must be in the MIL-STD-3 Business Code to avoid projecting confidence.

Golemboski, Matt R.

From: Zajk, Joseph J
 Sent: Tuesday, December 07, 1999 1:50 PM
 To: Morgan, Metty E.; Helmer, Gerald A.
 Cc: Golemboski, Matt R.
 Subject: FW: M/710 DAT Components

Importance: High

Metty & Jerry,

Can you see which vendor is most likely at this point to get each of the following parts and ask them if they would be willing to make Mike's 150 pc. sample of each, how much, and when they can deliver? Mike would like to begin his DAT testing for the 710 in mid to late February '00. We would need to let Mike know yea or nay on each component by the middle of next week.

Joe Z.

-----Original Message-----

From: Keeney, Mike
 Sent: Tuesday, December 07, 1999 1:15 PM
 To: Zajk, Joseph J
 Cc: Diaz, Danny; Golemboski, Matt R.
 Subject: M/710 DAT Components

Joe,

Per our discussion yesterday, the following is a list of 710 components that we would like to have DAT samples made by your vendors. Please proceed with procurement of these components. As we discussed, you purchase a minimum quantity of 150 pcs. of each component. If you are not able to supply a component please let me know asap so that I can make arrangements for prototypes through alternate sources.

Thanks

Mike

A-300347-A	THREADED INSERT	1.04
A-300328-1	SIDE PLATE PIN (ORDER 300 PGS, 2 PER GUN)	1.07 CA
B-300351	PIVOT PIN (ORDER 450 PGS, 3 PER GUN)	1.07 CA
B-300407-1	SAFETY SPRING	.06
A-300329-2	BOLT HANDLE PIN	1.10
B-300342-1	EJECTOR	.0
A-300367	EJECTOR SPRING	
C-300334-A	FIRING PIN	1.11
C-300385-2	FIRING PIN TIP	.33
A-300369-D	FIRING PIN SPRING	.10

Golemboski, Matt R.

From: Keeney, Mike
Sent: Tuesday, December 07, 1999 1:43 PM
To: Golemboski, Matt R.; Zajk, Joseph J
Cc: Diaz, Danny; Cook, Todd D.; Danner, Dale
Subject: M/710 Grip Cap Issues

Matt and Joe,

Todd has developed a core change to the stock that will allow us to add use the M/700 grip cap without modification. The change will allow for a snap fit assembly of the stock and grip cap similar to the M/597. The new core design is a line on line match with the grip cap model drawing. Our intent is to build the stock mold as designed and adjust the fit of the grip cap after trial assembly. To ensure the core remains steel safe, we do not want to design more interference than line on line. The alterations to obtain the proper grip cap/stock fit will be steel removal. Todd and I will review the entire stock one more time before forwarding the final file to Par 4. The file should be forwarded by Friday, 12/10/99.

CONFIDENTIAL 83

Golemboski, Matt R.

From: Zajk, Joseph J
Sent: Tuesday, December 07, 1999 9:30 AM
To: Golemboski, Matt R.
Subject: FW: Model 710 Core Issues

I'm having Todd pursue this idea further to see if it pans out.

Joe Z.

-----Original Message-----

From: Cook, Todd D.
Sent: Tuesday, December 07, 1999 8:03 AM
To: Zajk, Joseph J
Subject: RE: Model 710 Core Issues

Joe,

Sounds like you have a good direction. I noticed the tooling cost being an issue and brought it up to the toolmaker, that Par 4 uses for some of it's work (Quality Tooling). Gary Hiliard, their design engineer, seemed to think that a core set that could be used some of the time when the 710 caps are molded in the 700 cap mold would be cheap (a few thousand at most). It may pay for us to get a tool print on that mold to Gary (and other mold makers - TRT, Hi-Tech) and have them quote making a removable core set just for the 710 to fit that mold. That way we could make parts for both with the same mold. It may be a little difficult to find all the prints that you need, but many toolmakers I have worked with can quote something like that from some good photographs of the mold and a drawing of the new core. I can supply the drawing of the new part (and the old one). Let me know what you think.

Todd

From: Zajk, Joseph J
Sent: Monday, December 06, 1999 7:54 PM
To: Cook, Todd D.
Cc: Diaz, Danny; Keeney, Mike; Golemboski, Matt R.
Subject: RE: Model 710 Core Issues
Importance: High

Todd,

Here's a quick summary about what we discussed today and the paths we're pursuing:

- Options 1 & 2 are not viable options
- We will investigate options 3 & 4; in particular we need to see if a 700 grip cap, modified to fit in a 710, will still satisfy the requirements for the 700 stock

We are going to do some experimenting and investigation into the option 3 grip cap modification to see if its viable. If so, we will then need to weight the cost of modifying an existing tool vs. building a whole new one. This will require input from Mayfield, E'town and Ilion as to its viability. If you have any insight as to whether this is a good idea, please let me know.

In conclusion, as it stands now, we are only pursuing those options that give us the optimal coring for the 710 stock, with an emphasis on trying to find a modified 700 grip cap geometry that satisfies both 700 & 710 stocks in order to limit the amount of unplanned capital required. Any info on Ilion's grip cap/stock assembly process that you can offer will be of great help, as Ilion's knowledge base might be temporarily somewhat degraded now that Jeff Swanson is no longer with Remington. We will be attempting to gather as much information as we can from Ilion as well.

Joe Z.

-----Original Message-----

From: Cook, Todd D.
Sent: Friday, December 03, 1999 3:54 PM
To: Zajk, Joseph J
Cc: Diaz, Danny; Keeney, Mike
Subject: Model 710 Core Issues

Joe,

I know that you will be talking about these issues next week early, but I wanted to give you a heads up on the Model 710 core issue. We still have the potential problem of a thin steel condition with the coring as designed.

The issue falls out to a number of choices:

1. Use the current grip cap and have a steel condition that is not ideal. (The thin area in the mold may occasionally have to be repaired)
2. Use the current grip cap and fix the thin steel condition leading to bad sink problems and part distortion in the grip area. No core would be left in the area where your right hand would grip (for a right handed shooter).
3. Use the current grip cap, but sand off part of it so that both the sink and the thin steel condition in the grip area can be eliminated. (The same thing may be able to be accomplished with a new core or core modification in the existing grip cap mold for slightly more \$ but not as much as new grip cap mold)
4. Build a new mold for a grip cap that is idealized for this application, which reduces the piece cost, but drives up the capital needs.

None of these options is ideal, but I feel certain that with some discussion you can arrive at the one that makes the most sense for your current needs. My advice is option 3 to get started and not cause extra expense. It also seems to be more durable and better for cooling. There are other advantages to the current lay out as well like minimizing sink from the screw bosses for the recoil pad. In short, I think option three is best. You may be able to see issues with it, though. I am sending you some pictures (Mike will bring them) that show the cores for these options. They are labeled for the options from this E-mail. Hopefully, they will help you see what I was up against. Anyway, if you guys need more info, I will do whatever I can.

Todd

CONFIDENTIAL 83

ELSON MEETINGS

CONFIDENTIAL 83

MF0975

Golemboski, Matt R.

From: Sacharnoski, Kristan M.
Sent: Tuesday, February 29, 2000 1:47 PM
To: Gooch, Jim C.
Cc: Golemboski, Matt R.; Zajk, Joseph J
Subject: RE: List

Hey Jimmy,

Plan on using the weeks starting with the beginning of April until about the last week of May for runoff and delivery of the new machines. The runoff of the LB 300 will begin the week of April 10 in Louisville with the machine arriving the following week. The progressive weeks will be the runoff and delivery of the Induction, Eddie Current, and finally ending with the Laser Machine around the middle to end of May. Exact dates for the last three machines have not been established. The P.O. on the Laser will probably cut this Friday, bet on 10 weeks for the laser from that date. Consider the riggers that you will need for the LB 300 during its delivery date on the week of April 17th as well as any material needed to move the machine into the barrel cell. Also plan on the delivery of the Crown 4018 or similar model CNC on the first week of April, "give or take a week".

Thank you,

Kristan

-----Original Message-----

From: Gooch, Jim C.
Sent: Tuesday, February 29, 2000 12:52 PM
To: Sacharnoski, Kristan M.
Subject: RE: List

Hey dude, If possible could send me some dates for these runoffs. Thank ya.

From: Sacharnoski, Kristan M.
Sent: Monday, February 21, 2000 3:58 PM
To: Gooch, Jim C.
Subject: List

Here is the list of machines for runoff:

- Induction Hardening Machine
- Eddy Current Tester
- Laser
- LB 300

Each machine will take a most about 3 days for run off.

Golemboski, Matt R.

From: Morgan, Metty E.
Sent: Tuesday, February 29, 2000 1:14 PM
To: Golemboski, Matt R.
Subject: Valco

02/29/2000

Matt,

Valco / Valley Tool said today, that we should have our samples in about a week. (magazine spring)
I will call them again on Monday, the 6th as a follow up.

Also, I spoke with Gordon Dill, Engr. Mngr. for Northwest (bolt handle supplier),
I asked him to revisit the cost of the tool rebuild. I explained to him why I felt Remington
should not bare the brunt of the total expense. Joe was in on the conversation. Gordon is
going to discuss it further with William Somerville, General Manager, and get back with us.

Mett

CONFIDENTIAL 83

Golemboski, Matt R.

From: Keeney, Mike
Sent: Monday, February 28, 2000 9:45 AM
To: Zajk, Joseph J
Cc: Golemboski, Matt R.; Diaz, Danny
Subject: 710 drawings

I am shipping the following drawings today:

Box Bottom D-300365 Rev.20: Moved spring pocket rearward .130 and added Text recessed pocket
Bolt Head Magnum C-300416 Rev. F: C datum change
Trigger C-300435 Rev. C: Corrected dimesions per your request
Follower D-300364 Rev. 16: moved spring pocket .130 rearward, added clearance for box changes
Magazine Box E-300363 Rev. 14: adjustments for spot welding per Brainen rquest.

Mike

CONFIDENTIAL 83

FYI
COPY 01/06**Morgan, Metty E.**

From: Keeney, Mike
Sent: Thursday, January 06, 2000 11:56 AM
To: Morgan, Metty E.
Subject: RE: 710 Purchased Parts

Mett,
 here's my thoughts per part:

300327 Receiver Insert-- Mold is complete, Joe to inspect parts
 300333 Side Plate--OK to order tool
 300334 Safety-- Do not order, waiting for marketing approval
 300345 Bolt Stop--OK to order tool
 300361 Recoil Bracket--OK to order tool
 300360 Bolt Handle Blank--Do not order, waiting for knurling decision
 300366 Bolt Handle Braze--OK to order
 300368 Bolt Plug--OK to order tool
 300336 Firing Pin Head--OK to order tool
 300362 Magazine Latch--OK to order tool
 300363 Magazine Box--Hold/may order prototype tool?
 300364 Magazine Follower--OK to order tool
 300365 Magazine Bottom--OK to order tool, indicate insert will be required for

artwork 83

the partslist has all current levels of revisions, you should be linked to it to view, if not let kristan know, he can link you.

Any problems let me know
 Thanks
 Mike

From: Morgan, Metty E.
Sent: Thursday, January 06, 2000 11:58 AM
To: Keeney, Mike
Subject: 710 Purchased Parts

01/06/00.

Mike,

When you let me know which parts I can order, please include the latest and greatest Rev. level so I will be sure to use the most current dwg. when ordering.

Thanks,
 Mett

Remington Arms Company, Inc.
December 7, 1999

CONFIDENTIAL

Research and Development Technology Center
Elizabethtown, Kentucky

Mayfield Visit, Dec. 6, 1999

Attendance: Mayfield -- M. Golemboski, J. Zajk, S. Truax, G. Helmer
R&D -- D. Diaz, E. Schoppman, M. Keeney

M/ 710 Review:

Stock Grip Cap - Mayfield to investigate alteration of current M/700 grip cap mold to allow for common usage of grip cap for M/700 and M/710. If alterations are not possible, the development of a M/710 specific mold will be required.

Bolt Handle Assembly - Modification of the bolt handle pin will be required to eliminate burrs generated while pressing the pin into the bolt handle. The bolt body clearance cut on the bolt handle will be altered to .690" dia. to improve the braze characteristics.

Receiver and Bolt Body Drawings - Alterations requested by Mayfield to improve design intent relative to location and inspection of the components.

Magazine Bottom and Follower - The two components will be molded in a family tool, thus common material specifications are required.

Magazine Box - R&D will contact Deer Park Stamping to review possible coining operations to remove sharp edge on underside of feed lips. Drawings will be updated following the determination of resultant geometry.

Latch - Mayfield will quote as a Powder Metal component as back up to current synthetic direction. Based on cost, the group will decide if a metal latch is feasible. Concern is that the revised latching surface of the box may deform a synthetic latch. R&D to review synthetic material selection.

Stock Bushing Assembly - Mayfield to review stock bushing assembly and advise if there are design issues with current system.

Receiver Insert - Inspection report, program and fixture due this week, following setup, current receiver inserts will be inspected. Tool corrections to be based on inspection data and then trial quantity (1000-5000 pcs) of receiver inserts will be ordered.

Bolt Plug with ISS - R&D to generate exploded view of assembly. Mayfield to locate ultrasonic welder and proceed with assembly process development. Mayfield to investigate alternative processes to manufacture the bolt plug, such as investment casting.

Michael D. Keeney
Staff Engineer

Page 1 of 2

Mayfield Visit 12-06-99

MF0980

Remington Arms Company, Inc.
December 7, 1999

CONFIDENTIAL

Research and Development Technology Center
Elizabethtown, Kentucky

DAT Schedule - Design Acceptance Testing of 30-06 caliber firearms is scheduled to begin mid February, based on delivery of receiver and bolt body tubing. Mayfield vendors will be used to provide as many of the components as possible based on delivery schedules. Mayfield to investigate procurement of MIM material blanks for machining of firing pin heads. Final assembly of the DAT firearms will be in Mayfield. Following successful completion of the 30-06 DAT, the 270 DAT will follow in April.

Bolt Action Rimfire Review:

R&D presented the staffing and program direction for the Bolt Action Rimfire introduction. The first phase of the program will be to develop and verify a design concept. Upon preliminary verification of the design function through initial prototyping, process development and costing will follow. The objective is to have a detailed schedule by the end of January 2000.

Michael D. Keeney
Staff Engineer

Page 2 of 2

Mayfield Visit 12-06-99

MF0981

CONFIDENTIAL

11147214C SEC 3

MF0982

To: Joe Zajk
 From: James Urban
 Date: June 27, 2000
 Re: M/710 Barrel Locking Lug Microhardness

It was requested that microhardness measurements be made on the locking lugs of two M/710 barrels that were provided by Joe Zajk. The barrels were sectioned through a locking lug and then mounted and polished. Microhardness measurements, using the 1000g Vickers scale, were then taken through the locking lug, starting at the inside surface and spaced every 0.020". Figure 1 shows the location of the indents. The results are shown in figure 2. It appears that the parts are a little hard.




Figure 1: Location of Microhardness Indents.

Field #	Sample #1		Sample #2	
	Hardness		Hardness	
	HRC	Hv	HRC	Hv
1	46	457	47.8	482
2	47.1	472	48	484
3	46.4	463	47	471
4	46.3	462	47.4	476
5	47.6	479	47.8	481
6	46	458	47.2	474
7	46.3	462	48	484
8	46.2	460	47.7	480
9	46.5	464	47.2	474
10	47.2	474	47.2	473
11	45.3	450	44.4	439
12	44.4	439	47.2	473
Average	46.275	461.6667	47.24167	474.25
Std. Dev	0.85187	10.67992	0.960548	12.01609

Figure 2: Results of Microhardness Measurement.

James Urban
 Engineer

Page 1 of 1

MF0983

Remington®

REMINGTON ARMS COMPANY, INC.

22 RIFLE TRAIL
P.O. BOX 99
HICKORY, KY 42051

TEL: 270-856-4200
FAX: 270-856-3233

3/31/00

Mr. Sam Todd
Par 4 Plastics, Inc.
P.O. Box 385
Marion, KY 42064

Dear Sam,

As per our meeting on Friday, March 31st, this letter is to confirm the agreement on RTP material. Per a conversation between Steve Clemans of RTP and myself, Par 4 should be able to order 710 stock material from RTP at the quoted Remington cost per specific volume.

As the volumes increase the cost goes down, and it is in the best interest of all parties that the largest reasonable volume be ordered. Steve Clemans has agreed to reviewing a blanket order purchase plan that would allow Par 4 to order direct at Remington cost and have monthly quantities released against the PO. I would suggest you contact Steve and work out the plan that best suites the stock program.

Remington will commit to the maximum volume of 24,000# at this phase of the 710 program. Should the program slow or be deleted, Remington will pay for all remaining RTP material that Par 4 might still have for the 710 program, from this initial order.

If you have any questions or comments in regard to the above, please feel free to contact me.

Sincerely,

Metty E. Morgan

Metty E. Morgan
Materials Manager
Remington Arms Company, Hickory

cc: Matt Golemboski
Steve Clemans

MF0984

Golemboski, Matt R.

From: Cook, Todd D.
Sent: Monday, February 28, 2000 12:39 PM
To: Keeney, Mike; Golemboski, Matt R.
Subject: Mold Try-out on Bolt Plug

Mike & Matt,

Mike Bennett called from Kellems & Coe, and they want to do a trial on the new Bolt Plug mold on Friday. They wanted some help getting the material--which as you know has been specified the same as the stock, but in black.

I do NOT have the currently specified material, RTP 199X83039E, in black. However, I did have 199X83039D in black; and I shipped it to Kenny at Kellems & Coe, so they will have it in time for the Friday trial.

The "D" version differs from the currently specified "E" grade only in the UV stabilizer--which will not effect the color, shrink, or properties (other than UV stability). "D" should be fine for tool check out for dimensions and for testing. The correct thing to do is to order the "E" material and re-sample for T&P; but I am not convinced that would be necessary, as we do no long-term weathering tests in T&P. For EET & even DAT, I think these parts will be fine. We just need to make sure that the final product has the "E" version for added UV stability.

ASIDE

This bolt plug material is a common material with M/597 Magnum Stocks, so there may be some volume discounts available. If you need more info on the specifics, let me know.

Todd

CONFIDENTIAL

Golemboski, Matt R.

From: Cook, Todd D.
Sent: Monday, February 28, 2000 8:47 AM
To: Zajk, Joseph J
Cc: Golemboski, Matt R.; Morgan, Metty E.
Subject: RE: 710 Stock Color Sample

Joe,

I received the new color number from RTP. To order what we are now calling the M/710 material, you need:

RTP 199X83039E in S-880849

I have 100 pounds in house (reportedly) this morning--it shipped yesterday from RTP in Indianapolis. What I am planning to do now is to get a sampling run done on the M/597 prototype mold as soon as I can. I will ship the resulting parts to you and you can forward. If the sampling is at Par 4, would you want to come over?

Todd

From: Zajk, Joseph J
Sent: Friday, February 25, 2000 3:00 PM
To: Cook, Todd D.
Cc: Golemboski, Matt R.; Morgan, Metty E.
Subject: RE: 710 Stock Color Sample

We would prefer to have Par 4 buy the material, but we will try to get them the price they would give us as a "national" account. As it stands right now we are going to have the color used for the 710 alone.

Let us know when you get the RTP information.

Thanks for the info.

Joe Z.

-----Original Message-----
From: Cook, Todd D.
Sent: Friday, February 25, 2000 1:47 PM
To: Zajk, Joseph J
Subject: RE: 710 Stock Color Sample

Joe,

The new RTP 199X83039E was developed to match the DSM Material. It is a high flow, 20% chemically-coupled glass-filled polypropylene homopolymer with UV stabilizer just like DSM J-60/20/E/HF/UV--the current M/597 material. The purpose of all this craziness was to give us a chance to use a competitive process to get the price down on M/597 and to bring in the M/710 material BELOW budget, since its budget was based on the current material price.

Now, let's see...

RTP 199X83039E is a new grade and RTP's color numbers are grade specific, so they will have to issue new numbers (a formality as the UV stabilizer will not effect the color). I have requested those, I bet I should know something by Monday PM. Once I have it, I will send you an E-mail with the info. That will be color numbers for the three colors, so you can order them. Also, once the color numbers are issued, we can (and have) requested updated pricing to see if we can save some. I have informed these guys that their price needs to be exciting. Tell Metty that if she is not excited by it that she can tell them that. "Todd Cook said I would be excited--I ain't excited. Give me something better!" or words to that effect.

If you agree that the new RTP material's price is attractive, I would suggest that we negotiate a contract rate for the materials and have RTP ship to Hanson and Par 4 directly. If you are not going to "combine" the M/710 volume with M/597 volume, the price won't be as good, so you might think Par 4 could buy for the same cost as us...but ... the national accounts manager has some clout in RTP on pricing as RTP is trying this way of working with multi-region firms, which may lead to a better number than if Par 4 calls their RTP Sales Engineer and asks for this material. Besides, to keep Par 4 sharp, you want to know exactly what the resin costs.

I will get the color numbers to you as soon as I have them.

If we don't talk again on this one today, have a great weekend.

Todd

From: Zajk, Joseph J
Sent: Friday, February 25, 2000 1:38 PM
To: Keeney, Mike; Cook, Todd D.; Golemboski, Matt R.
Subject: FW: 710 Stock Color Sample
Importance: High

Its a go for the color.

Mike & Todd; please make sure the RTP chemical makeup (UV resistance, etc.) is agreeable to both of you.

Todd: Please confirm the shrink matching of the RTP material to the original material specified and let me know if its OK so I can tell Par 4 the material. If RTP is going to assign a new color number for this please let me know what it is.

The last question is: do we go through this new 'national accounts' program Todd was talking about or do we let Par 4 handle the material buy? Please let Matt & myself know you thoughts on this.

Thanks,

Joe Z.

-----Original Message-----

From: Kohler, Drew
Sent: Friday, February 25, 2000 12:32 PM
To: Zajk, Joseph J
Cc: Golemboski, Matt R.; Russo, Alfred D.; Cook, Todd D.
Subject: RE: 710 Stock Color Sample

Joe,

Al & I took a look at it yesterday and even though it's tough to tell what an entire stock will look like in that color, we feel that this color will work.

You have marketing's approval to proceed.

Drew

-----Original Message-----
From: Zajk, Joseph J
Sent: Friday, February 25, 2000 12:07 PM
To: Kohler, Drew
Subject: 710 Stock Color Sample

What do you think of the color? Let me and Matt know.

Thanks,

Joe Z.

Golemboski, Matt R.

From: Jiranek, Marlin R.
Sent: Tuesday, March 07, 2000 2:33 PM
To: Morgan, Metty E.; Zajk, Joseph J; Golemboski, Matt R.
Cc: Danner, Dale
Subject: RE: Material Specification

Here is the scoop - - -

Yes, the changes are OK (per my E-mail of 3/6) and the specification has been changed to 704 and is currently updated and ready to print on the server. This message was sent to you, and copied Zajk and Keeney. The new specification incorporates the changes Republic wanted with exception of using billets without size limitation (blooms are acceptable). To view and get access to the spec. simply follow the instructions of the e-mail I sent (2/21, "Material Specs and Material Codes"). If you need, I can re-send this e-mail to you. With the On-Line system, you have access to all of the specs which are generated for use from Elizabethtown. . . .

-----Original Message-----

From: Morgan, Metty E.
Sent: Tuesday, March 07, 2000 2:13 PM
To: Jiranek, Marlin R.
Cc: Zajk, Joseph J; Golemboski, Matt R.
Subject: RE: Material Specification

Ok, here is where I stand. I do not have a copy of any Material Spec that is number 704 in my file. I have #124. I need to place an order for 710 barrel material as soon as possible. Someone in the Engineering Dept. needs to let me know if the quote from Republic Steel is "Ok as is" to place this PO. Republic told me today the MIL Spec you have asked for is not faxable or mailable. It is on a 40 x 48 poster, and they suggested you contact the Government to get a copy of it. Can you or Joe Zajk please give me an answer as to whether or not the Exceptions noted on the Republic Steel Quote are acceptable. Thanks, Mett

-----Original Message-----

From: Jiranek, Marlin R.
Sent: Tuesday, March 07, 2000 11:52 AM
To: Morgan, Metty E.
Subject: RE: Material Specification

Not the Mil Spec - I mean could you view and print Spec 704 satisfactorily? ? ? ?

-----Original Message-----

From: Morgan, Metty E.
Sent: Tuesday, March 07, 2000 12:21 PM
To: Jiranek, Marlin R.
Subject: RE: Material Specification

He is looking into sending it to me this morning. The gentleman I normally deal with, (Mark Sullivan) is out this whole week.

I hope the guy I talked with this morning can get the info. I will keep you posted. Thanks, Mett

-----Original Message-----

From: Jiranek, Marlin R.
Sent: Tuesday, March 07, 2000 10:42 AM
To: Morgan, Metty E.
Subject: Material Specification

met,

Did you get all the info you needed regarding the M/710 Bbl Steel spec from Republic. It is the first attempt at using the ON-Line spec system between us. Just wanted to know. . . .

Marlin.

Marlin R. Jiranek, II
 Research Engineer
Remington Arms Company, Inc.
 Phone: (270) 769-7645
 FAX: (270) 737-9576
 E-mail: jiranekmr@etown.remington.com

MF0988

Golemboski, Matt R.

2000-14

From: Keeney, Mike
Sent: Tuesday, March 07, 2000 8:17 AM
To: Morgan, Metty E.
Cc: Golemboski, Matt R.
Subject: firing pin spring 300399 rev. E

Mett,
I have faxed the new firing pin spring drawing to your attention, A-300399 Rev. E. Please copy and replace 300399 Rev. D in drawing files. Also check delivery of a 15 piece minimum sample by 3/14/00.

thanks
Mike

CONFIDENTIAL 83

**FEDERAL STEEL SUPPLY, INC.**

747 Goddard Ave
P.O. Box 840
Chesterfield, MO 63006
636-537-2393 • 800-325-1584
FAX 636-537-8795

FEDERAL STEEL QUOTE#	71033	PAGE: 1
SALESMAN #	3	3 Vernon C. Smith
WAREHOUSE	2	
PROS / CUST #	51924	51924
QUOTE DATE	11/10/99	

ATTENTION: JOE ZAJK

FREIGHT INFO:

CUSTOMER P.O.#

YOUR INQUIRY #

COMPANY: REMINGTON ARMS CO.
MAYFIELD PLANT
P.O. BOX 99
HICKORY, KY 42051

ACCEPTED BY:

QUOTATION

LINE#	DESCRIPTION & PIECE LENGTH	QTY	PRICE	U/M	POUNDS	ITEM TOTAL
	REGRET 5' LENGTHS / 10' MNS ONLY LEAD TIME 7/8 WEEKS DEL PRICE / BOXED TO YOUR PLANT					
1	1.400 OD X 1.047 ID 12'6"	300 FT	4.8200	FT		1,266.00
	OD TOL: +.005/ -.000 ID TOL: -.000/ -.004 .010 MAX WALL VARIATION 11000' QTY PRICE =2.89/FT					
2	.6930 OD X .5010 ID 12'6"	300 FT	1.7700	FT		531.00
	OD TOL: +.003/ -.000 ID TOL: +.000 - .004 11000' QTY PRICE =1.12/FT					
This quotation and all sales resulting from it, are subject to FSSI Standard Terms & Conditions of Sale which are available upon your request.						TAXABLE TOTAL SALES TAX

ALL ITEMS ARE OFFERED SUBJECT TO PRIOR SALE. PRICES IN U.S.\$
ALL PRICES SUBJECT TO FINAL CONFIRMATION
TERMS: NET 30 DAYS UPON APPROVAL.
Visit our Web site at <http://www.fedsteel.com>

TOTAL AMOUNT	\$ 1,797.00
--------------	-------------

WT TOTAL

MF0990

Golemboski, Matt R.

From: Golemboski, Matt R.
Sent: Monday, January 31, 2000 12:17 PM
To: Keeney, Mike; Zajk, Joseph J
Subject: RE: Model 710 firing pin head FEA.

Mike, Looking at the lateral constraints and the location of the resultant stresses, do you think the lateral constraint patch is correct? I thought it would be more of a smaller area angling from the intersection of the "face of the head" the large flat surface with the hole and the location where the bottom of the head intersects cantilever. Usually when there is a mistake in modeling its in the constraints. Just a question.

-----Original Message-----

From: Keeney, Mike
Sent: Tuesday, January 25, 2000 3:12 PM
To: Golemboski, Matt R.; Zajk, Joseph J
Subject: FW: Model 710 firing pin head FEA.

Assuming the yield strength of the MIM material meets the specification, we should be OK. Marlin is going to test MIM samples to verify yield strength. Will keep you updated.

From: Rages, Brian L
Sent: Tuesday, January 25, 2000 2:51 PM
To: Keeney, Mike
Subject: Model 710 firing pin head FEA.

Mike,

Here is my report on the FEA I did on the 710 firing pin head. I'm interested in any feedback you have. It might be helpful to do the same analysis on a Model 700 firing pin head for comparison.

<< File: Firing Pin Head FEA.doc >>

-- Brian Rages

Haley, Melissa A.

From: Golemboski, Matt R.
Sent: Wednesday, January 26, 2000 7:45 AM
To: Haley, Melissa A.
Subject: FW: Model 710 firing pin head FEA.

please print this on your color printer. thanks

-----Original Message-----

From: Keeney, Mike
Sent: Tuesday, January 25, 2000 3:12 PM
To: Golemboski, Matt R.; Zajk, Joseph J
Subject: FW: Model 710 firing pin head FEA.

Assuming the yield strength of the MIM material meets the specification, we should be OK. Marlin is going to test MIM samples to verify yield strength. Will keep you updated.

From: Rages, Brian L
Sent: Tuesday, January 25, 2000 2:51 PM
To: Keeney, Mike
Subject: Model 710 firing pin head FEA

Mike,

Here is my report on the FEA I did on the 710 firing pin head. I'm interested in any feedback you have. It might be helpful to do the same analysis on a Model 700 firing pin head for comparison.


Firing Pin Head
FEA.doc

-- Brian Rages

Model 710 Firing Pin Head Finite Element Analysis

Brian Rages

1/26/00

OBJECTIVE

The purpose of this analysis is to evaluate the distribution of stress through the cam surface of a firing pin head developed for the Remington Model 710 rifle.

CONCLUSIONS

An ANSYS model was used to predict stress distribution in the firing pin head resulting from bolt-opening forces. Two areas of high stress were predicted. Along the 0.004-inch wide contact surface between the firing pin head and the bolt body, stress was predicted to be around 120,000 psi, below the 190,000 psi yield strength of the material. At small patches at the ends of this surface, however, predicted stress rose well over 200,000 psi. It is likely that a small degree of plastic deformation will occur at these patches, widening the contact area until the stress is spread out below the material's yield strength.

Another location of significant stress occurred on the edge of the lateral constraint applied on the firing pin head by the bolt plug. Stress along the edge was predicted by the ANSYS analysis to be around 30,000 psi, with a peak of 53,000 psi occurring in a small area at the end of the patch.

THEORY

The loading conditions at the firing pin head were calculated as follows:

The bolt body cam surface is a helix with 2.18 inches of rise per turn. The angle of a surface on the helix is given by

$$\theta = \tan^{-1} \frac{2.18}{\pi \cdot d}$$

where d is the diameter of the location on the helix. Using d values of 0.498 and 0.695, the inner and outer diameters of the bolt body, resulted in slopes of 55 and 45 degrees, respectively. The average, a slope of 50 degrees, was used to calculate forces.




Figure 1. Diagram of stresses.

Figure 1 depicts the stress situation in the firing pin head. B represents the normal force applied to the firing pin head by the bolt body. F is the frictional force applied to the firing pin head by the bolt body. T represents the force applied to the firing pin head by the firing pin spring. L is the lateral force applied by the bolt plug on the firing pin head. F is related to B by

$$F = \mu \cdot B$$

where μ represents the coefficient of friction between the two surfaces. *Mark's Engineering Handbook* gives μ values for steel-on-steel contact of 0.4 to 0.01, depending on lubrication. 0.4, the value for dry contact, was used.

The vertical components of the forces in Figure 1 were added and set to zero, resulting in

$$T + Fy - By = 0$$

The y components of B and F are given by

$$Fy = F \cos 50^\circ = B\mu \cos 50^\circ$$

and

$$By = B \sin 40^\circ$$

resulting in

$$T + B\mu \cos 50^\circ - B \sin 40^\circ = 0$$

From the spring specifications, T is 20 lbs. The above equation may be solved for B as

$$B = \frac{20}{\sin 40^\circ - 0.4 \cos 50^\circ} = 51.86 \text{ pounds}$$

Friction may be solved for from B :

$$F = \mu \cdot B = 0.4 \cdot 51.86 = 20.74 \text{ pounds}$$

Roark's Formulas for Stress & Strain gives the following equation for width of a contact patch in the interface between a cylinder and flat plate if both materials have a Poisson's ratio of 0.3 and share the same modulus of elasticity:

$$b = 2.15 \sqrt{p \frac{K_D}{E}}$$

where b is the contact patch width, p is the force over the length of the cylinder, K_D is the diameter of the cylinder, and E is the modulus of elasticity for the the plate and cylinder. Entering the appropriate values for the firing pin head to bolt body interface gives

$$b = 2.15 \sqrt{\frac{51.86 \cdot 0.170}{0.079830 \times 10^6}} = 4.13 \times 10^{-3} \text{ inches}$$

PROCEDURE

The analysis was conducted on a CADD5 model of the firing pin head developed for the Remington Model 710. The CADD5 model was simplified by the removal of all fillets not in the area of the cam surface. Faces on the model were split to provide a location to apply the side constraints and cam surface pressure. The model was brought into ANSYS. It was meshed with 10-node tetrahedral elements using the ANSYS Smartmesh tool with a coarseness level of six. The areas of the protrusion on which the cam surface acted were refined with ANSYS's Meshtool and a refinement level of one. The meshed model may be seen in Figure 2.




Figure 2. Meshed model of firing pin head.




Figure 3. Constraints placed on model.

The model was constrained as follows: A longitudinal displacement constraint and a vertical displacement constraint were placed on the cylindrical area where the firing pin head attached to the firing pin. The lateral position of the firing pin head was fixed by placing displacement constraints on the areas where the bolt plug cradled the cam surface protrusion of the firing pin head. The location of the displacement constraints may be seen in Figure 3.

The load on the cam surface was applied in two components. The force normal to the cam surface was applied as a 158,000-psi pressure over the entire 0.0041

wide area. This represented a force of 51.86 pounds. The second component of the cam surface load was the force applied by the friction between the cam surface of the firing pin head and the bolt body. This was applied by selecting all the nodes on the 0.0041-inch wide area, rotating the node coordinate system 50 degrees and applying a force to each node in the negative *y* direction of the new coordinate system. The mesh had resulted in 317 nodes on the contact area, so the frictional force of 20.74 pounds was applied as a force of 0.06544 pounds per node.

After the model had been fully constrained and loaded, the analysis was solved using the ANSYS PEG solver with a tolerance of 10^{-8} .

RESULTS




Figure 4. Stress distribution in firing pin head.


The Von Mises stress distribution predicted by the ANSYS model may be seen in Figure 4. Peak stress is concentrated in the 0.004-inch wide contact patch. Stress along the contact patch surface runs around 120,000 psi. Both the bottom and top ends of this patch contain areas, shown in gray on the above figure, where stress exceeds the 190,000 psi yield strength of the firing pin head material. One node on the bottom area returned a stress over 500,000 psi. The firing pin head may be expected to deform plastically in the regions at the ends of the contact patch. Plastic deformation in these areas will widen the contact patch area even out the stress distribution until stresses are below the yield strength of the material.

Another location of significant stress is farther back on the protrusion of the firing pin head, at the edge of the area where lateral constraints were applied. Stress in this location runs around 30,000 psi, peaking at 53,000 psi at the top end of the edge. The same pattern and levels of stress occur on the other side of the part.

APPENDIX

This appendix contains an enlarged Figure 4, as well as other views of the stress results.

Figure 4 (enlarged). Von Mises stress distribution in firing pin head.



ANSYS 5.5.1
JUN 24 2000
16:15:43
NODAL SOLUTION
STEP=1
SUB =1
TIME=1
SEQV (RVG
PowerGraphics
EFFECT=1
AVRES=Mat
DMX =.486E-03
SMN =13.461
SMX =413833
0
21111
42222
63333
84444
105556
126667
147778
168889
190000




Figure 5. Von Mises stress distribution in firing pin head, other side




Figure 6. Von Mises stress distribution, closeup of contact patch.

ANSYS 5.5.1
 JAN 24 2000
 16:13:52
 NODAL SOLUTION
 STEP=1
 SUB =1
 TIME=1
 SEQV (AVG)
 PowerGraphics
 EFACET=1
 AVRES=Mat
 DMX =.486E-03
 SMN =13.461
 SMX =413833
 0
 21111
 42222
 63333
 84444
 105556
 126667
 147778
 168889
 190000

Remington Arms Company, Inc.

MATERIAL SPECIFICATION #C4140

Material: Modified AISI 4140 Material intended for use in investment casting applications requiring high hardness properties in the finished product. This specification designed for use during prototyping of investment cast parts.

Analysis: The analysis of this material, shall check within the limits listed below.

Iron	(Fe)	Balance	Sulfur	(S)	0.040% MAX.
Carbon	(C)	0.40% - 0.45%	Silicon	(Si)	0.60% MAX.
Manganese	(Mn)	0.75% - 1.00%	Chromium	(Cr)	0.80% - 1.10%
Phosphorous	(P)	0.035% MAX.	Molybdenum	(Mo)	0.15% - 0.25%

Condition: The material is to be delivered to Remington as a cast part followed by a Carbon Restore / Anneal heat treatment as specified in this specification.

Certification: A copy of a chemical analysis from (1) the master melt alloy and (2) each investment tree is to be supplied with each shipment.

Heat Treatment: Choose either of the processes below.

**ALL PROCESSING TO BE DONE IN 0.40% - 0.45% CARBON
POTENTIAL ATMOSPHERE**

Heat to 1555°F (845°C) – Hold for 90 minutes or 1 hr/in casting thickness whichever is longer
Cool Rapidly to 1390°F (755°C)
Cool to 1230°F (665°C) rate not to exceed 25°F (14°C)/hr

Heat to 1555°F (845°C) – Hold for 90 minutes or 1 hr/in casting thickness, whichever is longer
Cool rapidly to 1245°F (675°C) – Hold for 5 hr

Identify: Each part should be marked with a permanent mark (scribe or stamp) tracing the chemistry to both the master melt alloy chemistry and the investment tree chemistry. This mark should be placed on the casting in the locations indicated on the cast blank prints, supplied by Remington Arms Company, Inc.

Remington Arms Company, Inc.

MATERIAL SPECIFICATION #602**MANDREL DRAWN, COLD FINISHED CARBON STEEL TUBING**

Spec. No. 602	-MD	Mandrel Drawn, No Thermal Treatment
	-MDSR	Mandrel Drawn, Stress Relieved
	-MDSA	Mandrel Drawn, Soft Annealed

Material: AISI 1018 Cold Finished Steel Tubing**Analysis:** The material shall conform to Grade Designation 1018 (ASTM A513-98).
The analysis of this material shall check within the limits listed below.

Carbon	(C)	0.14-0.20	- 0.02% +0.03%
Manganese	(Mn)	0.60-0.90	+/- 0.04%
Phosphorus	(P)	0.035	MAX.
Sulfur	(S)	0.035	MAX.

Quality: The tubing shall be cold finished, externally and internally (mandrel drawn). All material furnished under this specification shall be of commercial quality unless stated otherwise in the buyer's purchase order, and shall meet all applicable requirements of ASTM Specification A513-98, "Standard Specification for Electric-Resistance-Welded Carbon & Alloy Steel Mechanical Tubing".**Tolerances:** All material shall be furnished to the tolerances stated in ASTM Specification 513-98, unless otherwise specified on the buyer's purchase order.**Identify:** All material shall be tagged to show (1) the name of the vendor, (2) heat number, (3) size of the stock, and (4) Remington Specification Number.



Designation: A 513 - 98

An American National Standard

AMERICAN SOCIETY FOR TESTING AND MATERIALS
100 Barr Harbor Dr., West Conshohocken, PA 19428
Reprinted from the Annual Book of ASTM Standards, Copyright ASTM

Standard Specification for Electric-Resistance-Welded Carbon and Alloy Steel Mechanical Tubing¹

This standard is issued under the fixed designation A 513, the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ε) indicates an editorial change since the last revision or reapproval.

This standard has been approved for use by agencies of the Department of Defense

1. Scope

- 1.1 This specification covers electric-resistance-welded carbon and alloy steel tubing for use as mechanical tubing.
- 1.2 This specification covers mechanical tubing made from hot- or cold-rolled steel.
- 1.3 This specification covers round, square, rectangular, and special shape tubing.

Type	Size Range (Round Tubing)
Electric-Resistance-Welded Tubing from Hot-Rolled Steel	outside diameter from ½ to 15 in. (19.0 to 381.0 mm) wall from 0.065 to 0.650 in. (1.65 to 16.50 mm)
Electric-Resistance-Welded Tubing from Cold-Rolled Steel	outside diameter from ¾ to 12 in. (9.92 to 304.8 mm) wall from 0.022 to 0.134 in. (0.71 to 3.40 mm)

- 1.4 Optional supplementary requirements are provided and when desired, shall be so stated in the order.
- 1.5 The values stated in inch-pound units are to be regarded as the standard.

2. Referenced Documents

- 2.1 *ASTM Standards*²
 - A 370 Test Methods and Definitions for Mechanical Testing of Steel Products
 - E 89 Practice for Sampling Steel and Iron for Determination of Chemical Composition³
 - E 213 Practice for Ultrasonic Examination of Metal Pipe and Tubing⁴
 - E 273 Practice for Ultrasonic Examination of Longitudinal Welded Pipe and Tubing⁴
 - E 309 Practice for Eddy-Current Examination of Steel Tubular Products Using Magnetic Saturation⁴
 - E 570 Practice for Flux Leakage Examination of Ferromagnetic Steel Tubular Products⁴
- 2.2 *ANSI Standard*:

¹ This specification is under the jurisdiction of ASTM Committee A-1 on Steel, Stainless Steel, and Related Alloys and is the direct responsibility of Subcommittee A01.09 on Carbon Steel Tubular Products.

Current edition approved Sept. 10, 1998. Published March 1999. Originally published as A 513 - 64. Last previous edition A 513 - 97a.

² *Annual Book of ASTM Standards*, Vol 01.03.

³ *Annual Book of ASTM Standards*, Vol 03.05.

⁴ *Annual Book of ASTM Standards*, Vol 03.03.

B 46.1 Surface Texture⁵

2.3 *Military Standards*:

MIL-STD-129 Marking for Shipment and Storage⁶

MIL-STD-163 Steel Mill Products Preparation for Shipment and Storage⁶

2.4 *Federal Standard*:

Fed. Std. No. 123 Marking for Shipments (Civil Agencies)⁶

3. Ordering Information

3.1 Orders for material under this specification should include the following as required to adequately describe the desired material:

- 3.1.1 Quantity (feet or number of lengths),
- 3.1.2 Name of material (electric resistance-welded carbon or alloy steel mechanical tubing),
- 3.1.3 Type, description and code letters, (Section 1 and 12.1),
- 3.1.4 Thermal condition, (12.2),
- 3.1.5 Flash condition, (12.3),
- 3.1.6 Grade designation, if required, (Section 5),
- 3.1.7 Report chemical analysis and product analysis, if required (Sections 6 and 7),
- 3.1.8 Individual supplementary requirements, if required (S1 to S10, inclusive),
- 3.1.9 Cross section (round, square, rectangular and special shapes),
- 3.1.10 Dimensions, round, outside and inside and wall thickness (see 8.1 and 8.2) or square and rectangular, outside dimension and wall thickness and corner radii, if required (see 9.1 and 9.2),
- 3.1.11 Length, round, mill lengths or definite cut length (see 8.3), square and rectangular, specified length (see 9.4),
- 3.1.12 Squareness of cut, round tubing, if required, (see 8.4),
- 3.1.13 Burrs removed, if required (see 11.3),
- 3.1.14 Protective coating (see 14.1),
- 3.1.15 Special packaging (see 17.1),
- 3.1.16 Specification designation,

⁵ Available from American National Standards Institute, 11 West 42nd St., 13th Floor, New York, NY 10036.

⁶ Available from Standardization Documents Order Desk, Bldg. 4 Section D, 700 Robbins Ave., Philadelphia, PA 19111-5094, Attn: NPODS.

A 513

TABLE 1 Chemical Requirements for Standard Low-Carbon Steels^A

NOTE 1—Chemistry represents heat analysis. Product analysis, except for rimmed or capped steel, is to be in accordance with usual practice as shown in Table 3.

Grade Designation	Chemical Composition Limits, %			
	Carbon	Manganese	Phosphorus, max	Sulfur, max
MT ^B 1010	0.05–0.15	0.30–0.60	0.035	0.035
MT 1015	0.10–0.20	0.30–0.60	0.035	0.035
MT X 1015	0.10–0.20	0.60–0.90	0.035	0.035
MT 1020	0.15–0.25	0.30–0.60	0.035	0.035
MT X 1020	0.15–0.25	0.70–1.00	0.035	0.035

^A Rimmed or capped steels which may be used for the above grades are characterized by a lack of uniformity in their chemical composition, and for this reason product analysis is not technologically appropriate unless misapplication is clearly indicated.

^B The letters MT under grade designation indicate Mechanical Tubing.

- 3.1.17 End use,
3.1.18 Special requirements, and
3.1.19 Special marking (Section 16).

4. Materials and Manufacture

- 4.1 The steel may be made by any process
4.2 If a specific type of melting is required by the purchaser, it shall be as stated on the purchase order.
4.3 The primary melting may incorporate separate degassing or refining, and may be followed by secondary melting,

such as electroslog or vacuum-arc remelting. If secondary melting is employed, the heat shall be defined as all of the ingots remelted from a single primary heat.

4.4 Steel may be cast in ingots or may be strand cast. When steel of different grades is sequentially strand cast, identification of the resultant transition material is required. The producer shall remove the transition material by an established procedure that positively separates the grades.

4.5 Tubes shall be made by the electric-resistance-welded process and shall be made from hot- or cold-rolled steel as specified.

5. Chemical Composition

5.1 The steel shall conform to the requirements as to chemical composition prescribed in Tables 1 and 2. If no grade is specified, Grades MT 1010 to MT 1020 may be furnished. Analyses of steels other than those listed are available. To determine their availability, the purchaser should contact the producer.

5.2 When a carbon steel grade is ordered under this specification, supplying an alloy grade that specifically requires the addition of any element other than those listed for the ordered grade in Tables 1 and 2 is not permitted.

6. Heat Analysis

6.1 An analysis of each heat of steel shall be made by the steel manufacturer to determine the percentages of the elements specified; if secondary melting processes are employed,

TABLE 2 Chemical Requirements for Alloy Steels^A

NOTE 1—Chemistry represents heat analysis. Product analysis, except for rimmed or capped steel, is to be in accordance with usual practice as shown in Table 3.

Grade Designation	Chemical Composition Limits, %							
	Carbon	Manganese	Phosphorus, max	Sulfur, max	Silicon	Nickel	Chromium	Molybdenum
1008	0.10 max	0.50 max	0.035	0.035	...	...	...	...
1010	0.09–0.13	0.30–0.60	0.035	0.035	...	...	...	...
1012	0.10–0.15	0.30–0.60	0.035	0.035	...	...	...	...
1015	0.12–0.18	0.30–0.60	0.035	0.035	...	...	...	...
1016	0.12–0.18	0.60–0.90	0.035	0.035	...	...	...	...
1017	0.14–0.20	0.30–0.60	0.035	0.035	...	...	...	...
1018	0.14–0.20	0.60–0.90	0.035	0.035	...	...	...	...
1019	0.14–0.20	0.70–1.00	0.035	0.035	...	...	...	...
1020	0.17–0.23	0.30–0.60	0.035	0.035	...	...	...	...
1021	0.17–0.23	0.60–0.90	0.035	0.035	...	...	...	...
1022	0.17–0.23	0.70–1.00	0.035	0.035	...	...	...	...
1024	0.18–0.25	1.30–1.65	0.035	0.035	...	...	...	...
1025	0.22–0.28	0.30–0.60	0.035	0.035	...	...	...	...
1026	0.22–0.28	0.60–0.90	0.035	0.035	...	...	...	...
1027	0.22–0.29	1.20–1.55	0.035	0.035	...	...	...	...
1030	0.27–0.34	0.60–0.90	0.035	0.035	...	...	...	...
1033	0.29–0.36	0.70–1.00	0.035	0.035	...	...	...	...
1035	0.31–0.38	0.60–0.90	0.035	0.035	...	...	...	...
1040	0.36–0.44	0.60–0.90	0.040	0.050	...	...	...	...
1050	0.47–0.55	0.60–0.90	0.040	0.050	...	...	...	...
1060	0.55–0.66	0.60–0.90	0.040	0.050	...	...	...	...
1340	0.38–0.43	1.60–1.90	0.035	0.040	0.15–0.35	...	...	...
1524	0.18–0.25	1.35–1.65	0.040	0.050	...	...	...	...
4118	0.18–0.23	0.70–0.90	0.035	0.040	0.15–0.35	...	0.40–0.60	0.08–0.15
4130	0.28–0.33	0.40–0.60	0.035	0.040	0.15–0.35	...	0.80–1.10	0.15–0.25
4140	0.38–0.43	0.75–1.00	0.035	0.040	0.15–0.35	...	0.80–1.10	0.15–0.25
5130	0.23–0.33	0.70–0.90	0.035	0.040	0.15–0.35	...	0.80–1.10	...
8620	0.18–0.23	0.70–0.90	0.035	0.040	0.15–0.35	0.40–0.70	0.40–0.60	0.15–0.25
8630	0.28–0.33	0.70–0.90	0.035	0.040	0.15–0.35	0.40–0.70	0.40–0.60	0.15–0.25

^A Where the ellipsis (...) appears in this table, there is no requirement.

A 513

the heat analysis shall be obtained from one remelted ingot or the product of one remelted ingot of each primary melt. The heat analysis shall conform to the requirements specified, except that where the heat identity has not been maintained or where the analysis is not sufficiently complete to permit conformance to be determined, the chemical composition determined from a product analysis made by the tubular manufacturer shall conform to the requirements specified for heat analysis. When requested in the order or contract, a report of such analysis shall be furnished to the purchaser.

7. Product Analysis

7.1 When requested on the purchase order, a product analysis shall be made by the supplier. The number and source of samples for such product analysis shall be based on the individual heat or lot identity of one of the following forms of material:

7.1.1 *Heat Identity Maintained*—One product analysis per heat shall be made on either the flat-rolled stock or tube.

7.1.2 *Heat Identity Not Maintained*—A product from one tube per 2000 ft (610 m) or less for sizes over 3 in. (76.2 mm), and one tube per 5000 ft (150 m) or less for sizes 3 in. and under.

7.2 Samples for product analysis except for spectrochemical analysis shall be taken in accordance with Practice E 59. The composition thus determined shall correspond to the requirements of Tables 1-3.

7.3 If the original test for product analysis fails, retests of two additional lengths of flat-rolled stock or tubes shall be made. Both retests for the elements in question shall meet the requirements of the specification; otherwise, all remaining material in the heat or lot shall be rejected or, at the option of the producer, each length of flat-rolled stock or tube may be individually tested for acceptance. Lengths of flat-rolled stock or tubes which do not meet the requirements of the specification shall be rejected.

TABLE 3 Tolerances for Product Analysis for Steels Shown in Tables 1 and 2^{A,B}

Element	Limit, or Maximum of Specified Range, %	Variation, Over the Maximum Limit or Under the Minimum Limit	
		Under min, %	Over max, %
Carbon	to 0.15, incl	0.02	0.03
	over 0.15 to 0.40, incl	0.03	0.04
	over 0.40 to 0.55, incl	0.03	0.05
Manganese	to 0.60, incl	0.03	0.03
	over 0.60 to 1.15, incl	0.04	0.04
	over 1.15 to 1.85, incl	0.05	0.05
Phosphorus	..	..	0.01
Sulfur	..	..	0.01
Silicon	to 0.30, incl	0.02	0.03
	over 0.30 to 0.60	0.05	0.05
Nickel	to 1.00, incl	0.03	0.03
Chromium	to 0.90, incl	0.03	0.03
	over 0.90 to 2.10, incl	0.05	0.05
Molybdenum	to 0.20, incl	0.01	0.01
	over 0.20 to 0.40, incl	0.02	0.02

^A Individual determinations may vary from the specified heat limits or ranges to the extent shown in this table, except that any element in a heat may not vary both above and below a specified range.

^B Where the ellipsis (...) appears in this table, there is no requirement.

8. Permissible Variations in Dimensions for Round Tubing

8.1 *Diameter and Wall Thickness (Hot-Rolled Steel)*—Variations from specified outside diameter for “as-welded” and “as-welded and annealed” tubing made from hot-rolled steel shall not exceed the amounts prescribed in Table 4. Permissible variations in outside diameter for tubing that has been sink-drawn for closer tolerance on outside diameter are shown in Table 5. Permissible variations in wall thickness for tubing that has been sink-drawn for closer tolerances on outside diameters are $\pm 10\%$ of the nominal wall or ± 0.010 in. (0.25 mm), whichever is greater. Permissible variations in wall thickness for tubing made from hot-rolled steel are shown in Table 6. Permissible variation in outside and inside diameter for tubing made from hot-rolled steel that has been mandrel drawn for closer tolerances are shown in Table 5 with wall tolerances shown in Table 7.

8.2 *Diameter and Wall Thickness (Cold-Rolled Steel)*—Variations in outside diameter and inside diameter of “as-welded” and “as-welded and annealed” tubing made from cold-rolled steel are shown in Table 8. Outside diameter tolerances for cold-rolled steel tubing, sink drawn and mandrel drawn, are shown in Table 5. Wall thickness tolerances for “as-welded” tubing made from cold-rolled steel are shown in Table 9. Permissible variations in wall thickness for round tubing, mandrel drawn for closer tolerances, are shown in Table 7. Permissible variations in wall thickness for tubing that has been sink-drawn for closer tolerances on outside diameter are $\pm 10\%$ of the nominal wall or ± 0.010 in. (0.25 mm), whichever is greater.

8.3 *Length (Hot- and Cold-Rolled Steel)*—Mechanical tubing is commonly furnished in mill lengths 5 ft (1.5 m) and over. Definite cut lengths are furnished when specified by the purchaser. Tolerances for definite cut lengths round tubing shall be as given in Tables 10 and 11.

8.4 *Squareness of Cut (Hot- and Cold-Rolled Steel)*—When specified, tolerance for squareness of cut of round tubing shall be as given in Table 12. Measurements are made with use of an “L” square and feeler gage. Side leg of square to be equal to tube diameter except minimum length of 1 in. (25.4 mm) and maximum length of 4 in. (101.6 mm). Outside diameter burr to be removed for measurement.

8.5 *Straightness*—The straightness tolerance for round tubing is 0.030 in./3 ft (0.76 mm/1 m) lengths to 8.000 in. (203 mm) outside diameter. For 8.000 in. outside diameter and above, straightness tolerance is 0.060 in./3 ft (1.52 mm/1 m) lengths. For lengths under 1 ft the straightness tolerance shall be agreed upon between the purchaser and producer.

8.6 *Ovality (Hot- and Cold-Rolled Steel)*—The ovality shall be within the tolerances except when the wall thickness is less than 3 % of the outside diameter.

8.6.1 In such cases for Types 1 and 2 (A.W.H.R. and A.W.C.R.) the ovality may be 50 % greater than the outside tolerances but the mean outside diameter shall be within the specified tolerance.

8.6.2 For Types 3, 4, 5, and 6 (S.D.H.R., S.D.C.R., M.D., and S.S.I.D.) the additional ovality shall be as follows but the mean outside diameter shall be within the specified tolerance:



A 513

TABLE 4 Diameter Tolerances for Type I (A.W.H.R.) Round Tubing

NOTE 1—Measurements for diameter are to be taken at least 2 in.^A from the ends of the tubes.

Outside Diameter Range, in. ^A	Wall Thickness		Flash-In- Tubing ^{A,C}	Flash Controlled to 0.010 in. max Tubing ^{C,D}	Flash Controlled to 0.005 in. max Tubing ^{E,D}	
	Bwg ^F	in. ^A	Outside Diameter, ±	Outside Diameter, ±	Outside Diameter, ±	Inside Diameter, ±
			Tolerances, in. ^{A,G}			
½ to 1½, incl	16 to 10	0.065 to 0.134	0.0035	0.0035	0.0035	0.020
Over 1½ to 2, incl	16 to 14	0.065 to 0.083	0.005	0.005	0.005	0.021
Over 1½ to 2, incl	13 to 7	0.095 to 0.180	0.005	0.005	0.005	0.025
Over 1½ to 2, incl	6 to 5	0.203 to 0.220	0.005	0.005	0.005	0.029
Over 1½ to 2, incl	4 to 3	0.238 to 0.259	0.005	0.005	0.005	0.039
Over 2 to 2½, incl	16 to 14	0.065 to 0.083	0.006	0.006	0.006	0.022
Over 2 to 2½, incl	13 to 5	0.095 to 0.220	0.006	0.006	0.006	0.024
Over 2 to 2½, incl	4 to 3	0.238 to 0.259	0.006	0.006	0.006	0.040
Over 2½ to 3, incl	16 to 14	0.065 to 0.083	0.008	0.008	0.008	0.024
Over 2½ to 3, incl	13 to 5	0.095 to 0.220	0.008	0.008	0.008	0.026
Over 2½ to 3, incl	4 to 3	0.238 to 0.259	0.008	0.008	0.008	0.040
Over 2½ to 3, incl	2 to 0.320	0.284 to 0.320	0.010	0.010	0.010	0.048
Over 3 to 3½, incl	16 to 14	0.065 to 0.083	0.009	0.009	0.009	0.025
Over 3 to 3½, incl	13 to 5	0.095 to 0.220	0.009	0.009	0.009	0.027
Over 3 to 3½, incl	4 to 3	0.238 to 0.259	0.009	0.009	0.009	0.043
Over 3 to 3½, incl	2 to 0.360	0.284 to 0.360	0.012	0.012	0.012	0.050
Over 3½ to 4, incl	16 to 14	0.065 to 0.083	0.010	0.010	0.010	0.026
Over 3½ to 4, incl	13 to 5	0.095 to 0.220	0.010	0.010	0.010	0.028
Over 3½ to 4, incl	4 to 3	0.238 to 0.259	0.010	0.010	0.010	0.044
Over 3½ to 4, incl	2 to 0.500	0.284 to 0.500	0.015	0.015	0.015	0.053
Over 4 to 5, incl	16 to 14	0.065 to 0.083	0.020	0.020	0.020	0.036
Over 4 to 5, incl	13 to 5	0.095 to 0.220	0.020	0.020	0.020	0.045
Over 4 to 5, incl	4 to 3	0.238 to 0.259	0.020	0.020	0.020	0.054
Over 4 to 5, incl	2 to 0.500	0.284 to 0.500	0.020	0.020	0.020	0.058
Over 5 to 6, incl	16 to 10	0.065 to 0.134	0.020	0.020	0.020	0.036
Over 5 to 6, incl	9 to 5	0.148 to 0.220	0.020	0.020	0.020	0.040
Over 5 to 6, incl	4 to 3	0.238 to 0.259	0.020	0.020	0.020	0.054
Over 5 to 6, incl	2 to 0.500	0.284 to 0.500	0.020	0.020	0.020	0.058
Over 6 to 8, incl	11 to 10	0.120 to 0.134	0.025	0.025	0.025	0.043
Over 6 to 8, incl	9 to 5	0.148 to 0.220	0.025	0.025	0.025	0.045
Over 6 to 8, incl	4 to 3	0.238 to 0.259	0.025	0.025	0.025	0.059
Over 6 to 8, incl	2 to 0.500	0.248 to 0.500	0.025	0.025	0.025	0.063
Over 8 to 10, incl	14 to 12	0.083 to 0.109	0.030	0.030	0.030	0.041
Over 8 to 10, incl	11 to 10	0.120 to 0.134	0.030	0.030	0.030	0.043
Over 8 to 10, incl	9 to 5	0.148 to 0.220	0.030	0.030	0.030	0.045
Over 8 to 10, incl	4 to 3	0.238 to 0.259	0.030	0.030	0.030	0.059
Over 8 to 10, incl	2 to 0.500	0.248 to 0.500	0.030	0.030	0.030	0.063
Over 10 to 12, incl	14 to 12	0.083 to 0.109	0.035	0.035	0.035	0.041
Over 10 to 12, incl	11 to 10	0.120 to 0.134	0.035	0.035	0.035	0.043
Over 10 to 12, incl	9 to 5	0.148 to 0.220	0.035	0.035	0.035	0.045
Over 10 to 12, incl	4 to 3	0.238 to 0.259	0.035	0.035	0.035	0.059
Over 10 to 12, incl	2 to 0.500	0.284 to 0.500	0.035	0.035	0.035	0.063

^A 1 in. = 25.4 mm.^B Flash-In-Tubing is produced only to outside diameter tolerances and wall thickness tolerances and the inside diameter welding flash does not exceed the wall thickness or ½ in., whichever is less.^C Flash Controlled to 0.010 in. maximum tubing consists of tubing which is commonly produced only to outside diameter tolerances and wall thickness tolerances, in which the height of the remaining welding flash is controlled not to exceed 0.010 in.^D No Flash tubing is further processed for closer tolerances with mandrel-tubing produced to outside diameter and wall, inside diameter and wall, or outside diameter and inside diameter to tolerances with no dimensional indication of inside diameter flash. This condition is available in Types 5 and 6.^E Flash Controlled to 0.005 in. maximum tubing is produced to outside diameters and wall thickness tolerance, inside diameter and wall thickness tolerances, or outside diameters and inside diameter tolerances, in which the height of the remaining flash is controlled not to exceed 0.005 in. Any remaining flash is considered to be part of the applicable inside diameter tolerances.^F Birmingham Wire Gage.^G The ovality shall be within the above tolerances except when the wall thickness is less than 3 % of the outside diameter, in such cases see 8.6.1.

A 513

TABLE 5 Diameter Tolerances for Types 3, 4, 5, and 6 (S.D.H.R., S.D.C.R., M.D. and S.S.I.D) Round Tubing

NOTE 1—Measurements for diameter are to be taken at least 2 in. from the ends of the tubes.

be as given in Table 13. The wall thickness tolerance is $\pm 10\%$ of the nominal wall thickness.

9.2 *Corner Radii*—Unless otherwise specified, the corners of square and rectangular tubing shall be slightly rounded inside and outside, consistent with wall thickness. The outside corners may be slightly flattened. The radii of corners shall be as given in Table 14.

9.3 *Squareness*—Permissible variations for squareness shall be determined by the following equation:

$$\pm b = c \times 0.006 \text{ in.}$$

for out-of-square, and
nominal dimension across flats.

squareness is commonly determined by one of

two adjustable contact points on each side. A fixed feeler gage is then used to measure the distance between the free contact point and the fixed contact point.

or with a direct reading vernier, may be used to measure angular deviation which, in turn, may be converted to inches.

from the specified length shall not exceed the tolerance given in Table 15.

variations are shown in Table 16. The squareness of rectangular tubing may be measured by placing the tubing on a surface plate and noting the distance from the corner of the opposite end of same side above the surface plate. Twist may also be measured by the use of a level or a level equipped with a level, and noting the deviation on opposite ends, or at any point throughout the length.

9.6 *Straightness*—The straightness tolerance is $\frac{1}{16}$ in./3 ft (1.7 mm/1 m).

10. Tubing Sections Other Than Square and Rectangular

10.1 In addition to square and rectangular tubing, many producers supply a variety of special sections, such as oval, streamlined, hexagonal, octagonal, round inside and hexagonal or octagonal outside, ribbed inside or out, triangular, rounded rectangular and D shapes. Manufacturing practices limit the size range and section available from the various producers. These special sections may be made through turkshead rolls or through a die with or without use of a mandrel. Since the sections are special, dies and other tools are not held available. Therefore, when inquiring for shapes other than square and rectangular, it is essential to give full details as to dimensions and finish.

11. Workmanship, Finish, and Appearance

11.1 The tubing shall be free of injurious defects and shall have a workmanlike finish.

11.2 The tubing shall be free of scale. In the case of thermally treated tubing a slight amount of color will not be considered cause for rejection.

11.3 When burrs must be removed from one or both ends, it shall be specified in the purchase order.

^A Tubing, flash in or flash controlled which is further processed without mandrel to obtain tolerances closer than those shown in Tables 4 and 8.

^B The ovality shall be within the above tolerances except when the wall thickness is less than 3% of the outside diameter, in such cases see 8.6.2.

^C Tubing produced to outside diameter and wall thickness, or inside diameter and wall thickness, or outside diameter and inside diameter, with mandrel to obtain tolerances closer than those shown in Tables 4 and 8 and no dimensional indication of inside diameter flash.

^D Where the ellipsis (.) appears in this table, the tolerance is not addressed.

Outside Diameter, in. (mm)	Additional Ovality Tolerance, in. (mm)
Up to 2 (50.8), incl	0.010 (0.25)
Over 2 to 3 (50.8 to 76.2), incl	0.015 (0.38)
Over 3 to 4 (76.2 to 101.6), incl	0.020 (0.51)
Over 4 to 5 (101.6 to 127.0), incl	0.025 (0.64)
Over 5 to 6 (127.0 to 152.4), incl	0.030 (0.76)
Over 6 to 7 (152.4 to 177.8), incl	0.035 (0.89)
Over 7 to 8 (177.8 to 203.2), incl	0.040 (1.02)
Over 8 to 9 (203.2 to 228.6), incl	0.045 (1.14)
Over 9 to 10 (228.6 to 254.0), incl	0.050 (1.27)
Over 10 to 11 (254.0 to 279.4), incl	0.055 (1.40)
Over 11 to 12 (279.4 to 304.8), incl	0.060 (1.52)
Over 12 to 12.500 (304.8 to 317.5), incl	0.065 (1.65)

9. Permissible Variations in Dimensions of Square and Rectangular Tubing

9.1 *Diameter and Wall Thickness*—Permissible variations in outside dimensions for square and rectangular tubing shall

CONFIDENTIAL

83

TABLE 6 Wall Thickness Tolerance for Type I (A.W.H.R.) Round Tubing

Outside Diameter, in.	Over 1 to 1 1/2, incl.	Over 1 1/2 to 3 1/4, incl.	Over 3 1/4 to 4 1/2, incl.	Over 4 1/2 to 6, incl.	Over 6 to 8, incl.	Over 8 to 10, incl.	Over 10 to 12, incl.
Wall thickness							

MF1008

Golemboski, Matt R.

From: Zajk, Joseph J
Sent: Monday, December 20, 1999 5:39 PM
To: Golemboski, Matt R.
Subject: FW: 1018 Seamless Tubing Specification

Importance: High

I sent this to Marlin concerning the tubing specs. FYI.

Joe Z.

-----Original Message-----

From: Zajk, Joseph J
Sent: Monday, December 20, 1999 3:42 PM
To: Jiranek, Marlin R.
Subject: RE: 1018 Seamless Tubing Specification
Importance: High

Marlin,

Could you please include the following information in the 1018 material specification:

- Specify DOM (Drawn over Mandrel) for seamless tubing processing method
- Specify surface roughness as 63 RMS max. on ID of tubing
- Specify 10 foot length for bar material

I would like to have separate specifications for the 710 receiver and the 710 bolt body made out of the generic material spec (with the above additions). On the receiver I would like the following additional information:

- Maximum wall thickness variation of 3% (equivalent to .010 TIR)
- Specify maximum surface roughness of OD as 125 RMS

For the bolt body I would like the following additional information:

- Maximum wall thickness variation of 3% (equivalent to .006 TIR)
- Specify maximum surface roughness of OD as 63 RMS, ground finish.

I don't have any problem with the general material spec format as you have written them in the past or you assigning numbers from E-town. I would like to see a numbering system such as 710-001, etc., and I can add a cover sheet to list changes to the spec. I would like for material spec sheets to be changed using our current ECR/DCR change system.

As far as access, Mike has been posting out parts lists on Erdntas2 so we can access them from the network. You can place our material specs on the same server if you like. We'll have to talk about limiting access only to individuals in Mayfield and E-town who have a reason to be looking at our stuff.

You and I can work out the details after the holidays on the standardized system. For now assign the receiver 710-001 and 710-002. If possible, I would like to get these material specs updated ASAP for FreeMarkets. Our RFQ goes out on 12/29 and we need to get them this info before then, preferably before 12/23.

Thanks,

Joe Z.

-----Original Message-----

From: Jiranek, Marlin R.
Sent: Monday, December 20, 1999 8:24 AM
To: Golemboski, Matt R.; Zajk, Joseph J; Keeney, Mike; Morgan, Metty E.
Subject: 1018 Seamless Tubing Specification

Matt,

Attached are 2 specifications, one for the current 1010-1020 seamless tubing (lost the file in a hard drive crash last January) and one for the 1018 seamless tubing (requested by Mike Keeney). I assigned them both arbitrary numbers (600 & 601) and will use these unless you have a desire to change them to something different. I do not have any idea how Ilion and Hickory communicate specifications and the old system assignments were basically used for the VAX system which is being phased out. If we want to create a material specification database for Mayfield, we should discuss format and a method of putting it on the server, so that it can be viewed by your facility and ours. If we don't

want to do this, then use away and assign any number you want, which may fit your tracking needs. I am open to any suggestions.

Marlin.

<< File: Spec 600 1010-1020 ST.doc >> << File: Spec 601 1018 ST.doc >>

CONFIDENTIAL 83

Golemboski, Matt R.

From: Jiranek, Marlin R.
Sent: Monday, December 20, 1999 8:24 AM
To: Golemboski, Matt R.; Zajk, Joseph J; Keeney, Mike; Morgan, Metty E.
Subject: 1018 Seamless Tubing Specification

Matt,

Attached are 2 specifications, one for the current 1010-1020 seamless tubing (lost the file in a hard drive crash last January) and one for the 1018 seamless tubing (requested by Mike Keeney). I assigned them both arbitrary numbers (600 & 601) and will use these unless you have a desire to change them to something different. I do not have any idea how Ilion and Hickory communicate specifications and the old system assignments were basically used for the VAX system which is being phased out. If we want to create a material specification database for Mayfield, we should discuss format and a method of putting it on the server, so that it can be viewed by your facility and ours. If we don't want to do this, then use away and assign any number you want, which may fit your tracking needs. I am open to any suggestions.

Marlin.



Spec 600 1010-1020
ST.doc



Spec 601 1018
ST.doc

CONFIDENTIAL 83

Remington Arms Company, Inc.

MATERIAL SPECIFICATION #600

Spec. No. 600-CF-A Cold Finished Seamless Tube, Annealed – Standard Quality

Material: AISI 1010-1020 Seamless Steel Tubing**Analysis:** The material shall conform to Grade Designation MT1015 (ASTM A519-94). The analysis of this material shall check within the limits listed below.

Carbon	(C)	0.10-0.20	+/- 0.03%
Manganese	(Mn)	0.30-0.60	+/- 0.03%
Phosphorus	(P)	0.040	MAX.
Silicon	(Si)	0.050	MAX.

Quality: All material furnished under this specification shall be of commercial quality unless stated otherwise in the buyer's purchase order, and shall meet all applicable requirements of ASTM Specification A519-94, "Standard Specification for Seamless Carbon and Alloy Steel Mechanical Tubing".**Tolerance:** All material shall be furnished to the tolerances stated in ASTM Specification 519-94, unless otherwise specified on the buyer's purchase order.**Identity:** All material shall be tagged to show (1) the name of the vendor, (2) heat number, (3) size of the stock, and (4) Remington Specification Number.

Remington Arms Company, Inc.

MATERIAL SPECIFICATION #601

Spec. No. 601-CF-A Cold Finished Seamless Tube, Annealed – Standard Quality

Material: AISI 1018 Seamless Steel Tubing**Analysis:** The material shall conform to Grade Designation 1018 (ASTM A519-94).
The analysis of this material shall check within the limits listed below.

Carbon	(C)	0.15-0.20	+/- 0.02%
Manganese	(Mn)	0.60-0.90	+/- 0.03%
Phosphorus	(P)	0.040	MAX.
Silicon	(Si)	0.050	MAX.

Quality: All material furnished under this specification shall be of commercial quality unless stated otherwise in the buyer's purchase order, and shall meet all applicable requirements of ASTM Specification A519-94, "Standard Specification for Seamless Carbon and Alloy Steel Mechanical Tubing".**Tolerance:** All material shall be furnished to the tolerances stated in ASTM Specification A519-94, unless otherwise specified on the buyer's purchase order.**Identify:** All material shall be tagged to show (1) the name of the vendor, (2) heat number, (3) size of the stock, and (4) Remington Specification Number.

18 December, 1999

x.c. M. Golemboski
M. Keeney
J. Zajk

To: Jim Rabbia
From: Glen Sietsema

RE: Trip Report - Travel To Welduction Corp. - Novi, MI

On December 16 -- 17, 1999 Joe Zajk and I traveled to Welduction Corp. to evaluate Induction Equipment for hardening the lugs of the M/710 barrel. While at Welduction we set up the equipment and ran a number of sample barrels made from AISI 4140 material. These samples will be used for testing in E-Town. We also finalized the design concept for permanent fixturing and discussed a tentative schedule for delivery of production hardening equipment to Mayfield.

Our primary contacts at Welduction are:
Dan Williams - President
Bill Hutchinson - Metallurgical Manager
Tim G. Boussie - Engineering Director
Michael Doerr - Sales Manager

Summary:

The induction process successfully hardened the M/710 sample barrels made from AISI 4140 Material. A production fixturing concept for the induction equipment was agreed to. Delivery of the equipment will be approximately 16 - 18 weeks from time of PO. The delivery and price will be finalized after Welduction receives a formal RFQ including a machine specification from Remington Mayfield.

Purpose of Travel:

The purpose of the trip was to bring Joe Zajk up to date on the status of the M/710 Induction Hardening equipment. Joe will assume responsibility for the equipment now that the M/710 production will be in Mayfield. The trip was also to run AISI 4140 barrel samples. All previous samples were made from Remington Specification 155 Steel.

Both the short samples and full length barrels made of AISI 4140 were hardened. The process is capable of hardening the material.

Joe evaluated equipment that is very similar to that quoted to Remington. The controller, footprint, guarding, and mechanical aspects of the induction system were the same as that quoted to Remington. The power supply for the M/710 application will need to be larger than the system evaluated at Welduction.

We had a summary meeting where the final design concept was agreed to for the production equipment. Welduction indicated delivery would be approximately 16 - 18 weeks. The delivery schedule and price for the production equipment will be finalized after the RFQ and machine specification is received from Remington Mayfield.

A copy of my draft machine specification will be forwarded to Joe with his copy of this report.

MF1014

**Induction Hardening Equipment
Rifle Barrel**

MACHINE SPECIFICATION NO:

DATE: 1 March, 1999

INDEX

1. SCOPE OF WORK
2. EFFICIENCY AND CONTROLLABILITY
3. DRAWINGS
4. HYDRAULIC SYSTEMS
5. ELECTRICAL SYSTEMS
6. SAFETY
7. OPERATING AND MAINTENANCE
8. NON DISCLOSURE
9. ACCEPTANCE
10. DISASSEMBLY AND RE-ASSEMBLY
11. DELIVERY
12. TECHNICAL REPRESENTATIVE

CONFIDENTIAL

D:\METLAB\RIFLE\710\ENDUSCOP.DOC
GDS 3/1/99

MF1015

1. SCOPE OF WORK:

1.1 Develop a process for, and provide equipment to, harden the chamber area of a rifle barrel.

The is specification involves two parts.

- The first is to develop a process and induction coil to harden rifle barrel chambers. This coil will be used to heat treat development barrel samples on equipment at the supplier facility.
- The second is to provide the induction hardening system capable of heat treating the barrel chambers at Remington Arms Co. - Ilion, NY.

Both the process development and induction equipment will meet the Hardening Specification listed in 1.1.A. The process development will meet the schedule and volumes listed in 1.1.B and 1.1.C.

1.1.A Hardening Specifications:

Part Name: Barrel
 Material: AISI 1155 Modified - Or 4140
 Hardness: HRc 57 Min as Quenched
 HRc 37 - 42 After Temper
 Heat Treat Location: Breech End - See Drawing D-EXP 5806 Add Part No
 Transition Zone: 0.835 - 1.30 from breech end
 Atmosphere: The Inside Diameter requires a neutral atmosphere (Nitrogen Purge) during the hardening process. The rifled portion of the barrel is in it's finished condition and must be protected form scale and discoloration.
 Straightness: Increase of 0.006 IR on center Maximum
 Volume: 50,000 units per year or
 One part every 90 seconds.

1.1.B - Coil Development

Vendor shall develop an induction coil and process to harden the barrel chambers.

Remington will supply samples to demonstrate the capability of the coil. The coil design will be the property of Remington Arms Co.

Prior to purchase of the hardening equipment the vendor will be requested to harden three sample lots of barrels, each less than 50 pieces. These sample lots will be used by Remington to prove the design and the process prior to acceptance of the hardening equipment. The sample lots are described in section 1.1.C.

~~Above Complete~~

1.1.C - Development Samples: - Below complete

Twelve samples for process and coil development will be shipped with Purchase Order.

These samples are 1.230" Diameter x 6" long with I.D. geometry per D EXP 5806. These twelve samples are for process development only and can be destroyed.

A Twenty Barrel sample of the finished barrel to be heat treated the week of April 19, 1999.

A Fifty Barrel sample of the finished barrel to be heat treated in June, 1999.

1.2 The machines are to be used at the Remington Arms', Ilion, New York manufacturing facility.

1.3 The manufacturer or vendor shall include in the proposal,

Remington Arms Co., Inc.
 Met Chem Lab - Ilion, NY

Pg. 1 of 7

CONFIDENTIAL

MF1016

recommendations and pricing for any standard accessories or options, which are necessary to protect basic components and/or extend the precision life expectancy of the equipment.

- 1.4 Preliminary and final drawings of machine, fixtures, etc. must be approved by Remington Arms technical representative at all phases of the project.
- 1.5 The machine will be furnished complete and ready in all respects for immediate installation and operation.
- 1.6 Workmanship in all phases of fabrication and finishing of the specified equipment and attachments shall be equal to the best standard practices of the machine tool industry.
- 1.7 The bidder is required to provide, as part of the quotation, a detailed description of any deviations from the provisions of this specification. Failure to declare deviations or exceptions to this specification in the bid proposal will indicate to the buyer the bidder's intent to furnish equipment in strict compliance with the stated requirements.
- 1.8 The scope of work will not be expanded or contracted without formal alteration to the purchase order.

2. EFFICIENCY AND CONTROLLABILITY:

- 2.1 The vendor will be responsible for ensuring that the machine will have a 90% efficiency (up time). This does not include downtime or part load/unload time.
- 2.2 All specified equipment shall be guaranteed to perform satisfactorily up to the limits specified by the manufacturer. The vendor shall state in the proposal the nature and extent of warranty coverage on the equipment to be furnished.
- 2.3 All materials and standard purchased components incorporated in the design of the manufacturer's equipment, including attachments and accessories, shall be new and high quality, obtained from reputable manufacturers of such materials and components, and shall conform to industry standards for the class and type of equipment specified.

3. DRAWINGS:

Include Electronic Form

How many Drawings?

- o 2 sets drawings -- one at machine -- one in engineering
- o 3 sets instructions -- 1 machine, 2 process engineering, 3 plant engineering.

Remington Arms Co., Inc.
Met Chem Lab - Ilion, NY

Pg 2 of 7

CONFIDENTIAL

MF1017

- 3.1 The manufacturer shall provide all drawings of special attachments, special electrical, hydraulic and or mechanical interfacing.
- 3.2 The manufacturer shall provide maintenance and operating instruction manuals and a complete set of electrical drawings, elementary diagrams, wiring diagrams, panel layouts, electronic and electrical parts lists and sequence of operations.
- 3.3 The manufacturer shall provide installation drawings upon receipt of a purchase order. All necessary parts lists, instruction, operation and/or maintenance manuals pertaining to the furnished equipment and any attachments or accessories supplied therewith, shall be furnished upon delivery of the equipment, unless otherwise stated in the proposal.
- 3.4 Prior to delivery of the machine the vendor shall furnish a parts list detailing all special design and standard manufactured parts considered to be critical to the operation of the machine (components for which Remington should keep replacements in inventory due to long lead times or high usage) is to be provided by vendor.

4. HYDRAULIC SYSTEMS:

- 4.1 Hydraulic reservoirs to be equipped with heat exchangers.
- 4.2 Flow control valves to be pressure/temperature compensated for all feed applications if applicable.

5. ELECTRICAL/ELECTRONIC SYSTEMS:

- 5.1 Electrical controls to be of the following manufacture:

Motor starters (NEMA rated, not IEC), relays, push buttons, selector switches, pilot lights, terminal blocks (1492-F3, 1492-CA3), and pressure switches (with Brad Harrison quick disconnects, or equiv.) are to be Allen-Bradley only.

Adjustable frequency drives are to be Allen-Bradley 1333 (up to 2 HP) or 1336 (3 HP and above) only. Ratings are to be for 480V, 3 Phase.

Limit switches are to be Allen-Bradley, Square D, or Microswitch with quick disconnects (Brad Harrison or equiv.).

Proximity switches are to be Efecter or Balluff with quick disconnects (Brad Harrison or equiv.). Proximity switches should be used where ever possible to minimize use of mechanically actuated limit switches.

Photoelectric switches are to be Allen-Bradley, Banner, Efector, or Microswitch with quick disconnects (Brad Harrison or equiv.).

Temperature controllers are to be Partlow 1000 (high limits), MIC2000, MIC6000, MIC8200.

- 5.2 AC motors are to be a totally enclosed, fan cooled, ball bearing, energy efficient type.
 - 5.3 Programmable controllers are to be Allen-Bradley type SLC 5 series only. Full documentation of the controller program is required, including original tape/disk input to the documentation software package (Allen-Bradley preferred).
 - 5.4 Primary power supply shall be 480 volt, 3 phase, 60 hz. Power source is delta-corner ground. Do not provide fusing for the center phase but include motor overloads for all 3 phases.
 - 5.5 Electrical controls are to be 115 volt, grounded, single phase, in NEMA 12 enclosures and junction boxes.
 - 5.6 The main control panel must be equipped with a fusible knife type disconnect switch with visible blades and a lever type operating handle. Rotary actuated disconnects are not acceptable. All disconnect switches are to be of Square-D (preferred) or Allen-Bradley manufacture only.
 - 5.7 Construction is to be per applicable NEMA and NEC code requirements. All machine wiring, except quick disconnect cables and electronic control cables, is to be type MTF 600V stranded. 115VAC control wiring is to be 16AWG (red) minimum. DC control wiring is to be 16AWG (blue) minimum, and 600VAC wiring is to be 14AWG (black or color coded to indicate phases) minimum. All 600VAC wires are to be in a minimum of 3/4 in. rigid conduit or liquid tight flexible conduit. Wires are to be terminated at equipment with solderless compression type connectors made by Thomas and Betts Co. only. The use of wire nuts is to be minimized. Field wiring used to connect pieces of equipment in a system (HVAC equipment, pumping systems, power feeders, etc.) is to be type THHN 600V stranded to facilitate pulling through conduit.
- Liquid tight flexible conduit of a UL approved grounding type shall be used where a flexible raceway is required, keeping the lengths to the NEC requirements. If this is impractical, a hard service cord (oil-resistant thermoplastic elastomer, SEO, or equiv.) can be used on a limited basis, using rubber grommet type squeeze strain reliefs. Lengths of cord used with quick disconnects should be kept to a minimum.
- Conduits are to be reamed, burrs removed, and double locknuts and bushings used where they enter boxes, fittings, or cabinets, except at threaded hubs. In places where liquid is a problem, sealing type threaded hubs are to be used. Conduits are to be installed with cast conduit type fittings. Running threads on conduit will not be permitted.
- All wires are to be provided with a durable oil resistant wire number marker. All limit, proximity, photo, pressure switches, solenoid valves, etc. are to be labeled to assist in locating them for maintenance purposes (engraved laminated plastic, or embossed metal are preferred, flexible embossed self-adhesive plastic labels are not acceptable).
- Control cabinets are to be laid out neatly using terminal strips for all field wiring connections and plastic wire ducts to route wiring within the enclosure.

- 5.8 Complete documentation is to be provided on all systems, including schematic diagrams and maintenance manuals of all equipment. If schematics are available on computer disk, provide them on 3.5 inch media and in .DXF format.
- 5.9 If any specialized programming equipment is required for controls (programming pads for motor drives, software for controllers, etc.), this is to be provided with the equipment.

CONFIDENTIAL

Remington Arms Co., Inc.
Met Chem Lab - Ilion, NY

Pg. 5 of 7

CONFIDENTIAL

MF1020

6. SAFETY:

6.1 The equipment offered shall be quoted with all necessary safety devices, shields, guards, enclosures, electrical mechanical interlocks, etc., required to adequately protect the operator and/or persons in the immediate vicinity of the machines. The words "all necessary" relate to, but are not necessarily limited to, compliance with OSHA.

6.2 The design and quality of all safety devices, shields, guards enclosures, etc., shall be in compliance with, but not necessarily limited to OSHA requirements.

6.3 The bidder shall provide as part of the quotation the results of sound level tests on the quoted equipment. These must indicate the level of sound generated by the offered equipment running at maximum spindle speed (in each range if applicable) and with feeding and support systems operating. Test data may be limited to machine running noise only. Tool noise, etc., resulting from physical work is not required as part of this data. In general, sound level tests conducted in accordance with any of the following methods will be acceptable:

☐ United States Of America Standard (USAS) S1.2

☐ American Society Of Heating, Refrigeration, And Air Conditioning Engineers (ASHRAE) Standard 36.

☐ Ashrae Standard 36a.

☐ Ashrae Standard 36b.

☐ Institute Of Electrical And Electronics Engineering (IEEE) No. 85.

☐ Air Moving And Conditioning Association (AMCA) Bulletin No. 300.

6.4 The operator must have easy access to all controls that would be used for the normal operation of the machine, without violating any guards or otherwise endangering their well-being.

7. OPERATING AND MAINTENANCE:

7.1 Operating and maintenance instruction will be made available by the vendor.

7.2 The vendor is to quote training of Remington operating and

Remington Arms Co., Inc.
Met Chem Lab - Ilion, NY

Pg. 6 of 7

CONFIDENTIAL

MF1021

maintenance personnel as an option.

8. NON DISCLOSURE:

- 8.1 The vendor must sign Remington's Confidential Information Agreement Form before purchase of equipment.

9. ACCEPTANCE:

Define when machine is acceptable. If changes made during run-off now run off needed.

- 9.1 Machine manufacturer is to run machine for a minimum of six hours in the presence of a Remington Arms technical representative.

9.1.1 Vendor Run-Off

During the vendor run off a minimum of 100 pieces will be hardened at the manufacturers facility. Outside diameter (O.D.) hardness and straightness (TIR) will be measured 100%. A twenty barrel sample will be sectioned for microstructural and core hardness evaluation. This sample will be the barrels processed sequentially numbering 1,2,10,11,20,21,.....,90,91,99,100

Issues:

How to measure Hardnes:

- o Scale: HRc, 15n, Knopp
- o Location: OD Exatly where on part , cross section, where to measure core hardness.

How to mesure core hardness:

- o Knopp Hardness De-lug: From ID to OD, across length of lug

How to measure straightness:

TIR:

How many to do mic's on: 10 of 100 - at Vendor and after Remington Run Off at E Town

- 9.2 Final acceptance is to be conducted immediately following installation and run-off at Ilion.

9.2.1 Ilion Run-Off

During the Ilion Site Run-Off the same procedures will be followed as at the Vendor Run-Off. A 100 piece sample will be evaluated for O.D. Hardness, TIR, Microstructure and Core Hardness as described in 9.1.1.

10. DISASSEMBLY AND RE-ASSEMBLY:

- 10.1 Machine manufacturer will provide services of a machine tool serviceman to supervise and instruct Remington and/or third party personnel if requested, when the machine is disassembled for shipment. This serviceman, or an acceptable alternate, will supervise and instruct Remington personnel in the reassembly and operation of the machine, and final acceptance at Ilion within (1) week of notification.

Remington Arms Co., Inc.
Met Chem Lab - Ilion, NY

Pg 7 of 7

CONFIDENTIAL

MF1022

11. DELIVERY:

11.1 The vendor shall, as part of the proposal, provide the buyer with a firm delivery date computed in consecutive days from the date of purchase order receipt.

11.2 Outline drawings, floor space requirements, shipping weight and net installed weight of the equipment to be furnished, shall be included in the vendor's proposal.

11.3 Furnished equipment shall be skidded, blocked, braced, crated and/or boxed as necessary to adequately protect the equipment while in transit.

11.4 Vendor will provide for installation of equipment, any necessary slings, straps, and attachments necessary to safely install machine.

12. TECHNICAL REPRESENTATIVE:

Glen D. Sietsema, Metallurgical Engineer
Remington Arms Co., Inc.
14 Hoefler Avenue
Ilion, New York 13357
Telephone: (315) - 895 - 3234
Fax: (315) - 895 - 3407

Remington Arms Co., Inc.
Met Chem Lab - Ilion, NY

Pg 8 of 7

CONFIDENTIAL

MF1023

Golemboski, Matt R.

From: Keeney, Mike
Sent: Wednesday, December 15, 1999 3:35 PM
To: Zajk, Joseph J
Cc: Golemboski, Matt R.; Diaz, Danny
Subject: 710

Joe,
 per your request here are the MPIF standards for the PM and MIM components. The parts that are 710 only will have these spec assigned as material specifications. The add used M/700 parts will not have these specs added to the drawings until next year when you guys outsource them, at that point we will generate new drawings and part numbers.

Part	Current Spec	MPIF Standard
Tumbler	MIM Iron 2% NI	MIM-4600
Firing Pin Hd	MIM Iron 2% NI	MIM-4650
Bolt Stop	PM 4058	FC-0508-60
Sear	HD 2020	FN-0200-25
Trigger	HD 1000	F-0000-20
Front Sight	HD 1003	F-0005-25
R.S. Aperature	HD 1000	F-0000-15
R.S. Base	Injectalloy 2% NI	MIM-4600
R.S. Slide	Injectalloy Iron	MIM-FE

Stock Mold Texture will be specified as "Modified MT 11160" and referenced to Mold Tech shop order number 18664.

Bolt Plug texture will be an EDM finish referenced against a Sharnie (sp) scale that I will have tomorrow.

Kristan is bringing a drawing package along with him, in it is an exploded view of the bolt plug ISS assembly per your request.

Another drawing package will go out tomorrow or Friday with the bolt handle blank and finished drawings, trigger drawings, bolt plug and what ever else I can get done.


Mike

CONFIDENTIAL

83

OO: R&A

MF1025

COPY
FYI**PAR 4 PLASTICS, INC.**

(270) 965-9141
Fax (270) 965-9560

351 Industrial Drive
P.O. Box 385
Marion, KY 42064

11/3/00


Ms. Metty Morgan
Remington Arms Co, Inc.
22 Rifle Trail
Hickory, KY. 42051

Dear Metty,

Please issue a P.O. for the latest revisions to the Model 710 Stock completed at
"Remingtons" request. See list below.

#1.	Move B-Datum .006 per CAD Model.	\$ 1,375.00
#2.	Add .020 clearance to Grip Cap area and remove ribs.	\$ 3,600.00
#3.	Add clearance for scar pivot per CAD Model.	\$ 2,850.00
Total =		\$ 7,825.00

Sincerely
PAR 4 PLASTICS, INC.


Sam Todd
Dir. Sales/Marketing

MF1026

PO	Item	Material	Vendor	Name	Short text	Order qty	Un	Net Price	Curr.	Order date	Mat. group
	D I A	Plnt SLoc	SL del. date	Scheduled	Order qty	Un					per Un
M017602		ZZ	106719	CROUCH BUILDING ASSOCIATES, INC						M01 05/09/2000	
00010				CONSTRUCT 100 YARD RANGE PER QUOTE-90%						11CAPPROJ	
	F MAY			1.000	EA			419,999.10	USD		1 EA
	Order 292068			1.000	EA						
		D 08/18/2000		0.856	EA			354,383.23	USD		85.60 %
	Still to be delivered			0.856	EA			354,383.23	USD		85.60 %
	Still to be invoiced			10% OF TOTAL CONTRACT COST RETAINED						11CAPPROJ	
00020	F MAY			1.000	EA			419,999.90	USD		1 EA
	Order 292068			1.000	EA						
		D 08/18/2000		0.856	EA			39,383.91	USD		85.60 %
	Still to be delivered			1.000	EA			419,999.90	USD		100.00 %
	Still to be invoiced			QUICK TEK						M01 05/02/2000	
M017607		ZZ	106467	FIXTURING & PROGRAMMING / 710 BOLT HEAD						TOOLING	
00010	Y MAY			1	LOT			2,000.00	USD		1 LOT
	Order 292068			1	LOT						
		D 05/05/2000		0	LOT			0.00	USD		0.00 %
	Still to be delivered			0	LOT			0.00	USD		0.00 %
	Still to be invoiced			CARPENTER-RATHBONE PRECISION						M09 05/08/2000	
M017611		ZZ	106726	3 LEG PROFILE ENGINEERING CHARGE						TOOLING	
00010	F MAY			1.000	EA			2,600.00	USD		1 EA
	Order 292068			1.000	EA						
		D 05/31/2000		1.000	EA			2,600.00	USD		100.00 %
	Still to be delivered			1.000	EA			2,600.00	USD		100.00 %
	Still to be invoiced			FARRIS, MCINTOSH, & TRENGER, INC						M09 06/15/2000	
M017627		ZZ	106410	SOIL TESTING, MAY, 2000 TECHNICIAN						SERVICE	
00010	F MAY			11.750	HR			35.00	USD		1 HR
	Order 292068			11.750	HR						
		D 06/16/2000		0.000	HR			0.00	USD		0.00 %
	Still to be delivered			0.000	HR			0.00	USD		0.00 %
	Still to be invoiced			MILEAGE CHARGE FOR TECHNICIAN SOIL						SERVICE	
00020	F MAY			120.000	EA			0.32	USD		1 EA
	Order 292068			120.000	EA						
		D 06/16/2000		0.000	EA			0.00	USD		0.00 %
	Still to be delivered			0.000	EA			0.00	USD		0.00 %
	Still to be invoiced			0.000	EA			0.00	USD		0.00 %
M018374		ZZ	5390090	PHI ASSOCIATES						M09 05/22/2000	
00010	F MAY			TRIGGER ADJUSTING FIXTURE DK-10438						TOOLING	
	Order 292068			1.000	EA			5,995.00	USD		1 EA
		D 06/26/2000		1.000	EA						
	Still to be delivered			0.000	EA			0.00	USD		0.00 %
	Still to be invoiced			1.000	EA			5,995.00	USD		100.00 %
M018417		ZZ	106544	TENNESSEE SCALE WORKS						M09 05/22/2000	
00010	F MAY			LOAD CELL #DFGS-R-10						03	
	Order 292068			1.000	EA			2,000.00	USD		1 EA
		D 06/16/2000		1.000	EA						
	Still to be delivered			0.000	EA			0.00	USD		0.00 %
	Still to be invoiced			0.000	EA			0.00	USD		0.00 %
M018451		ZZ	103439	Falconite, Inc.						M09 05/26/2000	
00010	F MAY			RENTAL 30' ELECTRIC BOOM LIFT-4 WEEKS						MISC	
	Order 292068			1.000	EA			1,350.00	USD		1 EA
		D 05/30/2000		1.000	EA						

83

Confidential - Subject's 5.2.2.206100578 Order

Williams v. Remington

PO	Item	Material	Vendor	Name	Short text	Order qty	Un	Net Price	Order date	Mat. group
	D I A	Plnt	SLoc	SL del. date	Scheduled	qty	Un		Curr.	per Un
				F MAY		40.000	EA	0.32	USD	1 EA
				Order 292068						
				D 06/16/2000		40.000	EA	PReq 1000501804	00080	
				Still to be delivered		0.000	EA	0.00	USD	0.00 %
				Still to be invoiced		0.000	EA	0.00	USD	0.00 %
M018561				ZZ 106795	CRAWFORD ELECTRIC				M09 06/15/2000	
00010					INSTALL 50' 600 AMP 480 VOLT 3PHASE BUSS	15				
				F MAY		1.000	EA	10,500.00	USD	1 EA
				Order 292068						
				D 06/30/2000		1.000	EA	PReq 1000500843	00010	
				Still to be delivered		1.000	EA	10,600.00	USD	100.00 %
				Still to be invoiced		1.000	EA	10,600.00	USD	100.00 %
M018591				ZZ 102641	MSC INDUSTRIAL SUPPLY				M09 06/16/2000	
00030					#06556104 MASTER VIEW 14" COMPARTOR				LAB EQUIP	
				F MAY		1.000	EA	2,899.60	USD	1 EA
				Order 292068						
				D 06/30/2000		1.000	EA	PReq 1000504941	00040	
				Still to be delivered		0.000	EA	0.00	USD	0.00 %
				Still to be invoiced		0.000	EA	0.00	USD	0.00 %
M018615				ZZ 106694	KELLCO MACHINE				M09 06/19/2000	
00010					ASSEMBLY COMPLETE PER PACKAGE E-K-10491				TOOLING	
				F MAY		1.000	EA	4,200.00	USD	1 EA
				Order 292068						
				D 06/27/2000		1.000	EA	PReq 1000505216	00010	
				Still to be delivered		1.000	EA	4,200.00	USD	100.00 %
				Still to be invoiced		1.000	EA	4,200.00	USD	100.00 %
M018632				ZZ 103439	Falconite, Inc.				M09 06/21/2000	
00010					RENTAL 30' ELECTRIC BOOM LIFT-2ND 30 DAYS MISC					
				F MAY		1.000	EA	1,350.00	USD	1 EA
				Order 292068						
				D 06/23/2000		1.000	EA	PReq 1000506238	00010	
				Still to be delivered		0.000	EA	0.00	USD	0.00 %
				Still to be invoiced		0.000	EA	0.00	USD	0.00 %
00020					ESTIMATED KY SALES TAX 6% 2ND 4 WKS RENT SERVICE					
				F MAY		1.000	EA	81.00	USD	1 EA
				Order 292068						
				D 06/23/2000		1.000	EA	PReq 1000506238	00020	
				Still to be delivered		0.000	EA	0.00	USD	0.00 %
				Still to be invoiced		0.000	EA	0.00	USD	0.00 %
M018659				ZZ 105652	PAR 4 PLASTICS, INC.				M09 06/23/2000	
00010					710 GUN STOCKS SHIPPED TO ETOWN				RAW	
				F MAY		23.000	EA	5.38	USD	1 EA
				Order 292068						
				D 06/23/2000		23.000	EA	PReq 1000506317	00010	
				Still to be delivered		0.000	EA	0.00	USD	0.00 %
				Still to be invoiced		0.000	EA	0.00	USD	0.00 %
00020					MATERIAL-RTP 199X83039E USED IN SAMPLE				RAW	
				F MAY		106	LB	0.88	USD	1 LB
				Order 292068						
				D 06/23/2000		106	LB	PReq 1000506317	00020	
				Still to be delivered		0	LB	0.00	USD	0.00 %
				Still to be invoiced		0	LB	0.00	USD	0.00 %
M018676				ZZ 102574	Gen-Con, Inc.				M09 06/27/2000	
00010					FABRICATE AND INSTALL EXHAUST FAN AND				MISC	
				F MAY		1.000	EA	2,985.62	USD	1 EA
				Order 292068						
				D 07/31/2000		1.000	EA	PReq 1000507914	00010	
				Still to be delivered		1.000	EA	2,985.62	USD	100.00 %
				Still to be invoiced		1.000	EA	2,985.62	USD	100.00 %

PO	Type	Vendor	Name	PGp	Order date
Item	Material		Short text		Mat. group
D I A Plnt SLoc	SL del. date	Order qty.	Un	Price	Curr. per Un
		Scheduled qty.	Un		
F MAY		1.000	EA	4,250.00	USD 1 EA
Order 292068					
D 05/19/2000		1.000	EA	4,250.00	USD 100.00 %
Still to be delivered		1.000	EA	4,250.00	USD 100.00 %
Still to be invoiced		1.000	EA	4,250.00	USD 100.00 %
M17492	ZZ 100361				
00010					
F MAY		1.000	EA	52,400.00	USD 1 EA
Order 292068					
D 03/23/2000		1.000	EA	0.00	USD 0.00 %
Still to be delivered		0.000	EA	0.00	USD 0.00 %
Still to be invoiced		0.000	EA	0.00	USD 0.00 %

83

MF1030

PO	Type	Vendor	Name	PGp	Order	date
Item	Material	Short text	Order qty.	Un	Price	Mat. group
D I A Plnt Sloc	SI del. date	Scheduled qty.	Un	Curr.	per Un	
	Still to be delivered	1.000	EA	104,000.00	USD	100.00 %
	Still to be invoiced	1.000	EA	104,000.00	USD	100.00 %
M017546A	ZZ 105344	AB LASERS				M01 03/14/2000
00010		AB LASER MACHINE "StarMark LME-1D" BASIC MISC				
	F MAY	1.000	EA	104,000.00	USD	1 EA
	Order 292068					
	D 05/22/2000	1.000	EA			
	Still to be delivered	0.700	EA	72,800.00	USD	70.00 %
	Still to be invoiced	0.700	EA	72,800.00	USD	70.00 %
M017553	ZZ 106507	NORTH AMERICAN PRECISION CASTING				M01 03/24/2000
00010		4-CAVITY MOLD / KNURLED 710-BOLT HANDLE TOOLING				
	F MAY	1.000	EA	8,595.00	USD	1 EA
	Order 292068					
	D 05/01/2000	1.000	EA			
	Still to be delivered	0.000	EA	0.00	USD	0.00 %
	Still to be invoiced	0.500	EA	4,297.50	USD	50.00 %
M017559	ZZ 105652	PAR 4 PLASTICS, INC.				M01 03/27/2000
00010		710 STOCK DRILLING FIXTURE				
	F MAY	1.000	EA	7,500.00	USD	1 EA
	Order 292068					
	D 04/20/2000	1.000	EA			
	Still to be delivered	0.000	EA	0.00	USD	0.00 %
	Still to be invoiced	0.000	EA	0.00	USD	0.00 %
M017574	ZZ 106668	TECHNICAL EQUIPMENT SALES				M01 04/06/2000
00010		HAAS VF-3D APC VERTICAL MACHINING CENTER 11CAPPROJ				
	F MAY	1.000	EA	115,000.00	USD	1 EA
	Order 292068					
	D 05/09/2000	1.000	EA			
	Still to be delivered	0.850	EA	97,750.00	USD	85.00 %
	Still to be invoiced	1.000	EA	115,000.00	USD	100.00 %
M018069	ZZ 103437	Universal Machine, Inc.				M09 04/04/2000
00010		BUILDING PROOF TEST BOX PER DRAWING				
	F MAY	1.000	EA	5,052.75	USD	1 EA
	Order 292068					
	D 04/28/2000	1.000	EA			
	Still to be delivered	1.000	EA	5,052.75	USD	100.00 %
	Still to be invoiced	1.000	EA	5,052.75	USD	100.00 %
M018075	ZZ 106667	ORBITFORM				M09 04/04/2000
00010		Orbitform Orbital Riveter -see long text CAT				
	F MAY	1.000	EA	11,100.00	USD	1 EA
	Order 292068					
	D 05/19/2000	1.000	EA			
	Still to be delivered	1.000	EA	11,100.00	USD	100.00 %
	Still to be invoiced	1.000	EA	11,100.00	USD	100.00 %
M018084	ZZ 103024	Savage Range Systems, Inc.				M09 04/04/2000
00010		ONE 8' RIFLE RATED RANGE				
	F MAY	1.000	EA	13,600.00	USD	1 EA
	Order 292068					
	D 05/15/2000	1.000	EA			
	Still to be delivered	1.000	EA	13,600.00	USD	100.00 %
	Still to be invoiced	1.000	EA	13,600.00	USD	100.00 %
00020		MODIFY TRAP TO INCLUDE REPLACEABLE WEAR				MISC
	F MAY	1.000	EA	5,000.00	USD	1 EA
	Order 292068					
	D 05/15/2000	1.000	EA			
	Still to be delivered	1.000	EA	5,000.00	USD	100.00 %
	Still to be invoiced	1.000	EA	5,000.00	USD	100.00 %
M018158	ZZ 1689884	NECCO MARKING				M09 04/13/2000
00010		PNEUMATIC MARKER (NON IMPACT) COMPLETE				

PO	Type	Vendor	Name	PGP	Order date
Item	Material	Short text	Mat. group		
D I A	Print Sloc	Order qty.	Un	Price	Curr. per Un
SL del. date	Scheduled qty.	Un			
00010		MB-6 SINGLE STATION BRAZE MACHINE	11CAPPROJ		
F MAY		1.000 EA	59,635.00	USD	1 EA
Order 292068					
D 05/08/2000		1.000 EA	0.00	USD	0.00 %
Still to be delivered		0.000 EA	0.00	USD	0.00 %
Still to be invoiced		0.334 EA	19,216.09	USD	33.40 %
M017491	ZZ 1881473	SQUARE STAMPING MFG CORP.	M01 01/26/2000		
00010		MFR. STAMPING DIE FOR 710 SAFETY	TOOLING		
F MAY		1.000 EA	19,900.00	USD	1 EA
Order 292068					
D 04/11/2000		1.000 EA	19,900.00	USD	100.00 %
Still to be delivered		1.000 EA	19,900.00	USD	100.00 %
Still to be invoiced		1.000 EA	19,900.00	USD	100.00 %
00020		ADDITIONAL TOOL CHARGE FOR CHANGE OFF DIE	TOOLING		
F MAY		1.000 EA	2,900.00	USD	1 EA
Order 292068					
D 04/11/2000		1.000 EA	2,900.00	USD	100.00 %
Still to be delivered		1.000 EA	2,900.00	USD	100.00 %
Still to be invoiced		1.000 EA	2,900.00	USD	100.00 %
M017497	ZZ 106543	VALCO/ VALLEY TOOL AND DIE INC.	M01 02/04/2000		
00010		TOOL MOLD (TO PRODUCE TO PRINT C-300405)	TOOLING		
F MAY		1.000 EA	16,055.00	USD	1 EA
Order 292068					
D 04/27/2000		1.000 EA	0.00	USD	0.00 %
Still to be delivered		0.000 EA	0.00	USD	0.00 %
Still to be invoiced		0.333 EA	5,346.32	USD	33.30 %
M017498	ZZ 106543	VALCO/ VALLEY TOOL AND DIE INC.	M01 02/04/2000		
00010		PROTOTYPE MAGAZINE SPRING C-300405 / 710 MISC			
F MAY		1,000.000 EA	2.50	USD	1 EA
Order 292068					
D 03/02/2000		1,000.000 EA	0.00	USD	0.00 %
Still to be delivered		0.000 EA	0.00	USD	0.00 %
Still to be invoiced		0.000 EA	0.00	USD	0.00 %
M017530	ZZ 106500	BRAININ DEER PARK DIE & STAMPING	M01 03/06/2000		
00010		Design & build Progressive Die E-300363	TOOLING		
F MAY		1.000 EA	83,000.00	USD	1 EA
Order 292068					
D 06/09/2000		1.000 EA	55,278.00	USD	66.60 %
Still to be delivered		0.666 EA	55,278.00	USD	66.60 %
Still to be invoiced		0.666 EA	55,278.00	USD	66.60 %
M017531	ZZ 101155	INDUSTRIAL SPRING OF ST. LOUIS	M01 03/07/2000		
00010		PROTOTYPE FIRING PIN SPRINGS A-300399	SAMPLES		
F MAY		20.000 EA	10.00	USD	1 EA
Order 292068					
D 03/13/2000		20.000 EA	0.00	USD	0.00 %
Still to be delivered		0.000 EA	0.00	USD	0.00 %
Still to be invoiced		0.000 EA	0.00	USD	0.00 %
M017532	ZZ 106507	NORTH AMERICAN PRECISION CASTING	M01 03/07/2000		
00010		DESIGN & MFG. CUTTERS TO MAKE KNURLING	SAMPLES		
F MAY		1 ST	925.00	USD	1 ST
Order 292068					
D 03/15/2000		1 ST	0.00	USD	0.00 %
Still to be delivered		0 ST	0.00	USD	0.00 %
Still to be invoiced		0 ST	0.00	USD	0.00 %
M017546	ZZ 103386	Paulo, St. Louis	M01 03/14/2000		
00010		AB LASER MACHINE "StarMark LME-1D" BASIC MISC			
F MAY		1.000 EA	104,000.00	USD	1 EA
Order 292068					
D 05/22/2000		1.000 EA	Preq 1000443217	00010	

PO	Type	Vendor	Name	PGP	Order date
Item	Material	Short text	Mat. group		
D I A	Plnt Sloc	Order qty.	Un	Price	per Un
SL	del. date	Scheduled qty.	Un		
	D 04/26/2000	1.000	EA		
	Still to be delivered	0.300	EA	46,050.00	USD 30.00 %
	Still to be invoiced	0.300	EA	46,050.00	USD 30.00 %
M017477	ZZ 1881473	SQUARE STAMPING MFG CORP	M01	01/19/2000	
00010		PRODUCTION TOOL FOR B-300331 RE-ROLL BRKT	TOOLING		
	F MAY	1.000	EA	5,500.00	USD 1 EA
	Order 292068				
	D 03/15/2000	1.000	EA		
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M017478	ZZ 1881473	SQUARE STAMPING MFG CORP	M01	01/20/2000	
00010		TOOL FOR 710 PART# C-300333 SLIDE PLATE	TOOLING		
	F MAY	1.000	EA	7,500.00	USD 1 EA
	Order 292068				
	D 03/29/2000	1.000	EA		
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M017479	ZZ 1875145	ANDERSON SCREW PRODUCTS INC	M01	01/20/2000	
00010		TOOL FOR 710 BOLT PLUG INSERT #B-300346	TOOLING		
	F MAY	1.000	EA	2,250.00	USD 1 EA
	Order 292068				
	D 03/29/2000	1.000	EA		
	Still to be delivered	1.000	EA	2,250.00	USD 100.00 %
	Still to be invoiced	1.000	EA	2,250.00	USD 100.00 %
M017480	ZZ 106504	MEGAMET INDUSTRIES	M01	01/20/2000	
00010		TOOLING MOLD / 710 LOCK TUMBLER B-300420	TOOLING		
	F MAY	1.000	EA	20,000.00	USD 1 EA
	Order 292068				
	D 03/29/2000	1.000	EA		
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.333	EA	6,660.00	USD 33.30 %
M017484	ZZ 106507	NORTH AMERICAN PRECISION CASTING	M01	01/24/2000	
00010		4-CAVITY INJECTION MOLD/ 710 BOLT HANDLE	TOOLING		
	F MAY	1.000	EA	6,550.00	USD 1 EA
	Order 292068				
	D 03/27/2000	1.000	EA		
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M017486	ZZ 105686	STERLING SINTERED TECHNOLOGIES	M01	01/25/2000	
00010		TOOLING FOR 710 BOLT STOP C-300345	TOOLING		
	F MAY	1.000	EA	5,500.00	USD 1 EA
	Order 292068				
	D 04/03/2000	1.000	EA		
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.500	EA	2,750.00	USD 50.00 %
M017487	ZZ 105686	STERLING SINTERED TECHNOLOGIES	M01	01/25/2000	
00010		TOOLING MOLD FOR 710 TRIGGER C-300435	TOOLING		
	F MAY	1.000	EA	1,435.00	USD 1 EA
	Order 292068				
	D 04/11/2000	1.000	EA		
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00020		CANCELLATION CHARGE-CHARGE FOR DESIGN	TOOLING		
L	F MAY	1.000	EA	1,435.00	USD 1 EA
	Order 292068				
	D 04/11/2000	1.000	EA		
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M017490	ZZ 106533	CYBERTECH, INTERNATIONAL	M01	01/31/2000	

PO	Type	Vendor	Name	PGp	Order date
Item	Material		Short text		Mat. group
D I A Plnt SLoc	SL del. date	Order qty.	Un	Price	Curr. per Un
		Scheduled qty.	Un		
M016948	ZZ	103437	Universal Machine Inc.	M09	03/14/2000
00010			BUILD SIGHT HOLE FIXTURE EK-10452		TOOLING
	F MAY	1.000	EA	3,000.00	USD 1 EA
	Order 292068				
	D 04/11/2000	1.000	EA	3,000.00	USD 100.00 %
	Still to be delivered	1.000	EA	3,000.00	USD 100.00 %
	Still to be invoiced	1.000	EA	3,000.00	USD 100.00 %
M017435	ZZ	105652	PAR 4 PLASTICS, INC.	M01	12/13/1999
00010			1 CAVITY PRODUCTION MOLD FOR 710 STOCK		TOOLING
	F MAY	1.000	EA	145,300.00	USD 1 EA
	Order 292068				
	D 03/29/2000	1.000	EA	0.00	USD 0.00 %
	Still to be delivered	0.000	EA	48,384.00	USD 33.30 %
	Still to be invoiced	0.333	EA	48,384.00	USD 33.30 %
M017443	ZZ	101070	KELLEMS & COE TOOL CORP	M01	12/14/1999
00010			2-CAVITY PRODUCTION MOLD F300368 FOR 710		TOOLING
	F MAY	1.000	EA	38,000.00	USD 1 EA
	Order 292068				
	D 03/21/2000	1.000	EA	0.00	USD 0.00 %
	Still to be delivered	0.000	EA	12,654.00	USD 33.30 %
	Still to be invoiced	0.333	EA	12,654.00	USD 33.30 %
M017457	ZZ	102282	MATTHEW MACHINERY	M01	12/21/1999
00010			OKUMA LB-300 MY CNC TURNING CENTER 910		TOOLING
	F MAY	1.000	EA	219,700.00	USD 1 EA
	Order 292068				
	D 04/07/2000	1.000	EA	219,700.00	USD 100.00 %
	Still to be delivered	1.000	EA	219,700.00	USD 100.00 %
	Still to be invoiced	1.000	EA	219,700.00	USD 100.00 %
00020			LB-300 MACHINE RUN-OFF AND SET-UP 910		TOOLING
	F MAY	1.000	EA	5,000.00	USD 1 EA
	Order 292068				
	D 04/07/2000	1.000	EA	5,000.00	USD 100.00 %
	Still to be delivered	1.000	EA	5,000.00	USD 100.00 %
	Still to be invoiced	1.000	EA	5,000.00	USD 100.00 %
M017465	ZZ	105652	PAR 4 PLASTICS, INC.	M01	01/11/2000
00010			2 CAVITY PRODUCTION MOLD / 710 MAG LATCH		TOOLING
	F MAY	1.000	EA	31,806.00	USD 1 EA
	Order 292068				
	D 04/24/2000	1.000	EA	0.00	USD 0.00 %
	Still to be delivered	0.000	EA	10,591.40	USD 33.30 %
	Still to be invoiced	0.333	EA	10,591.40	USD 33.30 %
M017466	ZZ	105652	PAR 4 PLASTICS, INC.	M01	01/12/2000
00010			2+2 Family Mold- 710 Follower/Box Bottom		TOOLING
	F MAY	1.000	EA	73,786.00	USD 1 EA
	Order 292068				
	D 04/17/2000	1.000	EA	25,087.24	USD 34.00 %
	Still to be delivered	0.340	EA	25,087.24	USD 34.00 %
	Still to be invoiced	0.340	EA	25,087.24	USD 34.00 %
M017470	ZZ	106504	MEGAMET INDUSTRIES	M01	01/14/2000
00010			METAL INJECTION MOLD FOR 710 / C-300336		TOOLING
	F MAY	1.000	EA	16,000.00	USD 1 EA
	Order 292068				
	D 03/16/2000	1.000	EA	8,000.00	USD 50.00 %
	Still to be delivered	0.500	EA	8,000.00	USD 50.00 %
	Still to be invoiced	0.500	EA	8,000.00	USD 50.00 %
M017471	ZZ	105901	WELDUCTION CORP	M01	01/17/2000
00010			FLEXSCAN INDUCTION HEAT TREAT CENTER		11CAPPROJ
	F MAY	1.000	EA	153,500.00	USD 1 EA
	Order 292068				

PO	Type	Vendor	Name	PGP	Order date
Item	Material		Short text		Mat. group
D I A	Pint Sloc		Order qty.	Un	Price Curr.
SL del. date			Scheduled qty.	Un	per Un
00030	F MAY		WGC SPECIAL AIR PROBE TO CHK	3000/3010	03
	Order 292068		1.000 EA	2,605.38	USD 1 EA
	D 02/28/2000		1.000 EA	0.00	USD 0.00 %
	Still to be delivered		0.000 EA	0.00	USD 0.00 %
	Still to be invoiced		0.000 EA	0.00	USD 0.00 %
00090	F MAY		AEQ 21-33-10 MICRO-AIR DIGITAL COMPARATOR	03	
	Order 292068		1.000 EA	4,393.75	USD 1 EA
	D 02/28/2000		1.000 EA	0.00	USD 0.00 %
	Still to be delivered		0.000 EA	0.00	USD 0.00 %
	Still to be invoiced		0.000 EA	0.00	USD 0.00 %
M016619	ZZ	3557873	WILSON INSTRUMENT INC		M09 01/28/2000
00010	F MAY		MODEL 2001 DIGITAL ROCKWELL TESTER		LAB EQUIP
	Order 292068		1.000 EA	13,800.00	USD 1 EA
	D 02/29/2000		1.000 EA	0.00	USD 0.00 %
	Still to be delivered		0.000 EA	0.00	USD 0.00 %
	Still to be invoiced		0.000 EA	0.00	USD 0.00 %
M016649	ZZ	100361	REGAL INDUSTRIES INC		M09 02/04/2000
00010	F MAY		MEASURE MAX PROGRAMMING OF PARTS		LAB EQUIP
	Order 292068		1.000 EA	5,675.00	USD 1 EA
	D 03/01/2000		1.000 EA	0.00	USD 0.00 %
	Still to be delivered		1.000 EA	5,675.00	USD 100.00 %
	Still to be invoiced		1.000 EA	5,675.00	USD 100.00 %
M016749	ZZ	102282	MATTHEW MACHINERY		M09 02/15/2000
00010	F MAY		CHUCK		
	Order 292068		1.000 EA	5,155.00	USD 1 EA
	D 02/29/2000		1.000 EA	0.00	USD 0.00 %
	Still to be delivered		0.000 EA	0.00	USD 0.00 %
	Still to be invoiced		0.000 EA	0.00	USD 0.00 %
00020	F MAY		CYLINDER		
	Order 292068		1.000 EA	3,350.00	USD 1 EA
	D 02/29/2000		1.000 EA	0.00	USD 0.00 %
	Still to be delivered		0.000 EA	0.00	USD 0.00 %
	Still to be invoiced		0.000 EA	0.00	USD 0.00 %
00040	F MAY		PART OF ORDER TAXABLE KY TAX 6%		
	Order 292068		1.000 EA	2.51	USD 1 EA
	D 02/29/2000		1.000 EA	0.00	USD 0.00 %
	Still to be delivered		0.000 EA	0.00	USD 0.00 %
	Still to be invoiced		0.000 EA	0.00	USD 0.00 %
M016804	ZZ	103024	Savage Range Systems, Inc.		M09 02/22/2000
00010	F MAY		PROOF AND FUNCTION BULLET TRAP		910
	Order 292068		1.000 EA	11,000.00	USD 1 EA
	D 03/31/2000		1.000 EA	0.00	USD 0.00 %
	Still to be delivered		1.000 EA	11,000.00	USD 100.00 %
	Still to be invoiced		1.000 EA	11,000.00	USD 100.00 %
M016929	ZZ	5108204	BROOKFIELD MACHINE INC		M09 03/10/2000
00010	F MAY		PART #E-K-10462		MISC
	Order 292068		1.000 EA	5,530.00	USD 1 EA
	D 04/10/2000		1.000 EA	0.00	USD 0.00 %
	Still to be delivered		0.000 EA	0.00	USD 0.00 %
	Still to be invoiced		1.000 EA	5,530.00	USD 100.00 %

83

MF1035

Confidential - Subject - 5.22.0610010985 Order

Williams v. Remington

PO	Item	Type	Vendor	Name	Short text	Order qty.	Un	Net Price	Curr.	Order date	Mat. group
	D I A	Plnt	S Loc	SL del. date	Scheduled qty.						per Un
M016377	ZZ		5208718	GIDDINGS & LEWIS	K150 RETROFIT KIT RS-5; S/N: D-0323	1.000	EA	13,000.00	USD	M09 12/14/1999	0996 SERVICE
00010											1 EA
	F MAY										
	Order		292068			1.000	EA	PREq 1000270627	00010		
			D 01/17/2000			0.000	EA	0.00	USD		0.00 %
	Still to be delivered					0.000	EA	0.00	USD		0.00 %
	Still to be invoiced					0.000	EA	0.00	USD		0.00 %
00020				ESTIMATED	KY SALES TAX AT 6%	1.000	EA	780.00	USD		1 EA
	F MAY										
	Order		292068			1.000	EA				
			D 01/17/2000			0.000	EA	0.00	USD		0.00 %
	Still to be delivered					0.000	EA	0.00	USD		0.00 %
	Still to be invoiced					0.000	EA	0.00	USD		0.00 %
M016396	ZZ		106410	FARRIS, MCINTOSH, & TRENGER, INC.	TOPOGRAPHIC SURVEY	1.000	EA	1,300.00	USD	M09 12/14/1999	SERVICE
00010											1 EA
	F MAY										
	Order		292068			1.000	EA	PREq 1000274300	00010		
			D 01/31/2000			0.000	EA	0.00	USD		0.00 %
	Still to be delivered					0.000	EA	0.00	USD		0.00 %
	Still to be invoiced					0.000	EA	0.00	USD		0.00 %
00020				ENGINEERING CHARGE		1.000	EA	13,902.00	USD		1 EA
	F MAY										
	Order		292068			1.000	EA	PREq 1000274300	00020		
			D 01/31/2000			0.000	EA	0.00	USD		0.00 %
	Still to be delivered					1.000	EA	13,902.00	USD		100.00 %
	Still to be invoiced										
M016555	ZZ		106516	MICROCENTRIC	SF-1787-01 CB42-S/A6 LOW PROFILE COLLET	1.000	EA	3,645.00	USD	M09 01/21/2000	03
00010											1 EA
	F MAY										
	Order		292068			1.000	EA	PREq 1000321299	00010		
			D 02/10/2000			0.000	EA	0.00	USD		0.00 %
	Still to be delivered					1.000	EA	3,645.00	USD		100.00 %
	Still to be invoiced										
M016586	ZZ		5108204	BROOKFIELD MACHINE INC	DESIGN/BUILD DPTH GAGE RIFLE CHAM SHLD	1.000	EA	8,732.00	USD	M09 01/25/2000	TOOLING
00010											1 EA
	F MAY										
	Order		292068			1.000	EA	PREq 1000328051	00010		
			D 03/31/2000			0.000	EA	0.00	USD		0.00 %
	Still to be delivered					1.000	EA	8,732.00	USD		100.00 %
	Still to be invoiced										
00020				DESIGN/BUILD DPTH GAGE RIFLE CHAM NECK		1.000	EA	8,470.00	USD		1 EA
	F MAY										
	Order		292068			1.000	EA	PREq 1000328051	00020		
			D 03/31/2000			0.000	EA	0.00	USD		0.00 %
	Still to be delivered					1.000	EA	8,470.00	USD		100.00 %
	Still to be invoiced										
M016617	ZZ		106524	WESTERN GAGE CORPORATION	WGC SPECIAL TRIPLE CIRCUIT AIR SPINDLE	1.000	EA	5,467.25	USD	M09 01/28/2000	03
00010											1 EA
	F MAY										
	Order		292068			1.000	EA	PREq 1000328038	00010		
			D 02/28/2000			0.000	EA	0.00	USD		0.00 %
	Still to be delivered					0.000	EA	0.00	USD		0.00 %
	Still to be invoiced					0.000	EA	0.00	USD		0.00 %
00020				NON RECURRING ENGINEER CHARGE FOR ABOVE		1.000	EA	926.25	USD		1 EA
	F MAY										
	Order		292068			1.000	EA	PREq 1000328038	00020		
			D 02/28/2000			0.000	EA	0.00	USD		0.00 %
	Still to be delivered					0.000	EA	0.00	USD		0.00 %
	Still to be invoiced					0.000	EA	0.00	USD		0.00 %

END 292068

ME1036

Confidential - ~~SECRET~~ - 5.22.06/0010986 Order

Williams V. Remington

Cost center 0000028200

Material Requisition S C R OTy. I A	Item	Short text Requested qty. Ordered qty.	Un	Deliv. Date Release date	Requester Trackg.no.	PGp Mat. gp. Plnt SLoc SPL. MC
- 1000400248 00010 N R A NB Z Desired vendor		1-1/4" X 3" FLAT STOCK #8910K74 1.000 EA D 02/24/2000			M09 GOLEMBOSKIMR HUTSONLR	44 MAY
- 1000400251 00010 N R A NB Z Desired vendor		101041 MCMaster-CARR SUPPLY CO BK-8065 .0754/.0810 ZZ TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00020 N R A NB Z		1884329 HARVEY DAVIDSON SALES INC BK-8066 .2482/.2520 ZZ TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00030 N R A NB Z		BK-8067 .1482/.1520 ZZ TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00040 N R A NB Z		BK-8068 .1224/.128 ZZ TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00050 N R A NB Z		BK-8069 .0712/.075 ZZ TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00060 N R A NB Z		BK-8062 .2605/.2700 ZZ TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00070 N R A NB Z		BK-8063 .2745/.284 ZZ TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00080 N R A NB Z		BK-8064 1.043/1.0490 X TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00090 N R A NB Z		BK-8070 .3176/.3225 Z TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00100 N R A NB Z		BK-8071 .2482/.2520 Z TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00110 N R A NB Z		BK-8072 .2552/.2590 Z TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00120 N R A NB Z		BK-8073 .4952/.5010 Z TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00130 N R A NB Z		BK-8074 .2231/.2260 Z TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00140 N R A NB Z		BK-8075 .0956/.0985 Y TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00150 N R A NB Z		BK-8076 .2855/.2950 ZZ TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00160 N R A NB Z		BK-8077 .1225/.1320 ZZ TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00170 N R A NB Z		BK-8078 .1206/.1235 Y TOLERANCE GAGE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR HUTSONLR	03 MAY
- 1000400251 00180		BK-8079 .2305/.2500 ZZ TOLERANCE 1.000 EA D 03/20/2000			M09 GOLEMBOSKIMR	03 MAY

- 110 S/U

2/2/2000

83

BARBER - 5.22.06r0010987

ME1037

Confidential - Submitter: 522P060600987 Order

Williams V. Remington

Cost center 0000028200

Material Requisition. S C R Qty. I A	Item I A	Short text Requested qty. Ordered qty.	Un Deliv. date Un Release date	Requester Trackg.no.	PGP	Mat. gp. Plnt Sloc Spl. MC
N R A NB	Z		02/22/2000	HUTSONLR		
- 1000400251	00190	BK-1040 .699/.703 ZZ TOLERANCE	1.000 EA D 03/23/2000	GOLEMBOSKIMR	M09	03 MAY
N R A NB	Z		02/22/2000	HUTSONLR		
- 1000402335	00010	MAGAZINE LATCH COMPARATOR SCREEN K-10425	1.000 EA D 03/23/2000	GOLEMBOSKIMR	M09	TOOLING MAY
N R A NB	Z		02/23/2000	HUTSONLR		
Desired vendor		5390090 PHI ASSOCIATES				
- 1000402336	00010	RECEIVER PLUG GAGE K-10426	1.000 EA D 03/23/2000	GOLEMBOSKIMR	M09	TOOLING MAY
N R A NB	Z		02/23/2000	HUTSONLR		
Desired vendor		5390090 PHI ASSOCIATES				
- 1000402337	00010	2-COLLET-COOLANT ADAPTERS FOR .214 DIA	1.000 EA D 02/25/2000	GOLEMBOSKIMR	M09	MISC MAY
N R A NB	Z		02/23/2000	HUTSONLR		
Desired vendor		103437 Universal Machine, Inc.				

BARBER - 5.22.06/0010988

MF1038

Confidential - ~~SECRET~~ - 5.22.06/0010988 Order
Williams V. Remington

PO	Type	Vendor	Name	PGp	Order date
Item	Material		Short text		Mat. group
D I A	Plnt SLoc		Order qty.	Un	per Un
	SL del. date		Scheduled qty.	Un	
M016637	ZZ	104762	G AND H TOOL & DIE INC	M09	02/04/2000
00010			B-63907 EXTRACTOR FUNCTIONAL WIDTH GAGE TOOLING		
	Z MAY		1.000 EA	115.00 USD	1 EA
	Cost center 28200				
	D 02/29/2000		1.000 EA	Preq 1000342294	00010
	Still to be delivered		1.000 EA	115.00 USD	100.00 %
	Still to be invoiced		1.000 EA	115.00 USD	100.00 %
00020			C-45390 EXTRACTOR COMPARATOR AND FIXTURE TOOLING		
	Z MAY		1.000 EA	558.00 USD	1 EA
	Cost center 28200				
	D 02/29/2000		1.000 EA	Preq 1000342294	00020
	Still to be delivered		1.000 EA	558.00 USD	100.00 %
	Still to be invoiced		1.000 EA	558.00 USD	100.00 %
00030			C-44604 TRIGGER CONNECT SQUARENESS GAGE TOOLING		
	Z MAY		1.000 EA	105.00 USD	1 EA
	Cost center 28200				
	D 02/29/2000		1.000 EA	Preq 1000342294	00030
	Still to be delivered		1.000 EA	105.00 USD	100.00 %
	Still to be invoiced		1.000 EA	105.00 USD	100.00 %
00040			C-44522 TRIGGER CONNECT WIDTH GAGE TOOLING		
	Z MAY		1.000 EA	135.00 USD	1 EA
	Cost center 28200				
	D 02/29/2000		1.000 EA	Preq 1000342294	00040
	Still to be delivered		1.000 EA	135.00 USD	100.00 %
	Still to be invoiced		1.000 EA	135.00 USD	100.00 %
00050			C-43887 TRIGGER CONNECT & COMPARATOR FIX TOOLING		
	Z MAY		1.000 EA	595.00 USD	1 EA
	Cost center 28200				
	D 02/29/2000		1.000 EA	Preq 1000342294	00050
	Still to be delivered		1.000 EA	595.00 USD	100.00 %
	Still to be invoiced		1.000 EA	595.00 USD	100.00 %
M016638	ZZ	103982	MAYFIELD PLUMBING & ELEC. SUPPLY	M09	02/04/2000
00010			PVC SCH40 3/4 COUPLING 85203		
	Z MAY		10.000 EA	0.20 USD	1 EA
	Cost center 28200				
	D 02/04/2000		10.000 EA	Preq 1000348486	00010
	Still to be delivered		0.000 EA	0.00 USD	0.00 %
	Still to be invoiced		0.000 EA	0.00 USD	0.00 %
00020			2" PVC SCH 40 COUPLING 85211		
	Z MAY		1.000 EA	0.76 USD	1 EA
	Cost center 28200				
	D 02/04/2000		1.000 EA	Preq 1000348486	00020
	Still to be delivered		0.000 EA	0.00 USD	0.00 %
	Still to be invoiced		0.000 EA	0.00 USD	0.00 %
00030			UNIWELD PVC CEMENT 1 PINT 8367501246		
	Z MAY		1.000 EA	3.70 USD	1 EA
	Cost center 28200				
	D 02/04/2000		1.000 EA	Preq 1000348486	00030
	Still to be delivered		0.000 EA	0.00 USD	0.00 %
	Still to be invoiced		0.000 EA	0.00 USD	0.00 %
00040			UNIWELD PVC/CPVC CLNR 1 PT 8367507346		
	Z MAY		1.000 EA	2.81 USD	1 EA
	Cost center 28200				
	D 02/04/2000		1.000 EA	Preq 1000348486	00040
	Still to be delivered		0.000 EA	0.00 USD	0.00 %
	Still to be invoiced		0.000 EA	0.00 USD	0.00 %
M016642	ZZ	103681	YOUNGBLOOD'S TRUE VALUE HOME CTR	M09	02/04/2000
00010			#143743 MP205 1/4 PT PVC CEMENT		
	Z MAY		1.000 EA	1.68 USD	1 EA

83

MF1039

Confidential - Subject - 5.22.06r0010989 Order

Williams v. Remington

PO	Type	Vendor	Name	PGP	Order	date
Item	Material		Short text		Mat. group	
D I A	Plnt Sloc		Order qty.	Net Price	Curr.	per Un
SL	del. date		scheduled qty.	Un		
	Cost center 28200					
	D 02/04/2000		1.000	EA	Preq 1000348484	00010
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00020	#149658 MP214 1/4 PT PWD CLEANER		1.000	EA	1.48	USD MISC 1 EA
	Z MAY					
	Cost center 28200					
	D 02/04/2000		1.000	EA	Preq 1000348484	00020
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00030	#341040 3/4" X 10' SCH 40 PIPE		2.000	EA	1.50	USD MISC 1 EA
	Z MAY					
	Cost center 28200					
	D 02/04/2000		2.000	EA	Preq 1000348484	00030
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00040	#346764 3/4" PVC BALL VALVE-SXS		3.000	EA	3.18	USD MISC 1 EA
	Z MAY					
	Cost center 28200					
	D 02/04/2000		3.000	EA	Preq 1000348484	00040
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00050	#412783 8 PACK ENERGIZER AA BATTERIES		2.000	EA	5.49	USD MISC 1 EA
	Z MAY					
	Cost center 28200					
	D 02/04/2000		2.000	EA	Preq 1000348484	00050
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00060	#415281 164604 3/4" PVC SLIP UNION		4.000	EA	2.18	USD MISC 1 EA
	Z MAY					
	Cost center 28200					
	D 02/04/2000		4.000	EA	Preq 1000348484	00060
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00070	#544296 151051 1/2"-1" PVC PIPE CUTTER		2.000	EA	12.99	USD MISC 1 EA
	Z MAY					
	Cost center 28200					
	D 02/04/2000		2.000	EA	Preq 1000348484	00070
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00080	#740290 18260 10.5 OZ RELY-ON LATEX WHIT		2.000	EA	0.94	USD MISC 1 EA
	Z MAY					
	Cost center 28200					
	D 02/04/2000		2.000	EA	Preq 1000348484	00080
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00090	#34 PL 3/4" PVC 45 DEG ELBOW 4539		6.000	EA	0.48	USD MISC 1 EA
	Z MAY					
	Cost center 28200					
	D 02/04/2000		6.000	EA	Preq 1000348484	00090
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00100	#34PC 3/4" PVC COUPLING		8.000	EA	0.14	USD MISC 1 EA
	Z MAY					
	Cost center 28200					
	D 02/04/2000		8.000	EA	Preq 1000348484	00100
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00110	#34PL 30707 3/4" PVC 90 DEG ELBOW					MISC

PO	Item	Type	Vendor	Name	PGP	Order date
	Material			Short text		Mat. group
	D I A	Print	S Loc	Order qty.	Un	per Un
			SL del. date	Scheduled qty.	Un	
	Z MAY			10.000	EA	0.19 USD 1 EA
	Cost center 28200					
	D 02/04/2000			10.000	EA	PREq 1000348484 00110
	Still to be delivered			0.000	EA	0.00 USD 0.00 %
	Still to be invoiced			0.000	EA	0.00 USD 0.00 %
00120	#34PM 30407 3/4"			5.000	EA	PVC MALE ADAPTOR MISC 1 EA
	Z MAY					
	Cost center 28200					
	D 02/04/2000			5.000	EA	PREq 1000348484 00120
	Still to be delivered			0.000	EA	0.00 USD 0.00 %
	Still to be invoiced			0.000	EA	0.00 USD 0.00 %
M016657	ZZ 103982					MAYFIELD PLUMBING & ELEC. SUPPLY M09 02/04/2000
00010	1/2" BLACK PIPE			400.000	FT	0.62 USD MISC 1 FT
	Z MAY					
	Cost center 28200					
	D 02/04/2000			400.000	FT	PREq 1000348483 00010
	Still to be delivered			400.000	FT	248.00 USD 100.00 %
	Still to be invoiced			400.000	FT	248.00 USD 100.00 %
00020	3/4 X 1/2 BUSHING			25.000	EA	0.24 USD MISC 1 EA
	Z MAY					
	Cost center 28200					
	D 02/04/2000			25.000	EA	PREq 1000348483 00020
	Still to be delivered			25.000	EA	6.00 USD 100.00 %
	Still to be invoiced			25.000	EA	6.00 USD 100.00 %
00030	1/2 X 3/8 BUSHING			25.000	EA	0.21 USD MISC 1 EA
	Z MAY					
	Cost center 28200					
	D 02/04/2000			25.000	EA	PREq 1000348483 00030
	Still to be delivered			25.000	EA	5.25 USD 100.00 %
	Still to be invoiced			25.000	EA	5.25 USD 100.00 %
00040	1/2" 90 DEGREE ELBCW			25.000	EA	0.51 USD MISC 1 EA
	Z MAY					
	Cost center 28200					
	D 02/04/2000			25.000	EA	PREq 1000348483 00040
	Still to be delivered			25.000	EA	12.75 USD 100.00 %
	Still to be invoiced			25.000	EA	12.75 USD 100.00 %
00050	1/2" COUPLING			25.000	EA	0.70 USD MISC 1 EA
	Z MAY					
	Cost center 28200					
	D 02/04/2000			25.000	EA	PREq 1000348483 00050
	Still to be delivered			25.000	EA	17.50 USD 100.00 %
	Still to be invoiced			25.000	EA	17.50 USD 100.00 %
M016660	ZZ 106552					UNIVERSAL COATINGS CORPORATION M09 02/08/2000
00010	LBR & MTLS TO PREPARE SURFACE AND APPLY			1.000	EA	470.00 USD MISC 1 EA
	Z MAY					
	Cost center 28200					
	D 02/08/2000			1.000	EA	PREq 1000355094 00010
	Still to be delivered			0.000	EA	0.00 USD 0.00 %
	Still to be invoiced			0.000	EA	0.00 USD 0.00 %
M016676	ZZ 104046					SOUTHFORK ELECTRIC M09 02/10/2000
00010	SQD H362NRB 60A 600V 4SN SW			2.000	EA	347.77 USD 16 1 EA
	Z MAY					
	Cost center 28200					
	D 02/10/2000			2.000	EA	PREq 1000378492 00010
	Still to be delivered			0.000	EA	0.00 USD 0.00 %
	Still to be invoiced			2.000	EA	695.54 USD 100.00 %
00020	1706 1-1/2 D/C INS KO HUB ST-5/H0150-TB			1.000	EA	411.56 USD 16 100 EA
	Z MAY					
	Cost center 28200					

PO	Type	Vendor	Name	PGp	Order date
Item	Material	Short text	Mat. group		
D I A Plnt	Sloc	Order qty.	Net Price	Curr.	per Un
SL del. date	Scheduled qty.	Un			
	D 02/10/2000	1.000	EA PReq 1000378492	00020	
Still to be delivered		0.000	EA 0.00	USD	0.00 %
Still to be invoiced		0.000	EA 0.00	USD	0.00 %
00030	BUSS FRS-R60 600V RK TD FUSE	6.000	EA 10.30	USD	16 1 EA
Z MAY					
Cost center 28200					
	D 02/10/2000	6.000	EA PReq 1000378492	00030	
Still to be delivered		0.000	EA 0.00	USD	0.00 %
Still to be invoiced		0.000	EA 0.00	USD	0.00 %
00040	BUSS FRS-R30 600V RK TD FUSE	6.000	EA 10.30	USD	16 1 EA
Z MAY					
Cost center 28200					
	D 02/10/2000	6.000	EA PReq 1000378492	00040	
Still to be delivered		0.000	EA 0.00	USD	0.00 %
Still to be invoiced		0.000	EA 0.00	USD	0.00 %
00050	1702 1/2 D/C INS KO HUB ST-1/H050-TB	1.000	EA 200.85	USD	16 100 EA
Z MAY					
Cost center 28200					
	D 02/10/2000	1.000	EA PReq 1000378492	00050	
Still to be delivered		0.000	EA 0.00	USD	0.00 %
Still to be invoiced		0.000	EA 0.00	USD	0.00 %
00060	SQD H361NRB 30A-480V-4SN SW	1.000	EA 327.25	USD	16 1 EA
Z MAY					
Cost center 28200					
	D 02/10/2000	1.000	EA PReq 1000378492	00060	
Still to be delivered		0.000	EA 0.00	USD	0.00 %
Still to be invoiced		1.000	EA 327.25	USD	100.00 %
00070	SQD Q02140 SP-120/240V-40A CB	2.000	EA 15.00	USD	16 1 EA
Z MAY					
Cost center 28200					
	D 02/10/2000	2.000	EA PReq 1000378492	00070	
Still to be delivered		1.000	EA 15.00	USD	50.00 %
Still to be invoiced		1.000	EA 15.00	USD	50.00 %
00080	SQD Q00-4L70RB RT LD-CNTR	1.000	EA 43.27	USD	16 1 EA
Z MAY					
Cost center 28200					
	D 02/10/2000	1.000	EA PReq 1000378492	00080	
Still to be delivered		0.000	EA 0.00	USD	0.00 %
Still to be invoiced		0.000	EA 0.00	USD	0.00 %
00090	SQD FA34040 3P-480V-40A CB	1.000	EA 275.79	USD	16 1 EA
Z MAY					
Cost center 28200					
	D 02/10/2000	1.000	EA PReq 1000378492	00090	
Still to be delivered		0.000	EA 0.00	USD	0.00 %
Still to be invoiced		0.000	EA 0.00	USD	0.00 %
00100	1703 3/4 D/C INS KO HUB ST-2/H075-TB	1.000	EA 236.21	USD	16 100 EA
Z MAY					
Cost center 28200					
	D 02/10/2000	1.000	EA PReq 1000378492	00100	
Still to be delivered		0.000	EA 0.00	USD	0.00 %
Still to be invoiced		0.000	EA 0.00	USD	0.00 %
00110	BUSS FRS-R40 600V RK TD FUSE	3.000	EA 10.30	USD	16 1 EA
Z MAY					
Cost center 28200					
	D 02/10/2000	3.000	EA PReq 1000378492	00110	
Still to be delivered		0.000	EA 0.00	USD	0.00 %
Still to be invoiced		3.000	EA 30.90	USD	100.00 %
00120	WIRE THNN-8-BLK-19STR-CUICLCUT	1,500.000	EA 138.34	USD	16 1,000 EA
Z MAY					

PO	Type	Vendor	Name	PGP	Order date
Item	Material		Short text		Mat. group
D I A	Plant Sloc		Order qty.	Un	curr.
SL	del. date		Scheduled qty.	Un	per Un
	Cost center 28200				
	D 02/10/2000	1,500.000	EA	PReq 1000378492	00120
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00130	WIRE THNN-3-BLK-19STR	500.000	EA	419.07	USD 16 1,000 EA
	Z MAY				
	Cost center 28200				
	D 02/10/2000	500.000	EA	PReq 1000378492	00130
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00140	CONDUIT 1-1/2 EMT	120.000	EA	79.00	USD 16 100 EA
	Z MAY				
	Cost center 28200				
	D 02/10/2000	120.000	EA	PReq 1000378492	00140
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00150	2006 1-1/2 STL S/SCR EMT CONN TC125	3.000	EA	195.72	USD 16 100 EA
	Z MAY				
	Cost center 28200				
	D 02/10/2000	3.000	EA	PReq 1000378492	00150
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00160	2026 1-1/2 STL S/SCR EMT CPLG TK125	12.000	EA	231.87	USD 16 100 EA
	Z MAY				
	Cost center 28200				
	D 02/10/2000	12.000	EA	PReq 1000378492	00160
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00170	CONDUIT 3/4 EMT	360.000	EA	28.35	USD 16 100 EA
	Z MAY				
	Cost center 28200				
	D 02/10/2000	360.000	EA	PReq 1000378492	00170
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00180	2003 3/4 STEEL S/SCR EMT CONN TC122	9.000	EA	59.50	USD 16 100 EA
	Z MAY				
	Cost center 28200				
	D 02/10/2000	9.000	EA	PReq 1000378492	00180
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00190	2023 3/4 STEEL S/SCR EMT CPLG TK122	36.000	EA	75.20	USD 16 100 EA
	Z MAY				
	Cost center 28200				
	D 02/10/2000	36.000	EA	PReq 1000378492	00190
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00200	1403 3/4 105D PLSTC INS BUSH 322	10.000	EA	7.82	USD 16 100 EA
	Z MAY				
	Cost center 28200				
	D 02/10/2000	10.000	EA	PReq 1000378492	00200
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00210	3M 35-GRN-3/4 X 66 FT CODING TAPE	4.000	EA	3.72	USD 16 1 EA
	Z MAY				
	Cost center 28200				
	D 02/10/2000	4.000	EA	PReq 1000378492	00210
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	4.000	EA	14.88	USD 100.00 %
M016692	ZZ 103595			Consolidated Electrical Distributor	M09 02/08/2000

83

MF1043

Confidential - Barber - 5.22.06r0010993 Order

Williams v. Remington

PO	Type	Vendor	Name	PGp	Order	date
Item	Material	Sloc	Short text	Mat. group		
D I A	Plnt	SL del. date	Order qty.	Un	Net Price	Curr. per Un
			Scheduled qty.	Un		
00010			LAMP INSTALLER #800T-N82		16	
	Z MAY		2.000 EA		3.72 USD	1 EA
	Cost center 28200					
	D 02/18/2000		2.000 EA	PREq 1000355096	00010	
	Still to be delivered		0.000 EA		0.00 USD	0.00 %
	Still to be invoiced		2.000 EA		7.44 USD	100.00 %
00020			MOMENTARY PUSH BUTTON #800T-BTA		16	
	Z MAY		4.000 EA		48.41 USD	1 EA
	Cost center 28200					
	D 02/18/2000		4.000 EA	PREq 1000355096	00020	
	Still to be delivered		0.000 EA		0.00 USD	0.00 %
	Still to be invoiced		0.000 EA		0.00 USD	0.00 %
00030			ENCLOSURE #800T-ITZ		16	
	Z MAY		6.000 EA		55.86 USD	1 EA
	Cost center 28200					
	D 02/18/2000		6.000 EA	PREq 1000355096	00030	
	Still to be delivered		0.000 EA		0.00 USD	0.00 %
	Still to be invoiced		0.000 EA		0.00 USD	0.00 %
M016694	ZZ	102641	MSC INDUSTRIAL SUPPLY		M09 02/08/2000	
00010			FEDERAL SERIES C MODEL C81 DIAL INDICAT		03	
	Z MAY		2.000 EA		107.00 USD	1 EA
	Cost center 28200					
	D 02/18/2000		2.000 EA	PREq 1000355095	00010	
	Still to be delivered		2.000 EA		214.00 USD	100.00 %
	Still to be invoiced		2.000 EA		214.00 USD	100.00 %
M016695	ZZ	101041	MCMaster-CARR SUPPLY CO		M09 02/08/2000	
00010			DB9 MALE CONNECTOR #2146T11		16	
	Z MAY		2.000 EA		8.21 USD	1 EA
	Cost center 28200					
	D 02/10/2000		2.000 EA	PREq 1000355404	00010	
	Still to be delivered		0.000 EA		0.00 USD	0.00 %
	Still to be invoiced		0.000 EA		0.00 USD	0.00 %
00020			WIRE #75985K56		16	
	Z MAY		30.000 FT		0.38 USD	1 FT
	Cost center 28200					
	D 02/10/2000		30.000 FT	PREq 1000355404	00020	
	Still to be delivered		0.000 FT		0.00 USD	0.00 %
	Still to be invoiced		0.000 FT		0.00 USD	0.00 %
00030			CABLE #7925K57		16	
	Z MAY		1.000 EA		7.18 USD	1 EA
	Cost center 28200					
	D 02/10/2000		1.000 EA	PREq 1000355404	00030	
	Still to be delivered		0.000 EA		0.00 USD	0.00 %
	Still to be invoiced		0.000 EA		0.00 USD	0.00 %
00040			BRUSH-YELLOW #20175T1		16	
	Z MAY		2.000 EA		5.58 USD	1 EA
	Cost center 28200					
	D 02/10/2000		2.000 EA	PREq 1000355404	00040	
	Still to be delivered		0.000 EA		0.00 USD	0.00 %
	Still to be invoiced		0.000 EA		0.00 USD	0.00 %
M016696	ZZ	102641	MSC INDUSTRIAL SUPPLY		M09 02/08/2000	
00010			STARRETT MAG BASE INDICAT HLDR #86422177		MISC	
	Z MAY		4.000 EA		91.95 USD	1 EA
	Cost center 28200					
	D 02/18/2000		4.000 EA	PREq 1000355405	00010	
	Still to be delivered		0.000 EA		0.00 USD	0.00 %
	Still to be invoiced		0.000 EA		0.00 USD	0.00 %
M016700	ZZ	102641	MSC INDUSTRIAL SUPPLY		M09 02/10/2000	
00010			.696"/.694" DIA X 4" OAL SOLID CARBIDE		03	

PO	Type	Vendor	Name	PGp	Order date
Item	Material		Short text		Mat. group
D I A Plnt	S Loc		Order qty.	Unit	Net Price
SL del. date			Scheduled qty.	Un	Curr. per Un
	Z MAY		1.000	EA	287.50 USD 1 EA
	Cost center 28200				
	D 02/22/2000		1.000	EA	Preq 1000355408 00010
	Still to be delivered		0.000	EA	0.00 USD 0.00 %
	Still to be invoiced		1.000	EA	287.50 USD 100.00 %
M016701	ZZ 5390090	PHI ASSOCIATES			M09 02/08/2000
00010		DIMPLE FIXTURE	1.000	EA	TOOLING 1 EA
	Z MAY		1.000	EA	1,200.00 USD 1 EA
	Cost center 28200				
	D 04/08/2000		1.000	EA	Preq 1000355101 00010
	Still to be delivered		1.000	EA	1,200.00 USD 100.00 %
	Still to be invoiced		1.000	EA	1,200.00 USD 100.00 %
M016702	ZZ 5390090	PHI ASSOCIATES			M09 02/08/2000
00010		BOLT HANDLE FIXTURE	1.000	EA	TOOLING 1 EA
	Z MAY		1.000	EA	1,800.00 USD 1 EA
	Cost center 28200				
	D 04/08/2000		1.000	EA	Preq 1000355102 00010
	Still to be delivered		1.000	EA	1,800.00 USD 100.00 %
	Still to be invoiced		1.000	EA	1,800.00 USD 100.00 %
M016703	ZZ 5390090	PHI ASSOCIATES			M09 02/08/2000
00010		GRINDING FIXTURE	1.000	EA	TOOLING 1 EA
	Z MAY		1.000	EA	1,580.00 USD 1 EA
	Cost center 28200				
	D 05/12/2000		1.000	EA	Preq 1000355402 00010
	Still to be delivered		1.000	EA	1,580.00 USD 100.00 %
	Still to be invoiced		1.000	EA	1,580.00 USD 100.00 %
M016710	ZZ 5390090	PHI ASSOCIATES			M09 02/10/2000
00010		COMPARATOR FIXTURE M/710 TRIGGER	1.000	EA	TOOLING 1 EA
	Z MAY		1.000	EA	510.00 USD 1 EA
	Cost center 28200				
	D 02/29/2000		1.000	EA	Preq 1000378490 00010
	Still to be delivered		1.000	EA	510.00 USD 100.00 %
	Still to be invoiced		1.000	EA	510.00 USD 100.00 %
M016711	ZZ 5390090	PHI ASSOCIATES			M09 02/10/2000
00010		COMPARATOR SCREEN M/710 TRIGGER	1.000	EA	TOOLING 1 EA
	Z MAY		1.000	EA	180.00 USD 1 EA
	Cost center 28200				
	D 02/29/2000		1.000	EA	Preq 1000378491 00010
	Still to be delivered		1.000	EA	180.00 USD 100.00 %
	Still to be invoiced		1.000	EA	180.00 USD 100.00 %
M016733	ZZ 104762	G AND H TOOL & DIE, INC			M09 02/14/2000
00010		C-K-10407 & 10407-2 BOLT STOP COMPARATOR	1.000	EA	TOOLING 1 EA
	Z MAY		1.000	EA	720.00 USD 1 EA
	Cost center 28200				
	D 03/21/2000		1.000	EA	Preq 1000380697 00010
	Still to be delivered		1.000	EA	720.00 USD 100.00 %
	Still to be invoiced		1.000	EA	720.00 USD 100.00 %
M016734	ZZ 104762	G AND H TOOL & DIE, INC			M09 02/14/2000
00010		D-K-10412 EJECTOR COMPARATOR FIXTURE	1.000	EA	TOOLING 1 EA
	Z MAY		1.000	EA	490.00 USD 1 EA
	Cost center 28200				
	D 03/21/2000		1.000	EA	Preq 1000380698 00010
	Still to be delivered		1.000	EA	490.00 USD 100.00 %
	Still to be invoiced		1.000	EA	490.00 USD 100.00 %
M016735	ZZ 104762	G AND H TOOL & DIE, INC			M09 02/14/2000
00010		D-K-10420 & 10420-2 MAG BOX DMM FIXTURE	1.000	EA	TOOLING 1 EA
	Z MAY		1.000	EA	620.00 USD 1 EA
	Cost center 28200				
	D 03/21/2000		1.000	EA	Preq 1000380699 00010

PO	Type	Vendor	Name	PGp	Order date
Item	Material	Short text	Order qty.	Net Price	Mat. group
D I A	PLnt SLoc	Schedul	Un	Curr.	per Un
SL	del. date	qty.			
		1.000	EA	20.00	USD 100.00 %
		1.000	EA	20.00	USD 100.00 %
M016736	ZZ 104762	G AND H TOOL & DIE, INC		M09 02/14/2000	
00010		C-K-10415/10415-2 BLT PLG INSERT DET	1/2	TOOLING	
	Z MAY	1.000	EA	150.00	USD 1 EA
	Cost center 28200				
	D 03/21/2000	1.000	EA	150.00	USD 100.00 %
	Still to be delivered	1.000	EA	150.00	USD 100.00 %
	Still to be invoiced	1.000	EA	150.00	USD 100.00 %
00020		C-K-10415/10415-2 BLT PLG INSERT DET	2/2	TOOLING	
	Z MAY	1.000	EA	40.00	USD 1 EA
	Cost center 28200				
	D 03/21/2000	1.000	EA	40.00	USD 100.00 %
	Still to be delivered	1.000	EA	40.00	USD 100.00 %
	Still to be invoiced	1.000	EA	40.00	USD 100.00 %
00030		C-K-10415/10415-2 BLT PLG INSERT DET	4/2	TOOLING	
	Z MAY	1.000	EA	55.00	USD 1 EA
	Cost center 28200				
	D 03/21/2000	1.000	EA	55.00	USD 100.00 %
	Still to be delivered	1.000	EA	55.00	USD 100.00 %
	Still to be invoiced	1.000	EA	55.00	USD 100.00 %
M016740	ZZ 104762	G AND H TOOL & DIE, INC		M09 02/14/2000	
00010		D-K-10402 RECEIV INSERT FUNCTIONAL GAGE		TOOLING	
	Z MAY	1.000	EA	210.00	USD 1 EA
	Cost center 28200				
	D 03/21/2000	1.000	EA	210.00	USD 100.00 %
	Still to be delivered	1.000	EA	210.00	USD 100.00 %
	Still to be invoiced	1.000	EA	210.00	USD 100.00 %
M016754	ZZ 1884329	HARVEY DAVIDSON SALES INC		M09 02/15/2000	
00010		# BK-8062 PLUG GAGE .3000/.3010 XX	03		
	Z MAY	1.000	EA	48.25	USD 1 EA
	Cost center 28200				
	D 03/29/2000	1.000	EA	48.25	USD 100.00 %
	Still to be delivered	1.000	EA	48.25	USD 100.00 %
	Still to be invoiced	1.000	EA	48.25	USD 100.00 %
00020		# BK-8058 PLUG GAGE .7054/.711 ZZ	03		
	Z MAY	1.000	EA	23.00	USD 1 EA
	Cost center 28200				
	D 02/29/2000	1.000	EA	23.00	USD 100.00 %
	Still to be delivered	1.000	EA	23.00	USD 100.00 %
	Still to be invoiced	1.000	EA	23.00	USD 100.00 %
00030		# BK-8061 PLUG GAGE .3006/.3015 ZX	03		
	Z MAY	1.000	EA	28.00	USD 1 EA
	Cost center 28200				
	D 02/29/2000	1.000	EA	28.00	USD 100.00 %
	Still to be delivered	1.000	EA	28.00	USD 100.00 %
	Still to be invoiced	1.000	EA	28.00	USD 100.00 %
00040		# BK-8060 PLUG GAGE .2985/.299 X	03		
	Z MAY	1.000	EA	31.25	USD 1 EA
	Cost center 28200				
	D 02/29/2000	1.000	EA	31.25	USD 100.00 %
	Still to be delivered	1.000	EA	31.25	USD 100.00 %
	Still to be invoiced	1.000	EA	31.25	USD 100.00 %
00050		# BK-8059 PLUG GAGE .2911/.293 Z	03		
	Z MAY	1.000	EA	21.75	USD 1 EA
	Cost center 28200				
	D 02/29/2000	1.000	EA	21.75	USD 100.00 %
	Still to be delivered	1.000	EA	21.75	USD 100.00 %
	Still to be invoiced	1.000	EA	21.75	USD 100.00 %

83

MF1046

Confidential - SHARPER - 5.22.06r0010996 Order

Williams v. Remington

PO	Item	Type	Vendor	Name	Short text	Order qty.	Unit	Net Price	Curr.	Order date	Mat. group	per Un
D	I	A	PLnt SLoc	SL del. date	Scheduled qty.	Un						
00060				# BK-8057	PLUG GAGE	1.000	EA	702/.70722	USD	03		1 EA
	Z MAY							23.00				
	Cost center 28200					1.000	EA	PREq 1000385555	USD	00060		
	D 02/29/2000					1.000	EA	23.00			100.00 %	
	Still to be delivered					1.000	EA	23.00			100.00 %	
	Still to be invoiced					1.000	EA	23.00			100.00 %	
00070				# BK-8048	PLUG GAGE	1.000	EA	.2750/.6522	USD	03		1 EA
	Z MAY							85.75				
	Cost center 28200					1.000	EA	PREq 1000385555	USD	00070		
	D 03/29/2000					1.000	EA	85.75			100.00 %	
	Still to be delivered					1.000	EA	85.75			100.00 %	
	Still to be invoiced					1.000	EA	85.75			100.00 %	
00080				# BK-8049	PLUG GAGE	1.000	EA	.1255/.4265 XX	USD	03		1 EA
	Z MAY							53.50				
	Cost center 28200					1.000	EA	PREq 1000385555	USD	00080		
	D 03/29/2000					1.000	EA	53.50			100.00 %	
	Still to be delivered					1.000	EA	53.50			100.00 %	
	Still to be invoiced					1.000	EA	53.50			100.00 %	
00090				# BK-8050	PLUG GAGE	1.000	EA	.0752/.0850Z	USD	03		1 EA
	Z MAY							18.25				
	Cost center 28200					1.000	EA	PREq 1000385555	USD	00090		
	D 02/29/2000					1.000	EA	18.25			100.00 %	
	Still to be delivered					1.000	EA	18.25			100.00 %	
	Still to be invoiced					1.000	EA	18.25			100.00 %	
00100				# BK-8051	PLUG GAGE	1.000	EA	.0985/.1015 Y	USD	03		1 EA
	Z MAY							24.25				
	Cost center 28200					1.000	EA	PREq 1000385555	USD	00100		
	D 02/29/2000					1.000	EA	24.25			100.00 %	
	Still to be delivered					1.000	EA	24.25			100.00 %	
	Still to be invoiced					1.000	EA	24.25			100.00 %	
00110				# BK-8052	PLUG GAGE	1.000	EA	.1486/.1505 XX	USD	03		1 EA
	Z MAY							53.50				
	Cost center 28200					1.000	EA	PREq 1000385555	USD	00110		
	D 03/29/2000					1.000	EA	53.50			100.00 %	
	Still to be delivered					1.000	EA	53.50			100.00 %	
	Still to be invoiced					1.000	EA	53.50			100.00 %	
00120				# BK-8053	PLUG GAGE	1.000	EA	.2782/.2820 Z	USD	03		1 EA
	Z MAY							39.50				
	Cost center 28200					1.000	EA	PREq 1000385555	USD	00120		
	D 03/29/2000					1.000	EA	39.50			100.00 %	
	Still to be delivered					1.000	EA	39.50			100.00 %	
	Still to be invoiced					1.000	EA	39.50			100.00 %	
00130				# BK-8054	PLUG GAGE	1.000	EA	.1255/.1264 XX	USD	03		1 EA
	Z MAY							53.50				
	Cost center 28200					1.000	EA	PREq 1000385555	USD	00130		
	D 03/29/2000					1.000	EA	53.50			100.00 %	
	Still to be delivered					1.000	EA	53.50			100.00 %	
	Still to be invoiced					1.000	EA	53.50			100.00 %	
M016755				ZZ	102641							
					MSC INDUSTRIAL SUPPLY							
00010					THREAD GAGE-FIRING PIN #BK-9011	1.000	EA	100.30	USD	03		1 EA
	Z MAY											
	Cost center 28200					1.000	EA	PREq 1000387530	USD	00010		
	D 02/29/2000					1.000	EA	100.30			100.00 %	
	Still to be delivered					1.000	EA	100.30			100.00 %	
	Still to be invoiced					1.000	EA	100.30			100.00 %	
00020					THREAD GAGE-THREADED INSERT #BK-9010	1.000	EA	53.00	USD	03		1 EA
	Z MAY											
	Cost center 28200					1.000	EA	PREq 1000387530	USD	00020		
	D 02/29/2000											

83

MF1047

Confidential - SHARPER - 5.22.06r0010997 Order

Williams V. Remington

85

Confidential - ~~Superior~~ - 5:22 PM 6/6/2019
Williams v. Remington

PO	Type	Vendor	Name	PGp	Order date
Item	Material		Short text		Mat. group
D 1 A	Plnt Sloc		Order qty.	Un	Net Price
	SL del. date		Scheduled qty.	Un	Curr. per Un
Z MAY			1.000	EA	179.00 USD 1 EA
Cost center 28200					
D 03/26/2000			1.000	EA	PReq 1000387533 00010
Still to be delivered			1.000	EA	179.00 USD 100.00 %
Still to be invoiced			1.000	EA	179.00 USD 100.00 %
00020		THREAD RING GAGE	BK-7009 TRIGGER SCREWS 03		
Z MAY			1.000	EA	220.00 USD 1 EA
Cost center 28200					
D 03/26/2000			1.000	EA	PReq 1000387533 00020
Still to be delivered			1.000	EA	220.00 USD 100.00 %
Still to be invoiced			1.000	EA	220.00 USD 100.00 %
M016778	ZZ 102641	MSC INDUSTRIAL SUPPLY			M09 02/17/2000
00010		TP200 STYLUS MODULE A/1207	3.000	EA	630.00 USD 1 EA
Z MAY					
Cost center 28200					
D 02/29/2000			3.000	EA	PReq 1000389389 00010
Still to be delivered			3.000	EA	1,890.00 USD 100.00 %
Still to be invoiced			3.000	EA	1,890.00 USD 100.00 %

83

MF1049

PO	Item	Type	Vendor	Name	PGp	Order	date
	Material			Short text		Mat. group	
	D I A	Plnt	Sloc	Order qty.	Un	Curr.	per Un
		SL	del. date	Scheduled qty.	Un		
M015752	ZZ	102641		MSC INDUSTRIAL SUPPLY	M01	08/30/1999	
00020				FREIGHT		03	
	K MAY			1.000 EA	9.24	USD	1 EA
	Cost center 28200						
	D 09/30/1999			1.000 EA			
	Still to be delivered			0.000 EA	0.00	USD	0.00 %
	Still to be invoiced			0.000 EA	0.00	USD	0.00 %
M015787	ZZ	5888440		KAYS ENGINEERING INC	M01	09/02/1999	
00010				#00249 GIZMO #2		17	
	Z MAY			16.000 EA	120.00	USD	1 EA
	Cost center 28200						
	D 09/09/1999			16.000 EA			
	Still to be delivered			0.000 EA	0.00	USD	0.00 %
	Still to be invoiced			0.000 EA	0.00	USD	0.00 %
M015788	ZZ	6093720		EDGE TEK MACHINE CORP	M01	09/02/1999	
00010				A02B-0237-J895 EXTRA OFFSETS-48 PAL		17	
	Z MAY			1.000 EA	599.00	USD	1 EA
	Cost center 28200						
	D 09/10/1999			1.000 EA			
	Still to be delivered			0.000 EA	0.00	USD	0.00 %
	Still to be invoiced			0.000 EA	0.00	USD	0.00 %
M015802	ZZ	5380140		DANJON MANUFACTURING CORP	M01	09/08/1999	
00010				30-06 RIFLING BUTTON TICN COATED ON		03	
	Z MAY			1.000 EA	186.00	USD	1 EA
	Cost center 28200						
	D 09/29/1999			1.000 EA			
	Still to be delivered			0.000 EA	0.00	USD	0.00 %
	Still to be invoiced			0.000 EA	0.00	USD	0.00 %
00020				.299 CARBIDE BORE REAMERS ON 43" TUBES		03	
	Z MAY			4.000 EA	126.55	USD	1 EA
	Cost center 28200						
	D 09/29/1999			4.000 EA			
	Still to be delivered			0.000 EA	0.00	USD	0.00 %
	Still to be invoiced			0.000 EA	0.00	USD	0.00 %
00030				.292 DIA. A/C GUN DRILLS X 56" CAL		03	
	Z MAY			8.000 EA	90.00	USD	1 EA
	Cost center 28200						
	D 09/29/1999			8.000 EA			
	Still to be delivered			0.000 EA	0.00	USD	0.00 %
	Still to be invoiced			0.000 EA	0.00	USD	0.00 %
M015803	ZZ	102641		MSC INDUSTRIAL SUPPLY	M01	09/08/1999	
00010				FACE DRIVERS-ROHM-#089085		03	
	Z MAY			4.000 EA	182.77	USD	1 EA
	Cost center 28200						
	D 09/09/1999			4.000 EA			
	Still to be delivered			0.000 EA	0.00	USD	0.00 %
	Still to be invoiced			0.000 EA	0.00	USD	0.00 %
00020				FACE DRIVERS 089086		03	
	Z MAY			3.000 EA	162.00	USD	1 EA
	Cost center 28200						
	D 09/09/1999			3.000 EA			
	Still to be delivered			0.000 EA	0.00	USD	0.00 %
	Still to be invoiced			0.000 EA	0.00	USD	0.00 %
M015804	ZZ	104125		INTERNATIONAL DRILL GUIDE	M01	09/08/1999	
00010				DRILL GUIDES B140 .283-.296		03	
	Z MAY			100.000 EA	3.50	USD	1 EA
	Cost center 28200						
	D 09/15/1999			100.000 EA			
	Still to be delivered			0.000 EA	0.00	USD	0.00 %

83

MF1050

Confidential - Subject - 5.22.06r0011000 Order

Williams v. Remington

85

Confidential - ~~Subpoena~~ Protective Order
 Subpoena - 5:22-PG-00160
 Williams v. Remington

PO	Type	Vendor	Name	PGp	Order date
Item	Material	Short text	Mat. group		
D I A	Plnt Sloc	Order qty.	Un	Net Price	curr. per Un
SL del. date	Scheduled qty.	Un			
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M015849	ZZ 104762	G AND H TOOL & DIE, INC	M01	09/13/1999	
00010		RIFLER TAILSTOCK GUIDE BUSHING		TOOLING	
	Z MAY	1.000	EA	85.50	USD 1 EA
	Cost center 28200				
	D 09/24/1999	1.000	EA		
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00020		RIFLER HEADSTOCK BUSHING		TOOLING	
	Z MAY	1.000	EA	54.50	USD 1 EA
	Cost center 28200				
	D 09/24/1999	1.000	EA		
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M015851	ZZ 106259	PIONEER BROAD	M01	09/13/1999	
00010		SPECIAL SMALL BODY AUTOMATIC BROAD		TOOLING	
	Z MAY	1.000	EA	953.00	USD 1 EA
	Cost center 28200				
	D 09/27/1999	1.000	EA		
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M015853	ZZ 102641	MSC INDUSTRIAL SUPPLY	M01	09/13/1999	
00010		STOCK NUMBER 60329646 1" X 45 DEGREE		03	
	Z MAY	3.000	EA	102.81	USD 1 EA
	Cost center 28200				
	D 09/17/1999	3.000	EA		
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M015855	ZZ 101041	MCMaster-CARR SUPPLY CO	M09	09/15/1999	
00010		HONE #4424A15		03	
	Z MAY	1.000	EA	15.61	USD 1 EA
	Cost center 28200				
	D 09/17/1999	1.000	EA	PREq 1000166073	00010
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00020		HONE #4424A76		03	
	Z MAY	1.000	EA	23.44	USD 1 EA
	Cost center 28200				
	D 09/17/1999	1.000	EA	PREq 1000166073	00020
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00030		ALLEN SET #5709A52		03	
	Z MAY	2.000	EA	11.67	USD 1 EA
	Cost center 28200				
	D 09/15/1999	2.000	EA	PREq 1000166069	00010
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00040		1-1/8" GROUND ROD #6061K351		03	
	Z MAY	1.000	EA	15.81	USD 1 EA
	Cost center 28200				
	D 09/15/1999	1.000	EA	PREq 1000166069	00020
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00050		1/4" SOCKET #54615A25		03	
	Z MAY	1.000	EA	7.25	USD 1 EA
	Cost center 28200				
	D 09/15/1999	1.000	EA	PREq 1000166069	00030
	Still to be delivered	0.000	EA	0.00	USD 0.00 %

PO	Type	Vendor	Name	P6p	Order date
Item	Material	Short text	Order qty.	Mat. group	
D I A	PLnt Sloc	Schedul	Un	Curr.	per Un
SL	del. date	qty.			
00060		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
		5/16" SOCKET #54615A26	1.000 EA	7.25 USD	03 1 EA
	Z MAY	Cost center 28200	1.000 EA	7.25 USD	03 1 EA
		D 09/15/1999	1.000 EA	7.25 USD	03 1 EA
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
00070		3/8" SOCKET #54615A27	1.000 EA	7.25 USD	03 1 EA
	Z MAY	Cost center 28200	1.000 EA	7.25 USD	03 1 EA
		D 09/15/1999	1.000 EA	7.25 USD	03 1 EA
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
M015856	ZZ 103943	GRAINGER, INC.	2.000 EA	63.00 USD	03 1 EA
00010		DRILL #1M967	2.000 EA	63.00 USD	03 1 EA
	Z MAY	Cost center 28200	2.000 EA	63.00 USD	03 1 EA
		D 09/17/1999	2.000 EA	63.00 USD	03 1 EA
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
M015859	ZZ 102641	MSC INDUSTRIAL SUPPLY	10.000 EA	8.67 USD	03 1 EA
00010		GARR 5/32" 4 FL CARB, ENDMILL EDP #13090	10.000 EA	8.67 USD	03 1 EA
	Z MAY	Cost center 28200	10.000 EA	8.67 USD	03 1 EA
		D 09/20/1999	10.000 EA	8.67 USD	03 1 EA
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
00020		GARR 1/4" 3 FL CARB DRILL EDP #90550	10.000 EA	19.22 USD	03 1 EA
	Z MAY	Cost center 28200	10.000 EA	19.22 USD	03 1 EA
		D 09/20/1999	10.000 EA	19.22 USD	03 1 EA
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
00030		GARR 17/64" 3 FL CARB DRILL EDP #90570	10.000 EA	21.58 USD	03 1 EA
	Z MAY	Cost center 28200	10.000 EA	21.58 USD	03 1 EA
		D 09/20/1999	10.000 EA	21.58 USD	03 1 EA
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
00040		GARR 3/8" N/C CARB SPOT DRILL EDP #91130	10.000 EA	18.11 USD	03 1 EA
	Z MAY	Cost center 28200	10.000 EA	18.11 USD	03 1 EA
		D 09/20/1999	10.000 EA	18.11 USD	03 1 EA
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
00050		GARR 9/16" 4 FL CARB ENDMILL EDP #13320	12.000 EA	47.39 USD	03 1 EA
	Z MAY	Cost center 28200	12.000 EA	47.39 USD	03 1 EA
		D 09/20/1999	12.000 EA	47.39 USD	03 1 EA
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
00060		GARR 3/8" 4 FL CARB ENDMILL EDP #13230	10.000 EA	17.33 USD	03 1 EA
	Z MAY	Cost center 28200	10.000 EA	17.33 USD	03 1 EA
		D 09/20/1999	10.000 EA	17.33 USD	03 1 EA
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
00070		GARR 1/4" CYL SH STD CAR ROT FILE 60020	10.000 EA	5.99 USD	03 1 EA
	Z MAY	Cost center 28200	10.000 EA	5.99 USD	03 1 EA

83

MF1053

Confidential - Subject: 5.22.06/0011003e Order

Williams v. Remington

PO	Item	Type	Vendor	Name	Short text	Order qty.	Un	Net Price	Curr.	Order date	Mat. group
			SL del. date		Scheduled qty.		Un				per Un
			Cost center 28200								
			D 09/20/1999		10.000	EA		PRQ 1000166036	00070		
			Still to be delivered		0.000	EA		0.00	USD	0.00 %	
			Still to be invoiced		0.000	EA		0.00	USD	0.00 %	
00080			1/4-28 R&N SPIRAL BTM		12.000	EA		GARR EDP#V85015	03		
			Z MAY					8.73	USD		1 EA
			Cost center 28200								
			D 09/20/1999		12.000	EA		PRQ 1000166036	00080		
			Still to be delivered		0.000	EA		0.00	USD	0.00 %	
			Still to be invoiced		0.000	EA		0.00	USD	0.00 %	
00090			GARR 1/4" 4 FL CARB ENDMILL		20.000	EA		EDP#113450	03		
			Z MAY					9.92	USD		1 EA
			Cost center 28200								
			D 09/20/1999		20.000	EA		PRQ 1000166036	00090		
			Still to be delivered		0.000	EA		0.00	USD	0.00 %	
			Still to be invoiced		0.000	EA		0.00	USD	0.00 %	
00100			GARR 5/8 .030 COR RAD 4 FL CAR EM		12.000	EA		80390	03		
			Z MAY					59.48	USD		1 EA
			Cost center 28200								
			D 09/20/1999		12.000	EA		PRQ 1000166036	00100		
			Still to be delivered		0.000	EA		0.00	USD	0.00 %	
			Still to be invoiced		0.000	EA		0.00	USD	0.00 %	
00110			GARR 27/64 3 FL CARB ENDMILL		12.000	EA		EDP # 90755	03		
			Z MAY					48.38	USD		1 EA
			Cost center 28200								
			D 09/20/1999		12.000	EA		PRQ 1000166036	00110		
			Still to be delivered		0.000	EA		0.00	USD	0.00 %	
			Still to be invoiced		0.000	EA		0.00	USD	0.00 %	
00120			GARR 3/4 ENDMILL MODIFIED TO DRAW		3.000	EA		90755	03		
			Z MAY					111.75	USD		1 EA
			Cost center 28200								
			D 09/20/1999		3.000	EA		PRQ 1000166036	00120		
			Still to be delivered		0.000	EA		0.00	USD	0.00 %	
			Still to be invoiced		0.000	EA		0.00	USD	0.00 %	
00130			GARR EDP#18350		3.000	EA			03		
			Z MAY					87.53	USD		1 EA
			Cost center 28200								
			D 09/20/1999		3.000	EA		PRQ 1000166036	00130		
			Still to be delivered		0.000	EA		0.00	USD	0.00 %	
			Still to be invoiced		0.000	EA		0.00	USD	0.00 %	
00140			GARR 7.10 3 FLU CARBIDE DRILL		12.000	EA			03		
			Z MAY					28.35	USD		1 EA
			Cost center 28200								
			D 09/20/1999		12.000	EA		PRQ 1000166036	00140		
			Still to be delivered		0.000	EA		0.00	USD	0.00 %	
			Still to be invoiced		0.000	EA		0.00	USD	0.00 %	
00150			.213 DIA X 5/8 FL LGTH 1/4 SHK 2-1/2		13.000	EA		OAL	03		
			Z MAY					33.95	USD		1 EA
			Cost center 28200								
			D 09/20/1999		13.000	EA		PRQ 1000166036	00150		
			Still to be delivered		0.000	EA		0.00	USD	0.00 %	
			Still to be invoiced		0.000	EA		0.00	USD	0.00 %	
M015860			ZZ 102641							09/30/1999	
00010			MSC INDUSTRIAL SUPPLY		1.000	EA			03		
			ENERPAC GAUGE GF-230					153.00	USD		1 EA
			Cost center 28200								
			D 09/20/1999		1.000	EA		PRQ 1000166107	00010		
			Still to be delivered		0.000	EA		0.00	USD	0.00 %	
			Still to be invoiced		0.000	EA		0.00	USD	0.00 %	

83

MF1054

Confidential - SHARPER - 5.22.0610011004 Order

Williams v. Remington

PO	Type	Vendor	Name	PGp	Order	date
Item	Material	Short text	Order qty.	Net Price	Curr.	Mat. group
D i A	Plnt SLoc	Sched. qty.	Un			per Un
00020		ENERPAC ADAPTOR GA-1	1.000	25.50	USD	03
Z MAY			EA			1 EA
Cost center 28200						
D 09/20/1999			1.000	EA	PReq 1000166107	00020
Still to be delivered			0.000	EA	0.00	USD 0.00 %
Still to be invoiced			0.000	EA	0.00	USD 0.00 %
M015862	ZZ 102641	MSC INDUSTRIAL SUPPLY				M09 09/15/1999
00010		PARLEC ER 32-0196 COLLET	5.000	24.65	USD	03
Z MAY			EA			1 EA
Cost center 28200						
D 09/22/1999			5.000	EA	PReq 1000166074	00010
Still to be delivered			0.000	EA	0.00	USD 0.00 %
Still to be invoiced			0.000	EA	0.00	USD 0.00 %
00020		PARLEC ER32-0393 COLLET	4.000	24.65	USD	03
Z MAY			EA			1 EA
Cost center 28200						
D 09/22/1999			4.000	EA	PReq 1000166074	00020
Still to be delivered			0.000	EA	0.00	USD 0.00 %
Still to be invoiced			0.000	EA	0.00	USD 0.00 %
00030		PARLEC ER32-0275 COLLET	6.000	24.65	USD	03
Z MAY			EA			1 EA
Cost center 28200						
D 09/22/1999			6.000	EA	PReq 1000166074	00030
Still to be delivered			0.000	EA	0.00	USD 0.00 %
Still to be invoiced			0.000	EA	0.00	USD 0.00 %
00040		PARLEC ER32-0787 COLLET	4.000	24.65	USD	03
Z MAY			EA			1 EA
Cost center 28200						
D 09/22/1999			4.000	EA	PReq 1000166074	00040
Still to be delivered			0.000	EA	0.00	USD 0.00 %
Still to be invoiced			0.000	EA	0.00	USD 0.00 %
00050		PARLEC ER32-0275 COLLET	2.000	24.65	USD	03
Z MAY			EA			1 EA
Cost center 28200						
D 09/22/1999			2.000	EA	PReq 1000166074	00050
Still to be delivered			0.000	EA	0.00	USD 0.00 %
Still to be invoiced			0.000	EA	0.00	USD 0.00 %
00060		PARLEC ER32-0590 COLLET	2.000	24.65	USD	03
Z MAY			EA			1 EA
Cost center 28200						
D 09/22/1999			2.000	EA	PReq 1000166074	00060
Still to be delivered			0.000	EA	0.00	USD 0.00 %
Still to be invoiced			0.000	EA	0.00	USD 0.00 %
00070		PARLEC ER32-0315 COLLET	2.000	24.65	USD	03
Z MAY			EA			1 EA
Cost center 28200						
D 09/22/1999			2.000	EA	PReq 1000166074	00070
Still to be delivered			0.000	EA	0.00	USD 0.00 %
Still to be invoiced			0.000	EA	0.00	USD 0.00 %
00080		PARLEC ER32-0157 COLLET	6.000	24.65	USD	03
Z MAY			EA			1 EA
Cost center 28200						
D 09/22/1999			6.000	EA	PReq 1000166074	00080
Still to be delivered			0.000	EA	0.00	USD 0.00 %
Still to be invoiced			0.000	EA	0.00	USD 0.00 %
M015863	ZZ 102641	MSC INDUSTRIAL SUPPLY				M09 09/15/1999
00010		STOCK PILOT PRINT PER QUOTE #C-K10200	2.000	120.55	USD	03
Z MAY			EA			1 EA
Cost center 28200						

83

MFI1055

Confidential - Barber - 5.22.06r0011005 Order

Williams v. Remington

PO	Item	Type	Vendor	Name	PGp	Order	date
D I A	Material	PLnt	Sloc	Short text	Mat.	group	
SL	del. date			Order qty.	Un	per	Un
				Scheduled qty.			
			D 09/30/1999	2.000	EA	PReq 1000166076	00010
			Still to be delivered	0.000	EA	0.00 USD	0.00 %
			Still to be invoiced	0.000	EA	0.00 USD	0.00 %
M015865	ZZ		103497	SMW Systems, Inc.		M09 09/15/1999	
00010				SPHERICAL ROL ST	1.000	EA	17
			Z MAY	1.000	EA	619.00 USD	1 EA
			Cost center 28200				
			D 09/30/1999	1.000	EA	PReq 1000166131	00010
			Still to be delivered	0.000	EA	0.00 USD	0.00 %
			Still to be invoiced	0.000	EA	0.00 USD	0.00 %
M015868	ZZ		102719	KENNAMETAL, INC.		M09 09/15/1999	
00010				100DA0250 COLLET	1/4" ERICKSON	1014725	03
			Z MAY	4.000	EA	10.83 USD	1 EA
			Cost center 28200				
			D 09/24/1999	4.000	EA	PReq 1000166045	00010
			Still to be delivered	0.000	EA	0.00 USD	0.00 %
			Still to be invoiced	0.000	EA	0.00 USD	0.00 %
00020				100DA0500 COLLET	1/2" ERICKSON	1014934	03
			Z MAY	2.000	EA	10.83 USD	1 EA
			Cost center 28200				
			D 09/24/1999	2.000	EA	PReq 1000164685	00020
			Still to be delivered	0.000	EA	0.00 USD	0.00 %
			Still to be invoiced	0.000	EA	0.00 USD	0.00 %
00030				100DA0422 COLLET	27/64" ERICKSON	1014868	03
			Z MAY	2.000	EA	10.83 USD	1 EA
			Cost center 28200				
			D 09/24/1999	2.000	EA	PReq 1000164685	00100
			Still to be delivered	0.000	EA	0.00 USD	0.00 %
			Still to be invoiced	0.000	EA	0.00 USD	0.00 %
00040				KENNAMETAL A06NERI	GROOVING BORING BAR		03
			Z MAY	2.000	EA	84.28 USD	1 EA
			Cost center 28200				
			D 09/24/1999	2.000	EA	PReq 1000164685	00120
			Still to be delivered	0.000	EA	0.00 USD	0.00 %
			Still to be invoiced	0.000	EA	0.00 USD	0.00 %
00050				NG-1094L KC 720	INSERT		03
			Z MAY	12.000	EA	11.50 USD	1 EA
			Cost center 28200				
			D 09/24/1999	12.000	EA	PReq 1000164685	00130
			Still to be delivered	0.000	EA	0.00 USD	0.00 %
			Still to be invoiced	0.000	EA	0.00 USD	0.00 %
00060				KENN SS100FC108659	FLOATING TOOL HOLDER		03
			Z MAY	4.000	EA	264.18 USD	1 EA
			Cost center 28200				
			D 09/24/1999	4.000	EA	PReq 1000164685	00140
			Still to be delivered	0.000	EA	0.00 USD	0.00 %
			Still to be invoiced	0.000	EA	0.00 USD	0.00 %
00070				KENN SS100FC188688	FLOATING TOOL HOLDER		03
			Z MAY	2.000	EA	295.38 USD	1 EA
			Cost center 28200				
			D 09/24/1999	2.000	EA	PReq 1000164685	00150
			Still to be delivered	0.000	EA	0.00 USD	0.00 %
			Still to be invoiced	0.000	EA	0.00 USD	0.00 %
00080				KENNAMETAL C12-SCLPR2	BORING BAR		03
			Z MAY	2.000	EA	454.50 USD	1 EA
			Cost center 28200				
			D 09/24/1999	2.000	EA	PReq 1000164685	00160
			Still to be delivered	0.000	EA	0.00 USD	0.00 %
			Still to be invoiced	0.000	EA	0.00 USD	0.00 %

83

MF1056

Confidential - Subject - 5.22.06r0011006 Order

Williams v. Remington

PO	Item	Type	Vendor	Name	Short text	Order qty.	Un	Net Price	Curr.	Order date	Mat. group	per Un
D I A	Print	Sloc	SL del. date	Scheduled	Order qty.	Un						
	00090			KENNAMETAL CPMT	21.00-LF KC9010 INSERT	03						
	L	Z MAY			12.000	EA		12.59	USD		1	EA
		Cost center 28200										
		D 09/24/1999			12.000	EA	PReq 1000164685	00170				
		Still to be delivered			0.000	EA		0.00	USD		0.00	%
		Still to be invoiced			0.000	EA		0.00	USD		0.00	%
	00100			7/32" ERICKSON	100DA0219 COLLET	03						
		Z MAY			6.000	EA		12.80	USD		1	EA
		Cost center 28200										
		D 09/24/1999			6.000	EA	PReq 1000164685	00180				
		Still to be delivered			0.000	EA		0.00	USD		0.00	%
		Still to be invoiced			0.000	EA		0.00	USD		0.00	%
	00110			7/16" ERICKSON	100DA0438 COLLET	03						
		Z MAY			2.000	EA		10.85	USD		1	EA
		Cost center 28200										
		D 09/24/1999			2.000	EA	PReq 1000164685	00190				
		Still to be delivered			0.000	EA		0.00	USD		0.00	%
		Still to be invoiced			0.000	EA		0.00	USD		0.00	%
	00120			9/16" ERICKSON	100DA0562 COLLET	03						
		Z MAY			2.000	EA		10.83	USD		1	EA
		Cost center 28200										
		D 09/24/1999			2.000	EA	PReq 1000164685	00200				
		Still to be delivered			0.000	EA		0.00	USD		0.00	%
		Still to be invoiced			0.000	EA		0.00	USD		0.00	%
	M015876	ZZ	103554	Fluid Power Products						M09 09/30/1999		
	00010			HYD. CYLINDER 2"	STROKE HBT252B2P1T31	17						
		Z MAY			1.000	EA		1,537.10	USD		1	EA
		Cost center 28200										
		D 09/29/1999			1.000	EA	PReq 1000167658	00010				
		Still to be delivered			0.000	EA		0.00	USD		0.00	%
		Still to be invoiced			0.000	EA		0.00	USD		0.00	%
	00020			HYDROLIC CYLINER 6"	STROKE HBT256B2P1T31	17						
		Z MAY			1.000	EA		1,578.90	USD		1	EA
		Cost center 28200										
		D 09/29/1999			1.000	EA	PReq 1000167658	00020				
		Still to be delivered			0.000	EA		0.00	USD		0.00	%
		Still to be invoiced			0.000	EA		0.00	USD		0.00	%
	M015885	ZZ	102719	KENNAMETAL, INC.						M09 10/07/1999		
	00010			KENDEX BORING BARS	A08NEL2 1094825	03						
		Z MAY			2.000	EA		84.28	USD		1	EA
		Cost center 28200										
		D 10/06/1999			2.000	EA	PReq 1000193073	00010				
		Still to be delivered			0.000	EA		0.00	USD		0.00	%
		Still to be invoiced			0.000	EA		0.00	USD		0.00	%
	00020			K BAR 7000 SERIES	SOLID MINI E08NEL2 KWH	03						
		Z MAY			1.000	EA		342.18	USD		1	EA
		Cost center 28200										
		D 10/06/1999			1.000	EA	PReq 1000193073	00020				
		Still to be delivered			0.000	EA		0.00	USD		0.00	%
		Still to be invoiced			0.000	EA		0.00	USD		0.00	%
	00030			THREAD & GROOVING	INSERTS NG2125RK KC935	03						
		Z MAY			20.000	EA		16.49	USD		1	EA
		Cost center 28200										
		D 10/06/1999			20.000	EA	PReq 1000193073	00030				
		Still to be delivered			0.000	EA		0.00	USD		0.00	%
		Still to be invoiced			0.000	EA		0.00	USD		0.00	%
	00040			UPGRADE FROM C12NELR05	E12NKLOR05 KWH	03						
		Z MAY			1.000	EA		498.18	USD		1	EA
		Cost center 28200										

83

MF1057

Confidential - SHARPER - 5.22.06#0011007 Order

Williams V. Remington

PO	Item	Type	Vendor	Name	Short text	Order qty.	Unit	Net Price	Curr.	Order date	Mat. group
		Material	SL del. date		Scheduled qty.		Un			per Un	
			D 10/06/1999		1.000	EA		PREq 1000193073	00040		
		Still to be delivered			0.000	EA		0.00	USD	0.00 %	
		Still to be invoiced			0.000	EA		0.00	USD	0.00 %	
00050				K-BAR 7000 SERIES, SOLID MIN	12NKLCL05 03	1.000	EA	498.18	USD	1 EA	
		Z MAY									
		Cost center 28200									
		D 10/06/1999			1.000	EA		PREq 1000193073	00050		
		Still to be delivered			0.000	EA		0.00	USD	0.00 %	
		Still to be invoiced			0.000	EA		0.00	USD	0.00 %	
00060				TOP-NOTCH TURNING INSERTS	NPGR51R KC935 03	10.000	EA	11.46	USD	1 EA	
		Z MAY									
		Cost center 28200									
		D 10/06/1999			10.000	EA		PREq 1000193073	00060		
		Still to be delivered			0.000	EA		0.00	USD	0.00 %	
		Still to be invoiced			0.000	EA		0.00	USD	0.00 %	
00070				TOP-NOTCH TURNING INSERTS	NPGR51L KC935 03	10.000	EA	11.46	USD	1 EA	
		Z MAY									
		Cost center 28200									
		D 10/06/1999			10.000	EA		PREq 1000193073	00070		
		Still to be delivered			0.000	EA		0.00	USD	0.00 %	
		Still to be invoiced			0.000	EA		0.00	USD	0.00 %	
M015886		ZZ	104762	G AND H TOOL & DIE, INC						M01 09/17/1999	
00010				WIRECUT SLOT PER PRINT		1.000	EA	65.00	USD	1 EA	
		Z MAY									
		Cost center 28200									
		D 09/30/1999			1.000	EA					
		Still to be delivered			0.000	EA		0.00	USD	0.00 %	
		Still to be invoiced			0.000	EA		0.00	USD	0.00 %	
M015889		ZZ	101041	MCMaster-CARR SUPPLY CO						M09 09/30/1999	
00010				STEEL RECTANGLE 3' STICK	#8910K81	1.000	EA	117.06	USD	1 EA	
		Z MAY									
		Cost center 28200									
		D 09/23/1999			1.000	EA		PREq 1000172792	00010		
		Still to be delivered			0.000	EA		0.00	USD	0.00 %	
		Still to be invoiced			0.000	EA		0.00	USD	0.00 %	
00020				FLAT STOCK 18" LONG	#8892K39	1.000	EA	31.21	USD	1 EA	
		Z MAY									
		Cost center 28200									
		D 09/23/1999			1.000	EA		PREq 1000172792	00020		
		Still to be delivered			0.000	EA		0.00	USD	0.00 %	
		Still to be invoiced			0.000	EA		0.00	USD	0.00 %	
M015894		ZZ	102641	MSC INDUSTRIAL SUPPLY						M09 09/30/1999	
00010				3/8" N/C #91130 GARR CARBIDE SPOTTING DR	03	10.000	EA	18.11	USD	1 EA	
		L Z MAY									
		Cost center 28200									
		D 09/27/1999			10.000	EA		PREq 1000174573	00010		
		Still to be delivered			0.000	EA		0.00	USD	0.00 %	
		Still to be invoiced			0.000	EA		0.00	USD	0.00 %	
M015899		ZZ	103554	Fluid Power Products						M09 09/30/1999	
00010				ACCUMULATOR #AB00583T1A1		1.000	EA	331.20	USD	1 EA	
		Z MAY									
		Cost center 28200									
		D 09/30/1999			1.000	EA		PREq 1000174574	00010		
		Still to be delivered			0.000	EA		0.00	USD	0.00 %	
		Still to be invoiced			0.000	EA		0.00	USD	0.00 %	
00020				FITTING #12-8F50G5-S		2.000	EA	2.56	USD	1 EA	
		Z MAY									
		Cost center 28200									
		D 09/30/1999			2.000	EA		PREq 1000174574	00020		

PO	Type	Vendor	Name	PGP	Order date
Item	Material	Short text	Mat. group		
D 1 A	Plant Sloc	Order qty.	Net Price	Curr.	per Un
SL	del. date	Scheduled qty.	Un		
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00030		FITTING #8-6F50G5-S	17		
	Z MAY	2.000	EA	1.85	USD 1 EA
	Cost center 28200				
	D 09/30/1999	2.000	EA	Preq 1000174574	00030
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00040		MANIFOLD #AD03P022S/C	17		
	Z MAY	1.000	EA	83.38	USD 1 EA
	Cost center 28200				
	D 09/30/1999	1.000	EA	Preq 1000174574	00040
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M015900	ZZ 104140	BARLCAY'S METAL COMPANY	M09 10/07/1999		
00010		2" X 4" X 1/4" THICK TUBING 28 FOOT STIC	44		
	Z MAY	1.000	EA	72.00	USD 1 EA
	Cost center 28200				
	D 09/22/1999	1.000	EA	Preq 1000174575	00010
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00020		4' X 4' X 1/2 THICK PLATE STEEL	44		
	Z MAY	1.000	EA	106.00	USD 1 EA
	Cost center 28200				
	D 09/22/1999	1.000	EA	Preq 1000174575	00020
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00030		VIEW 3000 SAFETY GLASSES	44		
	Z MAY	4.000	EA	6.50	USD 1 EA
	Cost center 28200				
	D 09/22/1999	4.000	EA	Preq 1000174575	00030
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00040		VIEW 3000 50 REPLACEMENT LENS	44		
	Z MAY	4.000	EA	6.50	USD 1 EA
	Cost center 28200				
	D 09/22/1999	4.000	EA	Preq 1000174575	00040
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00050		ESTIMATED KY SALES TAX 6%	44		
	Z MAY	1.000	EA	13.80	USD 1 EA
	Cost center 28200				
	D 09/22/1999	1.000	EA	Preq 1000174575	00050
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M015903	ZZ 101041	MCMMASTER-CARR SUPPLY CO	M09 09/30/1999		
00010		3/16 & 1/4 BROACH SET #3152A16	03		
	Z MAY	1.000	EA	228.28	USD 1 EA
	Cost center 28200				
	D 09/27/1999	1.000	EA	Preq 1000175885	00010
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M015904	ZZ 102641	MSC INDUSTRIAL SUPPLY	M09 09/30/1999		
00010		ROHM LATHE CENTER #017172 CARBIDE TIP	03		
	Z MAY	1.000	EA	95.80	USD 1 EA
	Cost center 28200				
	D 09/27/1999	1.000	EA	Preq 1000175894	00010
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %

PO	Item	Type	Vendor	Name	PGp	Order date
	Material			Short text		Mat. group
	D I A Plnt Sloc			Order qty.	Net Price	Curr. per Un
	SL del. date			Scheduled qty.	Un	
00030				LATHE CENTER #00085035		03
	Z MAY			1.000 EA	22.60 USD	1 EA
	Cost center 28200					
	D 09/27/1999			1.000 EA	PReq 1000175894	00030
	Still to be delivered			0.000 EA	0.00 USD	0.00 %
	Still to be invoiced			0.000 EA	0.00 USD	0.00 %
M015909	ZZ 103595			Consolidated Electrical Distributor		M09 09/30/1999
00010				CONTACTOR #100-A12N3		16
	Z MAY			5.000 EA	70.26 USD	1 EA
	Cost center 28200					
	D 09/30/1999			5.000 EA	PReq 1000174580	00010
	Still to be delivered			0.000 EA	0.00 USD	0.00 %
	Still to be invoiced			0.000 EA	0.00 USD	0.00 %
00020				OVERLOAD #193-A1F1		16
	Z MAY			1.000 EA	38.84 USD	1 EA
	Cost center 28200					
	D 09/30/1999			1.000 EA	PReq 1000174580	00020
	Still to be delivered			0.000 EA	0.00 USD	0.00 %
	Still to be invoiced			0.000 EA	0.00 USD	0.00 %
00030				AUXILIARY CONTACTS # 195-BA02G		16
	Z MAY			4.000 EA	12.15 USD	1 EA
	Cost center 28200					
	D 09/30/1999			4.000 EA	PReq 1000174580	00030
	Still to be delivered			0.000 EA	0.00 USD	0.00 %
	Still to be invoiced			0.000 EA	0.00 USD	0.00 %
00040				FUSEABLE BLOCK #1492-WFB1024		16
	Z MAY			10.000 EA	24.54 USD	1 EA
	Cost center 28200					
	D 09/30/1999			10.000 EA	PReq 1000174580	00040
	Still to be delivered			0.000 EA	0.00 USD	0.00 %
	Still to be invoiced			0.000 EA	0.00 USD	0.00 %
00050				RAIL #1492-N1		16
	Z MAY			1.000 EA	6.92 USD	1 EA
	Cost center 28200					
	D 09/30/1999			1.000 EA	PReq 1000174580	00050
	Still to be delivered			0.000 EA	0.00 USD	0.00 %
	Still to be invoiced			0.000 EA	0.00 USD	0.00 %
00060				RAIL #199-OR1		16
	Z MAY			1.000 EA	6.79 USD	1 EA
	Cost center 28200					
	D 09/30/1999			1.000 EA	PReq 1000174580	00060
	Still to be delivered			0.000 EA	0.00 USD	0.00 %
	Still to be invoiced			0.000 EA	0.00 USD	0.00 %
00070				PRESS SWITCH #836T-T302J		16
	Z MAY			1.000 EA	293.82 USD	1 EA
	Cost center 28200					
	D 09/30/1999			1.000 EA	PReq 1000174580	00070
	Still to be delivered			0.000 EA	0.00 USD	0.00 %
	Still to be invoiced			0.000 EA	0.00 USD	0.00 %
00080				PUSH BUTTON #800T-A1A		16
	Z MAY			3.000 EA	30.59 USD	1 EA
	Cost center 28200					
	D 09/30/1999			3.000 EA	PReq 1000174580	00080
	Still to be delivered			0.000 EA	0.00 USD	0.00 %
	Still to be invoiced			0.000 EA	0.00 USD	0.00 %
00090				PUSH BUTTON #800T-A2A		16
	Z MAY			3.000 EA	30.59 USD	1 EA
	Cost center 28200					
	D 09/30/1999			3.000 EA	PReq 1000174580	00090

PO	Type	Vendor	Name	Pg	Order	date
Item	Material		Short text		Mat. group	
D I A	Plnt Sloc		Order qty.	Un		
SL	del. date		Scheduled qty.	Un	Net Price	Curr. per Un
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00100			PUSH BUTTON #800T-FX16AS		16	
	Z MAY		6.000	EA	65.66	USD 1 EA
	Cost center 28200					
	D 09/30/1999		6.000	EA	PRReq 1000174580	00100
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00110			ENCLOSURE #800T-3T2		16	
	Z MAY		2.000	EA	70.16	USD 1 EA
	Cost center 28200					
	D 09/30/1999		2.000	EA	PRReq 1000174580	00110
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00120			ENCLOSURE #800T-2T2		16	
	Z MAY		1.000	EA	59.36	USD 1 EA
	Cost center 28200					
	D 09/30/1999		1.000	EA	PRReq 1000174580	00120
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00130			TRANSFORMER #1497-N19		16	
	Z MAY		1.000	EA	224.93	USD 1 EA
	Cost center 28200					
	D 09/30/1999		1.000	EA	PRReq 1000174580	00130
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00140			ENCLOSURE NOMA4 #24X24X6		16	
	Z MAY		1.000	EA	228.18	USD 1 EA
	Cost center 28200					
	D 09/30/1999		1.000	EA	PRReq 1000174580	00140
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00150			ENCLOSURE PANEL #24X24		16	
	Z MAY		1.000	EA	39.25	USD 1 EA
	Cost center 28200					
	D 09/30/1999		1.000	EA	PRReq 1000174580	00150
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00160			EFFECTOR SWITCH #1G0351		16	
	Z MAY		2.000	EA	145.00	USD 1 EA
	Cost center 28200					
	D 09/30/1999		2.000	EA	PRReq 1000174580	00160
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00170			EFFECTOR SWITCH #L32043		16	
	Z MAY		2.000	EA	30.00	USD 1 EA
	Cost center 28200					
	D 09/30/1999		2.000	EA	PRReq 1000174580	00170
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00180			MANUAL INTERRUPTER 190-MN		16	
	Z MAY		1.000	EA	126.60	USD 1 EA
	Cost center 28200					
	D 09/27/1999		1.000	EA	PRReq 1000176121	00010
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00190			TRIE UNIT 190-P160L		16	
	Z MAY		1.000	EA	65.20	USD 1 EA
	Cost center 28200					

83

MF1061

Confidential - Barber - 5.22.06r0011011 Order

Williams V. Remington

PO	Type	Vendor	Name	PGP	Order date
Item	Material	Short text	Order qty.	Net Price	Mat. group
D I A	Plnt Sloc	Sched. qty.	Un	Curr.	per Un
		SL del. date			
		D 09/27/1999	1.000 EA	Preq 1000176121	00020
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
M015916	ZZ	102719	KENNAMETAL, INC.		M09 10/07/1999
00010			180 DA COLLET SS100DA101638	1015625	03
		Z MAY	1.000 EA	115.46 USD	1 EA
		Cost center 28200			
		D 10/07/1999	1.000 EA	Preq 1000194142	00010
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
M015918	ZZ	103437	Universal Machine, Inc.		M09 10/07/1999
00010			REAMER GUIDES MACHINED TO LARGER I.D.		TOOLING
		Z MAY	8.000 EA	40.00 USD	1 EA
		Cost center 28200			
		D 10/07/1999	8.000 EA	Preq 1000194145	00010
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
M015941	ZZ	102719	KENNAMETAL, INC.		M09 09/30/1999
00010			ERICKSON COLLET 9/16 #180DA0562		03
		Z MAY	2.000 EA	14.58 USD	1 EA
		Cost center 28200			
		D 09/30/1999	2.000 EA	Preq 1000184057	00010
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
M015960	ZZ	101041	MCMaster-CARR SUPPLY CO		M09 10/07/1999
00010			#9464K134 VITTON O-RING		19
		Z MAY	1.000 EA	7.13 USD	1 EA
		Cost center 28200			
		D 10/07/1999	1.000 EA	Preq 1000194145	00010
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
00020			#9452K138 BUNA-N O-RING		19
		Z MAY	1.000 EA	9.05 USD	1 EA
		Cost center 28200			
		D 10/07/1999	1.000 EA	Preq 1000194145	00020
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
M015961	ZZ	102641	MSC INDUSTRIAL SUPPLY		M09 10/07/1999
00010			#36889350 DUFF-NORTON ROTARY UNION		03
		Z MAY	1.000 EA	93.86 USD	1 EA
		Cost center 28200			
		D 10/12/1999	1.000 EA	Preq 1000193074	00010
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
00020			#40210726 HAND TAP		03
		Z MAY	1.000 EA	9.75 USD	1 EA
		Cost center 28200			
		D 10/12/1999	1.000 EA	Preq 1000193074	00020
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
00030			FREIGHT NDA		03
		K MAY	1.000 EA	20.75 USD	1 EA
		Cost center 28200			
		D 10/12/1999	1.000 EA		
		Still to be delivered	0.000 EA	0.00 USD	0.00 %
		Still to be invoiced	0.000 EA	0.00 USD	0.00 %
M015970	ZZ	5380140	DANJON MANUFACTURING CORP		M09 10/07/1999
00010			.29 DIA X54" GUNDRILLS; KIDNEY COOL HOLE		03
		Z MAY	8.000 EA	90.00 USD	1 EA

83

MF1062

Confidential - ~~BARBER~~ - 5.22.06/0011012 Order

Williams v. Remington

PO	Type	Vendor	Name	PGp	Order	date
Item	Material	Short text	Mat. group			
D I A	Pint Sloc	Order qty.	Net Price	Curr.	per	Un
SL	del. date	Scheduled qty.	Un			
Cost center 28200						
	D 10/15/1999	8.000 EA	PReq 1000193070	00010		
	Still to be delivered	0.000 EA	0.00 USD	0.00 %		
	Still to be invoiced	0.000 EA	0.00 USD	0.00 %		
M015975	ZZ 103437	Universal Machine, Intermittent	M09 10/12/1999			
00010		HUB MACHINED COMPLETE PER PRINT	TOOLING			
Z MAY		1.000 EA	220.00 USD	1 EA		
Cost center 28200						
	D 10/11/1999	1.000 EA	PReq 1000197474	00010		
	Still to be delivered	0.000 EA	0.00 USD	0.00 %		
	Still to be invoiced	0.000 EA	0.00 USD	0.00 %		
M016009	ZZ 102641	MSC INDUSTRIAL SUPPLY	M09 10/12/1999			
00010		DISTANCE MEASURING WHEEL #0104684	MISC			
Z MAY		1.000 EA	58.27 USD	1 EA		
Cost center 28200						
	D 10/11/1999	1.000 EA	PReq 1000197474	00010		
	Still to be delivered	0.000 EA	0.00 USD	0.00 %		
	Still to be invoiced	0.000 EA	0.00 USD	0.00 %		
M016025	ZZ 101041	MCMaster-CARR SUPPLY CO	M09 10/12/1999			
00010		12 MM DRILL #8950A28	MISC			
Z MAY		1.000 EA	17.39 USD	1 EA		
Cost center 28200						
	D 10/12/1999	1.000 EA	PReq 1000197484	00010		
	Still to be delivered	0.000 EA	0.00 USD	0.00 %		
	Still to be invoiced	0.000 EA	0.00 USD	0.00 %		
00020		SCRIBER #2157A12	MISC			
Z MAY		2.000 EA	4.91 USD	1 EA		
Cost center 28200						
	D 10/12/1999	2.000 EA	PReq 1000197484	00020		
	Still to be delivered	0.000 EA	0.00 USD	0.00 %		
	Still to be invoiced	0.000 EA	0.00 USD	0.00 %		
M016029	ZZ 101041	MCMaster-CARR SUPPLY CO	M09 10/12/1999			
00010		RIGHT-HAND ROD END #60645K36	MISC			
Z MAY		3.000 EA	6.86 USD	1 EA		
Cost center 28200						
	D 10/14/1999	3.000 EA	PReq 1000198613	00010		
	Still to be delivered	0.000 EA	0.00 USD	0.00 %		
	Still to be invoiced	0.000 EA	0.00 USD	0.00 %		
M016043	ZZ 5380140	DANJON MANUFACTURING CORP	M09 10/14/1999			
00010		COMBINATION 2-STAGE BUTTON W/ COAT & HT	03			
L Z MAY		2.000 EA	209.00 USD	1 EA		
Cost center 28200						
	D 11/15/1999	2.000 EA				
	Still to be delivered	0.000 EA	0.00 USD	0.00 %		
	Still to be invoiced	0.000 EA	0.00 USD	0.00 %		
00020		COMBINATION 2-STAGE BUTTON W/ COAT & HT	03			
Z MAY		2.000 EA	209.00 USD	1 EA		
Cost center 28200						
	D 11/15/1999	2.000 EA	PReq 1000199801	00010		
	Still to be delivered	0.000 EA	0.00 USD	0.00 %		
	Still to be invoiced	0.000 EA	0.00 USD	0.00 %		
M016056	ZZ 102641	MSC INDUSTRIAL SUPPLY	M09 11/02/1999			
00010		40210163 5/16-18 4FL LH TPR CLEV HAND TA	03			
Z MAY		1.000 EA	6.32 USD	1 EA		
Cost center 28200						
	D 10/27/1999	1.000 EA	PReq 1000217217	00010		
	Still to be delivered	0.000 EA	0.00 USD	0.00 %		
	Still to be invoiced	0.000 EA	0.00 USD	0.00 %		
00020		FREIGHT TO JOE ZAJK IN NC	03			

83

MF1063

Confidential - Subject - 5.22.06P0011013 Order

Williams v. Remington

PO	Type	Vendor	Name	PGP	Order date
Item	Material		Short text		Mat. group
D I A	Plnt SLoc		Order qty.	Un	per Un
SL	del. date		Scheduled qty.	Un	
	Z MAY		1.000	EA	5.28 USD 1 EA
	Cost center 28200				
	D 10/27/1999		1.000	EA	PReq 1000217217 00020
	Still to be delivered		0.000	EA	0.00 USD 0.00 %
	Still to be invoiced		0.000	EA	0.00 USD 0.00 %
M016082	ZZ 103554	Fluid Power Products			M09 10/21/1999
00010		6-8 F50X-S			MISC
	Z MAY		4.000	EA	1.45 USD 1 EA
	Cost center 28200				
	D 10/19/1999		4.000	EA	PReq 1000209369 00010
	Still to be delivered		0.000	EA	0.00 USD 0.00 %
	Still to be invoiced		0.000	EA	0.00 USD 0.00 %
00020		6-6-6 RTX-S			MISC
	Z MAY		2.000	EA	4.75 USD 1 EA
	Cost center 28200				
	D 10/19/1999		2.000	EA	PReq 1000209369 00020
	Still to be delivered		0.000	EA	0.00 USD 0.00 %
	Still to be invoiced		0.000	EA	0.00 USD 0.00 %
00030		6C50X-S			MISC
	Z MAY		4.000	EA	3.75 USD 1 EA
	Cost center 28200				
	D 10/19/1999		4.000	EA	PReq 1000209369 00030
	Still to be delivered		0.000	EA	0.00 USD 0.00 %
	Still to be invoiced		0.000	EA	0.00 USD 0.00 %
00040		6-1/4 F50G-S			MISC
	Z MAY		1.000	EA	1.55 USD 1 EA
	Cost center 28200				
	D 10/19/1999		1.000	EA	PReq 1000209369 00040
	Still to be delivered		0.000	EA	0.00 USD 0.00 %
	Still to be invoiced		0.000	EA	0.00 USD 0.00 %
00050		F451TC0606-6-6-6-60.00 6FJIC B/E 3/8" HO			MISC
	Z MAY		2.000	EA	20.00 USD 1 EA
	Cost center 28200				
	D 10/19/1999		2.000	EA	PReq 1000209369 00050
	Still to be delivered		0.000	EA	0.00 USD 0.00 %
	Still to be invoiced		0.000	EA	0.00 USD 0.00 %
00060		F451TC0606-6-6-6-48.00 6FJIC B/E 3/8" HO			MISC
	Z MAY		1.000	EA	18.00 USD 1 EA
	Cost center 28200				
	D 10/19/1999		1.000	EA	PReq 1000209369 00060
	Still to be delivered		0.000	EA	0.00 USD 0.00 %
	Still to be invoiced		0.000	EA	0.00 USD 0.00 %
00070		F451TC0606-6-6-6-36.00 6FJIC B/E 3/8" HO			MISC
	Z MAY		1.000	EA	16.00 USD 1 EA
	Cost center 28200				
	D 10/19/1999		1.000	EA	PReq 1000209369 00070
	Still to be delivered		0.000	EA	0.00 USD 0.00 %
	Still to be invoiced		0.000	EA	0.00 USD 0.00 %
00080		F451TC0606-6-6-6-38.00 6FJIC B/E 3/8" HO			MISC
	Z MAY		1.000	EA	18.00 USD 1 EA
	Cost center 28200				
	D 10/19/1999		1.000	EA	PReq 1000209369 00080
	Still to be delivered		0.000	EA	0.00 USD 0.00 %
	Still to be invoiced		0.000	EA	0.00 USD 0.00 %
00090		F451TC0606-6-6-6-8.00 6FJIC B/E 3/8" HO			MISC
	Z MAY		1.000	EA	13.00 USD 1 EA
	Cost center 28200				
	D 10/19/1999		1.000	EA	PReq 1000209369 00090
	Still to be delivered		0.000	EA	0.00 USD 0.00 %

PO	Item	Type	Vendor	Name	Short text	Order qty.	Un	Net Price	Curr.	Order date	Mat. group
		D I A	Plnt Sloc								
			SL del. date		Scheduled qty.		Un				per Un
	00100			Still to be invoiced	F451TC0606	0.000	EA	0.00	USD	0.00 %	
		Z MAY				1.000	EA	5.00	USD	10FJ12 B/E 5/8" MISC	1 EA
		Cost center 28200									
		D 10/19/1999				1.000	EA	20.50	USD	00100	
		Still to be delivered				0.000	EA	0.00	USD	0.00 %	
		Still to be invoiced				0.000	EA	0.00	USD	0.00 %	
	00110			Still to be invoiced	F451TC0606	0.000	EA	0.00	USD	0.00 %	
		Z MAY				1.000	EA	25.00	USD	10FJ12 B/E 5/8" MISC	1 EA
		Cost center 28200									
		D 10/19/1999				1.000	EA	25.00	USD	00110	
		Still to be delivered				0.000	EA	0.00	USD	0.00 %	
		Still to be invoiced				0.000	EA	0.00	USD	0.00 %	
	00170			Still to be invoiced	6-4 HTXS UNION	0.000	EA	0.00	USD	0.00 %	
		Z MAY				1.000	EA	53.50	USD	MISC	1 EA
		Cost center 28200									
		D 10/26/1999				1.000	EA	53.50	USD	00010	
		Still to be delivered				0.000	EA	0.00	USD	0.00 %	
		Still to be invoiced				0.000	EA	0.00	USD	0.00 %	
	00180			Still to be invoiced	F451TC0606	0.000	EA	0.00	USD	0.00 %	
		Z MAY				1.000	EA	25.00	USD	10FJ12 B/E 5/8" MISC	1 EA
		Cost center 28200									
		D 10/26/1999				1.000	EA	25.00	USD	00010	
		Still to be delivered				0.000	EA	0.00	USD	0.00 %	
		Still to be invoiced				0.000	EA	0.00	USD	0.00 %	
	00190			Still to be invoiced	6 C50X-S STR THD ELBOW	0.000	EA	0.00	USD	0.00 %	
		Z MAY				4.000	EA	15.00	USD	MISC	1 EA
		Cost center 28200									
		D 10/26/1999				4.000	EA	15.00	USD	00010	
		Still to be delivered				0.000	EA	0.00	USD	0.00 %	
		Still to be invoiced				4.000	EA	60.00	USD	10FJ12 B/E 5/8" MISC	1 EA
	M016104	ZZ	102719	KENNAMETAL INC.							
	00010			HOLDER S520WN32M525		1.000	EA	81.00	USD	MISC	1 EA
		Z MAY									
		Cost center 28200									
		D 11/19/1999				1.000	EA	81.00	USD	00010	
		Still to be delivered				1.000	EA	81.00	USD	100.00 %	
		Still to be invoiced				1.000	EA	81.00	USD	100.00 %	
	00020			Still to be invoiced	ENDMILL F3AH1500AOK30	0.000	EA	0.00	USD	0.00 %	
		Z MAY				2.000	EA	147.00	USD	MISC	1 EA
		Cost center 28200									
		D 10/27/1999				2.000	EA	147.00	USD	00020	
		Still to be delivered				0.000	EA	0.00	USD	0.00 %	
		Still to be invoiced				0.000	EA	0.00	USD	0.00 %	
	00030			Still to be invoiced	ENDMILL K1CR-0.50-S02.8-0	0.000	EA	0.00	USD	0.00 %	
		Z MAY				2.000	EA	75.68	USD	MISC	1 EA
		Cost center 28200									
		D 10/27/1999				2.000	EA	75.68	USD	00030	
		Still to be delivered				0.000	EA	0.00	USD	0.00 %	
		Still to be invoiced				0.000	EA	0.00	USD	0.00 %	
	00040			Still to be invoiced	ENDMILL K1PR-125-RP3	0.000	EA	0.00	USD	0.00 %	
		Z MAY				1.000	EA	91.54	USD	MISC	1 EA
		Cost center 28200									
		D 10/27/1999				1.000	EA	91.54	USD	00040	
		Still to be delivered				0.000	EA	0.00	USD	0.00 %	
		Still to be invoiced				0.000	EA	0.00	USD	0.00 %	
	00050			Still to be invoiced	INSERT SDCH2.61-52ENLO KC 725M	0.000	EA	0.00	USD	0.00 %	
		Z MAY				10.000	EA	11.41	USD	MISC	1 EA
		Cost center 28200									

83

MF1065

Confidential - Subject: 5.22.06r0011015 Order

Williams v. Remington

PO	Type	Vendor	Name	PGp	Order date
Item	Material	Short text	Mat. group		
D I A	Plnt Sloc	Order qty.	Net Price	Curr.	per Un
SL del. date	Scheduled	qty. Un			
	D 10/27/1999	10.000 EA	Preq 1000214194	00050	
Still to be delivered		0.000 EA	0.00 USD	0.00 %	
Still to be invoiced		0.000 EA	0.00 USD	0.00 %	
00060	INSERT RP	832.5 KC 725M		MISC	
Z MAY		10.000 EA	12.65 USD	1 EA	
Cost center 28200					
	D 10/27/1999	10.000 EA	Preq 1000214194	00060	
Still to be delivered		0.000 EA	0.00 USD	0.00 %	
Still to be invoiced		0.000 EA	0.00 USD	0.00 %	
M016105	ZZ 102641	MSC INDUSTRIAL SUPPLY		M09	11/02/1999
00010		63804462 17/64 SCREW MACHINE DRILL		03	
Z MAY		10.000 EA	8.06 USD	1 EA	
Cost center 28200					
	D 10/29/1999	10.000 EA	Preq 1000217222	00010	
Still to be delivered		0.000 EA	0.00 USD	0.00 %	
Still to be invoiced		0.000 EA	0.00 USD	0.00 %	
00020		63792105 "K" DRILL		03	
Z MAY		10.000 EA	1.97 USD	1 EA	
Cost center 28200					
	D 10/29/1999	10.000 EA	Preq 1000217222	00020	
Still to be delivered		0.000 EA	0.00 USD	0.00 %	
Still to be invoiced		0.000 EA	0.00 USD	0.00 %	
00030		#06761464 GARR 51234 3/8 TICN 6 FLUTE		03	
Z MAY		5.000 EA	25.38 USD	1 EA	
Cost center 28200					
	D 10/29/1999	5.000 EA	Preq 1000217222	00030	
Still to be delivered		0.000 EA	0.00 USD	0.00 %	
Still to be invoiced		5.000 EA	126.90 USD	100.00 %	
00040		#06758998 GARR 51154 1/4 TICN 6 FLUTE		03	
Z MAY		5.000 EA	15.16 USD	1 EA	
Cost center 28200					
	D 10/29/1999	5.000 EA	Preq 1000217222	00040	
Still to be delivered		0.000 EA	0.00 USD	0.00 %	
Still to be invoiced		5.000 EA	75.80 USD	100.00 %	
00050		#06820591 GARR 12234 3/8 TICN 223 MC		03	
Z MAY		5.000 EA	23.46 USD	1 EA	
Cost center 28200					
	D 11/10/1999	5.000 EA	Preq 1000217222	00050	
Still to be delivered		0.000 EA	0.00 USD	0.00 %	
Still to be invoiced		5.000 EA	117.30 USD	100.00 %	
00060		#06851273 GARR 12194 5/16 TICN 223 MC		03	
Z MAY		5.000 EA	20.04 USD	1 EA	
Cost center 28200					
	D 10/29/1999	5.000 EA	Preq 1000217222	00060	
Still to be delivered		0.000 EA	0.00 USD	0.00 %	
Still to be invoiced		3.000 EA	60.12 USD	60.00 %	
M016107	ZZ 106259	PIONEER BROACH		M09	10/26/1999
00010		SPECIAL PULLER DOGS FOR PAS-291 S BROACH		MISC	
Z MAY		1.000 EA	150.00 USD	1 EA	
Cost center 28200					
	D 10/22/1999	1.000 EA	Preq 1000211097	00010	
Still to be delivered		0.000 EA	0.00 USD	0.00 %	
Still to be invoiced		0.000 EA	0.00 USD	0.00 %	
00020		FREIGHT CHARGES		MISC	
Z MAY		1.000 EA	32.20 USD	1 EA	
Cost center 28200					
	D 10/22/1999	1.000 EA	Preq 1000211097	00020	
Still to be delivered		0.000 EA	0.00 USD	0.00 %	
Still to be invoiced		0.000 EA	0.00 USD	0.00 %	

83

MF1066

Confidential - Subject - 5.22.06r0011016 Order

Williams v. Remington

PO	Type	Vendor	Name	Pg	Order date
Item	Material	Short text	Order qty.	Net Price	Mat. group
D I A	PLnt SLoc	Sched. qty.	Un	Curr.	per Un
M016114	ZZ	5885460	PACIFIC PRECISION GRINDING	M09	10/26/1999
00010			30/06 CHAMBER REAMER	MISC	
	Z MAY	4.000	EA	187.00	USD 1 EA
	Cost center 28200				
	D 10/25/1999	4.000	EA	187.00	USD 0.00 %
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00020			FREIGHT CHARGES	MISC	
	Z MAY	1.000	EA	52.25	USD 1 EA
	Cost center 28200				
	D 10/25/1999	1.000	EA	52.25	USD 0.00 %
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M016116	ZZ	103388	DoAll Louisville Co.	M09	10/27/1999
00010			SANDVICK U-MAX DRILL ENDMILL #R216.2-08 02 04-2A 235 03		
	Z MAY	1.000	EA	181.00	USD 1 EA
	Cost center 28200				
	D 11/01/1999	1.000	EA	181.00	USD 0.00 %
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00020			SANDVICK INSERT #R216.2-08 02 04-2A 235 03		
	Z MAY	10.000	EA	8.72	USD 1 EA
	Cost center 28200				
	D 11/01/1999	10.000	EA	8.72	USD 0.00 %
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M016133	ZZ	101041	MCMMASTER-CARR SUPPLY CO	M09	11/02/1999
00010			HIGH SPPD REAMER #3002A34		
	Z MAY	3.000	EA	13.87	USD 1 EA
	Cost center 28200				
	D 10/29/1999	3.000	EA	13.87	USD 0.00 %
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M016143	ZZ	102719	KENAMETAL, INC.	M09	11/02/1999
00010			ROYAL VERSA-TURN LIFE CENTER		
	Z MAY	1.000	EA	194.00	USD 1 EA
	Cost center 28200				
	D 11/10/1999	1.000	EA	194.00	USD 0.00 %
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M016148	ZZ	103554	Fluid Power Products	M09	11/12/1999
00010			D27AA1A GEAR PUMP		
	Z MAY	1.000	EA	122.10	USD 1 EA
	Cost center 28200				
	D 11/10/1999	1.000	EA	122.10	USD 0.00 %
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
00030			#686632K D SERIES KIT P326G		
	Z MAY	1.000	EA	27.50	USD 1 EA
	Cost center 28200				
	D 11/08/1999	1.000	EA	27.50	USD 0.00 %
	Still to be delivered	0.000	EA	0.00	USD 0.00 %
	Still to be invoiced	0.000	EA	0.00	USD 0.00 %
M016150	ZZ	5208718	GIDDINGS & LEWIS	M09	11/02/1999
00010			MEASURE MAX INSPECTION PART PROGRAM	MISC	
	K MAY	1.000	EA	5,565.00	USD 1 EA
	Cost center 28200				
	D 11/10/1999	1.000	EA	5,565.00	USD 0.00 %
	Still to be delivered	0.000	EA	0.00	USD 0.00 %

PO	Type	Vendor	Name	PGP	Order	date
Item	Material		Short text		Mat.	group
D I A	Plnt	SLOC	Order qty.	Un	Net Price	Curr. per Un
	SL	del. date	Scheduled qty.			
M016169	Still to be invoiced		1.000	EA	5,585.00	USD 100.00 %
00010	ZZ	106410	FARRIS, MCINTOSH, & TRENGER, INC.	M09	11/18/1999	
	K MAY		BUILD A 100 METER RICE RANGE SITE	MISC		1 EA
	Cost center 28200		1.000	EA	1,442.00	USD 1 EA
	D 11/19/1999		1.000	EA	Preq 1000217197	00010
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
M016186	Still to be invoiced					
00010	ZZ	106014	CAMPBELL'S MACHINE SHOP INC.	M09	12/01/1999	
	Z MAY		C-300360 BOLT HANDLE BLANK	TOOLING		1 EA
	Cost center 28200		50.000	EA	8.83	USD 1 EA
	D 12/01/1999		50.000	EA	Preq 1000254133	00010
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
M016201	Still to be invoiced					
00010	ZZ	102641	MSC INDUSTRIAL SUPPLY	M09	11/16/1999	
	Z MAY		CARR LANE COLLET CLR-100-VS VISE SINGLE #03			1 EA
	Cost center 28200		1.000	EA	1,311.00	USD 1 EA
	D 11/17/1999		1.000	EA	Preq 1000242375	00010
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
M016206	Still to be invoiced					
00010	ZZ	102719	KENAMETAL, INC.	M09	11/12/1999	
	Z MAY		KENDEX BORING BARS-EXC DEVIBRATORS	03		1 EA
	Cost center 28200		1.000	EA	399.12	USD 1 EA
	D 11/08/1999		1.000	EA	Preq 1000232557	00010
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		1.000	EA	399.12	USD 100.00 %
00020	Z MAY		KENDEX SCREW ON INSERT	03		1 EA
	Cost center 28200		5.000	EA	14.63	USD 1 EA
	D 11/08/1999		5.000	EA	Preq 1000232557	00010
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		5.000	EA	73.15	USD 100.00 %
M016242	Still to be invoiced					
00010	ZZ	102641	MSC INDUSTRIAL SUPPLY	M09	11/16/1999	
	Z MAY		#13 1500 SERIES DRILL #59430	03		1 EA
	Cost center 28200		6.000	EA	12.59	USD 1 EA
	D 11/30/1999		6.000	EA	Preq 1000242482	00010
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00020	Z MAY		#13 3FL DRILL MODIF .185 DIA +.00-.0005	03		1 EA
	Cost center 28200		6.000	EA	49.81	USD 1 EA
	D 11/30/1999		6.000	EA	Preq 1000242482	00020
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
M016270	Still to be invoiced					
00010	ZZ	106411	MID AMERICA MACHINE, INC.	M09	11/18/1999	
	Z MAY		BARREL BLKS SAWED & FACED ENDS TO LENGTH	MISC		1 EA
	Cost center 28200		120.000	EA	5.00	USD 1 EA
	D 10/08/1999		120.000	EA	Preq 1000246560	00010
	Still to be delivered		0.000	EA	0.00	USD 0.00 %
	Still to be invoiced		0.000	EA	0.00	USD 0.00 %
00020	K MAY		ESTIMATED KY SALES TAX 6%	MISC		1 EA
	Cost center 28200		1.000	EA	36.00	USD 1 EA
	D 10/08/1999		1.000	EA		

83

MF1068

Confidential - Barber - 5.22.06r0011018 Order

Williams V. Remington

85

Confidential - ~~Shriber - 522-3606~~ Protective Order
Williams v. Remington

PO	Type	Vendor	Name	PGp	Order	date
Item	Material	Sloc	Short text	Mat. group		
D I A	Plnt	SL	Order qty.	Un	Net Price	Curr. per Un
		del. date	Scheduled qty.	Un		
M016378	Still to be invoiced	ZZ 106467	QUICK TEK	0.000	EA	0.00 USD 0.00 %
00010			FIX AND PROGRAM CHARGE C-300333 REV 2	1.000	EA	460.00 USD 100.00 %
	K MAY			1.000	EA	460.00 USD 100.00 %
	Cost center 28200			1.000	EA	460.00 USD 100.00 %
	D 12/14/1999			1.000	EA	460.00 USD 100.00 %
	Still to be delivered			1.000	EA	460.00 USD 100.00 %
	Still to be invoiced			1.000	EA	460.00 USD 100.00 %
00020			FIX AND PROGRAM CHARGE C-300334 REV A	1.000	EA	460.00 USD 100.00 %
	K MAY			1.000	EA	460.00 USD 100.00 %
	Cost center 28200			1.000	EA	460.00 USD 100.00 %
	D 12/14/1999			1.000	EA	460.00 USD 100.00 %
	Still to be delivered			1.000	EA	460.00 USD 100.00 %
	Still to be invoiced			1.000	EA	460.00 USD 100.00 %
M016416	Still to be invoiced	ZZ 2643807	CHROMALOX CORP	1.000	EA	390.00 USD 100.00 %
00010			GS3-184 CHROMALOX IMMERSION HEATER	1.000	EA	537.00 USD 100.00 %
	Z MAY			1.000	EA	537.00 USD 100.00 %
	Cost center 28200			1.000	EA	537.00 USD 100.00 %
	D 12/23/1999			1.000	EA	537.00 USD 100.00 %
	Still to be delivered			1.000	EA	537.00 USD 100.00 %
	Still to be invoiced			1.000	EA	537.00 USD 100.00 %
M016435	Still to be invoiced	ZZ 101041	MCMASTER-CARR SUPPLY CO	1.000	EA	1.89 USD 100.00 %
00020			KEYSTOCK #92530A100	1.000	EA	1.89 USD 100.00 %
	Z MAY			1.000	EA	1.89 USD 100.00 %
	Cost center 28200			1.000	EA	1.89 USD 100.00 %
	D 12/22/1999			1.000	EA	1.89 USD 100.00 %
	Still to be delivered			1.000	EA	1.89 USD 100.00 %
	Still to be invoiced			1.000	EA	1.89 USD 100.00 %
00030			RECTANGLES #8992K22	2.000	EA	16.16 USD 100.00 %
	Z MAY			2.000	EA	16.16 USD 100.00 %
	Cost center 28200			2.000	EA	16.16 USD 100.00 %
	D 12/22/1999			2.000	EA	16.16 USD 100.00 %
	Still to be delivered			2.000	EA	16.16 USD 100.00 %
	Still to be invoiced			2.000	EA	16.16 USD 100.00 %
00040			RECTANGLES #8992K21	1.000	EA	11.31 USD 100.00 %
	Z MAY			1.000	EA	11.31 USD 100.00 %
	Cost center 28200			1.000	EA	11.31 USD 100.00 %
	D 12/22/1999			1.000	EA	11.31 USD 100.00 %
	Still to be delivered			1.000	EA	11.31 USD 100.00 %
	Still to be invoiced			1.000	EA	11.31 USD 100.00 %
M016450	Still to be invoiced	ZZ 106014	CAMPBELL'S MACHINE SHOP INC.	50.000	EA	8.83 USD 100.00 %
00010			C-300360 BOLT HANDLE BLANK	50.000	EA	8.83 USD 100.00 %
	Z MAY			50.000	EA	8.83 USD 100.00 %
	Cost center 28200			50.000	EA	8.83 USD 100.00 %
	D 12/31/1999			50.000	EA	8.83 USD 100.00 %
	Still to be delivered			50.000	EA	8.83 USD 100.00 %
	Still to be invoiced			50.000	EA	8.83 USD 100.00 %
00020			1-300329 BOLT HANDLE PIN	50.000	EA	2.50 USD 100.00 %
	Z MAY			50.000	EA	2.50 USD 100.00 %
	Cost center 28200			50.000	EA	2.50 USD 100.00 %
	D 12/31/1999			50.000	EA	2.50 USD 100.00 %
	Still to be delivered			50.000	EA	2.50 USD 100.00 %
	Still to be invoiced			50.000	EA	2.50 USD 100.00 %
M016477	Still to be invoiced	ZZ 5380140	DANJON MANUFACTURING CORP	16.000	EA	76.80 USD 100.00 %
00010			.263 DIA A/C GUN DRILLS X 54" OAL	16.000	EA	76.80 USD 100.00 %
	Z MAY			16.000	EA	76.80 USD 100.00 %
	Cost center 28200			16.000	EA	76.80 USD 100.00 %
	D 02/28/2000			16.000	EA	76.80 USD 100.00 %
	Still to be delivered			16.000	EA	76.80 USD 100.00 %

PO	Item	Type	Vendor	Name	Short text	Order qty.	Un	Net Price	Pgp	Order date
	D I A	Material	Sloc			Scheduled	Un		Curr.	Mat. group
		SL del. date				qty.				per Un
				Still to be invoiced		16.000	EA	1,228.80	USD	100.00 %
00020				.269 CARBIDE BORE REAMER ON 5/8" TUBE		8.000	EA	152.80	USD	03 1 EA
				Z MAY						
				Cost center 28200						
				D 02/28/2000		8.000	EA	1,062.40	USD	100.00 %
				Still to be delivered		8.000	EA	1,062.40	USD	100.00 %
				Still to be invoiced		8.000	EA	1,062.40	USD	100.00 %
00030				.280/.2715 CARBIDE COMB. BUT. R# 1T 10"		2.000	EA	196.00	USD	03 1 EA
				Z MAY						
				Cost center 28200						
				D 02/28/2000		2.000	EA	392.00	USD	100.00 %
				Still to be delivered		2.000	EA	392.00	USD	100.00 %
				Still to be invoiced		2.000	EA	392.00	USD	100.00 %
M016508	ZZ	5390090		PHI ASSOCIATES						M09 01/18/2000
00010				RECEIVER INSERT CMM FIXTURE #K-10400		1.000	EA	960.00	USD	TOOLING 1 EA
				Z MAY						
				Cost center 28200						
				D 02/24/2000		1.000	EA	960.00	USD	100.00 %
				Still to be delivered		1.000	EA	960.00	USD	100.00 %
				Still to be invoiced		1.000	EA	960.00	USD	100.00 %
00020				RECEIVER INSERT PLUG GAGE # K-10401		1.000	EA	120.00	USD	TOOLING 1 EA
				Z MAY						
				Cost center 28200						
				D 02/24/2000		1.000	EA	120.00	USD	100.00 %
				Still to be delivered		1.000	EA	120.00	USD	100.00 %
				Still to be invoiced		1.000	EA	120.00	USD	100.00 %
00030				RECEIVER INSERT FUNCTION GAGE # K-10402		1.000	EA	360.00	USD	TOOLING 1 EA
				Z MAY						
				Cost center 28200						
				D 02/24/2000		1.000	EA	360.00	USD	100.00 %
				Still to be delivered		1.000	EA	360.00	USD	100.00 %
				Still to be invoiced		1.000	EA	360.00	USD	100.00 %
M016509	ZZ	5390090		PHI ASSOCIATES						M09 01/18/2000
00010				SIDE PLATE COMPARATOR FIXTURE # K-10403		1.000	EA	300.00	USD	TOOLING 1 EA
				Z MAY						
				Cost center 28200						
				D 02/24/2000		1.000	EA	300.00	USD	100.00 %
				Still to be delivered		1.000	EA	300.00	USD	100.00 %
				Still to be invoiced		1.000	EA	300.00	USD	100.00 %
00020				SIDE PLATE COMPARATOR SCREEN #K-10404		1.000	EA	240.00	USD	TOOLING 1 EA
				Z MAY						
				Cost center 28200						
				D 02/24/2000		1.000	EA	240.00	USD	100.00 %
				Still to be delivered		1.000	EA	240.00	USD	100.00 %
				Still to be invoiced		1.000	EA	240.00	USD	100.00 %
M016510	ZZ	5390090		PHI ASSOCIATES						M09 01/18/2000
00010				SAFETY COMPARATOR FIXTURE #K-10405		1.000	EA	360.00	USD	TOOLING 1 EA
				Z MAY						
				Cost center 28200						
				D 02/24/2000		1.000	EA	360.00	USD	100.00 %
				Still to be delivered		1.000	EA	360.00	USD	100.00 %
				Still to be invoiced		1.000	EA	360.00	USD	100.00 %
00020				SAFETY COMPARATOR SCREEN #K-10406		1.000	EA	180.00	USD	TOOLING 1 EA
				Z MAY						
				Cost center 28200						
				D 02/24/2000		1.000	EA	180.00	USD	100.00 %
				Still to be delivered		1.000	EA	180.00	USD	100.00 %
				Still to be invoiced		1.000	EA	180.00	USD	100.00 %
M016511	ZZ	5390090		PHI ASSOCIATES						M09 01/18/2000

PO	Type	Vendor	Name	PGP	Order	date
Item	Material		Short text		Mat. group	
D I A	Plnt Sloc		Order qty.	Un	Net Price	Curr. per Un
	SL del. date		Scheduled qty.	Un		
00010			BOLT STOP COMPARATOR FIXTURE #K-10407		TOOLING	
Z MAY			1.000 EA		600.00 USD	1 EA
Cost center 28200						
D 02/24/2000			1.000 EA		600.00 USD	100.00 %
Still to be delivered			1.000 EA		600.00 USD	100.00 %
Still to be invoiced			1.000 EA		600.00 USD	100.00 %
00020			BOLT STOP COMPARATOR SCREEN #K-10408		TOOLING	
Z MAY			1.000 EA		180.00 USD	1 EA
Cost center 28200						
D 02/24/2000			1.000 EA		180.00 USD	100.00 %
Still to be delivered			1.000 EA		180.00 USD	100.00 %
Still to be invoiced			1.000 EA		180.00 USD	100.00 %
M016512	ZZ	5390090	PHI ASSOCIATES			M09 01/18/2000
00010			BOLT HAND BLANK COMPARATOR FIX #K-10409		TOOLING	
Z MAY			1.000 EA		280.00 USD	1 EA
Cost center 28200						
D 02/24/2000			1.000 EA		980.00 USD	100.00 %
Still to be delivered			1.000 EA		980.00 USD	100.00 %
Still to be invoiced			1.000 EA		980.00 USD	100.00 %
00020			BOLT HAND BLANK COMPARATOR SCR #K-10410		TOOLING	
Z MAY			1.000 EA		360.00 USD	1 EA
Cost center 28200						
D 02/24/2000			1.000 EA		360.00 USD	100.00 %
Still to be delivered			1.000 EA		360.00 USD	100.00 %
Still to be invoiced			1.000 EA		360.00 USD	100.00 %
M016513	ZZ	5390090	PHI ASSOCIATES			M09 01/18/2000
00010			BOLT HEAD BLANK COMPARATOR SCR # K-10411		TOOLING	
Z MAY			1.000 EA		120.00 USD	1 EA
Cost center 28200						
D 02/24/2000			1.000 EA		120.00 USD	100.00 %
Still to be delivered			1.000 EA		120.00 USD	100.00 %
Still to be invoiced			1.000 EA		120.00 USD	100.00 %
M016514	ZZ	5390090	PHI ASSOCIATES			M09 01/18/2000
00010			EJECTOR COMPARATOR FIXTURE # K-10412		TOOLING	
Z MAY			1.000 EA		360.00 USD	1 EA
Cost center 28200						
D 02/24/2000			1.000 EA		360.00 USD	100.00 %
Still to be delivered			1.000 EA		360.00 USD	100.00 %
Still to be invoiced			1.000 EA		360.00 USD	100.00 %
00020			EJECTOR COMPARATOR SCREEN #K-10413		TOOLING	
Z MAY			1.000 EA		120.00 USD	1 EA
Cost center 28200						
D 02/24/2000			1.000 EA		120.00 USD	100.00 %
Still to be delivered			1.000 EA		120.00 USD	100.00 %
Still to be invoiced			1.000 EA		120.00 USD	100.00 %
M016515	ZZ	5390090	PHI ASSOCIATES			M09 01/18/2000
00010			BOLT PLUG FUNCTIONAL GAGE # K-10414		TOOLING	
Z MAY			1.000 EA		720.00 USD	1 EA
Cost center 28200						
D 02/24/2000			1.000 EA		720.00 USD	100.00 %
Still to be delivered			1.000 EA		720.00 USD	100.00 %
Still to be invoiced			1.000 EA		720.00 USD	100.00 %
M016516	ZZ	5390090	PHI ASSOCIATES			M09 01/18/2000
00010			BOLT PLUG INSERT COMPARATOR FIX #K-10415		TOOLING	
Z MAY			1.000 EA		360.00 USD	1 EA
Cost center 28200						
D 02/24/2000			1.000 EA		360.00 USD	100.00 %
Still to be delivered			1.000 EA		360.00 USD	100.00 %
Still to be invoiced			1.000 EA		360.00 USD	100.00 %

83

MF1072

Confidential - SHARPER - 5.22.06r0011022 Order

Williams v. Remington

PO	Type	Vendor	Name	PGp	Order	date
Item	Material		Short text		Mat.	group
D I A Plnt	S Loc		Order qty.	Un	Curr.	per Un
SL del. date			Scheduled qty.	Un		
00020			BOLT PLUG INSERT	COMPARATOR SCR #K-10416	TOOLING	
Z MAY			1.000	EA	180.00	USD 1 EA
Cost center 28200						
D 02/24/2000			1.000	EA	180.00	USD 100.00 %
Still to be delivered			1.000	EA	180.00	USD 100.00 %
Still to be invoiced			1.000	EA	180.00	USD 100.00 %
M016517	ZZ	5390090	PHI ASSOCIATES			M09 01/18/2000
00010			FIRING PIN TIP	COMPARATOR SCR #K-10417	TOOLING	
Z MAY			1.000	EA	120.00	USD 1 EA
Cost center 28200						
D 02/24/2000			1.000	EA	120.00	USD 100.00 %
Still to be delivered			1.000	EA	120.00	USD 100.00 %
Still to be invoiced			1.000	EA	120.00	USD 100.00 %
M016518	ZZ	5390090	PHI ASSOCIATES			M09 01/18/2000
00010			FIRING PIN HEAD	COMPARATOR FLX #K-10418	TOOLING	
Z MAY			1.000	EA	480.00	USD 1 EA
Cost center 28200						
D 02/24/2000			1.000	EA	480.00	USD 100.00 %
Still to be delivered			1.000	EA	480.00	USD 100.00 %
Still to be invoiced			1.000	EA	480.00	USD 100.00 %
00020			FIRING PIN HEAD	COMPARATOR SCR #K-10419	TOOLING	
Z MAY			1.000	EA	180.00	USD 1 EA
Cost center 28200						
D 02/24/2000			1.000	EA	180.00	USD 100.00 %
Still to be delivered			1.000	EA	180.00	USD 100.00 %
Still to be invoiced			1.000	EA	180.00	USD 100.00 %
M016519	ZZ	5390090	PHI ASSOCIATES			M09 01/18/2000
00010			MAGAZINE BOX CMM	FIXTURE # K-10420	TOOLING	
Z MAY			1.000	EA	960.00	USD 1 EA
Cost center 28200						
D 02/24/2000			1.000	EA	960.00	USD 100.00 %
Still to be delivered			1.000	EA	960.00	USD 100.00 %
Still to be invoiced			1.000	EA	960.00	USD 100.00 %
M016520	ZZ	5390090	PHI ASSOCIATES			M09 01/18/2000
00010			MAG FOLLOWER	COMPARATOR FIXTURE #K-10421	TOOLING	
Z MAY			1.000	EA	360.00	USD 1 EA
Cost center 28200						
D 02/24/2000			1.000	EA	360.00	USD 100.00 %
Still to be delivered			1.000	EA	360.00	USD 100.00 %
Still to be invoiced			1.000	EA	360.00	USD 100.00 %
00020			MAG FOLLOWER	COMPARATOR SCREEN #K-10422	TOOLING	
Z MAY			1.000	EA	120.00	USD 1 EA
Cost center 28200						
D 02/24/2000			1.000	EA	120.00	USD 100.00 %
Still to be delivered			1.000	EA	120.00	USD 100.00 %
Still to be invoiced			1.000	EA	120.00	USD 100.00 %
M016537	ZZ	104140	BARLCAY'S METAL COMPANY			M09 01/18/2000
00010			200' PIECE 2" X 2" X 1/4" ANGLE		44	
Z MAY			1.000	EA	173.64	USD 1 EA
Cost center 28200						
D 01/18/2000			1.000	EA	0.00	USD 0.00 %
Still to be delivered			0.000	EA	0.00	USD 0.00 %
Still to be invoiced			0.000	EA	0.00	USD 0.00 %
00020			40' PIECE 1/4" X 1-1/4" FLAT		44	
Z MAY			1.000	EA	17.00	USD 1 EA
Cost center 28200						
D 01/18/2000			1.000	EA	0.00	USD 0.00 %
Still to be delivered			0.000	EA	0.00	USD 0.00 %
Still to be invoiced			0.000	EA	0.00	USD 0.00 %

PO	Type	Vendor	Name	PGP	Order date
Item	Material	Short text	Order qty.	Un	Mat. group
D I A Plnt	Sloc	Order qty.	Un	Mat Price	Curr.
SL del. date	Schedul	Un			per Un
00030		16 GA METAL 4' X 3'	2.000	EA	44
Z MAY					2 EA
Cost center 28200					
D 01/18/2000					
Still to be delivered					0.00 %
Still to be invoiced					0.00 %
00040		ESTIMATED KY SALES TAX 6%	1.000	EA	44
Z MAY					1 EA
Cost center 28200					
D 01/18/2000					
Still to be delivered					0.00 %
Still to be invoiced					0.00 %
M016538	ZZ	103943	GRAINGER, INC.		M09 01/18/2000
00010		4" SWIVEL CASTER #2G130	8.000	EA	MISC
Z MAY					1 EA
Cost center 28200					
D 01/20/2000					
Still to be delivered					0.00 %
Still to be invoiced					0.00 %
00020		4" RIGID CASTER #2G131	8.000	EA	MISC
Z MAY					1 EA
Cost center 28200					
D 01/20/2000					
Still to be delivered					0.00 %
Still to be invoiced					0.00 %
M016546	ZZ	102855	Lohn & Associates		M09 01/18/2000
00010		BARREL BASKET 18" HIGH X 36" DIAMETER	1.000	EA	TOOLING
Z MAY					1 EA
Cost center 28200					
D 03/27/2000					
Still to be delivered					100.00 %
Still to be invoiced					100.00 %
M016555	ZZ	106516	MICROCENTRIC		M09 01/25/2000
00020		SK-1787-01 SPECIAL 42BZ1 QUICK CHANGE	2.000	EA	03
Z MAY					1 EA
Cost center 28200					
D 02/10/2000					
Still to be delivered					100.00 %
Still to be invoiced					100.00 %
00030		AS-1787-01 HARDENED STOP BUSHING	2.000	EA	03
Z MAY					1 EA
Cost center 28200					
D 02/10/2000					
Still to be delivered					100.00 %
Still to be invoiced					100.00 %
M016558	ZZ	104140	BARLCAY'S METAL COMPANY		M09 01/25/2000
00010		20' SQ TUBE 2" X 1/4"	3.000	EA	44
Z MAY					1 EA
Cost center 28200					
D 01/25/2000					
Still to be delivered					0.00 %
Still to be invoiced					100.00 %
00020		14" WALTER C.O.W	6.000	EA	44
Z MAY					6 EA
Cost center 28200					
D 01/25/2000					
Still to be delivered					0.00 %
Still to be invoiced					100.00 %
00030		1/4" PLATE 4' X 4'			44

PO	Item	Type	Vendor	Name	PGp	Order	date
		Material		Short text			
	D I A	Plnt Sloc		Order qty.	Un	Net Price	Mat. group
		SL del. date		Scheduled qty.	Un	Curr.	per Un
	Z MAY			2.000	EA	102.92	USD 2 EA
	Cost center 28200						
	D 01/25/2000			2.000	EA	PReq 1000328053	00030
	Still to be delivered			0.000	EA	0.00	USD 0.00 %
	Still to be invoiced			2.000	EA	102.92	USD 100.00 %
00040			ESTIMATED	1.000	EA	102.92	USD 44
	Z MAY			1.000	EA	102.92	USD 1 EA
	Cost center 28200						
	D 01/25/2000			1.000	EA	PReq 1000328053	00040
	Still to be delivered			0.000	EA	0.00	USD 0.00 %
	Still to be invoiced			1.000	EA	102.92	USD 100.00 %
M016559	ZZ	101041	MCMaster-CARR SUPPLY CO				M09 01/25/2000
00010			3/4" DELRIN ROD #8572K58	15.000	FT	1.75	USD MISC 1 FT
	Z MAY			15.000	FT	PReq 1000323224	00010
	Cost center 28200						
	D 01/31/2000			0.000	FT	0.00	USD 0.00 %
	Still to be delivered			0.000	FT	0.00	USD 0.00 %
	Still to be invoiced			0.000	FT	0.00	USD 0.00 %
00020			1-1/4" DELRIN ROD #8572K23	15.000	FT	5.04	USD MISC 1 FT
	Z MAY			15.000	FT	PReq 1000323224	00020
	Cost center 28200						
	D 01/31/2000			0.000	FT	0.00	USD 0.00 %
	Still to be delivered			0.000	FT	0.00	USD 0.00 %
	Still to be invoiced			0.000	FT	0.00	USD 0.00 %
M016563	ZZ	102641	MSC INDUSTRIAL SUPPLY				M09 01/25/2000
00010			PRECISION BENCH CENTER #09131301	2.000	EA	1,931.16	USD 03 1 EA
	Z MAY			2.000	EA	PReq 1000323153	00010
	Cost center 28200						
	D 01/31/2000			0.000	EA	0.00	USD 0.00 %
	Still to be delivered			2.000	EA	3,862.32	USD 100.00 %
	Still to be invoiced						
M016581	ZZ	3557873	WILSON INSTRUMENT INC				M09 01/25/2000
00010			VARI-REST SIZE 8 USE W/ MODEL A644T TEST 46	1.000	EA	890.00	USD 1 EA
	Z MAY			1.000	EA	PReq 1000330024	00010
	Cost center 28200						
	D 02/28/2000			1.000	EA	890.00	USD 100.00 %
	Still to be delivered			1.000	EA	890.00	USD 100.00 %
	Still to be invoiced						
M016587	ZZ	106411	MID AMERICA MACHINE, INC.				M09 01/25/2000
00010			MACHINE 100 OFF OF OD OF BARREL BLANKS	102.000	EA	7.50	USD MISC 1 EA
	Z MAY			102.000	EA	PReq 1000328052	00010
	Cost center 28200						
	D 01/25/2000			0.000	EA	0.00	USD 0.00 %
	Still to be delivered			102.000	EA	765.00	USD 100.00 %
	Still to be invoiced						
M016599	ZZ	101041	MCMaster-CARR SUPPLY CO				M09 01/28/2000
00010			9/32 ENDMILL #89145A42	1.000	EA	14.64	USD 03 1 EA
	Z MAY			1.000	EA	PReq 1000330051	00010
	Cost center 28200						
	D 01/27/2000			0.000	EA	0.00	USD 0.00 %
	Still to be delivered			1.000	EA	14.64	USD 100.00 %
	Still to be invoiced						
00020			19/64 ENDMILL #89145A43	1.000	EA	14.72	USD 03 1 EA
	Z MAY			1.000	EA	PReq 1000330051	00020
	Cost center 28200						
	D 01/27/2000			0.000	EA	0.00	USD 0.00 %
	Still to be delivered			1.000	EA	14.72	USD 100.00 %
	Still to be invoiced						
00030			5/16 ENDMILL #89145A44				03

83

MF1075

Confidential - SHARPER - 5.22.06r0011025 Order

Williams V. Remington

PO	Type	Vendor	Name	PGP	Order date
Item	Material	Short text	Mat. group		
D I A	Plnt Sloc	Order qty.	Un	Curr.	per Un
SL del. date	Scheduled	Un	Net Price		
Z MAY		1.000	EA	14.02	USD 1 EA
Cost center 28200					
D 01/27/2000		1.000	EA	PReq 1000330051	00030
Still to be delivered		0.000	EA	0.00	USD 0.00 %
Still to be invoiced		1.000	EA	14.02	USD 100.00 %
00040		21/64 ENDMILL #89145A45			03
Z MAY		1.000	EA	14.72	USD 1 EA
Cost center 28200					
D 01/27/2000		1.000	EA	PReq 1000330051	00040
Still to be delivered		0.000	EA	0.00	USD 0.00 %
Still to be invoiced		1.000	EA	14.72	USD 100.00 %
00050		PLUMB BOB AND CASE #2178A1			03
Z MAY		5.000	EA	11.56	USD 1 EA
Cost center 28200					
D 01/27/2000		5.000	EA	PReq 1000330051	00050
Still to be delivered		0.000	EA	0.00	USD 0.00 %
Still to be invoiced		5.000	EA	57.80	USD 100.00 %
M016610	ZZ 102641	MSC INDUSTRIAL SUPPLY			M09 01/28/2000
00010		#06235691 MITUTOYO MINI-MIKE			03
Z MAY		1.000	EA	174.31	USD 1 EA
Cost center 28200					
D 02/10/2000		1.000	EA	PReq 1000335542	00010
Still to be delivered		1.000	EA	174.31	USD 100.00 %
Still to be invoiced		1.000	EA	174.31	USD 100.00 %
00020		#01044585 MTI DIGITEST CALIPER GAGE			03
Z MAY		1.000	EA	686.40	USD 1 EA
Cost center 28200					
D 02/10/2000		1.000	EA	PReq 1000335542	00020
Still to be delivered		1.000	EA	686.40	USD 100.00 %
Still to be invoiced		1.000	EA	686.40	USD 100.00 %
00030		#98668130 CHAMFER CHECK			03
Z MAY		1.000	EA	122.06	USD 1 EA
Cost center 28200					
D 02/10/2000		1.000	EA	PReq 1000335542	00030
Still to be delivered		1.000	EA	122.06	USD 100.00 %
Still to be invoiced		1.000	EA	122.06	USD 100.00 %
00040		#98556434 NON-CAT MTI CORP			03
Z MAY		1.000	EA	257.84	USD 1 EA
Cost center 28200					
D 02/10/2000		1.000	EA	PReq 1000335542	00040
Still to be delivered		1.000	EA	257.84	USD 100.00 %
Still to be invoiced		1.000	EA	257.84	USD 100.00 %
00050		#00622464 MITUTOYO DIG DEPTH GAGE			03
Z MAY		1.000	EA	302.72	USD 1 EA
Cost center 28200					
D 02/10/2000		1.000	EA	PReq 1000335542	00050
Still to be delivered		1.000	EA	302.72	USD 100.00 %
Still to be invoiced		1.000	EA	302.72	USD 100.00 %
M016612	ZZ 101041	MCMASER-CARR SUPPLY CO			M09 01/28/2000
00010		RODS 3/32 5 LB BOX #7972A278			44
Z MAY		1.000	EA	36.50	USD 1 EA
Cost center 28200					
D 02/03/2000		1.000	EA	PReq 1000335541	00010
Still to be delivered		1.000	EA	36.50	USD 100.00 %
Still to be invoiced		1.000	EA	36.50	USD 100.00 %
00020		7/8" ROUND 6' LENGTH #89325K19			44
Z MAY		16.000	EA	70.50	USD 1 EA
Cost center 28200					
D 02/03/2000		16.000	EA	PReq 1000335541	00020

83

MF1076

Confidential - SHARPER - 5.22.06#0011026 Order

Williams v. Remington

PO	Item	Type	Vendor	Name	Short text	Order qty.	Un	Net Price	PGp	Order date	Mat. group
D I A Plnt Sloc	SL del. date	Scheduled qty.	Un	Curr.	per Un						
	Still to be delivered	16.000	EA	1,128.00	USD	100.00 %					
	Still to be invoiced	16.000	EA	1,128.00	USD	100.00 %					
00030		1/8" ROUND 6' LENGTH #89325K1	16.000	EA	7.20	USD	44	1 EA			
	Z MAY										
	Cost center 28200										
	D 02/03/2000	16.000	EA	PReq 100033541	00030						
	Still to be delivered	16.000	EA	115.20	USD	100.00 %					
	Still to be invoiced	16.000	EA	115.20	USD	100.00 %					
00040		1/8" PRESSURE GUAGE #38105K13	4.000	EA	8.85	USD	03	1 EA			
	Z MAY										
	Cost center 28200										
	D 02/03/2000	4.000	EA	PReq 100033541	00040						
	Still to be delivered	4.000	EA	35.40	USD	100.00 %					
	Still to be invoiced	4.000	EA	35.40	USD	100.00 %					
00050		GRINDER #46225A81	1.000	EA	136.25	USD	03	1 EA			
	Z MAY										
	Cost center 28200										
	D 02/03/2000	1.000	EA	PReq 100033541	00050						
	Still to be delivered	1.000	EA	136.25	USD	100.00 %					
	Still to be invoiced	1.000	EA	136.25	USD	100.00 %					
M016613	ZZ 104762	G AND H TOOL & DIE, INC								01/28/2000	
00010		ALIGNMENT BORE PER PRINT	1.000	EA	375.00	USD	03	1 EA			
	Z MAY										
	Cost center 28200										
	D 02/15/2000	1.000	EA	PReq 100033543	00010						
	Still to be delivered	1.000	EA	375.00	USD	100.00 %					
	Still to be invoiced	1.000	EA	375.00	USD	100.00 %					
M016614	ZZ 102641	MSC INDUSTRIAL SUPPLY								01/28/2000	
00010		FEDERAL SERIES C MODEL C81 DIAL INDICATOR	2.000	EA	107.00	USD	03	1 EA			
	Z MAY										
	Cost center 28200										
	D 02/04/2000	2.000	EA	PReq 100033544	00010						
	Still to be delivered	2.000	EA	214.00	USD	100.00 %					
	Still to be invoiced	2.000	EA	214.00	USD	100.00 %					
M016617	ZZ 106524	WESTERN GAGE CORPORATION								01/28/2000	
00040		RGM-XX-C-3000 RING GAGE, MASTER	1.000	EA	114.95	USD	03	1 EA			
	Z MAY										
	Cost center 28200										
	D 02/28/2000	1.000	EA	PReq 1000328038	00040						
	Still to be delivered	1.000	EA	114.95	USD	100.00 %					
	Still to be invoiced	1.000	EA	114.95	USD	100.00 %					
00050		RGM-XX-C-3010 RING GAGE, MASTER	1.000	EA	114.95	USD	03	1 EA			
	Z MAY										
	Cost center 28200										
	D 02/28/2000	1.000	EA	PReq 1000328038	00050						
	Still to be delivered	1.000	EA	114.95	USD	100.00 %					
	Still to be invoiced	1.000	EA	114.95	USD	100.00 %					
00060		WGC SPECIAL AIR PROBE TO CHK	1.000	EA	1,895.25	USD	03	1 EA			
	Z MAY										
	Cost center 28200										
	D 02/28/2000	1.000	EA	PReq 1000328038	00060						
	Still to be delivered	1.000	EA	1,895.25	USD	100.00 %					
	Still to be invoiced	1.000	EA	1,895.25	USD	100.00 %					
00070		RGM-XX-C-.3080 RING GAGE, MASTER	1.000	EA	114.95	USD	03	1 EA			
	Z MAY										
	Cost center 28200										
	D 02/28/2000	1.000	EA	PReq 1000328038	00070						
	Still to be delivered	1.000	EA	114.95	USD	100.00 %					
	Still to be invoiced	1.000	EA	114.95	USD	100.00 %					

PO	Item	Type	Vendor	Name	Short text	Order qty.	Un	Net Price	Curr.	Order date	Mat. group
D I A	Plnt	Sloc	SL del. date	Scheduled qty.	Un					per Un	
00080				RGM-XX-C-.3090 RING GAGE, MASTER		1.000	EA	114.95	USD	03	1 EA
	Z MAY										
	Cost center 28200										
	D 02/28/2000					1.000	EA	114.95	USD	00080	
	Still to be delivered					1.000	EA	114.95	USD	100.00 %	
	Still to be invoiced					1.000	EA	114.95	USD	100.00 %	
M016618	ZZ	5380140		DANJON MANUFACTURING CORP						M09 01/28/2000	
00010				DRILL .292 DIA X 54" LONG W/ KIDNEY		36.000	EA	76.00	USD	03	1 EA
	Z MAY										
	Cost center 28200										
	D 02/21/2000					36.000	EA	114.95	USD	00010	
	Still to be delivered					36.000	EA	114.95	USD	100.00 %	
	Still to be invoiced					36.000	EA	114.95	USD	100.00 %	
00020				REAMERS .299 DIA. TO BE PVD COATED WITH		12.000	EA	145.80	USD	03	1 EA
	Z MAY										
	Cost center 28200										
	D 02/21/2000					12.000	EA	114.95	USD	00020	
	Still to be delivered					12.000	EA	1,749.60	USD	100.00 %	
	Still to be invoiced					12.000	EA	1,749.60	USD	100.00 %	
00030				BUTTON .3112 GROOVE X .301 BORE DIAMETER		5.000	EA	209.00	USD	03	1 EA
	Z MAY										
	Cost center 28200										
	D 02/21/2000					5.000	EA	114.95	USD	00030	
	Still to be delivered					5.000	EA	1,045.00	USD	100.00 %	
	Still to be invoiced					5.000	EA	1,045.00	USD	100.00 %	
M016621	ZZ	106525		TBI STEEL						M09 01/28/2000	
00010				3/16" RND STAINLESS 316 GRADE X 12' STICK		2.000	EA	3.00	USD	44	1 EA
	Z MAY										
	Cost center 28200										
	D 02/04/2000					2.000	EA	114.95	USD	00010	
	Still to be delivered					2.000	EA	6.00	USD	100.00 %	
	Still to be invoiced					2.000	EA	6.00	USD	100.00 %	
00020				1/4" RND STAINLESS 316 GRADE X 12' STICK		21.000	EA	5.45	USD	44	1 EA
	Z MAY										
	Cost center 28200										
	D 02/04/2000					21.000	EA	114.45	USD	00020	
	Still to be delivered					21.000	EA	114.45	USD	100.00 %	
	Still to be invoiced					21.000	EA	114.45	USD	100.00 %	
00030				1/2" RND STAINLESS 316 GRADE X 12' STICK		1.000	EA	20.95	USD	44	1 EA
	Z MAY										
	Cost center 28200										
	D 02/04/2000					1.000	EA	20.95	USD	00030	
	Still to be delivered					1.000	EA	20.95	USD	100.00 %	
	Still to be invoiced					1.000	EA	20.95	USD	100.00 %	
00040				1" X 1/2" FLAT STNLESS 316 GRD X 12' STIC		16.000	EA	59.70	USD	44	1 EA
	Z MAY										
	Cost center 28200										
	D 02/04/2000					16.000	EA	955.20	USD	00040	
	Still to be delivered					16.000	EA	955.20	USD	100.00 %	
	Still to be invoiced					16.000	EA	955.20	USD	100.00 %	
M017369	ZZ	103096		FEDERAL STEEL SUPPLY						M01 09/10/1999	
00010				1.437 OD X .937 ID DOM TUBE TO CLEAN		300.000	FT	4.83	USD	RAW	1 FT
	Z MAY										
	Cost center 28200										
	D 09/14/1999					300.000	FT	0.00	USD	0.00 %	
	Still to be delivered					0.000	FT	0.00	USD	0.00 %	
	Still to be invoiced					0.000	FT	0.00	USD	0.00 %	
00020				.750 OD X .482 ID DOM TUBE TO CLEAN		300.000	FT	2.60	USD	RAW	1 FT
	Z MAY										

PO	Type	Vendor	Name	PGp	Order date
Item	Material		Short text		Mat. group
D I A	Plnt	SLoc	Order qty.	Un	Curr.
		SL del. date	Scheduled qty.	Un	per Un
		Cost center 28200			
		D 09/14/1999	300.000	FT	
		Still to be delivered	0.000	FT	0.00 USD 0.00 %
		Still to be invoiced	0.000	FT	0.00 USD 0.00 %
M017372	ZZ	102282	MATTHEW MACHINERY	M01	09/17/1999
00010			710 RUN-OFF OF THREE PARTS		SERVICE
L	K MAY		1.000	EA	21,950.00 USD 1 EA
		Cost center 28200			
		D 10/05/1999	1.000	EA	
		Still to be delivered	0.000	EA	0.00 USD 0.00 %
		Still to be invoiced	0.000	EA	0.00 USD 0.00 %
00020			710 RUN-OFF OF THREE PARTS		SERVICE
	K MAY		1.000	EA	22,780.00 USD 1 EA
		Cost center 28200			
		D 10/05/1999	1.000	EA	PRQ 100079480 00010
		Still to be delivered	0.000	EA	0.00 USD 0.00 %
		Still to be invoiced	0.000	EA	0.00 USD 0.00 %
M017442	ZZ	105149	ISELI CO.	M01	12/14/1999
00030			NON-RECURRING ENGINEERING CHARGE F300328-RAW		
	K MAY RM20		1.000	EA	225.00 USD 1 EA
		Cost center 28200			
		D 01/25/2000	1.000	EA	
		Still to be delivered	0.000	EA	0.00 USD 0.00 %
		Still to be invoiced	1.000	EA	225.00 USD 100.00 %
00040			NON-RECURRING ENGINEERING CHARGE F300342 RAW		
	K MAY RM20		1.000	EA	400.00 USD 1 EA
		Cost center 28200			
		D 01/25/2000	1.000	EA	
		Still to be delivered	0.000	EA	0.00 USD 0.00 %
		Still to be invoiced	1.000	EA	400.00 USD 100.00 %

Quick Tek
MFG, INC.

*COPY
FYI
1/25*

Quotation

Date: Januart 25, 2000		☒ Via Fax only ☐ Via Fax, confirmed by Mail ☐ Via Phone, confirmed by Fax ☐ Via Phone, confirmed by Mail ☐ Via U.S. Mail only ☐ Via e-mail only ☐ xc:	
To: Metty E. Morgan, Materials Manager Remington Arms, Mayfield Plant 22 Rifle Trail Trail, P.O. Box 99 Hickory, KY 42051			
Inquiry Date: 1/24/00		Inquiry Number:	
Terms: 1%10 net 30		F.O.B. Paris, KY	
We are pleased to submit the following quotation.			
Item #	Dwg. Number	Description	Annual Quantity Unit Price \$ Delivery
	B-300346	Bolt Plug Insert per REV D Dwg. Dated 1/20/00	300 10.70 2 to 3 wks
With your needs of a fast delivery, we cannot have a cutter ground for the .020R/.125R form. . Instead, we would finish contour the form with a 3/64 (.047) diameter end mill. We could lower the price if a larger radius than .020±.005 would be allowed.			
☐ Attached Information:			
Prices quoted are firm for 30 days after date of quotation. Delivery times quoted are time after receipt of order and credit/terms acceptability. Delivery times are based upon lead time at date of quotation and are subject to change at time of order. Subject to acceptability of credit, our regular terms are 1%10 net 30 days from invoice date. We appreciate prompt payments. Past Due Amounts will be assessed a 1-1/2% per month service charge.			
Submitted by Chuck Ulinski or Tim Fryman		Signature: <i>Chuck Ulinski</i>	

Manufacturing Services, Conventional & CNC Machining

104 Second St. Paris, KY 40361 606-987-2591 Fax 606-987-2563 e-mail quicktek1@aol.com

01-25-00 11:01 TO: REMINGTON ARMS MAYFIELD KY

FROM: 6069872563

P02

MF1080

Confidential - Subject to Protective Order
 BARBER - 5.22.06r0011030
 Williams v. Remington

PHONE (901) 536-6473 • FAX (901) 536-5813 • 898 N. HWY. 45 WEST • UNION CITY, TN 38261

Quote # 3524

ATTN: JIM GOOCH

The Following is a Quotation

83

QUANTITY	DESCRIPTION	PRICE
1	FIXTURE PER PRINTS	\$778.00 EA

FROM: BILL HUTCHISON

Confidential - Subject to Protective Order
BARBER - 5.22.06 P1031
Williams v. Remington

Material	Short text	PGp	Mat. gp.
Requisn. Item	Requested qty. Un Deliv. date Requester	Plnt SLoc	
S C R Qty. I A	Req. val. Cur Release date Trackg.no.	Spl. MC	
Release strategy	Release indicator Release option		
X	U-SHAPED LIGHT BULBS #8315K15 M09 28		
1000319551 00010	12.000 EA D 01/21/2000 GOLEMBOSKIMR MAY		
N R A NB Z	128.40 USD 01/20/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	101041 MCMMASTER-CARR SUPPLY CO		
X	SF-1787-01 CB42-S/A6 LOW PROFILE COLLET M09 03		
1000321299 00010	1.000 EA D 02/10/2000 GOLEMBOSKIMR MAY		
N R A NB F	3,645.00 USD 01/20/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	106516 MICROCENTRIC		
X	SK-1787-01 SPECIAL 42BZ1 QUICK CHANGE M09 03		
1000321299 00020	2.000 EA D 02/10/2000 GOLEMBOSKIMR MAY		
N R A NB Z	1,124.00 USD 01/20/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	AS-1787-01 HARDENED STOP BUSHING M09 03		
1000321299 00030	2.000 EA D 02/10/2000 GOLEMBOSKIMR MAY		
N R A NB Z	1,170.00 USD 01/20/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	"COPY" STAMP M09 02		
1000321300 00010	1.000 EA D 01/20/2000 GOLEMBOSKIMR MAY		
N R A NB Z	7.16 USD 01/20/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	102249 HOWARD D. HAPPY CO		
X	BOX OF LARGE BINDER CLEPS M09 02		
1000321300 00020	5.000 EA D 01/20/2000 GOLEMBOSKIMR MAY		
N R A NB Z	14.45 USD 01/20/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
REPORT COVERS	M09 02		
1000321300 00030	25.000 EA D 01/20/2000 GOLEMBOSKIMR MAY		
N R A NB Z	22.00 USD 01/20/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	WASTE RECEPTACLE M09 02		
1000321300 00040	1.000 EA D 01/20/2000 GOLEMBOSKIMR MAY		
N R A NB Z	33.78 USD 01/20/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	REMINGTON SHIPPING LABELS M09 47		
1000321346 00010	3,000.000 EA D 01/20/2000 GOLEMBOSKIMR MAY		
N R A NB Z	108.60 USD 01/20/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	102514 MAYFIELD PRINTING INC		
X	CARBIDE REAMERS M09 03		
1000321347 00010	3.000 EA D 01/20/2000 GOLEMBOSKIMR MAY		
N R A NB Z	24.51 USD 01/20/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	2486462 BALZERS TOOL COATING INC		
X	UPS RED CHARGES M09 03		
1000321347 00020	1.000 EA D 01/20/2000 GOLEMBOSKIMR MAY		
N R A NB Z	18.50 USD 01/20/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	PRECISION BENCH CENTER #09131301 M09 03		
1000323153 00010	2.000 EA D 01/31/2000 GOLEMBOSKIMR MAY		
N R A NB Z	3,862.32 USD 01/21/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	102641 MSC INDUSTRIAL SUPPLY		

MF1082

Remington Arms, Co., Inc.

Please deliver to:

Remington Arms Co., Inc.
Mayfield Plant
22 Rifle Trail
HICKORY KY 42051

Purchase order

Page

1

PO number/date

M017471 01/17/2000

Contact

Telephone

M. Morgan/502-856-4204

Fax Number/

Vendor: 105901

WELDUCTION CORP
22750 HESLIP DRIVE
NOVI MI 48375
TELEPHONE: 248 735-2800
FAX: 248 735-2821

Currency USD

ATTN: MR. MICHAEL DOERR

Item	Material	Quantity	Unit	Description	Unit Price	Per/Un	Net price
------	----------	----------	------	-------------	------------	--------	-----------

00010		1	EA	FLEXSCAN INDUCTION HEAT TREAT CENTER	153,500.00	EA	153,500.00
-------	--	---	----	--------------------------------------	------------	----	------------

Delivery date: 04/26/2000

MANUFACTURE AND PROVIDE TO REMINGTON PER WELDUCTION
QUOTE #99-113C DATED 01/14/2000, AND REMINGTON MACHINE
SPECIFICATION 710-03, ONE FLEXSCAN INDUCTION HEAT TREAT
CENTER.

ITEM 10:

START-UP, DEBUG, AND TEST RUN WILL BE COMPLETED AT
WELDUCTION PRIOR TO DELIVERY. A WRITTEN ACCEPTANCE
OF EQUIPMENT WILL BE REQUIRED FROM REMINGTON BEFORE
DELIVERY OF SAID EQUIPMENT. TRYOUT PARTS TO PRINT
SPECIFICATIONS WILL BE SUPPLIED TO WELDUCTION FOR
RUN-OFF, AT NO CHARGE. TO MEET THE MAY 12TH DEADLINE,
MACHINE MUST BE SHIPPED BY APRIL 26TH. RUN-OFF MUST
BE CONDUCTED BY APRIL 20TH.

ITEM 11:

INSTALLATION AND START-UP SERVICE WILL CONSISTS OF (3)
24 HOUR DAYS OF ASSISTANCE FROM A QUALIFIED FIELD
SERVICE ENGINEER PROVIDED BY WELDUCTION. THIS
INSTALLATION SHOULD TAKE PLACE BETWEEN APRIL 26TH AND
MAY 12TH FOR COMPLETION. WELDUCTION WILL PROVIDE A
FIELD SERVICE REP TO INSPECT INSTALLATION, AND INSTRUCT
OPERATING PERSONNEL AFTER INSTALLATION HAS BEEN COMPLETED.

OPTIONAL EQUIPMENT:

OPTIONS A THROUGH E, WILL NOT BE REQUIRED BY REMINGTON

MF1083

Purchase order

PO number/date

M017471 01/17/2000

Page

2

WELDUCTION CORP
22750 HESLIP DRIVE
NOVI MI 48375
TELEPHONE: 248 735-2800
FAX: 248 735-2821

Item	Material	Quantity	Unit	Description	Unit Price	Per/Un	Net price
------	----------	----------	------	-------------	------------	--------	-----------

AT THIS TIME.

MACHINE WARRANTY IS 12 MONTHS AFTER DELIVERY SET-UP.
PERISHABLE TOOLING AND CONTACT SURFACES ARE EXCLUDED.

PAYMENT TERMS: FOR 3% DISCOUNT
10% DOWN WITH PURCHASE ORDER
30% UPON COMPLETION OF ENGINEERING
30% UPON SUBSTANTIAL RECEIPT OF PURCHASED COMPONENTS
20% UPON EQUIPMENT SHIPMENT
FINAL 10% UPON INSTALLATION ACCEPTANCE, NET 45 DAYS
** INVOICING WILL BE REQUIRED **

TOTAL REMINGTON EXPENSE (EXCLUDING FREIGHT) SHOULD NOT
EXCEED \$148,895.00

Total net value USD

153,500.00

MF1084

Cost center 0000028200

Material Requisn. S C R Qty. I A	Item	Short text Requested qty. Ordered qty.	Un	Deliv. date Release date	Requester Trackg.no.	PGp	Mat. gp. Pint Sloc Spl. MC
- 1000321299	00020	SK-1787-01 SPECIAL 42BZ1 QUICK CHANGE			M09		03
N R A NB	Z	2.000 EA	D	02/10/2000	GOLEMBOSKIMR		MAY
				01/20/2000	HUTSONLR		
- 1000321299	00030	AS-1787-01 HARDENED STOP BUSHING			M09		03
N R A NB	Z	2.000 EA	D	02/10/2000	GOLEMBOSKIMR		MAY
				01/20/2000	HUTSONLR		
- 1000323153	00010	PRECISION BENCH CENTER #09131301			M09		03
N R A NB	Z	2.000 EA	D	01/31/2000	GOLEMBOSKIMR		MAY
				01/21/2000	HUTSONLR		
Desired vendor		102641			MSC INDUSTRIAL SUPPLY		

7/10 Charges

BARBER - 5.22.06r0011035

83

ME1085

Confidential - ~~Subsequent~~ - 5.22.06r0011035 Order
Williams v. Remington

Cost center 0000028200

Material Requisition S C R	Item Qty. I A	Short text Requested qty. Ordered qty.	Un Deliv. date Release date	PGP Requester Backg.no.	Mat. gp. Plnt SLoc SPL. MC
- 1000315827	00010 N R A NB Z Desired vendor	BARREL BASKET 18" HIGH X 36" DIAMETER 1.000 EA D 03/27/2000 102855 Lohn & Associates RECEIVER INSERT CMM FIXTURE #K-10400 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY
- 1000315829	00010 N R A NB Z Desired vendor	5390090 PHI ASSOCIATES RECEIVER INSERT PLUG GAGE # K-10401 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY
- 1000315829	00020 N R A NB Z	RECEIVER INSERT FUNCTION GAGE # K-10402 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY
- 1000315829	00030 N R A NB Z	SIDE PLATE COMPARATOR FIXTURE # K-10403 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY
- 1000316063	00010 N R A NB Z Desired vendor	5390090 PHI ASSOCIATES SIDE PLATE COMPARATOR SCREEN #K-10404 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY
- 1000316063	00020 N R A NB Z	SAFETY COMPARATOR FIXTURE #K-10405 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY
- 1000316064	00010 N R A NB Z Desired vendor	5390090 PHI ASSOCIATES SAFETY COMPARATOR SCREEN #K-10406 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY
- 1000316064	00020 N R A NB Z	BOLT STOP COMPARATOR FIXTURE #K-10407 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY
- 1000316065	00010 N R A NB Z Desired vendor	5390090 PHI ASSOCIATES BOLT STOP COMPARATOR SCREEN #K-10408 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY
- 1000316065	00020 N R A NB Z	BOLT HAND BLANK COMPARATOR FIX #K-10409 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY
- 1000316066	00010 N R A NB Z Desired vendor	5390090 PHI ASSOCIATES BOLT HAND BLANK COMPARATOR SCR #K-10410 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY
- 1000316066	00020 N R A NB Z	BOLT HEAD BLANK COMPARATOR SCR # K-10411 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY
- 1000316067	00010 N R A NB Z Desired vendor	5390090 PHI ASSOCIATES EJECTOR COMPARATOR FIXTURE # K-10412 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY
- 1000316068	00010 N R A NB Z Desired vendor	5390090 PHI ASSOCIATES EJECTOR COMPARATOR SCREEN #K-10413 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY
- 1000316068	00020 N R A NB Z	BOLT PLUG FUNCTIONAL GAGE # K-10414 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY
- 1000316069	00010 N R A NB Z Desired vendor	5390090 PHI ASSOCIATES BOLT PLUG INSERT COMPARATOR FIX #K-10415 1.000 EA D 02/24/2000	01/17/2000 HUTSONLR	M09 GOLEMBOSKIMR	TOOLING MAY

710
Purchase
per

BARBER - 5.22.06r0011036

Confidential - SHARRET - 5.22.06r0011036 Order
Williams V. Remington

MF1086

Cost center 0000028200

Material Requisition S C R Qty. I A	Item I A	Short text Requested qty. Un Ordered qty. Un	Deliv. date Release date	PGP Requester Trackg.no.	Mat. gp. Plnt Sloc SPL. MC
1000316070	00010	1.000 EA	D 02/24/2000	GOLEMBOSKIMR	MAY
N R A NB	Z		01/17/2000	HUTSONLR	
Desired vendor					
1000316070	00020	1.000 EA	D 02/24/2000	GOLEMBOSKIMR	MAY
N R A NB	Z		01/17/2000	HUTSONLR	
Desired vendor					
1000316071	00010	1.000 EA	D 02/24/2000	GOLEMBOSKIMR	MAY
N R A NB	Z		01/17/2000	HUTSONLR	
Desired vendor					
1000316072	00010	1.000 EA	D 02/24/2000	GOLEMBOSKIMR	MAY
N R A NB	Z		01/17/2000	HUTSONLR	
Desired vendor					
1000316072	00020	1.000 EA	D 02/24/2000	GOLEMBOSKIMR	MAY
N R A NB	Z		01/17/2000	HUTSONLR	
Desired vendor					
1000316073	00010	1.000 EA	D 02/24/2000	GOLEMBOSKIMR	MAY
N R A NB	Z		01/17/2000	HUTSONLR	
Desired vendor					
1000316074	00010	1.000 EA	D 02/24/2000	GOLEMBOSKIMR	MAY
N R A NB	Z		01/17/2000	HUTSONLR	
Desired vendor					
1000316074	00020	1.000 EA	D 02/24/2000	GOLEMBOSKIMR	MAY
N R A NB	Z		01/17/2000	HUTSONLR	
Desired vendor					
1000316080	00010	1.000 EA	D 01/18/2000	GOLEMBOSKIMR	MAY
N R A NB	Z		01/18/2000	HUTSONLR	
Desired vendor					
1000316080	00020	1.000 EA	D 01/18/2000	GOLEMBOSKIMR	MAY
N R A NB	Z		01/18/2000	HUTSONLR	
Desired vendor					
1000316080	00030	2.000 EA	D 01/18/2000	GOLEMBOSKIMR	MAY
N R A NB	Z		01/18/2000	HUTSONLR	
Desired vendor					
1000316080	00040	1.000 EA	D 01/18/2000	GOLEMBOSKIMR	MAY
N R A NB	Z		01/18/2000	HUTSONLR	
Desired vendor					
1000316081	00010	8.000 EA	D 01/20/2000	GOLEMBOSKIMR	MAY
N R A NB	Z		01/18/2000	HUTSONLR	
Desired vendor					
1000316081	00020	8.000 EA	D 01/20/2000	GOLEMBOSKIMR	MAY
N R A NB	Z		01/18/2000	HUTSONLR	
Desired vendor					

BARBER - 5.22.06/0011037

83

ME1087

Confidential - ~~SECRET~~ - 52250606041037e Order
Williams V. Remington

1/13/99

Cost center 0000028200

Material Requish. S C R Qty.	Item I A	Short text Requested qty. Ordered qty.	Un Un	Deliv. date Release date	PGp Requester Trackg.no.	Mat. gp. Plnt SLoc Spl. MC
- 1000290268	00010	.263 DIA A/C GUN DRILLS X 54" OAL			M09	03
N R B NB	Z	16.000 EA	D	01/31/2000	GOLEMBOSKIMR	MAY
Desired vendor		5380140 DANJON MANUFACTURING CORP		12/22/1999	HUTSONLR	
- 1000290268	00020	.269 CARBIDE BORE REAMER ON 54" TUBE			M09	03
N R B NB	Z	8.000 EA	D	01/31/2000	GOLEMBOSKIMR	MAY
				12/22/1999	HUTSONLR	
- 1000290268	00030	.280/.2715 CARBIDE COMB. BUT. RH 1T 10"			M09	03
N R B NB	Z	2.000 EA	D	01/31/2000	GOLEMBOSKIMR	MAY
				12/22/1999	HUTSONLR	
- 1000295956	00010	C-300360 BOLT HANDLE BLANK			M09	03
N R B NB	Z	50.000 EA	D	12/31/1999	GOLEMBOSKIMR	MAY
Desired vendor		106014 CAMPBELL'S MACHINE SHOP INC.		01/05/2000	HUTSONLR	
- 1000295956	00020	1-300329 BOLT HANDLE PIN			M09	03
N R B NB	Z	50.000 EA	D	12/31/1999	GOLEMBOSKIMR	MAY
				01/05/2000	HUTSONLR	
- 1000296261	00010	PARTS FOR THE TRIG ASSY FIXTURE CK10129			M09	03
N R B NB	Z	3.000 EA	D	12/22/1999	GOLEMBOSKIMR	MAY
Desired vendor		104762 G AND H TOOL & DIE, INC		01/05/2000	HUTSONLR	

83

CONFIDENTIAL

MF1088

Capital-Machinery

Part Name	Receiver	Operation Name	machine receiver
Part Number	300340	Operation Number	

Capital Required

Machine or Fixture	Dollars	Expected Delivery
Okuma LT-15 MY Twin Spindle/Twin Turret Turning Center	\$ 389,200.00	12 wks ARO
Manual Touch Setter for LT-15MY	\$ 22,203.00	
LNS THB 42-LC Bar Feeder (Single Bar)	\$ 16,570.00	
Okuma Part Catcher for RH Turret	\$ 11,385.00	
Side Chip Conveyor	\$ 10,530.00	
Barfeeder Modification	\$ 2,673.00	
Barfeeder Interface	\$ 2,420.00	
Extra Memory(2100 ft.)	\$ 3,710.00	
Signal Tower	\$ 1,400.00	
Tool Life Management	\$ 1,740.00	
G&L Discovery CMM	\$ 52,000.00	
Installation	\$ 3,651.82	
TOTAL CAPITAL	\$ 517,482.82	

GOSIGERinc.

January 20, 2000

Joe Zajk Mett Morgan
Remington Arms Company, Inc.
22 Rifle Trail
Mayfield, Ky. 42051

Dear Joe,

We are pleased to offer the following proposal for your consideration:

OKUMA Model Crown V Vertical Machining Center.

Machine Price	\$110,200.00
<u>Options Required:</u>	
Midaco M3020FL Pallet Changer	\$19,500.00
Cast Iron Option inc. Tslots	\$25,400.00
Midaco Factory Trained Installation	\$1,500.00
Haas HA5C/2 Indexer W/AC 125 closer	\$12,900.00
32 Tool ATC	\$7,070.00
50 Set work Coordinate	NC
Thru Spindle Coolant	\$10,620.00
1280 Tape Storage	\$3,070.00
Tool Life Management	\$1,914.00
Read Write Get Put for Haas Indexer	\$1,890.00
Lift Up Chip Conveyor	\$10,020.00
Prep for Lift Up Chip Conveyor	\$3,080.00
User Task II W/ I/O Variables	\$3,980.00
Total.....	\$185,744.00 W/Aluminum Pallets \$191,644.00 Cast Iron Pallets

Remington Price **\$163,744.00** Aluminum Pallets
Remington Price **\$169,204.00** Cast Iron T Slotted Pallets

DELIVERY: 4 to 6 Weeks
F.O.B: Charlotte, NC
TERMS: 10% Down, Net 25 Days or Gosiger Financial Program

Joe, Mett thank you for the opportunity of quoting on your requirements and we hope to be favored with your valued order.


Sincerely,

Michael T. Mooney
Michael T. Mooney, CMfgE
Engineering / Key Accounts Manager


KENTUCKY DIVISION
4104 Bishop Lane
Louisville, KY 40218
(502) 962-9889 Fax (502) 962-8595

MF1090

STERLING SINTERED TECHNOLOGIES, INC.

COPY
FYI
1/25

249 Rockwell St.
Winsted, CT 06098
Phone (860) 379-2753
Fax (860) 738-0664



To: Metty Macgarr Date: 1/25/00
Company: Remington Arms Co. Fax #: 270-856-3233
Subject: Revised Quotes From: Poland
Message:

Hello! Below are the updated quotes on the
Bolt Stop and Trigger

Q/A C-300345 Bolt Stop

20M @ \$223.60/M

40M @ \$191.95/M

120M @ \$188.85/M

Tooling \$5500

Q/A C-300435 Trigger

20M @ \$501.50/M/M

40M @ \$492.75/M

120M @ \$486.90/M

Tooling \$14100

Lead Time 10 weeks RPO

Questions? Please call me.

PAGE 1 of 1

**PRECISION POWDERED METAL
STRUCTURAL COMPONENTS
SELF-LUBRICATING BEARINGS**

270 856-3232

MF1091

QUOTATION

Quotation Number: 00011701
Date: January 17, 2000
Prepared By: Jim Mullineaux



**Megamet
Industries**

Powder Injection Molding

4073 Wedgeway Court • Earth City, MO 63045
314 739-4499 fax 314 739-5281

To: Remington Arms Co., Inc.
22 Rifle Trail
P.O. Box 99
Hickory, KY 42051
Attn. Metty Morgan

Phone: 270-856-4200
Fax: 270-856-3233

CONFIDENTIAL

RE: REVISED QUOTE FOR RFQ

LOCK TUMBLER RE-QUOTE

Quantity	Part Description	Description of Work	Price
1 ea	Mold	Metal injection mold	\$ 17,500.00
1 ea	Furnace Fixture	Furnace fixtures to hold parts during processing	\$ 2,500.00
20K pcs.	B300420	Metal injection molded Alloy FN02 parts per drawing	\$0.63 each
40K pcs.	B300420	Metal injection molded Alloy FN02 parts per drawing	\$ 0.60 each
60K pcs.	B300420	Metal injection molded Alloy FN02 parts per drawing	\$0.55 each
1 ea	Mold	Metal injection mold	\$ 15,000.00
1 ea	Furnace Fixture	Furnace fixtures to hold parts during processing	\$ 1,000.00
20K pcs.	B300336	Metal injection molded Alloy FN02 parts per drawing	\$ 1.50 each
40K pcs.	B300336	Metal injection molded Alloy FN02 parts per drawing	\$ 1.45 each
60K pcs.	B300336	Metal injection molded Alloy FN02 parts per drawing	\$ 1.35 each

* Notes: Mold cost is higher for B300420 because of the part's complex shape will require more slides in the mold.

DESIGN INFO: Complete, original, signed and dated print complete and ready for tooling design is required. A 3D solid model database in acceptable format if available is requested. Additional charges will apply if engineering time is required.

TOOLING: Tooling charges listed above include design and fabrication of said tools. Upon receipt of final tooling payment, customer will obtain ownership of those tools. Tooling charge is based upon maximum capacity stated. Tooling is guaranteed to last at least the lesser of 3 times the order quantity or 36 months unless there is a customer-originated design change.

PARTS: Parts will be supplied in the heat treated, surface finish, and surface coating conditions specified. Engineering reviews with the customer as well as sample pieces submitted will be used to evaluate acceptable mold design and molding and sintering practices with regard to gate location, shrinkage, appearance, and tooling design.

SAMPLES: Samples 10 weeks ARO and acceptance of purchase order by Megamet. See below for multiple orders.

CONFIDENTIAL

MF1092

FAX**GOSIGERinc.**

Date 3/2/00

Number of pages including cover sheet

2

TO:

Joe Gayle

Phone

Fax Phone (270) 856-3233

FROM:

Dan Gwinn

MATTHEW MACHINERY
DIVISION

Phone

502-962-9889

Fax Phone

502-962-8595

CC:

REMARKS:

☐

Urgent

☐

For your review

☐

Reply ASAP

☐

Please Comment

Joe:

① I did not quote freight & rigging, this would be easier and cheaper if handled by Remington, we can discuss.

② Also the 32 tool ATC option is not retrofittable

Call me
Charles
Dan

Thanks.

Dan Gwinn

Sales Manager

MF1093

GOSIGER Inc.

March 2, 2000

Remington Arms Co.
22 Rifle Trail
Hickory, KY 42051

Attn: Joe Zayk

I am pleased to quote the following Okuma Vertical Machining Centers for your consideration.

OKUMA CROWN V4018.....\$110,200.00

Options:

- Chip Conveyor.....\$13,108.00
- Tool Lift Management.....1,910.00
- Additional Tape Storage 1280M.....4,960.00
- Work Coordinate System 50 sets.....640.00
- Through-Spindle Coolant.....9,280.00

Total for all above.....\$140,098.00

- 32 Tool ATC additional.....10,719.00

OKUMA MX45 VAE.....\$ 89,200.00

Options:

- Chip Conveyor.....\$13,108.00
- Tool Lift Management.....1,910.00
- Additional Tape Storage 1280M.....5,080.00
- Work Coordinate System 50 sets.....640.00
- Through-Spindle Coolant.....9,648.00

Total for all above.....\$119,586.00

- 32 Tool ATC additional.....10,719.00

OKUMA CADET MATE.....\$ 78,700.00

Options:

- Chip Conveyor.....\$5,110.00
- Tool Lift Management.....1,910.00
- Additional Tape Storage 1280M.....6,660.00
- Work Coordinate System 50 sets.....640.00
- Through-Spindle Coolant.....5,040.00

Total for all above.....\$ 98,060.00

Dan Gwinn
Sales Manager



MATTHEW MACHINERY DIVISION

4104 Bishop Lane
Louisville, KY 40218
502-982-9889 FAX 502-962-8595

MF1094

QUOTATION

Quotation Number: 00011701
 Date: January 17, 2000
 Prepared By: Jim Mullineaux



**Megamet
Industries**

Powder Injection Molding

4073 Wedgeway Court - Earth City, MO 63045
 314 739-4499 fax 314 739-5281

To: Remington Arms Co., Inc.
 22 Rifle Trail
 P.O. Box 99
 Hickory, KY 42051
 Attn. Metty Morgan

Phone: 270-856-4200
 Fax: 270-856-3233

CONFIDENTIAL

RE: REVISED QUOTE FOR RFQ

LOCK TUMBLER RE-QUOTE

Quantity	Part Description	Description of Work	Price
1 ea	Mold	Metal injection mold	\$ 17,500.00
1 ea	Furnace Fixture:	Furnace fixtures to hold parts during processing	\$ 2,500.00
20K pcs.	B300420	Metal injection molded Alloy FN02 parts per drawing	\$0.63 each
40K pcs.	B300420	Metal injection molded Alloy FN02 parts per drawing	\$ 0.60 each
60K pcs.	B300420	Metal injection molded Alloy FN02 parts per drawing	\$ 0.55 each
1 ea	Mold	Metal injection mold	\$ 15,000.00
1 ea	Furnace Fixtures:	Furnace fixtures to hold parts during processing	\$ 1,000.00
20K pcs.	B300336	Metal injection molded Alloy FN02 parts per drawing	\$ 1.50 each
40K pcs.	B300336	Metal injection molded Alloy FN02 parts per drawing	\$ 1.45 each
60K pcs.	B300336	Metal injection molded Alloy FN02 parts per drawing	\$ 1.35 each

* Notes: Mold cost is higher for B300420 because of the part's complex shape will require more slides in the mold.

DESIGN RPO: Complete, original, signed and dated print complete and ready for tooling design is required. A 3D solid model database in acceptable format if available is requested. Additional charges will apply if engineering time is required.

TOOLING: Tooling charges listed above include design and fabrication of said tools. Upon receipt of final tooling payment, customer will obtain ownership of those tools. Tooling charge is based upon maximum capacity stated. Tooling is guaranteed to last at least the lesser of 3 times the order quantity or 36 months unless there is a customer-originated design change.


PARTS: Parts will be supplied in the heat treated, surface finish, and surface coating conditions specified. Engineering reviews with the customer as well as sample pieces submitted will be used to evaluate acceptable mold design and molding and sintering practices with regard to gate location, shrinkage, appearance, and tooling design.

SAMPLES: Samples 10 weeks ARO and acceptance of purchase order by Megamet. See below for multiple orders.

CONFIDENTIAL

MF1095

CONFIDENTIAL 83



MF1096



Date: 4/24/00

No. of pages including cover sheet: 6

Remington Arms Co., Inc.
R&D Technical Center
315 W. Ring Road
Elizabethtown, KY 42701

Phone: 270-789-7600
Fax: 270-737-9576

Please note our new area code.

TO:

From:

Matt G.

Mike R.

Phone

Fax Phone

CC:

Phone

Fax Phone

REMARKS:

☐ Urgent ☐ For your review ☐ Reply ASAP ☐ Please comment

TRIAGE & SEAR THIS W/ RETAINING CLIP.

PLEASE REVIEW AND ADD TO YOUR DRAWING FILE.


THESE ARE NEW PARTS SO MIETT WILL HAVE TO ORDER.

Mike

MF1097

Confidential - Submitter - 522-06-0011047
Williams v. Remington

Price \$2.00



CERTIFIED TO QS-9000

REGISTERED TO ISO-9001

1-800-55-ROTOR




ROTOR CLIP COMPANY, INC.
187 Davidson Avenue Somerset, New Jersey 08875-0461

732-469-7333 1-800-557-8867 Fax: 732-469-7898

Visit our site on the internet: rotorclip.com



MF1098

[illegible]

PLATED RINGS ADD (.02") TO MAXIMUM THICKNESS AND HEIGHT.
 2. NO. 3 THICKNESS FOR STAINLESS STEEL IS AS FOLLOWS TX-6-TX-9, 0.017; TX-4-TX-10H, 0.06".
 3. 4-TX-1B IS OPTIONAL THICKNESS (.015). ADD .05" TO RING HEIGHT VALUES (+.6 SHOWN
 4. 5-TX-3) OPTIONAL THICKNESS (.015) DEDUCT .06" FROM RING HEIGHT VALUES (1.6 SHOWN
 5. THICKNESS SPEC. OPTIONS SEE PAGE 94.

SHAFT DIAMETER INCHES				OUTSIDE DIAMETER		No Of Prongs	THICKNESS		T Tensile Load	WEIGHT Per 1000 Fos	Min. Distance From part end to shaft
D _s DEC			D _o mm	Tol	T		Tot				
FROM	To	FRAC									
	.080	.085	3/32	2.38	.000	3	D10	± .001	13	.09	.040
	.121	.126	1/8	3.17	.025	4			20	.11	.040
	.155	.157	5/32	3.96	.036	4			22	.17	.040
	.187	.189	3/8	4.77	.061	4			35	.20	.040
	.233	.240	7/16	5.58	.078	4	35	.28	.040	.040	
	.287	.291	-	8.10	.080	4	D15	± .002	40	.35	.080
	.343	.351	1/2	8.93	.080	4	D15	± .001	40	.38	.040
	.411	.423	5/8	9.22	.012	4			45	.26	.040
	.474	.476	3/4	9.63	.075	4			45	.27	.040
	.437	.439	3/4	11.1	.036	4			50	.47	.080
	.480	.502	1/2	12.7	.060	4	D15	± .002	50	.72	.025
	.580	.584	1 1/4	34.27	.012	4			50	.75	.020
	.623	.627	3/8	16.88	.075	7			50	.80	.080
	.745	.750	1 1/4	19.05	.000	8			50	.97	.060
	.873	.877	1 1/8	22.23	.125	10	10		50	1.1	.060
	.930	1.00	1	25.4	.050	10			65	1.2	.060

PLATED RINGS/DC .50" TO MAXIMUM THICKNESS AND HEIGHT
SIZES MAY BE AVAILABLE UPON REQUEST
FOR CHAIN DRIVES/SHAFTS MADE OF COLD ROLLED STEEL FOR AN EXPLANATION OF FORMULAS USED TO DERIVE
AND OTHER PERFORMANCE DATA CONTACT THE ROTOR CLIP ENGINEERING DEPT
UNLESS SPECIFICATIONS SEE PAGE 14

MATERIAL AND HEAT TREAT

MATERIAL _____

HEAT TREAT _____

HARDNESS _____

FINISH _____

HEAT TREAT AND COLOR TO BE DONE BY REMINGTON _____

FOR PART NO. 300465 ORDER
ROTOR CLIP COMPANY PART# TY-12

ALTERATIONS

SOFTWARES FILENAME - ERDINTAS3\CAD FILES\RIFLEY\MODEL 710\CONVERSION\300


A-300465

BARBER, 5-22-06 11051

SOLIDWORKS FILENAME - E:\RONTAS\CAO FILES\RIFLE\MODEL 710\CONVERTION\300454

UNLESS OTHERWISE NOTED
TOLERANCES ON DECIMAL DIMENSIONS ARE:
1 PLACE 1/16" TOLERANCE ± .005
2 PLACE 1/100" TOLERANCE ± .010
3 PLACE 1/1000" TOLERANCE ± .005
& ON FRACTIONAL DIMENSIONS ± 1/64"
& ON ANGULAR DIMENSIONS ± .00° - .30°
FINISHES ARE SPECIFIED BY FOOT MEAN
SQUARE RMS MICRO INCH ROUGHNESS
VALUES AND ARE THE MAXIMUM ROUGHNESS
ACCEPTABLE, UNLESS OTHERWISE SPECIFIED.
FINISH ROUGHNESS TO BE $\sqrt{7}$ OR BETTER

TERIAL AISI 1018
TREAT CARBURIZE (70% POTENTIAL)
HARDNESS RISEN 88-92 (008 MIN CASE)
FINISH BLACK OXIDE
HEAT TREAT AND COLOR TO BE DONE BY BENTON

[illegible]

M710	300464	SEAR RETAINING PIN
MODEL	PART NO.	PART USE
DER. BY DATE MDK 4-25-00	ORN. BY DATE JAW 4-25-00	CHK. BY DATE
TITLE SEAR RETAINING PIN		
NUMBER B-300464	SCALE 10:1	SUPERSEDES REFERENCE
Remington		

MF1101

Confidential - Subject - Subpoena
 BARBER - 5.22.2016
 Williams v. Remington

710	300463	TRIGGER PIVOT PIN
MODEL	PART NO.	PART USE
DES. BY DATE MCK 4-25-00	DRN. BY DATE JAW 4-25-00	CHK. BY DATE
TITLE TRIGGER PIVOT PIN		
NUMBER B-300463	SCALE 10:1	SUPERSEDES
	REFERENCE	
Remington.		

FD:
1 ETTYCOPY
6/20**Dollar A Day Auto & R.V.**2905 Lone Oak Road
Paducah, Kentucky 42001
(502) 554-5674Jack N. Clark
Billie Clark

Greg L. Clark

LOCAL

1 DAY ESTIMATE

"RETURNED BACK TO ME"

\$19.95

.39 MILE

\$14.00 INSURANCE

10 FT

83

29.95

.39 MILE

14

14 FT

.49 MILE

14

17 FT

39.95

.49 MILE

14

24+26
FT

\$80.00

DEPOSIT - PLUS, DEPENDS
ON ESTIMATED
COSTNOTE. BUSINESS CHECKS; CASH, CREDIT
CARDS

OVER

THANKS
GREG

MF1103

1-WAY RENTALS

\$80.⁰⁰ DEPOSIT ALWAYS

2 PRO RATED RATES TO ALL CITIES

2 INSURANCE IS OPTIONAL; COVERAGE IS ON TRUCK OR EQUIPMENT + CONTENTS.

a. DEPENDS ON MILES WHAT INS. COVERAGE WOULD BE.

3 MILES ALLOWED + \$40 PER MILES OVER ALLOWED

4 DAYS ALLOWED + \$40.⁰⁰ A DAY OVER ALLOWED

5 PLOS TX

EXAMPLE: NASHVILLE

10 FT	14 FT	17 FT	24 FT	26 FT
\$154. ⁰⁰	\$161. ⁰⁰	\$179. ⁰⁰	\$220. ⁰⁰	\$227. ⁰⁰
2 DAYS	2 DAYS	2 DAYS	2 DAYS	2 DAYS
189 MILES	189 Mi	189 Mi	189 Mi	189 Mi
28. ⁰⁰ INS.	28. ⁰⁰ INS	28. ⁰⁰ INS	28. ⁰⁰ INS	28. ⁰⁰ INS

MF1104

facsimile
transmittal

Copy

FYI

BUSHNELL**SPORTS OPTICS WORLDWIDE**

9200 Cody ~ Overland Park, KS 66214

To: Metty Morgan

Fax: (270) 856-3233

From: Chris Lalik

Date: June 5, 2000

Phone: (913) 752-3431

Fax: (913) 752-3580

Re: Quote

Pages: 2

CC: Drew Kohler

☐ Urgent☐ For Review☐ Please Comment☐ Please Reply☐ Please Recycle

Notes:

Thanks for working with me on this. Call me with any questions.

Chris

83

MF1105

BUSHNELL
SPORTS OPTICS WORLDWIDE

9200 Cody • Overland Park, Kansas 66214-1734
(913) 752-3400 • Fax (913) 752-3550

BUSHNELL

**BAUSCH
& LOMB**

06/05/00

Ms. Met Morgan
Remington Arms Company, Inc.
PO. Box 99
Hickory, KY 42051

Dear Mettie.

Thank you for giving BUSHNELL® the opportunity to bid on the 3-9x40 riflescope which will be used on your new rifle for WAL*MART. Given that we have similarly positioned brands, combining our products into a package deal makes a lot of sense. Hopefully this will be the start of additional projects.

We would like to offer our 3-9x40 Matte or Gloss SHARPSHOOTER® Details are as follows:

Price for 10000 pieces	25.00
Price for 20000 pieces	24.50
Scheduled Shipments assuming 10000 piece order	1000 pieces by the end of July 9000 pieces in August
Ongoing Order Lead time	90 Days
Terms	Net 45
Freight	F.O.B Kansas City
Warranty	Lifetime Limited
Instructions	Enclosed with product
Packaging	Shipped in bubble wrap

I will get you 2 samples for testing by June 15th, although they probably will be gloss. Drew thinks that a matte finish will probably be best, but if you decide that you prefer the gloss, that will be OK.

Please call with any questions. I look forward to working with you.

Sincerely,



Chris Lalik
Riflescope and HOLOsight Product Manager

MF1106

Morgan, Metty E.

From: Golemboski, Matt R.
Sent: Saturday, May 20, 2000 7:17 AM
To: Morgan, Metty E.
Subject: FW: trigger

reload the demand for transport orders to look like this.

5/31-200
6/20-400
6/29-300
7/12-600

*F109835
TLO
5/25
m m*

-----Original Message-----

From: Balio, John R.
Sent: Saturday, May 20, 2000 6:46 AM
To: Morgan, Metty E.; Ferreira, Louis B.
Cc: Haggerty, David C.; Golemboski, Matt R.; Traut, John A.
Subject: RE: trigger

Lou,

We cannot afford 1,500 triggers - MIM is behind so we are too. Mayfield needs 200 by 5/31 and 400 more by 6/20. Pick the remainder once MIM gets back on schedule.

-----Original Message-----

From: Morgan, Metty E.
Sent: Thursday, May 18, 2000 2:20 PM
To: Balio, John R.
Cc: Golemboski, Matt R.
Subject: trigger

05/18/2000

John,

I have created a transport order for part # F109835 trigger. PO # 5500004152. The due date for Mayfield is 6/01. Could you please see that these parts (1500) are shipped and transferred in the appropriate time to arrive into Mayfield by 6/01/00.

Thank you in advance.
Metty


Golemboski, Matt R.

From: Keeney, Mike
Sent: Friday, March 17, 2000 8:42 AM
To: Zajk, Joseph J
Cc: Golemboski, Matt R.; Morgan, Metty E.
Subject: 710 Safety Samples

Joe,
I received three safety samples from Square yesterday. Square further developed their tooling to produce more consistent contour and surface finish while eliminating the sharp burr. I spoke with Dan this morning and instructed him to proceed with this contour and to provide firm numbers for a secondary operation. Based on Marketing input, we need to coin the outside edge of the button and add serrations across the button. I asked for a .02 to .03 Radius on the top edge and serrations across the surface. Dan will provide an estimate and drawing details based on their capability.

Mike

CONFIDENTIAL 83



PAR 4 PLASTICS, INC.

(502) 965-9141
Fax (502) 965-9560

Princeton Road
P.O. Box 385
Marion, KY 42064

1/31/00

Ms. Metty Morgan
Remington Arms Co, Inc.
22 Rifle Trail
P.O. Box 99
Hickory, KY. 42051

Copy: Mr. Matt Golemboski
Mr. Joe Zajk
File

Dear Metty;

Per Remingtons request, we are pleased to quote the following:

- #1. Piece price change for 710 Latch, PN # C-3000362 reflecting material change to Ultem 1000 from originally quoted material Nylon-66. Annual volumes of 20,000 pieces.

COST \$411 EA..

PLEASE NOTE: Our cost for the Ultem 1000 material is \$ 7.25 per lb. as opposed to \$ 1.75 lb. for the Nylon. Also, scrap rates for this material run higher which is why the price had to increase. Once this job is in production we will evaluate cycle times and scrap to see if we can reduce the price.

- #2. 710 Stock Sub Assembly, which includes Par 4 Plastics, Inc. installing the Butt Spacer, Recoil Pad, and Screws, then installing the Latch and Spring Assembly. The Stock will then be placed into a divider sleeve and carton for shipping.

*Worst Case by Adding
Second Operator.*

COST \$ 1.05 EA.

*Will match internal price
for assy of butt plate.*

NOTE: It may be possible to incorporate this operation in with molding the stock if the cycle time permits. In which case the entire operation could be performed with one operator. Par 4 will work with Remington to see if this is feasible. If so, there would be no additional charge for this operation unless we agreed to change the cycle time, which could affect the molding price.

If you have any questions, or I can be of any assistance, please let me know.

*2.5 min Press Cycle Time
For Stock Mold.*

SINCERELY
PAR 4 PLASTICS, INC.

Sam Todd
SAM TODD
DIR. SALES & MARKETING

MF1109

1/16 LATCH 2X PRICE INCREASE.

\$2. - \$2.25 / 16 FOR GREY Bishop Custom Color.

\$0.91 WAS THE ESTIMATE BECAUSE WE SPECIFIED
GREY.

WE COULD GO 597 GREY.

CONFIDENTIAL

MF1110

Golemboski, Matt R.

From: Keeney, Mike
Sent: Thursday, January 20, 2000 2:21 PM
To: Russo, Alfred D.; Kohler, Drew; Zajk, Joseph J; Golemboski, Matt R.
Cc: Diaz, Danny
Subject: M/710 Cosmetic Issues

I would like to set up a conference call to discuss the outstanding 710 issues. I realize Al and Drew will be busy catching up from the SHOT show, so I will leave the time up to them. We need to review the issues as soon as possible, preferably by 1/27. I will ship the M/710 cosmetic sample to Drews attention. The sample is exactly as Al saw it during his visit to E-town. The safety arm is cosmetically correct but the movement is not. Al and Drew please review the cosmetics, prior to the conf. call, in reference to:

synthetic part colors
box bottom artwork
trigger - smooth finger radius
safety button
barrel and receiver rollmarks

Al and Drew, when you get this message and have a chance, give me a call to set up a time.

Thanks
Mike

CONFIDENTIAL 83

Confidential

Remington Arms Co.

Memo

To: 710 team
From: Matt Golemboski
CC: Joe Zajk
Date: 01/13/00
Re: M/710 lock tumbler (B-300420-A)

The lock tumbler blank 300420 was not available at the time of the estimate, the white paper did not reflect the addition of the tooling, estimated cost \$35,000. This tool should be made in Ilion to be consistent in processing with all other safety locks. The development time would be decreased, as well.

If the tool has not been quoted through Ilion, make sure that happens and the tool is ordered ASAP.

Confidential

Remington Arms Co.

Memo

To: 710 team
From: Matt Golemboski
CC: Joe Zajk
Date: 01/13/00
Re: M/710 Magazine Spring 300405

During the initial quoting process the magazine spring did not have a print. The M/700 magazine spring was used for costing. In October the design of the magazine spring 300405 was received. This was quoted by at least two people F&G Multislide and North American Spring and Stamping. Brainin should be in this mix, because we may want to ship the box bottom and follow from Par 4 to Brainin and receive a part complete. North American should be dropped due to the comments about quality on the quote, I do not want to purchase a blank and have to heat treat it.

The White Paper listed the part at \$0 capital and \$ 0.42 each (ref part #17026). The F&G quote was \$.55 each, and 24 weeks for production parts.

MF1113

Confidential

Remington Arms Co.

Memo

To: 710 team
From: Matt Golemboski
CC: Joe Zajk
Date: 01/13/00
Re: M/710 Trigger Pt#300435

The white paper was based on the Iliion SAP cost of \$1.53 for the M/700 trigger C-15280. We requested the serrations be removed from the trigger bow to get a trigger per Sterling Sintered Quote #2965A for \$0.37 each and a capital charge of \$15,225 that was not in the white paper budget. This expense should be made and a new tool purchased. The tool has a payback of 8 months and is justified.

Some of the necessary notes are not on the print. This can be followed after the PO is placed.

STERLING SINTERED TECHNOLOGIES, INC.

P.O. BOX 1057 • WINSTED, CONNECTICUT 06098
(860) 379-2753 • FAX: (860) 738-0664

Q U O T A T I O N

NUMBER 2965A

DATE 10/06/99

TO REMINGTON ARMS CO., INC.
ATTN: MATT GOLEMBOSKI
MAYFIELD PLANT
22 RIFLE TRAIL
HICKORY KY 42051

SHIP
TO

PH 270/856-4204 Fax 270/856-3233

TERMS		SHIP VIA		SALES PERSON	PAGE
NET 30 DAYS				633	1
QUANTITY	DESCRIPTION	UNIT PRICE	AMOUNT		
	Part # C-15280				
	TRIGGER				
	Rev 31				
	Ref: NO SERRATIONS				
20,000		377.10/M	7,542.00		
40,000		367.55/M	14,702.00		
120,000		347.70/M	41,724.00		
	Misc Charges:				
	TOOLING		15,225.00		
* PLEASE NOTE: QUOTED WITH NO SERRATIONS					
50% OF TOOLING CHARGE DUE WITH PURCHASE ORDER					
BALANCE UPON APPROVAL OF TOOLING SAMPLES.					
TOOLING SAMPLES WILL BE SHIPPED 12 WEEKS ARO					
PRODUCTION TO FOLLOW TOOL APPROVAL BY 6-8					
WEEKS UNLESS CUSTOMER ACCEPTS RESPONSIBILITY					
FOR PRODUCTION, GIVEN THAT IT MEETS THE PRINT					
THIS QUOTE IS GOOD FOR 30 DAYS FROM THE QUOTE					
DATE.					
OUR REVISION CONTROL PROCEDURE REQUIRES THAT					
PRINT REVISION LEVELS ACCOMPANY ALL PURCHASE					
ORDERS. PLEASE ASSIST US IN OUR CONTINUOUS					
IMPROVEMENT PROCESS.					
THANK-YOU FOR THE OPPORTUNITY TO QUOTE.					
ANN DELUTRIE					

MF1115

CONFIDENTIAL 83

WEEKLY UPDATES

MF1116

Golemboski, Matt R.

From: Helmer, Gerald A.
Sent: Tuesday, January 18, 2000 4:04 PM
To: Truax, Sheldon F.
Cc: Zajk, Joseph J; Golemboski, Matt R.; Gooch, Jim C.; Chavis, William T.; Morgan, Metty E.
Subject: Coloring Racks

Shelly, Jimmy Gooch has quoted to build 6 racks for coloring M/710 barrels, bolt bodies and bolt heads (4 racks for barrels and 2 racks for the bodies and heads). His total quote for material and labor is \$3,831.98 versus a vendor quote of \$12,220.00 (diff. of \$8,388.02). He will order material 1/19/00 and a sample of each rack is to be completed in 2 to 3 weeks. The barrel racks will hold 50 barrels each and the two racks for bodies and heads will hold 100 bodies and 100 heads on each rack.

CONFIDENTIAL 83

Golemboski, Matt R.

From: Zajk, Joseph J
Sent: Tuesday, January 18, 2000 1:16 PM
To: Connell, Chris
Cc: Golemboski, Matt R.; Morgan, Metty E.
Subject: RE: HS Code

I agree. Go ahead and use that code. I don't recall off hand if the parts for our plant were to have the freight charges paid for by the supplier, but if the bolt body & receiver have the same stipulation (supplier to pay freight & shipping charges), we want the same note added to your addendum stating "Remington is not the importer of record".

-----Original Message-----

From: Connell, Chris [mailto:CConnell@freemarkets.com]
Sent: Tuesday, January 18, 2000 11:57 AM
To: 'Zajk, Joseph J'
Subject: FW: HS Code
Importance: High

Joe

Sorry for the confusion. HS stands for the Harmonized System (Harmonized Commodity Description And Coding System) which is used by the government to classify items for duty. Below is Ilion's response and I think you would probably use the same one. It stands for: parts or accessories of shotguns or rifles. Ill use this if you concur.

Chris

-----Original Message-----

From: Rabbia, James A. [mailto:rabbiaja@remington.com]
Sent: Monday, January 17, 2000 4:41 PM
To: 'Connell, Chris'
Subject: HS Code

I talked to our logisitics guys and they told me the HS code for choke tubes is HS9305290000

Also they have great concern that even though we are requesting all freight and duty be paid for by the supplier we may be still responsible for the importing. Therefore they would like you to specify in your addendum that "Remington is not to the importer of record". The importer of record needs to be the supplier.

Remington Arms, Co., Inc.

Please deliver to:

Remington Arms Co., Inc.
Mayfield Plant
22 Rifle Trail
HICKORY KY 42051

Purchase order

Page

1

PO number/date

M018020 03/24/2000

Contact

Telephone

M. Morgan/502-856-4204

Fax Number/

Vendor: 103212

AUTOMATIC SWISS CORPORATION
PO BOX 416
ADDISON IL 60101
TELEPHONE: 630-543-3888
FAX: 630-543-1486

Delivery : UPS UPS 3rd Party Billing (922W20)
Terms of pmt: Within 45 days Due net

Currency USD

** ATTN: MR. JIM RUPPRECHT **

83

Item	Material	Quantity	Unit	Description	Unit Price	Per/Un	Net price
------	----------	----------	------	-------------	------------	--------	-----------

00010	F300329	9,500		710 BOLT HANDLE PIN			
		20,000.000	EA		0.14	EA	2,800.00

MANUFACTURE PER REMINGTON DRAWING SPECIFICATIONS.
DRWG. #A-300329 REV 2

REMINGTON OBLIGATION TO QUANTITY SHOWN WILL BE BASED ON
ACCEPTANCE OF THE FIRST ARTICLE APPROVAL SAMPLE LOT OF 50 PIECES,
TO BE IN MAYFIELD PLANT NO LATER THAN DATE SHOWN.

PRICE SHOWN PER QUOTE DATED 12-10-1999 FROM JIM TO METT.
AUTOMATIC SWISS CONTACT IS MR. JIM RUPPRECHT AT 630-543-3888
PLEASE CONTACT METT MORGAN WITH ANY DELIVERY SCHEDULE PROBLEMS AT
270-856-4204 PINS TO BE BLACK OXIDED, COMPLETE UPON ARRIVAL.

Please deliver according to the following schedule:

Qty.	Unit	Delivery date	Time
10,000.000	Each	05/10/2000	00:00:00
10,000.000	Each	11/20/2000	:

00020		NON-RECURRING ENGINEERING CHARGE	
	1.000 EA	450.00 EA	450.00
Delivery date		05/10/2000	

Total net value USD 3,250.00

5-8-00 5000056.99

MF1119

Automatic Swiss Corp.

• SWISS SCREW MACHINE PRODUCTS •

1130 W. National Avenue • P.O. Box #416 • Addison, Illinois 60101

Phone: (630) 543-3888

Fax #: (630) 543-1486

38081

SHIP TO

Remington
22 Rifle Tray
L Hickory, Ky 42050

Shipped Via UPS Third Party Date 5/24/06

DESCRIPTION

QUANTITY

10,500 2# 300327
30 m018020

2 Boxes
5250pc 231

Box Handle Pin
F300327

Received By _____

UPS Tracking #'s
12 6 20 472 03 100 7134 9
11 11 1358

CONFIDENTIAL

MF1120

Golemboski, Matt R.

From: Morgan, Metty E.
Sent: Wednesday, May 31, 2000 9:41 AM
To: Golemboski, Matt R.
Cc: Hobbs, Janice M.; Chamblee, Danny
Subject: F300329 Pins

05/31/2000

Per Peter at Automatic Swiss, they ran the entire order when they ran this pin. He checked his records, and they are as follows: Bolt Handle Pin for 710
ran 21,600
shipped to Mayfield 10,500 in two boxes 23# ea.
remaining quantity on their shelf is 11,580 ea (Peter checked their stock today)

This means that we did receive 10,500 and we have either misplaced them or lost them. We need to look further for them.

Mett

CONFIDENTIAL 83

Vendor	Part#	Direct Material	Direct Labor	Packaging	OH	Freight	Landed Cost	Unit Cost
Remington	300340	2.18	0.06	0	3.04	0	0	5.28
TNH	300340	1.21	0.57	0.09	2.8	0.47	0.17	5.31
Hauser	300340	1.4	1.26	0.02	4.21	0.11	0	7
Impro	300340	0.545	1.45	0.103	2.57	0.31	0.2	5.1875
Delta Max to Min		0.855	0.88	0.083	1.64	0.36	0.2	1.8125
Remington	300339	0.74	0.03	0	1.2	0	0	1.97
THN	300339	0.33	0.28	0.03	1.15	0.19	0.07	2.05
Hauser	300339	0.59	0.46	0.02	1.54	0.02	0	2.63
Impro	300339	0.178	0.57	0.04	1.035	0.1225	0.099	2.04

	Receiver	Revised Receiver	Revised Bolt Body
	597	710	710
Run Time	0.0530	0.0058	0.0033
Material (inclu	3.40	2.18	0.74
Labor	0.56	0.06	0.03
Incremental Overhead			
Employee Ben	0.32	0.04	0.02
Tooling Costs	0.30	1.43	0.29
Deprciation	0.32	1.38	0.80
Property Taxes (.008 of Fixed			
Asset Cost	0.04	0.11	0.05
Electricity (esti	0.02	0.08	0.04
	4.96	5.28	1.98

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

02/03/00

C:\WINDOWS\Desktop\710 Capital & Start up Costs.xls\710 capital by operation

In House Capital

Part Name	Operation	Equipment	Capital Required	Capital Actual	(Under)/ Over	Date Ordered	Expected Delivery Date	PO #
Barrel	Cut off		\$0		0			
	Drill	cones	\$9,960	0	(9,960)	canceled		
	Ream		\$0		0			
	Rifle	gages	\$9,800		(9,800)			
	Wash & Stress Relieve	baskets	\$6,900		(6,900)			
	Turn	gages	\$10,100		(10,100)			
	Face & Chamber	gages	\$33,300	23,595	(9,705)			See BBL Capital OP. 70
	Face & Chamber	machine	\$222,880	226,500	3,620	12/21	4/7	M017457
	Cut off and Crown	chuck	\$15,000		(15,000)			
	wash and eddy current test	machine	\$75,000		(75,000)			
	Induction Harden	machine	\$166,000	153,500	(12,500)	1/17	4/20	M017471
	Inspect Hardness	machine	\$12,000	13,800	1,800	1/28	2/29	M016619
	Drill and tap sight	fix & gages	\$7,600		(7,600)			
	Roll mark	fix & gages	\$6,300		(6,300)			
	Angularity Straighten	fix & gages	\$3,500		(3,500)			
	Centerless Polish		\$0		0			
	Glass Bead Blast	fixtures	\$2,500		(2,500)			
	Color	racks	\$6,000		(6,000)			
Bolt Head	Inspect Purchased Part							
	Blank	gage	\$2,500		(2,500)			
	Superabrasive Grind Lugs	fix & gage	\$43,800		(43,800)			
	CNC Machine Bolt Face							
	Complete	fix & gage	\$174,784		(174,784)			
	CNC Machine Cam Cuts							
	Ejector Retaining Pin Hole	fix & gage	\$15,000		(15,000)			
	CNC Machine Bolt Head							
	Retaining Pin Hole	fix & gage	\$15,000		(15,000)			
	Punch Pin Extractor							
	Rotation Notch	fix & gage	\$10,000		(10,000)			
	Vendor Heat Treat		\$0		0			
Bolt Body	Inspect for Hardness		\$0		0			
	Black Oxide		\$0		0			
	Inspect Purchased Part							
	Blank	gage	\$2,000		(2,000)			
	Machine Cam Cuts	machine	\$0		0			
	Assemble Braze Bolt	machine	\$90,000	59,635	(30,365)	31-Jan	8-May	M17490
	Deplate	tanks	\$9,500		(9,500)			
Receiver	Eddy Current Test		\$0		0			
	Glass Bead Blast	fix	\$2,500		(2,500)			
	Black Oxide		\$0		0			
	Inspect Purchased Part							
	Blank	gage	\$2,500		(2,500)			
	Machine A-load	Machine	\$461,831		(461,831)			
	CMM		\$52,000	52000	0			
	Machine B-load		\$0		0			
	Vibratory tumble deburr		\$0		0			

MF1123

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

02/03/00

C:\WINDOWS\Desktop\710 Capital & Start up Costs.xls\710 capital by operation

Barrel

Assembly	Press Receiver to Barrel	fixture	\$0	0
	Inspect for straightness	gage	\$3,500	6000 2,500

Final

Assembly	Gallery	100yd range	\$100,000	(100,000)
		snails	\$30,000	(30,000)
		HVAC	\$25,000	(25,000)
		other	\$10,000	15202 5,202
			\$100,000	(100,000)
			\$65,000	(65,000)

TOTAL IN HOUSE CAPITAL	\$1,801,755	550,232	(\$1,251,523)
------------------------	-------------	---------	---------------

Purchased Parts

Part #	Part Name	Capital	Tool	Capital Actual	Date Ordered	Expected Delivery Date	PO #
300327	Receiver Insert	48,000	Mold	45,227	1/20	3/29	M017478
300333	Side Plate	10,000	Stamping Die	7500	1/20	4/11	M017491
300334	Safety Arm	23,880	Stamping Die	19,900	1/26	2/28	M017486
300345	Bolt Stop	6,820	Pin	5500	1/25	3/15	M017477
300361	Recoil Bracket	2,225	Stamping Die	500	1/19	3/27	M017484
300360	Bolt Handle Blank	12,800	Invest Cast Die	6885	1/24		
300366	Bolt H. Braze Shim	0	Use Paste	0	canceled		
300368	Bolt Plug	38,088	Mold	38,000	12/14	3/21	M017443
300336	Firing pin head	23,000	MIM Mold	16,000	1/14	3/16	M017470
300362	Mag Latch	23,480	Mold	31,806	1/11	4/24	M017465
300363	Magazine Box	28,000	Mold	0	1/13	3/9	
300364	Magazine Follower	33,300	Mold	0	see Mag Bottom		M017466
300365	Magazine Bottom	47,880	Mold	73,786	1/12	4/17	M017466
	Stock	150,300	Mold	145,300	12/13	3/29	M017435
	Stereoam Bed	0	Die	0			
	PPI	38000	See PPI Detail	13000			
	} follower and box bottom family mold						
TOTAL VENDOR CAPITAL		\$495,773		\$ 403,464	(92,309)		

Addition Items Unbudgeted

Trigger	0	PM Die	16,000	16,000	14-Jan	16-Mar	M01740
Bolt Plug Insert	0	Extrusion die	2250	2,250	20-Jan	29-Mar	M017479
Tumbler	0	MIM Mold	20,000	20,000	20-Jan	29-Mar	M017480
Micro Centric Chuck	0	Chuck head	3645	3,645	21-Jan	10-Feb	M016555
Magazine Spring	0	Stamping Die					

TOTAL UNBUDGETTED	41,895	41,895
-------------------	--------	--------

Total Budget	\$2,297,528	Outstanding Purchases	\$833,784
Total Committed	\$ 995,591	Remainder to Budget	\$840,106
Remaining	\$1,301,937	Projected Capital Spending Over/(under)	(6,322)
Free Markets Avoidance	\$461,831		
Remainder to Budget	\$840,106		

About \$30,000 additional dollars will be available with outsourcing the bolt head

MF1124

710 Capital & Start up Costs

Barrel Capital - Line item Detail

	Item	Estimated Price	Actual Price	Date Ordered	Date Due	PO Number
	Air Gauge	\$ 6,080.00				
	Basket	\$ 4,708.00				
	Basket	\$ 4,708.00				
	Profile Gauge	\$ 5,000.00				
OP 70	AIR GAGE, SETRINGS, MASTER TAPER	\$ 6,390.00	6393	28-Jan	28-Feb	M016617
OP 70	SHOULDER DEPTH GAGE W/MASTER AND DESIGN COST	\$ 3,780.00	8732	25-Jan	31-Mar	M016586
OP 70	THROAT DEPTH GAGE W/MASTER AND DESIGN COST	\$ 3,780.00				
OP 70	NECK DEPTH GAGE W/MASTER AND DESIGN COST	\$ 3,780.00	8470	25-Jan	31-Mar	M016586
OP 70	2.995 LENGTH GAGE	\$ 3,500.00				
OP 70	HEADING GAGE, HEADING PLUGS	\$ 9,240.00				
	Okuma LB-300 MY 250T Space Turn Lathe	\$ 201,700.00	226,500	12/21	4/7	M017457
	Thru-Spindle Coolant	\$ 6,669.00				
	Hi-Pressure Coolant	\$ 981.00				
	Manual Touch Setter	\$ 3,200.00				
	Extra Memory (2100 ft)	\$ 3,710.00				
	Chip Conveyor	\$ 6,620.00				
	Installation	\$ 2,138.22				
	Clamping Chuck	\$ 15,000.00				
	Sight Hole location Fixture - Design & Build	\$ 7,040.00				
	Sight Hole Position Gage - Design & Build	\$ 6,875.00				
	Induction Hardening Machining	\$ 166,000.00	153,500	1/17	4/20	M017471
	Rockwell 20B/T Hardness Testers	\$ 14,800.00	13800	1/28	2/29	M016619
	Installation	\$ 766.26				
	wash and eddy current test	\$ 75,000.00				
	New Barrel Ejection System for Ilion's Press Machine	\$ 5,000.00				
	Bench centers	\$ 4,530.00				
	Hydraulic Press	\$ 5,000.00				
	Roll Mark Fixture - Design and build	\$ 3,730.00				
	Color Racks	\$ 6,000.00				
	Glass Bead Fixture	\$ 2,500.00				
	Locator/Roller Adapter	\$ 1,500.00				
		\$ 584,245	417395			
			\$ (166,850)			

Additional Non Capital items that were included as capital tooling in the estimate

.708 C'BORE PLUG GAGE	\$ 67.00
.7045 C'BORE PLUG GAGE	\$ 67.00
C'BORE DIAL GAGE	\$ 550.00
PISTOL GRIP INDICATOR	\$ 500.00
CHAMFER GAGE	\$ 220.00
.325 PLUG GAGE W/DESIGN	\$ 960.00
FORM GAGE/LOCKING LUG W/DE	\$ 570.00

Barrel Capital Sheet

MF1125

710 Capital & Start up Costs

Item	Estimated Price	Actual Price	Date Ordered	Date Due	PO Number
G&L Retrofit	\$ 10,000.00	13000	14-Dec	17-Jan	M016377

TOTAL PPI

\$13,000

PPI Capital

83

MF1126

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

02/03/00

710 Start Up Costs White Paper vs Actual

C:\WINDOWS\Desktop\710 Capital & Start up Costs.xls\Start Up Costs

	White Paper Costs	Actual Costs						Total	(Under)/ Over
		Aug-99	Sep-99	Oct-99	Nov-99	Dec-99	Jan-00		
Direct Labor	44,537.04							-	(44,537.04)
From Overhead									
Setters	25,914.48			1,394.36				1,394.36	(24,520.12)
Maintenance	27,083.36							-	(27,083.36)
EBs	56,570.23			648.62				648.62	(55,921.61)
Other Costs									
Travel	10,124.93	124.93		1,303.39	3,168.68	(1,010.34)	202.37	4,289.03	(5,835.90)
Material for Receiver	2,175.00		1,425.00					1,425.00	(750.00)
Material for Bolt Body	3,000.00		750.00					750.00	(2,250.00)
Material for 1,000 Learning Guns (\$43.86/ea)	43,860.00							-	(43,860.00)
Material for 60 T&P Guns (\$43.86/ea)	2,631.60							-	(2,631.60)
Material for 30 DAT Guns (\$43.86/ea)	1,315.80							-	(1,315.80)
15,000 rns of Ammo	3,000.00							-	(3,000.00)
Disassembly & Rearrange	6,000.00							-	(6,000.00)
Tooling & Inspection	64,015.47		16,503.92	15,521.26	4,735.20	2,949.01		39,712.39	(24,303.09)
Prototype Parts	32,000.00		149.75		23,780.00		765.00	24,694.75	(7,305.25)
Material Handling Purchases	58,000.00						3,862.32	3,862.32	(54,137.68)
Miscellaneous	36,906.85				1,288.00		1,638.77	2,926.77	(33,980.08)
1999 startup Costs	417,134.76	124.93	18,828.67	19,367.63	32,974.88	1,938.67	6,468.46	79,703.24	(337,431.52)

Golemboski, Matt R.

From: Golemboski, Matt R.
Sent: Friday, January 14, 2000 11:46 AM
To: Bristol, II Ronald H.
Subject: m710

Just a quick update on M/710

Total capital committed to date	\$530,000
Actual Capital outlay to date	\$133,000 (downpayments)
Capital to be committed 1st quarter	\$475,000 (downpayments)

Tooling is being ordered. Not all designs are firmed (safety arm and bolt handle) is the main concern. Progress is gaining speed on our end, slow start getting everyone organized.

I will be out of the office on Tuesday and Wednesday (1/18-1/19/99) to go to a possible 710 bolt head vendor in Lexington, KY in effort to reduce machining in plant and to review M710 and NAS in E'town on Wednesday. Longo should be ready begining of February to take customer service parts. After that I will announce warehouse changes to come and start D&R of the warehouse in February. I will try to send you an update each week on the status of the spending and performance to the original plan that will be more complete than this.

Matt Golemboski

CONFIDENTIAL 83

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

01/21/00

C:\windows\TEMP\Book1.xls]710 capital by operation

In House Capital

Part Name	Operation	Equipment	Capital Required	Capital Actual	Date Ordered	Expected Delivery Date
Barrel	Cut off		\$0			
	Drill	cones	\$9,960			
	Ream		\$0			
	Rifle	gages	\$9,800			
	Wash & Stress Relieve	baskets	\$6,900			
	Turn	gages	\$10,100			
	Face & Chamber	gages	\$33,300			
	Face & Chamber	machine	\$222,880	221,500	12/21	4/7
	Cut off and Crown	chuck	\$15,000			
	wash and eddy current test	machine	\$75,000			
	Induction Harden	machine	\$166,000	148,950	1/17	4/20
	Inspect Hardness	machine	\$12,000			
	Drill and tap sight	fix & gages	\$7,600			
	Roll mark	fix & gages	\$6,300			
	Angularity Straighten	fix & gages	\$3,500			
	Centerless Polish		\$0			
	Glass Bead Blast	fixtures	\$2,500			
	Color	racks	\$6,000			
Bolt Head	Inspect Purchased Part					
	Blank	gage	\$2,500			
	Superabrasive Grind Lugs	fix & gage	\$43,880			
	CNC Machine Bolt Face					
	Complete	fix & gage	\$174,784			
	CNC Machine Cam Cuts					
	Ejector Retaining Pin Hole	fix & gage	\$15,000			
	CNC Machine Bolt Head					
	Retaining Pin Hole	fix & gage	\$15,000			
	Batch Form Extractor					
	Rotation Notch	fix & gage	\$10,000			
	Vendor Heat Treat		\$0			
	Inspect for Hardness		\$0			
Bolt Body	Black Oxide		\$0			
	Inspect Purchased Part					
	Blank	gage	\$2,000			
	Machine Cam Cuts	machine	\$0			
	Assemble Braze Bolt	machine	\$90,000			
	Deplate	tanks	\$9,500			
	Eddy Current Test		\$0			
Receiver	Glass Bead Blast	fix	\$2,500			
	Black Oxide		\$0			
	Inspect Purchased Part					
	Blank	gage	\$2,500			
	Machine A-load	machine & CMM	\$513,831			
	Machine B-load		\$0			

REMINGTON ARMS COMPANY, INC.
FIREARMS - MAYFIELD

01/21/00

C:\windows\TEMP\Book1.xls]710 capital by operation
Vibratory tumble deburr

\$0

Barrel

Assembly	Press Receiver to Barrel	fixture	\$0
	Inspect for straightness	gage	\$3,500

**Final
Assembly**

Gallery	100yd range	\$100,000
	snails	\$30,000
	HVAC	\$25,000
	other	\$10,000
		\$100,000
		\$65,000

\$1,801,755

Purchased Parts

Part #	Part Name	Capital	Tool	Capital Actual	Date Ordered	Expected Delivery Date
300327	Receiver Insert	48,000	Mold			
300333	Side Plate	10,000	Stamping Die			
300334	Safety Arm	23,880	Stamping Die			
300345	Bolt Stop	6,820	PM			
300361	Recoil Bracket	2,225	Stamping Die	550	1/19	3/15
300360	Bolt Handle Blank	12,800	Invest Cast Die			
300366	Bolt H. Braze Shim	0	Use Paste			
300368	Bolt Plug	38,088	Mold	38,000	12/14	3/21
300336	Firing pin head	23,000	MIM Mold	16,000	1/14	3/16
300362	Mag Latch	33,480	Mold	31,806	1/11	4/24
300363	Magazine Box	28,000	Mold	12,500	1/13	3/9
300364	Magazine Follower	33,300	Mold	-		
300365	Magazine Bottom	47,880	Mold	73,786	1/12	4/17
	Stock	150,300	Mold	145,300	12/13	3/29
	Styrofoam Bed	0	Die			
	PPI	38000				
		\$495,773				
	Total	\$2,297,528				
	Installation	\$0				
		<u>\$2,297,528</u>				

MF1130

REMINGTON ARMS COMPANY, INC.

01/21/00

FIREARMS - MAYFIELD

710 Capital White Paper vs Actual

C:\windows\TEMP\[710 Capital Start up Costs.xls]Capital Spend Out

Barrel	White Paper	Vendor	PO #	Amt	(Under)/ Over
cones	9,960				(9,960)
gages & fixtures	73,100				(73,100)
baskets	6,900				(6,900)
machine	222,880			221,500	(1,380)
chuck	15,000				(15,000)
machine	75,000				(75,000)
machine	166,000			148,950	(17,050)
machine	12,000				(12,000)
racks	6,000				(6,000)
Total	586,840			370,450	(216,390)
Bolt Head					
fix & gage	42,500				(42,500)
Superabrasive Grind Lugs	43,800				(43,800)
CNC Machine	174,784				(174,784)
Total	261,084			-	(261,084)
Bolt Body					
gage & Fixture	4,500				(4,500)
machine	90,000				(90,000)
tanks	9,500				(9,500)
Total	104,000			-	(104,000)
Receiver					
fix & gage	2,500				(2,500)
machine	513,831				(513,831)
Total	516,331			-	(516,331)
Range					
100yd range	290,000				(290,000)
snails	30,000				(30,000)
other	10,000				(10,000)
Total	330,000			-	(330,000)
Purchased Parts					
Receiver Insert	48,000	Hanson		48,000	-
Side Plate	10,000	quare Stamping			(10,000)
Safety Arm	23,880				(23,880)
Bolt Stop	6,820				(6,820)
Recoil Bracket	2,225	quare Stamping		550	(1,675)
Bolt Handle Blank	12,800				(12,800)
Bolt Plug	38,088	Kellems & Coe	M017443	38,000	(88)
Firing pin head	23,000	Megamet		16,000	(7,000)
Mag Latch	33,480	Par 4 Plastics		31,806	(1,674)
Magazine Box	28,000	Brainin		12,500	(15,500)
Magazine Follower	33,300	Par 4 Plastics		73,786	40,486
Magazine Bottom	47,880	Par 4 Plastics		-	(47,880)
Stock	150,300	Par 4 Plastics	M017435	145,348	(4,952)
PPI	41,500				(41,500)

MF1131

REMINGTON ARMS COMPANY, INC.

01/21/00

FIREARMS - MAYFIELD

710 Capital White Paper vs Actual

C:\windows\TEMP\710 Capital Start up Costs.xls]Capital Spend Out

	White			(Under)/
Total	<u>499,273</u>			<u>365,990 (133,283)</u>
Other				
Press to attach Barrel/Receiver	-	In House	N/A	5,811 5,811
Installation	<u>61,000</u>			<u>(61,000)</u>
Total	<u>61,000</u>			<u>5,811 (55,189)</u>
Total Capital	<u><u>2,358,528</u></u>			<u><u>742,251 (1,616,277)</u></u>

83

CONFIDENTIAL

M/710 Weekly Progress Report -- 1/20/00

	Actual	Budget
Capital Dollars Spent (Total Project)		\$2,350,000
Capital Dollars Committed Dollars (Total Project)	\$721,144.00	
Pre-op Dollars Spent (Total Project)		\$414,000
Capital Dollars Spent (month to date)		
Capital Dollars Committed Dollars (month to date)	\$282,142.00	
Pre-op Dollars Spent (month to date)	0	
T&P Date (estimated build completion date)	6/9/00	5/30/00
Product Price	\$89.00	\$92.79

- Product price as of information at close of business 1/19/00. Price includes \$42 for 1st year amortization of Par 4 drilling fixture.
- T&P date pushed out as a result of delay in getting safety arm tool ordered. Current lead time 18-20 wks, which puts us in the end of May for part delivery. Delay is Marketing. Safety arm is currently the constraint.
- Overhead percentages standardized with white paper at 291% variable and 157% fixed, resulting in a price drop of approximately \$4.00 from last week's price report.

MF1133

23

FIRST QUARTER CAPITAL TOOL EXPENDITURES

PART Number	DESCRIPTION	VENDOR	TOOLING CHARGE	AMOUNT OF TOOLING CHARGE DUE 1ST QTR.
300437	STOCK	PAR 4 PLASTIC	\$145,300.00	***\$48,433.33
300365	BOX BOTTOM	PAR 4 PLASTIC	\$73,786.00	***\$24,595.33
300333	SIDE PLATE	SQUARE STAMPING	\$8,500.00	\$4,250.00
300364	FOLLOWER	PAR 4 PLASTIC	\$33,300.00	---\$11,100.00
300362	LATCH	PAR 4 PLASTIC	\$31,806.00	***\$10,602.00
300368	BOLT PLUG	KELLEMS AND COE	\$38,000.00	***\$12,666.67
300405	MAGAZINE SPRING		\$13,900.00	\$4,633.33
300345	BOLT STOP	STERLING SINTERED	\$6,820.00	\$3,410.00
300370	BOLT HANDLE	NORTH AMERICAN	\$6,895.00	\$3,447.50
300336	FIRING PIN HEAD		\$17,500.00	\$5,833.33
300361	RECOIL BRACKET	SQUARE STAMPING	\$550.00	\$550.00
300420	LOCK TUMBLER	ILION	\$39,000.00	\$13,000.00
300435	TRIGGER	STERLING SINTERED	\$15,225.00	\$5,075.00
300363	MAG BOX	BRAININ DEER PARK	\$12,500.00	***\$4,166.67
	INDUCTION HEAT TREAT CENTER	WELDUCTION		\$156,450.00
	TOTAL			\$207,749.16

***THESE PURCHASE ORDERS ARE ALREADY IN PLACE AS OF 1/14/00

MF1135

Remington Arms Company, Inc.
Mayfield Plant
22 Rifle Trail
P.O. Box 99
Hickory, KY 42061
Phone: (270) 856-4200
Fax: (270) 856-3233

Remington.

Fax

To: TERRY DIAZ From: MATT G.
Fax: _____ Pages: 2
Phone: _____ Date: 12/14/99
Re: _____ CC: MIKE KRECHT
☐ Urgent ☐ For Review ☐ Please Comment ☐ Please Reply ☐ Please Recycle

• Comments:

THIS IS THE QUOTE FOR THE
MAGAZINE BOX

MF1136

STERLING SINTERED TECHNOLOGIES
249 ROCKWELL STREET
WINSTED CT 06098

FACSIMILE TRANSMITTAL SHEET

TO:	FROM:
JOE ZAJK	ANN DELUTRIE
COMPANY:	DATE:
REMINGTON	12/08/99
FAX NUMBER:	TOTAL NO. OF PAGES INCLUDING COVER:
270-856-3233	1
PHONE NUMBER:	SENDER'S REFERENCE NUMBER:
270-856-4209	
RE:	YOUR REFERENCE NUMBER:
RFQ	

☐ URGENT ☐ FOR REVIEW ☐ PLEASE COMMENT ☐ PLEASE REPLY ☐ PLEASE RECYCLE

JOE,

IN REFERENCE TO P/N C-300362 REV 4, WE SINCERELY APPRECIATE THE OPPORTUNITY TO LOOK AT THIS, BUT FEEL THE LEAST COSTLY P.M. APPROACH WOULD NOT BE COMPETITIVE WITH A DIE CASTING.

IF YOU HAVE ANY QUESTIONS, PLEASE DON'T HESITATE TO CALL.

REGARDS,
ANN

PHONE: 860-379-2753

FAX: 860-738-0664

MF1137

Brainin

ISO 9001

Deer Park Die & Stamping Division

Fairfield

QUOTATION

December 8, 1999

Remington Arms Company, Inc.
 22 Rifle Trail
 PO Box 99
 Hickory, Ky 42051

Attn: Metty Morgan
 Ref: Part # D-300408 rev. 7

We are pleased to submit the following quotation for your consideration.

TOOLING COST

Design and build progressive and secondary die to stamp part complete \$42,000.00

PRODUCTION COST PER/M

Quantities:	Price/M
20/M	\$212.93/M
40/M	\$166.78/M
60/M	\$151.39/M

Notes: Quote based on running part in quarterly production runs.
 Parts will be bulk packed in Deer Park boxes on a skid.
 Quote is based on stamping of part ONLY. Material quoted is a 1010/1020 CRS.
 Remington to be responsible for Black Oxide and Heat Treating.
 Brainin-Deer Park takes exception to holding the 0.006" True Position tolerance.

Inspection: Production parts to be sample inspected per Deer Park's internal procedure when no other standard is specified by the client.

Delivery: Tooling, 14-16 weeks. Production, 4-6 weeks upon receipt of raw material.


Terms: Tooling, 1/3 at PO, 1/3 at sample submission, 1/3 at customer approval.

Terms: Production, Net 30 days.


FOB: Deer Park

Thank you for considering Deer Park Die & Stamping, an ISO 9001 certified firm, as your supplier.

Best Regards,



Jerry Rossman, Sales Engineer



Edward J. Kreuzer, Vice President/General Manager

Brainin

ISO 9001

Deer Park Die & Stamping Division

Fairfield

QUOTATION

December 8, 1999

Remington Arms Company, Inc.
 22 Rifle Trail
 PO Box 99
 Hickory, Ky 42051

Attn: Metty Morgan

Ref: Part # C-306333 rev. 5, Side Plate

We are pleased to submit the following quotation for your consideration.

TOOLING COST

Design and build progressive and secondary die to stamp part complete \$17,500.00

PRODUCTION COST PER M

Quantities:	Price/M
20/M	\$160.88/M
40/M	\$114.72/M
60/M	\$ 99.34/M

Notes: Quote based on running part in quarterly production runs.
 Parts will be bulk packed in Deer Park boxes on a skid.
 Quote is based on stamping of part ONLY. Material quoted is a 1010/1020 CRS.
 Remington to be responsible for Black Oxide.

Inspection: Production parts to be sample inspected per Deer Park's internal procedure when no other standard is specified by the client.

Delivery: Tooling, 14-16 weeks. Production, 4-6 weeks upon receipt of raw material.


Terms: Tooling, 1/3 at PC, 1/3 at sample submission, 1/3 at customer approval.

Terms: Production, Net 30 days.


FOB: Deer Park

Thank you for considering Deer Park Die & Stamping, an ISO 9001 certified firm, as your supplier.

Best Regards,



Jerry Rossman, Sales Engineer



Edward J. Kreuzer, Vice President/General Manager

Swiss Precision Machining, Inc.

7550 N. Oak Park Ave., Niles, IL 60714 (847) 647-7111 / FAX (847) 647-7110

December 8, 1999

Remington Arms Company, Inc.
22 Rifle Trail
P.O. Box 99
Hickory, KY 42051
ATTN: Metty Morgan

Dear Metty:

We are pleased to submit the following quotation for your consideration:

Part #B-17043

20,000 @ \$.165 each

40,000 @ \$.149 each

60,000 @ \$.143 each


Non-recurring engineering fee \$150.00

Note: Part is quoted less color as we could not identify the Nitre Black with our outside sources.

Our current lead time is 6-8 weeks and our terms are Net 30. All parts will be shipped
FOB Niles, IL. If you have any questions please don't hesitate to call.

Sincerely,

SWISS PRECISION MACHINING, INC.


Joseph A. Haupers
Sales Manager

JAH/kas

SPM

TOTAL P.02

MF1140

PRICE QUOTATION

Automatic Swiss Corporation

1130 W. National Avenue
P.O. Box 416
Addison, IL. 60101
Phone: (630) 543-3888
Fax: (630) 543-1486

To : REMINGTON ARMS
Attn : METTY MORGAN
PHONE:

Date 12/8/99
Quote #
Rep.

Part # B0-17043
Part Description PIN
Material Type 12L14
Exceptions:

Quantity	Price/Pc
20000	\$ 0.150
40000	\$ 0.125
60000	\$ 0.115

SMALL CUT-OFF TIP ONE END

Engineering 350

By JIM RUPPRECHT

Lead Time 6 WEEKS

Terms Are 1/2 10 Net 30 F.O.B. Addison

Note: All quotations and agreements are contingent upon strikes, accidents, fires, availability of materials and all other causes beyond our control. Prices are based on costs and conditions existing on date of quotation and are subject to change by Seller before final acceptance.

Typographical and stenographic errors are subject to correction. Purchaser assumes liability for patent and copyright infringement when goods are made to Purchaser's specifications. Conditions not specifically stated herein shall be governed by established trade customs. Terms inconsistent with those stated herein which may appear on Purchaser's formal order will not be binding on the Seller.

MF1141

47794

ISELI — WALWORTH, WI 53184PRECISION MACHINED COMPONENTS - PHONE (414) 275-2108 - FAX (414) 275-6094
402 NORTH MAIN STREET, P.O. BOX 1060**QUOTATION****A DANAHER COMPANY**ATTN: Metty Morgan
Remington Arms Company
P.O. Box 99
Hickory, KY 42051BY SUBMITTING YOUR PURCHASE ORDER
FOR THESE GOODS, YOU AGREE TO THE
TERMS AND CONDITIONS OF SALE SET
FORTH ON THE FACE AND REVERSE SIDES
HEREOF. ANY DIFFERENT OR ADDITIONAL
TERMS IN YOUR ACCEPTANCE OF THIS OFFER
ARE HEREBY OBJECTED TO.

THANK YOU FOR YOUR INQUIRY. WE ARE PLEASED TO SEND THE FOLLOWING QUOTATION.

PLEASE REFER ALL CORRESPONDENCE TO ISELI COMPANY AT WALWORTH, WISCONSIN.

DATE	REFERENCE	
12-7-99		OUR TERMS ARE NET 30 DAYS
QUANTITY	DESCRIPTION	PRICE

20,000 pcs.	P/N B-17043 Safety Pivot Pin	\$.14/ea.
40,000 pcs.	"	\$.12/ea.
60,000 pcs.	"	\$.11/ea.

Non-recurring Engineering Charge - \$325.00

Quoted in C12L14 material.

Quoted with Nigre Black reading Black Oxide.

Quoted with .010" Max. cornerbreaks unless noted.

ABOVE PRICES FIRM UNTIL 6-30-00 - Subject to raw material costs.

DELIVERY CAN ONLY BE ASCERTAINED AT TIME OF ORDER PLACEMENT.

"It is unwise to pay too much, but it is worse to pay too little. When you pay too much, you lose a little money, that is all. When you pay too little, you sometimes lose everything, because the thing you bought was incapable of doing the thing it was bought to do. The common law of business balance prohibits paying a little and getting a lot — It can't be done.

If you deal with the lowest bidder, it is well to add something for the risk. And if you do that, you will have enough for something better."

John Ruskin (1819-1900)

Our quality standards are based on
individual customer preference

Very truly yours,


Carey Luyling
 SALES MANAGER
ISELI COMPANY

MF1142

 Confidential - Subject to Protective Order
 BARBER - 5.22.06r0011092
 Williams v. Remington

47795

ISELI — WALWORTH, WI 53184PRECISION MACHINED COMPONENTS - PHONE (414) 275-2108 - FAX (414) 275-6094
402 NORTH MAIN STREET, P.O. BOX 1060**QUOTATION****A DANAHER COMPANY**ATTN: Metty Morgan
Remington Arms Company
P.O. Box 99
Hickory, KY 42051BY SUBMITTING YOUR PURCHASE ORDER
FOR THESE GOODS, YOU AGREE TO THE
TERMS AND CONDITIONS OF SALE SET
FORTH ON THE FACE AND REVERSE SIDES
HEREOF. ANY DIFFERENT OR ADDITIONAL
TERMS IN YOUR ACCEPTANCE OF THIS OFFER
ARE HEREBY OBJECTED TO.

THANK YOU FOR YOUR INQUIRY. WE ARE PLEASED TO SEND THE FOLLOWING QUOTATION.

PLEASE REFER ALL CORRESPONDENCE TO ISELI COMPANY AT WALWORTH, WISCONSIN.

DATE	REFERENCE	OUR TERMS ARE NET 30 DAYS ⁸³	
12-7-99			
QUANTITY	DESCRIPTION	PRICE	
20,000 pcs.	P/N A-300427 Spring Retainer	\$.09/ea.	
40,000 pcs.	"	\$.08/ea.	
60,000 pcs.	"	\$.07/ea.	

Non-recurring Engineering Charge - \$200.00

Quoted with .010" Max. cut-off nib on one end.

ABOVE PRICES FIRM UNTIL 6-30-00 - Subject to raw material costs.

DELIVERY CAN ONLY BE ASCERTAINED AT TIME OF ORDER PLACEMENT.


"It is unwise to pay too much, but it is worse to pay too little. When you pay too much, you lose a little money, that is all. When you pay too little, you sometimes lose everything, because the thing you bought was incapable of doing the thing it was bought to do. The common law of business balance prohibits paying a little and getting a lot — It can't be done.

If you deal with the lowest bidder, it is well to add something for the risk. And if you do that, you will have enough for something better."

John Ruskin (1819-1900)

Our quality standards are based on
individual customer preference

Very truly yours,


Carey Luning
 SALES MANAGER
ISELI COMPANY

MF1143

copy
Remington®

REMINGTON ARMS COMPANY, INC.

22 RIFLE TRAIL
P.O. BOX 99
HICKORY, KY 42051

TEL: 270-856-4200
FAX: 270-856-3233

3/3/00

Sterling Sintered Technologies
249 Rockwell Street
Winsted, CT 06098-1946

Attn: Roland

Due to some possible design changes, we regretfully request that Sterling please put a "hold" on the manufacturing of the Trigger tool. Drawing # C-300435, PO# M017487. 83

A meeting will be held today in hopes of making final decisions in this matter. Please hold all production of this tool until you are contacted by myself or our Engineering Manager, Joe Zajk.

Thank you for your understanding and cooperation in this matter.

Sincerely,

Metty E. Morgan

Metty E. Morgan
Materials Manager
Mayfield Plant

MF1144

Material	Short text	PGp	Mat. gp.
Requisn. Item	Requested qty. Un Deliv. date Requester		Plnt SLoc
S C R Qty. I A	Req. val. Cur Release date Trackg.no.		SPl. MC
Release strategy	Release indicator Release option		
X	WGC SPECIAL. TRIPLE CIRCUIT, AIR SPINDLE M09	03	
1000328038 00010	1.000 EA D 02/28/2000 GOLEMBOSKIMR MAY		
N R A NB F	5,467.25 USD 01/27/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	NON RECURRING ENGINEER CHARGE FOR ABOVE M09	03	
1000328038 00020	1.000 EA D 02/28/2000 GOLEMBOSKIMR MAY		
N R A NB F	926.25 USD 01/27/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	WGC SPECIAL AIR PROBE TO CHK .3000/.3010 M09	03	
1000328038 00030	1.000 EA D 02/28/2000 GOLEMBOSKIMR MAY		
N R A NB F	2,605.38 USD 01/27/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	RGM-XX-C-3000 RING GAGE, MASTER M09	03	
1000328038 00040	1.000 EA D 02/28/2000 GOLEMBOSKIMR MAY		
N R A NB Z	114.95 USD 01/27/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	RGM-XX-C-3010 RING GAGE, MASTER M09	03	
1000328038 00050	1.000 EA D 02/28/2000 GOLEMBOSKIMR MAY		
N R A NB Z	114.95 USD 01/27/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	WGC SPECIAL AIR PROBE TO CHK .3080/.3090 M09	03	
1000328038 00060	1.000 EA D 02/28/2000 GOLEMBOSKIMR MAY		
N R A NB Z	1,895.25 USD 01/27/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	RGM-XX-C-.3080 RING GAGE, MASTER M09	03	
1000328038 00070	1.000 EA D 02/28/2000 GOLEMBOSKIMR MAY		
N R A NB Z	114.95 USD 01/27/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	RGM-XX-C-3090 RING GAGE, MASTER M09	03	
1000328038 00080	1.000 EA D 02/28/2000 GOLEMBOSKIMR MAY		
N R A NB Z	114.95 USD 01/27/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	AEQ 21-33-10 MICRO-AIR DIGITAL COMPARATOR M09	03	
1000328038 00090	1.000 EA D 02/28/2000 GOLEMBOSKIMR MAY		
N R A NB F	4,393.75 USD 01/27/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	9/32 ENDMILL #89145A42 M09	03	
1000330051 00010	1.000 EA D 01/27/2000 GOLEMBOSKIMR MAY		
N R A NB Z	14.64 USD 01/25/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	101041 MCMaster-CARR SUPPLY CO		
X	19/64 ENDMILL #89145A43 M09	03	
1000330051 00020	1.000 EA D 01/27/2000 GOLEMBOSKIMR MAY		
N R A NB Z	14.72 USD 01/25/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	5/16 ENDMILL #89145A44 M09	03	
1000330051 00030	1.000 EA D 01/27/2000 GOLEMBOSKIMR MAY		
N R A NB Z	14.02 USD 01/25/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	21/64 ENDMILL #89145A45 M09	03	
1000330051 00040	1.000 EA D 01/27/2000 GOLEMBOSKIMR MAY		
N R A NB Z	14.72 USD 01/25/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	PLUMB BOB AND CASE #2178A1 M09	03	
1000330051 00050	5.000 EA D 01/27/2000 GOLEMBOSKIMR MAY		
N R A NB Z	57.80 USD 01/25/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	.834 DIAMETER 5C COLLET M09	03	
1000330052 00010	2.000 EA D 01/27/2000 GOLEMBOSKIMR MAY		

MF1145

Material Requisition. S C R Qty. I A Release strategy	Item	Short text Requested qty. Un Deliv. date Requester Req. val. Cur Release date Trackg.no. Release indicator Release option	PGp	Mat. gp. Plnt SLOC SPL. MC
N R A NB Z	S1	68.00 USD 01/25/2000 HUTSONLR		
	Desired vendor	1658772 HARDINGE BROTHERS INC		
X	1000330053 00010	F40 CW RS WM 25 LIGHT BULBS M09 28		
	N R A NB Z	30.000 EA D 01/31/2000 GOLEMBOSKIMR MAY		
	S1	37.50 USD 01/25/2000 HUTSONLR		
	Desired vendor	103595 Consolidated Electrical Distributor		
X	1000330054 00010	DREMEL GRINDSTONE 3/16 #454-9411-4501 M09 MISC		
	N R A NB Z	6.000 EA D 01/31/2000 GOLEMBOSKIMR MAY		
	S1	28.68 USD 01/25/2000 HUTSONLR		
	Desired vendor	102641 MSC INDUSTRIAL SUPPLY		
X	1000330054 00020	SANDING BELT/DRUMS #09023904 M09 MISC		
	N R A NB Z	4.000 EA D 01/31/2000 GOLEMBOSKIMR MAY		
	S1	9.00 USD 01/25/2000 HUTSONLR		
X	1000331759 00010	78678612 46040 SER 830M 4 FL ENDMILLS M09 03		
	N R A NB Z	2.000 EA D 01/26/2000 GOLEMBOSKIMR MAY		
	S1	15.90 USD 01/26/2000 HUTSONLR		
	Desired vendor	102641 MSC INDUSTRIAL SUPPLY		
X	1000331759 00020	01192715 3/32 4 FL 1/8 SHK SOLID CARBIDE M09 03		
	N R A NB Z	2.000 EA D 01/26/2000 GOLEMBOSKIMR MAY		
	S1	10.00 USD 01/26/2000 HUTSONLR		
X	1000331759 00030	FREIGHT M09 03		
	N R A NB Z	1.000 EA D 01/26/2000 GOLEMBOSKIMR MAY		
	S1	7.93 USD 01/26/2000 HUTSONLR		
X	1000331761 00010	SD601416 SPINDLE, 4X REACH 4S2-107-1D05 M09 17		
	N R A NB Z	1.000 EA D 01/26/2000 GOLEMBOSKIMR MAY		
	S1	10,535.00 USD 01/26/2000 HUTSONLR		
	Desired vendor	6093720 EDGETEK MACHINE CORP		
X	1000331761 00020	GATES BELT, 10 RIB #10/5M775JB M09 17		
	N R A NB Z	1.000 EA D 01/26/2000 GOLEMBOSKIMR MAY		
	S1	149.17 USD 01/26/2000 HUTSONLR		
X	1000331761 00030	FREIGHT M09 17		
	N R A NB Z	1.000 EA D 01/26/2000 GOLEMBOSKIMR MAY		
	S1	219.65 USD 01/26/2000 HUTSONLR		
X	1000331768 00010	DRILL .292 DIA X 54" LONG W/ KIDNEY M09 03		
	N R A NB Z	36.000 EA D 02/21/2000 GOLEMBOSKIMR MAY		
	S1	2,736.00 USD 01/26/2000 HUTSONLR		
	Desired vendor	5380140 DANJON MANUFACTURING CORP		
X	1000331768 00020	REAMERS .299 DIA. TO BE PVD COATED WITH M09 03		
	N R A NB Z	12.000 EA D 02/21/2000 GOLEMBOSKIMR MAY		
	S1	1,749.60 USD 01/26/2000 HUTSONLR		
X	1000331768 00030	BUTTON .3112 GROOVE X .301 BORE DIAMETER M09 03		
	N R A NB Z	5.000 EA D 02/21/2000 GOLEMBOSKIMR MAY		
	S1	1,045.00 USD 01/26/2000 HUTSONLR		
X	1000331809 00010	DRILL BIT 5/8 #2906A11 M09 03		
	N R A NB Z	1.000 EA D 01/28/2000 GOLEMBOSKIMR MAY		
		21.59 USD 01/26/2000 HUTSONLR		

MF1146

Material	Short text	PGp	Mat. gp.
Requisn. Item	Requested qty. Un Deliv. date Requester	Plnt Sloc	
S C R Qty. I A	Req. val. Cur Release date Trackg.no.	SPL. MC	
Release strategy	Release indicator Release option		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	101041 MCMaster-CARR SUPPLY CO		
X	MODEL 2001T DIGITAL ROCKWELL TESTER M09	LAB EQUIP	
1000335538 00010	1.000 EA D 02/29/2000 GOLEMBOSKIMR MAY		
N R A NB F	13,800.00 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	3557873 WILSON INSTRUMENT INC		
X	REPLENISH POSTAGE MACHINE METER M09	02	
1000335539 00010	1.000 EA D 01/28/2000 GOLEMBOSKIMR MAY		
N R A NB K	375.00 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	102634 United States Postal Service		
X	3/16" RND STAINLESS 316 GRADE X 12" STICK M09	44	
1000335540 00010	2.000 EA D 02/04/2000 GOLEMBOSKIMR MAY		
N R A NB Z	6.00 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	106525 TBI STEEL		
X	1/4" RND STAINLESS 316 GRADE X 12" STICK M09	44	
1000335540 00020	21.000 EA D 02/04/2000 GOLEMBOSKIMR MAY		
N R A NB Z	114.45 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	1/2" RND STAINLESS 316 GRADE X 12" STICK M09	44	
1000335540 00030	1.000 EA D 02/04/2000 GOLEMBOSKIMR MAY		
N R A NB Z	20.95 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	1" X 1/2" FLAT STAINLESS 316 GRD X 12" STIC M09	44	
1000335540 00040	16.000 EA D 02/04/2000 GOLEMBOSKIMR MAY		
N R A NB Z	955.20 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	RODS 3/32 5 LB BOX #7972A278 M09	44	
1000335541 00010	1.000 EA D 02/03/2000 GOLEMBOSKIMR MAY		
N R A NB Z	36.00 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	101041 MCMaster-CARR SUPPLY CO		
X	7/8" ROUND 6' LENGTH #89325K19 M09	44	
1000335541 00020	16.000 EA D 02/03/2000 GOLEMBOSKIMR MAY		
N R A NB Z	1,128.00 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	1/8" ROUND 6' LENGTH #89325K11 M09	44	
1000335541 00030	16.000 EA D 02/03/2000 GOLEMBOSKIMR MAY		
N R A NB Z	115.20 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	1/8" PRESSURE GAUGE #38105K13 M09	03	
1000335541 00040	4.000 EA D 02/03/2000 GOLEMBOSKIMR MAY		
N R A NB Z	35.40 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	GRINDER #46225A81 M09	03	
1000335541 00050	1.000 EA D 02/03/2000 GOLEMBOSKIMR MAY		
N R A NB Z	136.25 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	#06235691 MITUTOYO MINI-MIKE M09	03	
1000335542 00010	1.000 EA D 02/10/2000 GOLEMBOSKIMR MAY		
N R A NB Z	174.31 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	102641 MSC INDUSTRIAL SUPPLY		
X	#01044585 MTI DIGITEST CALIPER GAGE M09	03	
1000335542 00020	1.000 EA D 02/10/2000 GOLEMBOSKIMR MAY		
N R A NB Z	686.40 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		

MF1147

Material	Short text	PGp	Mat. gp.
Requish. Item	Requested qty. Un Deliv. date Requester	Plnt SLoc	
S C R Qty. I A	Req. val. Cur Release date Trackg.no.	Spl. MC	
Release strategy	Release indicator Release option		
X	#98668130 CHAMFER CHECK M09 03		
1000335542 00030	1.000 EA D 02/10/2000 GOLEMBOSKIMR MAY		
N R A NB Z	122.06 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	#98556434 NON-CAT MTI CORP M09 03		
1000335542 00040	1.000 EA D 02/10/2000 GOLEMBOSKIMR MAY		
N R A NB Z	257.84 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	#00622464 MITUTOYO DIG DEPTH GAGE M09 03		
1000335542 00050	1.000 EA D 02/10/2000 GOLEMBOSKIMR MAY		
N R A NB Z	302.72 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	ALIGNMENT BORE PER PRINT M09 TOOLING		
1000335543 00010	1.000 EA D 02/15/2000 GOLEMBOSKIMR MAY		
N R A NB Z	214.00 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	104762 G AND H TOOL & DIE, INC		
X	FEDERAL SERIES C MODEL C81 DIAL INDICATQ M09 03		
1000335544 00010	2.000 EA D 02/04/2000 GOLEMBOSKIMR MAY		
N R A NB Z	214.00 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	102641 MSC INDUSTRIAL SUPPLY		
X	TOTAL LABOR-8 HOURS AT REGULAR TIME M09 SERVICE		
1000335545 00010	1.000 EA D 01/28/2000 GOLEMBOSKIMR MAY		
N R A NB Z	544.00 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
Desired vendor	102390 PROCESS & POWER		
X	TOTAL LABOR OF 1-1/2 HOURS M09 SERVICE		
1000335545 00020	1.000 EA D 01/28/2000 GOLEMBOSKIMR MAY		
N R A NB Z	153.00 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	MILEAGE-150 MILES AT .85 A MILE M09 SERVICE		
1000335545 00030	1.000 EA D 01/28/2000 GOLEMBOSKIMR MAY		
N R A NB Z	127.50 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		
X	COUPLING SET I-R NEEDED FOR REPAIR M09 SERVICE		
1000335545 00040	1.000 EA D 01/28/2000 GOLEMBOSKIMR MAY		
N R A NB Z	14.90 USD 01/28/2000 HUTSONLR		
S1	B APPROVED FOR PURCHAS Release effected		

MF1148

Order 000000292068

Material Requisition. S C R O Ty. I A	Item	Short text Requested qty. Ordered qty.	Un Deliv. date. Release date.	Requester Trackg.no.	PGp	Mat: gp. Plnt Sloc SPL. MC
- 1000328038	00010	WGC SPECIAL. TRIPLE CIRCUIT, AIR SPINDLE M09	1.000 EA D 02/28/2000	GOLEMBOSKIMR	03	MAY
N R A NB	F		01/27/2000	HUTSONLR		
- 1000328038	00020	NON RECURRING ENGINEER CHARGE FOR ABOVE M09	1.000 EA D 02/28/2000	GOLEMBOSKIMR	03	MAY
N R A NB	F		01/27/2000	HUTSONLR		
- 1000328038	00030	WGC SPECIAL AIR PROBE TO CHK 3000/3010 M09	1.000 EA D 02/28/2000	GOLEMBOSKIMR	03	MAY
N R A NB	F		01/27/2000	HUTSONLR		
- 1000328038	00090	AEQ 21-33-10 MICRO-AIR DIGITAL COMPARTOR M09	1.000 EA D 02/28/2000	GOLEMBOSKIMR	03	MAY
N R A NB	F		01/27/2000	HUTSONLR		
- 1000335538	00010	MODEL 2001T DIGITAL ROCKWELL TESTER M09	1.000 EA D 02/29/2000	GOLEMBOSKIMR	LAB EQUIP	MAY
N R A NB	F		01/28/2000	HUTSONLR		
Desired vendor		3557873 WILSON INSTRUMENT INC				

710 Equipment

BARBER - 5.22.06r0011099

DECLASSIFIED

83

MF1149

Confidential - ~~SECRET~~ - 5.22.06r0011099 Order
Williams v. Remington

Cost center 0000028200

Material Requisition S C R QTY. I A	Short text Requested qty. Ordered qty.	Un Del Un Release date	PGP Requester Trackg.no.	Mat. gp. Pint SLoc SPL. MC
- 1000328038 00040 N R A NB Z	RGM-XX-C-3000 RING GAGE MASTER 1.000 EA D 02/28/2000	01/27/2000	GOLEMBOSKIMR HUTSONLR	M09 03 MAY
- 1000328038 00050 N R A NB Z	RGM-XX-C-3010 RING GAGE MASTER 1.000 EA D 02/28/2000	01/27/2000	GOLEMBOSKIMR HUTSONLR	M09 03 MAY
- 1000328038 00060 N R A NB Z	WGC SPECIAL AIR PROBE TO CHK 3080 3090 1.000 EA D 02/28/2000	01/27/2000	GOLEMBOSKIMR HUTSONLR	M09 03 MAY
- 1000328038 00070 N R A NB Z	RGM-XX-C-.3080 RING GAGE MASTER 1.000 EA D 02/28/2000	01/27/2000	GOLEMBOSKIMR HUTSONLR	M09 03 MAY
- 1000328038 00080 N R A NB Z	RGM-XX-C-.3090 RING GAGE MASTER 1.000 EA D 02/28/2000	01/27/2000	GOLEMBOSKIMR HUTSONLR	M09 03 MAY
- 1000330051 00010 N R A NB Z Desired vendor	9/32 ENDMILL #89145A42 1.000 EA D 01/27/2000	01/25/2000	GOLEMBOSKIMR HUTSONLR	M09 03 MAY
- 1000330051 00020 N R A NB Z	101041 MCMASTER-CARR SUPPLY CO 19/64 ENDMILL #89145A43 1.000 EA D 01/27/2000	01/25/2000	GOLEMBOSKIMR HUTSONLR	M09 03 MAY
- 1000330051 00030 N R A NB Z	5/16 ENDMILL #89145A44 1.000 EA D 01/27/2000	01/25/2000	GOLEMBOSKIMR HUTSONLR	M09 03 MAY
- 1000330051 00040 N R A NB Z	21/64 ENDMILL #89145A45 1.000 EA D 01/27/2000	01/25/2000	GOLEMBOSKIMR HUTSONLR	M09 03 MAY
- 1000330051 00050 N R A NB Z	PLUMB BOB AND CASE #2178A1 5.000 EA D 01/27/2000	01/25/2000	GOLEMBOSKIMR HUTSONLR	M09 03 MAY
- 1000331768 00010 N R A NB Z Desired vendor	DRILL .292 DIA X 54" LONG W/ KIDNEY 36.000 EA D 02/21/2000	01/26/2000	GOLEMBOSKIMR HUTSONLR	M09 03 MAY
- 1000331768 00020 N R A NB Z	5380140 DANJON MANUFACTURING CORP REAMERS .299 DIA. TO BE PVD COATED WITH 12.000 EA D 02/21/2000	01/26/2000	GOLEMBOSKIMR HUTSONLR	M09 03 MAY
- 1000331768 00030 N R A NB Z	BUTTON .3112 GROOVE X .301 BORE DIAMETER 5.000 EA D 02/21/2000	01/26/2000	GOLEMBOSKIMR HUTSONLR	M09 03 MAY
- 1000335540 00010 N R A NB Z Desired vendor	3/16" RND STAINLESS 316 GRADE X 12' STICK 2.000 EA D 02/04/2000	01/28/2000	GOLEMBOSKIMR HUTSONLR	M09 44 MAY
- 1000335540 00020 N R A NB Z	106525 TBI STEEL 1/4" RND STAINLESS 316 GRADE X 12' STICK 21.000 EA D 02/04/2000	01/28/2000	GOLEMBOSKIMR HUTSONLR	M09 44 MAY
- 1000335540 00030 N R A NB Z	1/2" RND STAINLESS 316 GRADE X 12' STICK 1.000 EA D 02/04/2000	01/28/2000	GOLEMBOSKIMR HUTSONLR	M09 44 MAY
- 1000335540 00040 N R A NB Z	1" X 1/2" FLAT STNLESS 316 GRD X 12' STIC 16.000 EA D 02/04/2000	01/28/2000	GOLEMBOSKIMR HUTSONLR	M09 44 MAY
- 1000335541 00010 N R A NB Z Desired vendor	RODS 3/32 5 LB BOX #7972A278 1.000 EA D 02/03/2000	01/28/2000	GOLEMBOSKIMR HUTSONLR	M09 44 MAY
	101041 MCMASTER-CARR SUPPLY CO			

710 Start-up

BARBER - 5.22.06r0011100

Confidential - ~~Shane~~ - 5.22.06r0011100 Order
Williams v. Remington

MF1150

83

Cost center 0000028200

Material Requisition S C R Qty. I A	Item	Short text Requested qty. Ordered qty.	Un	Deliv. date Release date	Requester Trackg.no.	PGp	Mat. gp. Pint Sloc Spl. MC
- 1000335541	00020	7/8" ROUND 6' LENGTH #89325K19				M09	44
N R A NB	Z	16.000 EA	D	02/03/2000	GOLEMBOSKIMR		MAY
				01/28/2000	HUTSONLR		
- 1000335541	00030	1/8" ROUND 6' LENGTH #89325K11				M09	44
N R A NB	Z	16.000 EA	D	02/03/2000	GOLEMBOSKIMR		MAY
				01/28/2000	HUTSONLR		
- 1000335541	00040	1/8" PRESSURE GUAGE #38105K13				M09	03
N R A NB	Z	4.000 EA	D	02/03/2000	GOLEMBOSKIMR		MAY
				01/28/2000	HUTSONLR		
- 1000335541	00050	GRINDER #46225A81				M09	03
N R A NB	Z	1.000 EA	D	02/03/2000	GOLEMBOSKIMR		MAY
				01/28/2000	HUTSONLR		
- 1000335542	00010	#06235691 MITUTOYO MINI-MIKE				M09	03
N R A NB	Z	1.000 EA	D	02/10/2000	GOLEMBOSKIMR		MAY
				01/28/2000	HUTSONLR		
		Desired vendor					
- 1000335542	00020	102641 MSC INDUSTRIAL SUPPLY				M09	03
N R A NB	Z	#01044585 MTI DIGITEST CALIPER GAGE				M09	03
		1.000 EA	D	02/10/2000	GOLEMBOSKIMR		MAY
				01/28/2000	HUTSONLR		
- 1000335542	00030	#98668130 CHAMFER CHECK				M09	03
N R A NB	Z	1.000 EA	D	02/10/2000	GOLEMBOSKIMR		MAY
				01/28/2000	HUTSONLR		
- 1000335542	00040	#98556434 NON-CAT MTI CORP				M09	03
N R A NB	Z	1.000 EA	D	02/10/2000	GOLEMBOSKIMR		MAY
				01/28/2000	HUTSONLR		
- 1000335542	00050	#00622464 MITUTOYO DIG DEPTH GAGE				M09	03
N R A NB	Z	1.000 EA	D	02/10/2000	GOLEMBOSKIMR		MAY
				01/28/2000	HUTSONLR		
- 1000335543	00010	ALIGNMENT BORE PER PRINT				M09	03
N R A NB	Z	1.000 EA	D	02/15/2000	GOLEMBOSKIMR		MAY
				01/28/2000	HUTSONLR		
		Desired vendor					
- 1000335544	00010	104762 G AND H TOOL & DIE, INC				M09	03
N R A NB	Z	FEDERAL SERIES C MODEL C81 DIAL INDICATO				M09	03
		2.000 EA	D	02/04/2000	GOLEMBOSKIMR		MAY
				01/28/2000	HUTSONLR		
		Desired vendor					
		102641 MSC INDUSTRIAL SUPPLY					

BARBER - 5.22.06/0011101

Confidential - SHARPER - 5.22.06/0011101 Order

Williams v. Remington

MF1151

PO number/date
M016617 01/28/2000Page
2

WESTERN GAGE CORPORATION
3316-A MAYA LINDA
CAMARILLO CA 93012-8059
TELEPHONE: 805-445-1410
FAX: 805-445-7530

Item	Material	Quantity	Unit	Description	Unit Price Per/Un	Net price
00060		1 EA		WGC SPECIAL AIR PROBE TO CHK .3080/.3090	1,895.25 EA	1,895.25
				Delivery date 02/28/2000		
				GROOVE, MAJOR, CHROME, STD JET SERIES 50 COMPLETE WITH 28" HANDLE, HOSE & FITTING		
00070		1 EA		RGM-XX-C-.3080 RING GAGE, MASTER	114.95 EA	114.95
				Delivery date 02/28/2000		
				CLASS XX, CHROME		
00080		1 EA		RGM-XX-C-.3090 RING GAGE, MASTER	114.95 EA	114.95
				Delivery date 02/28/2000		
				CLASS XX, CHROME		
00090		1 EA		AEQ 21-33-10 MICRO-AIR DIGITAL COMPARATOR	4,393.75 EA	4,393.75
				Delivery date 02/28/2000		
				TRIPLE CHANNEL, TRIPLE DISPLAY, STANDARD AMPL, RS-232 SERIAL OUTPUT		
Total net value USD						15,747.68
=====						

MF1152

Remington Arms, Co., Inc.

Please deliver to:
 Remington Arms Co., Inc.
 Mayfield Plant
 22 Rifle Trail
 HICKORY KY 42051

Purchase order

Page
 1

PO number/date
 M016617 01/28/2000

Contact Telephone
 M. Morgan/502-856-4204
 Fax Number/

Vendor: 106524

WESTERN GAGE CORPORATION
 3316-A MAYA LINDA
 CAMARILLO CA 93012-8059
 TELEPHONE: 805-445-1410
 FAX: 805-445-7530

COPY

Terms of pmt: Within 45 days Due net

Currency USD

Item	Material	Quantity	Unit	Description	Unit Price	Per/Un	Net price
00010		1 EA		WGC SPECIAL. TRIPLE CIRCUIT AIR SPINDLE	5,467.25	EA	5,467.25
				Delivery date 02/28/2000			
				TO CHECK INTERNAL CHAMBER DIAMETERS			
				.4708/.4728; .4425/4440; AND .3404/.3424, SERIES 50, CHROME;			
				COMPLETE WITH MIN/MAX SETTING MASTERS, HOSES, AND FITTINGS			
00020		1 EA		NON RECURRING ENGINEER CHARGE FOR ABOVE	926.25	EA	926.25
				Delivery date 02/28/2000			
00030		1 EA		WGC SPECIAL AIR PROBE TO CHK .3000/.3010	2,605.38	EA	2,605.38
				Delivery date 02/28/2000			
				LAND DIA, MINOR, CHROME, LEAF STYLUS,			
				SERIES 50, COMPLETE WITH 28" HANDLE, HOSE AND FITTING.			
00040		1 EA		RGM-XX-C-3000 RING GAGE, MASTER	114.95	EA	114.95
				Delivery date 02/28/2000			
				CLASS XX, CHROME			
00050		1 EA		RGM-XX-C-3010 RING GAGE, MASTER	114.95	EA	114.95
				Delivery date 02/28/2000			
				CLASS XX, CHROME			

MF1153

Remington Arms, Co., Inc.**Please deliver to:**

Remington Arms Co., Inc.
Mayfield Plant
22 Rifle Trail
HICKORY KY 42051

Purchase order**Page**

1

PO number/date

M016618 01/28/2000

Contact**Telephone**

M. Morgan/502-856-4204

Fax Number/

Vendor: 5380140

DANJON MANUFACTURING CORP
PO BOX 212
CHESHIRE CT 06410
TELEPHONE: 203-272-7258
FAX: 203-272-7259

COPY**Delivery :** UPS UPS 3rd Party Billing (922W20)**Terms of pmt:** Within 45 days Due net

Currency USD

83

Item	Material	Quantity	Unit	Description	Unit Price	Per/Un	Net price
00010		36	EA	DRILL .292 DIA X 54" LONG W/ KIDNEY	76.00	EA	2,736.00
				Delivery date 02/21/2000			
				COOLANT HOLE AND C-3 CARBIDE DRIVE END			
				COOL HOLE TO BE TAPPED FOR 3/8-24 THREAD			
00020		12	EA	REAMERS .299 DIA. TO BE PVD COATED WITH	145.80	EA	1,749.60
				Delivery date 02/21/2000			
				BALZER'S HARDLUBE OR EQUIV.			
00030		5	EA	BUTTON .3112 GROOVE X .301 BORE DIAMETER	209.00	EA	1,045.00
				Delivery date 02/21/2000			
				TICN OR HARDLUBE COATED. BUTTON TO BE			
				SIX GROOVES, 1 TURN IN 10 INCHES RH TWIST; RIFLE LAND GEOMETRY			
				PER CHAMBER DRAWING LB-153			

Total net value USD

5,530.60

MF1154