	D	E
367	EJECTOR DOES NOT HAVE ENOUGH TENSION	X
368	EJECTOR STUCK IN BOLT	X
369	FREEBORE MISCUT / MIN	X
370	SCOPE MOUNT THREADS UPSET IN RECEIVER	X
371	CLOSES HARD OVER SHELL	X
372	BARREL BRACKET OUT OF POSITION	X
373	BOLT STOP STICKS	X
374	ISS BOLT LOCKED IN THE "OPEN" POSITION	X
375	STOCK NOT BEDDED PROPERLY	X
376	TRIG ADJ SCREWS RESET, CANNOT READJUST	X
377		
378	**MALFUNCTIONS**	MODELS 700ML
379	ACCURACY	X
380	BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER REPAIR	X
381	BUTT PLATE / RECOIL PAD IS BROKEN	X
382	CHAMBER ROUGH / RINGS / TEARS / TIGHT	X
383	CONSIGNED GUN	X
384	COULD NOT DUPLICATE CUSTOMERS COMPLAINT	X
385	CREDIT RETURN	X
386	DAMAGE APPEARS TO HAVE OCCURRED IN TRANSIT	X
387	DAMAGES CASES, BULLETS OR SHELLS	X
388	FAILS TO FIRE	X
389	FINISH IS DAMAGED ON TRIGGER GUARD/PLATE	X
390	HEADSPACE IS EXCESSIVE	X
391	MUZZLE DAMAGE	X
392	NO CORRESPONDENCE	X
393	NO FAULT FOUND AT BENCH	X
394	PACKING ERROR	X
395	POOR FINISH - BARREL	X
396	POOR FINISH - FORE END	X
397	POOR FINISH - RECEIVER (OR FRAME)	X
398	POOR FINISH - STOCK	X
399	RECEIVER IS MISCUT	X
400	RUSTED COMPONENT	X
401	SAFETY CONCERN, EXAMINED BY PRODUCT SERVICE	X
402	SIGHTS OFF CENTER	X
403	STOCK CRACKED	X
404	STOCK MARRED	X
405	TRIGGER PULL IS OUT OF FACTORY SPECS.	X
406	LIGHT OR NO INDENT FROM FIRING PIN	X
407	BLUING SALTS ARE BLEEDING FROM METAL	X
408	EXTRACTOR MISSING	X
409	FAULTY MAGAZINE	X
410	TRIGGER CONNECTOR BINDS	X
411	RIFLING ROUGH / MISCUT / DAMAGED	X
412	EXTRACTOR IS CATCHING ON SHELL HEAD	X
413	POOR RECOIL PAD TO STOCK FIT	X
414	ROLL MARKING VISIBLE INSIDE BORE	X
415	BOLT HANDLE FELL OFF, BOLT IS BROKEN	X
416	RECEIVER PLUG SCREWS BROKEN	X
417	RECEIVER SCOPE MOUNT HOLES OFF CENTER	X
418	BOLT FACE / SHROUD DAMAGED	X
419	EJECTOR STUCK IN BOLT	X
420	FREEBORE MISCUT / MIN	X
421	SCOPE MOUNT THREADS UPSET IN RECEIVER	X
422	BARREL BRACKET OUT OF POSITION	X
423	BOLT STOP STICKS	X
424	ISS BOLT LOCKED IN THE "OPEN" POSITION	X
425	RETURNED FOR RECALL/UPDATE	X
426	TRIG ADJ SCREWS RESET, CANNOT READJUST	X
427	BREECH PLUG FROZE IN BREECH	X