RD-6542-1 Rev. 2-15-61

F NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 PCL

GENERAL CONDITION: GOOD R #: 002118

OUTSIDE WORK: [illegible] DATE: 2-1-72

[illegible] FROM: [illegible]

FIRED AMMO TYPE: [illegible]

& CONDITION: GUN #: [illegible]

PROOF: [illegible] INSP.: [illegible] TEST: 13 CODE: [illegible]

HEADING: CAL./CAL.: 270 [illegible]

BREECH OPENING: O.K. CHECKED BY: [illegible]

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN ETC. [illegible] & [illegible] TRIGGER PIN [illegible] 16,000) NONE OF [illegible] SCREW STAMPED BY [illegible] ON CONNECTOR NOT HARDENED.

COMPLAINT: RIFLE FIRES PROBABILITY.

INCIDENT: FOLLOW DOWN

COMMENTS: THE COMBINATION OF INSUFFICIENT [illegible] BURRS PROBABLY PREVENTED THE [illegible] FROM RETRACTING INTO FIRING POSITION CAUSING THE FIRING PIN TO FOLLOW DOWN.

PLAINTIFF'S EXHIBIT 3258

1 of 1

AL 0029790