> 1. Fuzzy optics on some scopes
> 2. Crosshairs rotated approx. 30 deg. on 1 scope
> * * Box bottoms - Falling off during shooting
> * * Magazine followers - Sticking in box (cause of stem low malfunction)
> * Safety in Fire Position as received - 1 of 30
> * "Pillar bedding" on hang tag
> * Box removal difficult - varies
> * Bolt Stops Loose - detent force varies
> * Trigger position relative to trigger guard - side to side
> * Take down screws - loosening during shooting
> * Scope rail deformation
>
> The topics in red are classified as potential show stoppers. These effect function and short term customer perception. We will discuss all topics in more detail at 4:00 today.
>
>

CONFIDENTIAL

Subject to Protective Order - Williams v. Remington