RECEIVING AND ESTIMATING REPORT

INITIAL FPS	CUSTOMER ORDER NO.	COMMENTS *F. Supry*

R ORDER 94-14520

DATE RECEIVED 04/28/94	DATE OPENED 04/28/94	DATE CODE	SERIAL NUMBER A6471639	NEW SERIAL NUMBER	MODEL AND GRADE 700 7MM MAG BDL

ACCESSORIES W/STUDS

DO

FROM:

AAA ACE BUYERS
823 B HWY. 99N
EUGENE   OR 97402

SHIP TO:

AAA ACE BUYERS
823 B HWY. 99N
EUGENE   OR
97402

CUST NO: 096689 C.O.D.

ACCOUNT NUMBER 063103	ACCOUNT NUMBER N/C	WRITE ☐		PROM. DATE	ESTIMATED	VIA UPS

GUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☑ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

Expedite per C. Mocko

REPAIR CHARGE	20.
EXCISE	
TAX	
INSURANCE	
UPS	8.0
PARCEL POST	
TOTAL	28.0

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	*Safety is defective sometimes it fires*			E1	F1
TRIGGER GROUP		B2				
BOLT ASSY.		*when the safety is disengaged*				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Pounds pull and trigger overtravel screw has been adjusted outside of the factory. Remington does not recommend that the trigger adjusting screws be altered outside of the factory. Exchange trigger assy at a special price strictly as a gesture of good will and to restore customers confidence in rifle. Front Guard screw does not tighten properly exchange N/C*

PARTS *Front guard screw*

COMMENTS *Trigger pull measured 2 LBS Rec'd and sear lift was .010*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PAT
GALLERY TESTER	DATE	DATE	DATE	DATE	DAT

OFFICE COPY

RD6925 RE

PPS 00001