RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 92-00204

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/23/91	01/03/92	XE 12-84	7641400		7 308

ACCESSORIES W/STUDS SCOPE BASE L/REAR SIGHT

FROM:
ACES GUNS
INTERSECTION 271 & 334
RT 2 BOX 98
HAWESVILLE KY 42348
USA

SHIP TO:
ACES GUNS
INTERSECTION 271 & 334
RT 2 BOX 98
HAWESVILLE KY
USA 42348

CUST NO:001867 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

"... the gun has discharged shots when they were placed in the gun, without even touching the trigger."

MAIN FAULT Cannot duplicate complaint. However, it was noted trigger assembly is gummed with excess oil and the trigger pull weight has been adjusted outside of factory to below our minimum specification.

Trigger pull $2\frac{3}{4}$ pounds; sear-lift .016".

PARTS

COMMENTS Offer to clean and re-adjust present trigger assembly, or we can install a new trigger assembly at ½ normal cost as a gesture of good will. Better to have satisfied customer for the rifle.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
ML					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8

PPS 00016