

Customer Com

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: GOOD R #: 001432
OUTSIDE WORK: SCOPE MOUNTED DATE: 1-16-73
FROM: BEIKIRCH
AMMUNITION CORP.
FIRE AMMO TYPE: - ROCHESTER, N.Y.
& CONDITION: _____ GUN #: 375936
ASSEMBLER 30 CODE: ER = '10/68
PROOF: RE.P. INSP.: U TEST: 87 GA./CAL.: 3006
HEADING: O.K. CHECKED BY: C. PROSSER
BREECH OPENING: - APPROVED: _____
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: N/O APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONSIDERABLE DIRT INCLUDING METAL PARTICLES
INSIDE HOUSING. HARDENED LUBRICATION ON TRIGGER.
CONNECTOR = 1.083 (^{1.080}/_{1.083} MODEL DRAWING) TRIGGER = 1.076
(^{1.076}/_{1.079} MODEL DRAWING) SAFETY & TO CAM = .291 (^{.292}/_{.296} MODEL
DRAWING)

COMPLAINT: "FIRES WITH SAFETY ON"

INCIDENT: FOLLOW DOWN

COMMENTS: THE CONNECTOR CAN WORK UP TO INTERFERE
WITH THE SEAR AND PREVENT RETRACTION INTO
COCKED POSITION.