


Since we found the trigger assembly to be outside our specifications, we can either readjust the present assembly or, if it will better restore your confidence in the rifle, we will install a new trigger assembly at no-charge as a gesture of good-will. We will await your decision and reply.

Thank you for affording us the opportunity to examine your rifle and report our findings.

Sincerely,

A handwritten signature in cursive script, appearing to read "J.A. Stekl".

J.A. Stekl, Specialist
Product Service

JAS:tp

Remington Arms Company, Inc.