

Customer Complaint

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: NEW R #: 24195
OUTSIDE WORK: SEAR ANGLE ON FIRING PIN DATE: 11-30-71
HEAD MAY HAVE BEEN GROUND MOUNTED, ^{SCOFF} FROM: Boss's Gun Shop
FIRED AMMO TYPE: — LANSING, MICH.
& CONDITION: _____ GUN #: 6361958
PROOF: R.E.P.E ASSEMBLER 30 INSP.: 9 TEST: 29 CODE: W.T. = 8/70
HEADING: O.K. GA./CAL.: 7MM REM. MAG.
BREECH OPENING: — CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO DAMAGED, OR BROKEN COMPONENTS. SOME FRICTION
MARKS ON TRIGGER AND INSIDE HOUSING. CONNECTOR-
SEAR ENGAGEMENT .005 MIN. = .015, TRIGGER PULL =
FOUR POUNDS.
COMPLAINT: "GUN DISCHARGES WHEN BOLT IS BEING OPENED"
INCIDENT: FOLLOW DOWN
COMMENTS: CUSTOMER'S MALFUNCTION NOT DUPLICATED.
IT IS POSSIBLE THAT A SLIGHT TRIGGER BIND CAUSED
FAILURE TO RETRACT, REDUCING THE CONNECTOR-SEAR
ENGAGEMENT SO THAT A MOVEMENT OF THE BOLT
HANDLE RELEASED THE FIRING PIN TO FIRE THE
ROUND IN THE CHAMBER.