

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
94-14539

ATTN: DENNIS SANITA

CUSTOMER ORDER NO.

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/28/94

04/29/94

OK 7-90

C6567884

700

308 WIN

PSS

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

CITY OF BRECKSVILLE
POLICE DEPARTMENT
9069 BRECKSVILLE ROAD
BRECKSVILLE

OH 44141

CITY OF BRECKSVILLE
POLICE DEPARTMENT
9069 BRECKSVILLE ROAD
BRECKSVILLE

OH

44141

CUST NO: 096728 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
- ☒ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

B3

B5

C1

C2

E1

E2

E3

E4

E5

F1

F2

F3

F4

F5

MAIN FAULT

Upon receipt rifle in inspection. Trigger would not actuate. Examination revealed that rust was found inside of the trigger housing assembly. The spring in the unit is second place near the trigger. The trigger adjustment screw has been moved. The trigger was found to be damaged by the rust. Rust found on screw.

PARTS

COMMENTS

Follow cleaning instructions on page 12 of the attached owner manual. Attach Manual. Repair complete trigger assembly and. Examination in section of good work. Again pointing with officer Varga via phone 4/29/94.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD8825 REV. 1/94