

*Remington.*



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

August 25, 1988

Mr. Thomas Brooks  
563 57 St.  
Brooklyn, NY 11220

Dear Mr. Brooks:

Examination has been completed on your Model Seven rifle, serial number 7693688, which you returned for evaluation.

Your firearm, produced in July of 1984, bears all required safety proof and inspection stampings and looks very well maintained although the gun's wood and metal finish were somewhat marred as received.

Our examining expert gauged the trigger pull between 4-3/4 and 5 pounds. The sear lift measured .012" and the sear-connector engagement is excellent. All these specifications are well within Remington specifications.

Repeated attempts were made to make the rifle follow down (fire upon bolt closing) with no malfunction. Repeated attempts were made to make the rifle fire upon safety release, again, with no malfunctions.

In short, the trigger assembly was found to be safe in every respect and could not be made to malfunction. The only way the gun was made to fire was to move the safety switch from the safe to fire position and to pull the trigger.

As absolutely nothing was found wrong with the rifle, we are prepared to return it to you, as received. However, from the gist of your letter, you apparently have lost confidence in the fire assembly. In this regard, for a C.O.D. charge of \$15.00, we will install a new entire trigger assembly. In this way, any personal doubts on your part can be eliminated so that you can enjoy your Model Seven with complete confidence.

We will hold your rifle pending your decision and written reply.