

RECEIVED

FFR 2 3 1988

CONSUMER SERVICE

Telephone (702) 322-5989

February 18, 1988

Remington Arms Company 1007 Market Street Wilmington, Delaware 19898

Attention: Product Information

Gentlemen:

I purchased a Remington Model 700 BDL some 20 years ago. I have never had a problem with it until my last hunt. After subjecting the rifle in its scabbard to a tremendous jolt (when my horse walked into a tree), it discharged when a round was chambered.

I am writing for 2 reasons:

- I am scared to death of the rifle now, and
- I need to know what caused it.

Can you help?.

Robert F. Buther Buther of Parties of Sending rifle to Arms Service for inspection fast.