

that oil be used sparingly and not let accumulate in or on the trigger assembly as this condition can adversely effect its operation.

As a gesture of good-will, and to insure that your customer's faith in the rifle is restored, we will clean the action of the rifle, check the feeding cycle, and install a new trigger assembly at no-charge. Please allow sufficient time for this service and return of the rifle.

Thank you for affording us the opportunity to be of service, and we trust that our handling meets with your approval.

Sincerely,


D.J. Sanita
Product Service

DJS:tpp

Remington Arms Company, Inc.