


1000. 17, 1754

Remington Arms Co. Inc.
Bridgeport, Conn. 06602



Re: Model 700 30-06 Springfield
Serial # 6259346

Dear Sirs:

I purchased the above mentioned rifle about 1971 from Mackeys Sporting Goods Co. in Abilene, Texas.

During the hunting season of 1971, I placed the rifle in my truck. I was traveling on a dirt road when I was stopped to pick up my hunting buddy. Before he entered the pickup, I attempted to breach the bolt to eject the live ammo. When I pushed the safety lever forward the rifle fired. The bullet penetrated the floor and the water jacket of the engine.

It happened so quickly I thought in pushing the safety forward I might have touched the trigger and didn't consider a claim against Remington. I also purposely tried to repeat the procedure of pushing the safety forward to see if the rifle would fire. I could never make it fire again. I have used the rifle most each season since that time, always aware the rifle might accidentally fire.