

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 660

GENERAL CONDITION: GOOD R # : 06392

OUTSIDE WORK: SCOPE MOUNTED DATE: 3-15-71

FROM: CHUBON'S HDW.

FIRED AMMO TYPE: - KANE, PA.

& CONDITION: _____ GUN # : 6270126

PROOF: R.E.P.-E INSP.: D TEST: 13 CODE: RT-12/70

HEADING: BOLT WILL NOT CLOSE ON MIN. HEAD. GA./CAL.: 243

DUMMY.

BREECH OPENING: 1 CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: No APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

REAR SIGHT LEAF ASSEMBLY REMOVED.

COMPLAINT: BOLT WILL NOT CLOSE OVER SHELL. FIRES WHEN SAFETY IS PUSHED OFF.

INCIDENT: MIN. HEADER, FOLLOW DOWN.

COMMENTS: HEADING REAMER MAY HAVE BEEN WORN. APPARENTLY THE WARPED TRIGGER CONNECTOR MADE ENGAGEMENT WITH THE SEAR ERRATIC (AS LITTLE AS .007, PROCESS RECORD SPECIFIES .020) THIS, COUPLED WITH EXCESSIVE CLEARANCE BETWEEN TRIGGER & CONNECTOR, CAUSED THE FOLLOW DOWN MALFUCTION.