

I have also included two (2) once fired cases
that show you another problem I am having.
It seems that with a moderate reload: - 42.0
Grains of H380 powder, A Nosler 150 Gr. Ballistic
tip bullet and a Federal 210 Match primer the
primers will pop out of the case. (see enclosed
rifle cases) My thinking is that there could
possibly be a headspace problem?

I would appreciate very much if you would
give this gun a complete inspection and correct
any problem that there might be. I feel that
possibly there might still be a problem in
the Trigger Assembly of the Model Seven rifle
that should be corrected.

Your prompt and courteous attention to this
letter will be appreciated.

Sincerely
William Cinti
P.O. Box 385
Claridge, Pa. 15623