

RECEIVING AND ESTIMATING REPORT

CUST NO: 049349 C.O.D		COMMENTS	
AL	CUSTOMER ORDER NO.		
M			
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER
7/12/91	09/18/91	KW 5-72	6552407
ESSORIES	W/STUDS	W/SWIVELS	SCOPE BASE
			L/SIGHTS
MODEL AND GRADE			ORDER
700 270 BDL			R 91-18387

DM:	SHIP TO:
CLARK, JIM RT 2 BOX 111 FREINDSHIP RD AMITE USA	CLARK, JIM RT 2 BOX 111 FREINDSHIP RD AMITE USA
LA 70422	LA 70422

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					10-2-91	UPS

IR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

N CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

TOMER'S REQUEST "My Benington 700 went off when I chambered a round."

FAULT Cannot make up malfunction in any way. However, trigger assembly is been adjusted outside factory - Trigger pull medium 2 lbs. 10 oz. per minimum specification. Safety is missing from all 3 trigger screws. See Ref. 008"

Based on attached letter, customer would prefer a non-coat lock safety. As a gesture of good-will, offer a new style trigger assembly at \$15.00 refund.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
DE					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90