

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: GOOD R #: 005856
OUTSIDE WORK: No DATE: 3-7-72
FROM: CONNORS SPT. GDS.
FIRED AMMO TYPE: — MOBERLY, MO.
& CONDITION: _____ GUN #: 624339G
PROOF: R.E.P.-E INSP.: 9 TEST: 13 CODE: 05-6/69
HEADING: — GA./CAL.: 308 WIN.
BREECH OPENING: — CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED, BROKEN COMPONENTS. TRIGGER PULL 3 LBS.,
NO TRIGGER-TRIGGER GUARD INTERFERENCE. GEAR-COLLECTOR
ECTOR ENGAGEMENT = .020 (MIN. IS .020) SEALS INTACT.
HEAVILY OILED.

COMPLAINT: "GUN SOMETIMES WILL FIRE AS SOON AS BOLT IS
ENGAGED, WITHOUT TRIGGER BEING PULLED.

INCIDENT: FOLLOW DOWN

COMMENTS: IT APPEARS, DEFECTS BEING ABSENT THAT THE
OIL USED PROBABLY CAUSED THE TRIGGER TO
REMAIN IN FIRED POSITION, ALLOWING THE FOLLOWING
DOWN MALFUNCTION.