

DEAR SIR:

SEE ATTACHED STATEMENT.

THE RIFLE IS HAVING THE SAME
PROBLEM AS BEFORE. I HAVE NOT
SINCE PUT ONE DROP OF OIL ON THE
TRIGGER ASSEMBLY OR ACTION.

PLEASE ADVISE AS TO WHAT CAN BE DONE
(IF ANYTHING) TO CORRECT THIS SITUATION.

SINCERELY,

CARMINE P. CONTI
89 RICCIARDONE AVE,
TORRINGTON, CT 06790

