Duane COOMBS
January 10, 1989
Box 10
Somerset, CA 95684
(916) 622-5622

UPS Shipping address: 3741 Sandlewood Shingle Springs, CA 9568

Remington Arms Company Arms Service Division Ilion, N.Y. 13357

Dear Sirs:

RE: RENINGTON Model 600 Serial # 43565

We bought this gun new in 1967

The fun was for my wife and on a hunting trip, the day we bought it, my wife was loading it in our camper. Without pulling the trigger, the gun discharged and shot a hole in the side of the camper.

Years later I read in the Rifleman of a recall on this model. I phoned you and was advised to take the gun to Simms Hardware in Sacramento.

They examined it and returned it saying there was nothing wrong with it.

Later I loaned the gum to my Brother-in Law while he was vising us. When we returned we found a hole in the ceiling of our living room. He said while loading the gum, and without touching the trigger the gum had discharged..

after several calls to them, I finally went down and picked up the gun on 11-5-82. They offered to send it to the factory, but I thought if wone they could lose the gun for 6 months at the store it would be gone for good if they sent it away. Because the gun has twice accidently discharged., my wife is afraid to use it so it has sat idle since we got it.

Pursuant to my phone conversations this date to Laurie and Ed Joy, I am returning the gun for repair at no cost under the Model 600 RECALL program.

PS. I checked Gra This

Thorning - Liding Fire Localenty Sincerely

But Trusger Poll extremely light!

Diane Contractions of the contraction of th