

WHL-66

11-18-83

DEAR JIM

THIS IS THE RIFEL WE TALKED ABOUT TODAY ON THE TELEPHONE.

ON TWO OCCASIONS, 11-15-82 AND 11-15-83, THIS RIFEL HAS FAILED TO OPERATE PROPERLY. BOTH TIMES I WAS AIMING AT A DEER. THE SAFETY WAS OFF AND I COULD NOT PULL THE TRIGGER. THERE WAS NO CLICK AND NO TRIGGER MOVEMENT. BOTH TIMES WHEN I LOWERED THE RIFEL TO SEE WHAT WAS WRONG IT FIRED WITHOUT TOUCHING THE TRIGGER.

YOU WILL NOTICE THE CHECKERING IS ALMOST GONE DUE TO REFINISHING THE WOOD. IF IT IS POSSIBLE TO RECHECKER THE WOOD SEND ME THE COST AND I WILL MAIL A CHECK TO COVER THE WORK. DON'T WORRY ABOUT THE FINISH ON THE WOOD AFTER CHECKERING (IF POSSIBLE) I WILL TAKE CARE OF THAT.

YOUR FRIENDLY COURTEOUS ATTITUDE DURING OUR TELEPHONE CONVERSATION