

Mr. Potter;

Please find enclosed customized XP-100
in IHMSA Trim International.

All inletting of the receiver and milled
portion of the bolt was done at my request in order
to meet weight specifications.

My complaint is the shoddy work and
craftsmanship and the treatment I received. The
bolt has been backed to the point its unacceptable.
The parkerized finish is sloppy and they even
failed to buff the barrel before it was applied.

After numerous trips and ~~and~~
very vocal complaints, I've received a "one less"
attitude from him. I'm referring to your
repair station Darnall Gun Works
Bloomington, Ill.

Unauthorized welding and gundring
resulted in failure (breakage) of the bolt handle.
Also the original configuration was altered without
my knowledge. Darnall tried to "stick" weld it but
made matter worse in function and appearance and
has failed miserably. The treatment and service I
received has upset me tremendously.

In desperation I finally called
Remington and suggested I send the entire pistol
for evaluation.

Since the shooting season is here
for IHMSA I would greatly appreciate the early