Mr. David Cunningham 1102 E. 14 1/2 Street Cameron, Tx. 76520 September 19, 1979

Model 500 Rifle A6569817 Repair Order R-20414-600

Dear Mr. Qunningham:

We recently received your Model 600 rifle, covered by your correspondence of recent date.

Upon examining your gun, we do find that it is a max header, and it is in need of a new action.

However, before supplying a new action, we would appreciate it if you would advise up as to whether or not the gun has been altered to a 222 Remmag.

If it has, we cannot supply the new bannel state it is not made of this caliber.

As can supply you with a 222 Rem Juliban.

When replying, please refer to this letter and our number R-20414-800 for identification.

Condially,

F. D. Cole:cm

Arms Service Division

200 X Y S Y

223 Remm46