

*Custom Complaints*

P.I. No GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700 ADL  
 GENERAL CONDITION: NEW R # : 26143  
 OUTSIDE WORK: NO DATE: 11-12-70  
 FROM: DAKIN OPTS, G.D.S. Co.  
 FIRED AMMO TYPE: - BANGOR, MAINE  
 & CONDITION: \_\_\_\_\_ GUN # : 6219140  
 PROOF: R.E.P. INSP.: \_\_\_\_\_ TEST: ASSEMBLER 41 CODE: LS-2/69  
 HEADING: O.K. GAU/CAL.: 3006  
 BREACH OPENING: - CHECKED BY: C. PROSSER  
 RECOIL SHOULDERS: - APPROVED: \_\_\_\_\_  
 CHAMBER: O.K. APPROVED: \_\_\_\_\_  
 TEST: No APPROVED: \_\_\_\_\_  
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

TRIGGER CONNECTOR BROKEN.

COMPLAINT: "WILL NOT STAY COCKED"

INCIDENT: FOLLOWS DOWN

COMMENTS: THE BROKEN CONNECTOR MAKES RETRACTION  
UNDER SEAR UNCONTROLLABLE. THE CONNECTOR  
FAILING TO RETRACT CAUSES FOLLOW DOWN.