

12-22-93

DEAR SIR:

I PURCHASED THE ENCLOSED REM 700
56233971 LAST FALL JUST BEFORE
ELK SEASON. I GOT IT HOME AND
CLEANED IT. WHEN WORKING THE BOLT
SEVERAL TIMES IT DID NOT COCK.
I THOUGHT THAT JUST MAYBE I HI-
THE TRIGGER AND LET IT DOWN. I
WORKED THE BOLT CAREFULLY AB
20 TIMES + THE STRIKER FELL AC-
THINKING THAT IT MIGHT BE HANG-
IN THE STOCK, I REMOVED IT.
RIFLE FAILED TO COCK ON SEVERAL
OCCASIONS. I TOOK IT TO A LOCAL
GUNSMITH, HE CHECKED IT AND IT
FINALLY DID IT FOR HIM. HE WORE
ON IT FOR A COUPLE OF DAYS AND
UP WITHOUT SUCCESS. THIS RIFLE
NEVER BEEN FIRED AND I'M AF-
OF IT. IF IT SHOULD LET DOWN
A LIVE PRIMER IT MIGHT FIRE.
THE EASIEST WAY TO GET IT TO COCK
IS TO HOLD THE TRIGGER AND LET THE
BOLT DOWN. BY RAISING AND THEN LOWER-
ING THE BOLT HANDLE IT SHOULD COCK. 5
TIMES IT DOES AND SOMETIMES IT DON'T
BILL DALLEY TELEPHONE 303-356-0011
4325 WEST 14th ST. ROAD, GREELEY, COLORADO