

11-23-88

Repair Dept. Supervisor,

Enclosed please find my Remington 700 BDL, 30-06 rifle, Serial #A6833899. I purchased it from Herman's Sporting Goods in Paramus N.Y. several years ago. Going back to 1985 I was hunting deer in Pennsylvania and when I shot at a deer the weapon did not go off. It appeared that it did not release the firing pin. After cleaning the weapon I dry fired it & then fired live rounds through it & it fired well. I take very good care of my weapons & do not adjust any of the mechanisms. The very next deer season in 1986 the weapon did not fire at 4 different deer the same day. The weather was very cold, but dry. I use very little Rem oil on it, not to let it build up. I did not hunt in 1987 but used the weapon regularly for varmint hunting. In warm weather there's no problem. ~~Before~~ 1988 New York Deer season (11/22/88 exact date) I brought the weapon to an authorized gunsmith & he cleaned & checked the gun over & stated that he could not find anything wrong with it. On 11-22-88 I went to N.Y. to