

Cash Comp

P.I. 110 GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL

GENERAL CONDITION: GOOD R #: 020932

OUTSIDE WORK: BY ARDEN SPORTS UNLIMITED DATE: 10/13/72

SACRAMENTO, CAL.

FROM: DENNY'S HOME

FIRE AMMO TYPE: - ARBUCKLE, CAL

& CONDITION: _____ GUN #: 6423256

PROOF: R.E.P. ASSEMBLER INSP.: 9 TEST: ST CODE: AU = 3/71

HEADING: O.K. GA./CAL.: 3006

BREECH OPENING: - CHECKED BY: G. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: N/D APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010
(MIN. IS .020) TRIGGER PULL SET TOO LIGHT.

COMPLAINT: SAFETY DOES NOT WORK.

INCIDENT: FOLLOW DOWN

COMMENTS: COMBINATION OF LIGHT TRIGGER PULL, UNDER
MIN. ENGAGEMENT AND TRIGGER BURRS, CAUSED
THE TRIGGER TO STAY IN FIRED POSITION RESULTING
IN FOLLOW DOWN.