

RECEIVING AND ESTIMATING REPORT

INITIALS: **FRS** CUSTOMER ORDER NO.: **66722/92** COMMENTS: **BBL NOT OF OUR MFG** ORDER NO.: **R92-13632**

DATE RECEIVED: **06/22/92** DATE OPENED: **06/23/92** DATE CODE: **PV3 6-79** SERIAL NUMBER: **6200976** NEW SERIAL NUMBER: MODEL AND GRADE: **660 220S**

ACCESSORIES: **W/STUDS** **W/1 SWIVEL**

FROM: **DINUNZIO, WILLIAM**
PQ BOX 1307
SOUTH STREAM ROAD
BENNINGTON VT 05201

SHIP TO: **DINUNZIO, WILLIAM**
PO BOX 1307
SOUTH STREAM ROAD
BENNINGTON VT 05201

CUST NO: **038921 C.O.D.**

ACCOUNT NUMBER: ACCOUNT NUMBER N/C: WRITE CLEAN/TEST PROM. DATE: ESTIMATED: **7-7-92** VIA: **UPS**

GUN CONDITION:
 NEW
 LIGHTLY WORN
 WORN
 VERY WORN
 UNREPAIRABLE
 MARRIED

REPAIR CHARGE:
 EXCISE
 TAX
 INSURANCE
 UPS
 PARCEL POST
 TOTAL

bbl not our mfg

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY		B3			E2	F2
BARREL ASSY		B4		D1	E3	F3
REC. ASSY		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METALS			C2			

fires when safe is released

MAIN FAULT: *Cannot duplicate in my hand - rifle cannot be made to malfunction. However, weight of pull adjustment has been altered outside factory (spring missing from adjustment screw). Weight of pull measured at 8 1/2 pounds.*

Scalift - .012"

ARTS: COMMENTS: *We can either re-adjust present assembly to our specifications, or we can offer to install a new trigger assembly at a normal cost, less rest of good-will if that will better serve you confidence in the rifle.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
<i>FRS</i>					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE