Remington.

QIPIND

REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

August 1, 1990

Mr. Philip R. Donner 2247 Hemlock Ave. San Diego, CA 92154

Dear Mr. Donner:

Your letter of July 14, 1990 that was addressed to our Wilmington, DE facility, advising of the accidental firing you experienced while unloading your Model 700 ADL rifle, serial number A6343780, has been forwarded to this office for handling.

We were indeed sorry to learn of your having a problem of the na-

Generally the type of problem you related results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or from inadvertent contact with the trigger when the safety was in the "fire" position.

Based on the serial number of your rifle, it is not subject to our Model 700 trigger assembly recall. However, we would very much like to have the opportunity to examine your rifle so that we can evaluate the cause of your accident. Additionally, if you do desire the new style trigger assembly that does not lock the bolt closed; this must be installed here at our factory, as it is a restricted part.