

Remington.



bcc: Arms Service
R#87-26054
Return rifle as
received

REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

January 8, 1988

Mr. Roger F. Dula
RT10, Box 505
Lenoir, NC 28645

Dear Mr. Dula:

Examination has been completed on the Model 700 BDL 243 Win caliber rifle, serial number B6771944, which you returned to us because of the accidental firings you experienced.

The returned firearm, which was produced in February of 1986, was found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to shipment from our factory.

The general condition of the gun appeared to be very good, and in going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal. The bolt stop was found to stick sometimes, however, this condition has no connection to the reported malfunction and can easily be corrected.

Examination of the rifle and trigger assembly could not duplicate the malfunction that was reported. All dimensions and tolerances were found to be normal. Also, factory seals were intact on the trigger adjustment screws, indicating no alterations were made to the trigger adjustments outside our factory.