

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 92-00059

INITIAL JJM	CUSTOMER ORDER NO.	COMMENTS			
DATE RECEIVED 12/20/91	DATE OPENED 01/02/92	DATE CODE ET 10-70	SERIAL NUMBER 6376910	NEW SERIAL NUMBER	MODEL AND GRADE 700 7MMAG ADL
ACCESSORIES W/STUDS		SCOPE BASE			

FROM:	SHIP TO:
EAST, JOHN C/O ERRECA'S INC 8555 PARADISE VALLEY RD SPRING VALLEY, CA 91977 USA	EAST, JOHN C/O ERRECA'S INC 8555 PARADISE VALLEY RD SPRING VALLEY, CA 91977 USA
CUST NO: 055444 C-D.DL	

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED	VIA UPS
WRITE <input type="checkbox"/> CLEAN/TEST				
GUN CONDITION	[REPAIR CHARGE]			REPAIR CHARGE
<input type="checkbox"/> NEW				EXCISE
<input type="checkbox"/> LIGHTLY WORN				TAX
<input type="checkbox"/> WORN				INSURANCE
<input type="checkbox"/> VERY WORN				UPS
<input checked="" type="checkbox"/> UNREPAIRABLE				PARCEL POST
		TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

When you lift bolt to eject shell, it will fire - happened three times - started jamming

MAIN FAULT *Cannot duplicate reported complaint - however, trigger assembly has been adjusted without failure, as evidenced by adjustment made from adjustment screw - trigger pull measured at 2 3/4 pounds - this is below our maximum of 3 lbs. Inspecting trigger assembly contained a black greasy substance also.*

Trigger pull 2 3/4 pounds - near left 1007"

COMMENTS *Offer to clean and readjust present trigger assembly, or, we can install a new trigger assembly at \$ normal cost as a gesture of good will. If this will permit a star complaint in the field.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY/TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY