

January 9, 1988

Peron Einkauf
2417 Highway 36 N.
Sealy, Texas 77474

Remington Arms Co.
14 Hoefler Ave.
Ilion, NY 13357

Attn: Mr. St. John

I talked to you on the phone about the results of the flaw in my rifle and you instructed me to return it to you U.P.S. with full explanation as follows:

On January 3, 1988 I fired my Mohawk-600 (A6530928), bolted another load (Remington R308W1-150 grain core-LOKT soft PT) and tried to fired again. There was no action so I raised the bolt and noticed the back of the bolt didn't stay cocked over the firing pin. After working the safety the bolt stayed cocked, but after putting the safety on with a live round in the chamber I pushed the safety forward to the off position and the rifle discharged.

By this time I was sitting inside the warmth of my Dad's pick-up when my inspection of the gun turned into this near catastrophe. My boot wasn't hurt bad, by thumb on my right hand was bleeding and numb, and there was a hole in the floor board.

Dad asked if I was hurt, then said "let's see if we can get home.". We had all the gears in the four speed transmission but oil was splashing through the hole. I put a glove over the hole and slowed the loss of the gear lube, We made it home - this was my birthday.

Attached is a copy of the bill for fixing the transmission.

I paid the U.P.S. postage for returning the gun which I assume you will re-imburse me.

Sincerely,

Peron Einkauf