

REPAIR GUN INQUIRY FUNCTION: E (N)EXT (P)REV (I)NO (E)NACT 04/04/91
ENTER REPAIR NUMBER -----> 9024787 13 11 59

120272 MODEL: 660
FROM: (CUST NUM: 030234) ANDERSON GA/CAL: 06.5 MM
ANDERSON HAROLD TYPE: LS
PO BOX 171 ACCESSORIES: W/STUDS
100 ELDER RD

MANCELONA MI 49659

SHIPPED TO:

ANDERSON HAROLD

PO BOX 171

100 ELDER RD

MANCELONA

MI 49659

COMMENTS: ATTN JIM STEKL

DATE CODES: OR 7-68

OTHER ACCESSORIES:

DATES:

RECEIVED 09 14 90

OPENED 09 26 90

ESTIMATED 10 01 90

PROMISED 00 00 00

REPAIRED 00 00 00

SHIPPED 10 16 90

TO

FROM

GALLERY 09 28 90 10 15 90

PROD SERV 00 00 00 09 27 90

TAG GUNS 00 00

REJECTED 00 00

CASH RECEIVED:\$ 0.00

ENTERED BY: FJB

REPAIRMAN: BW

TYPIST:

CORRESPONDENT:

BILL TYPE N/C

PF1 = VIEW DETAIL

REPAIR NUMBER: 9024787 NO CHARGE

EST/LETTER LSTD

04/04/91

CUSTOMER NAME: ANDERSON HAROLD

13 12 46

REQUEST: SEE ATTACHED LETTER.

MAIN FAULT: TRIGGER ASSEMBLY CONTAMINATED WITH GUMMY RESIDUE; INTERNAL
PARTS NOT MOVING FREELY - SEAR SAFETY CAM IS STUCK TO
ASSEMBLY SIDE PLATES.

PARTS: \$ 0.00 1 91469 TRIGGER HOUSING ASSEM

LABOR: \$ 0.00 THIS GUN SUBJECT TO M/600 RECALL - STILL HAS ORIGINAL

\$ 0.00 TRIGGER ASSEMBLY.

\$ 0.00 INSTALL NEW TRIGGER ASSEMBLY AT N/C UNDER RECALL.

\$ 0.00 TEST.

TOTAL VALUE:\$ 0.00

CLEAR = RETURN

NO MORE DATA AVAILABLE FOR THIS REPAIR