

# RECEIVING AND ESTIMATING REPORT

COMMENTS <b>ATT. J. KAST</b>					
INITIAL	CUSTOMER ORDER NO.				
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
09/14/88	09/22/88	XF 12-B5	B6762876	700 286 MTN	R 88-2A918
ACCESSORIES W/STUDS		SCOPE BASE			

FROM: EMERSON AND SON, INC. 28 STATE ST. GROVETON, N.H. 03582	SHIP TO: EMERSON AND SON, INC. 28 STATE ST. GROVETON, N.H. 03582
--	---

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	FROM DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	-----------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

**GUN CONDITION:**     NEW     SLIGHTLY WORN     VERY WORN     MISUSED     MARRED

*Customer's Request: Trigger does not return after every shot and consequently on the following round the gun would discharge upon moving the safety to the fire position.*

*Main Fault: Trigger has been removed from fire control assembly and improperly replaced outside of factory, causing a bind in the housing. (2) trigger adjustment and external screws have also been improperly adjusted outside of factory.*

*Parts: Based upon Dealer comments about gun in service in attached correspondence, replace trigger assembly at no-charge.*

*9/22/88  
Jds*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY