

EMERSON AND SON, INC.

28 STATE STREET

GROVETON, N.H. 03582

(603) 636-1220

DATE 9/13/88

TO Remington Arms Co
Service Dept
Ilion, NY 13357

SUBJECT Faulty trigger
mechanism
(Recall)

Dear Sirs,

Enclosed is a Model 700 Mtn. Rifle
280 Cal. Serial #86762876. According to
the owner, he nearly shot his friend on
one occasion, and himself on another
due to the faulty trigger mechanism
on the rifle - needless to say, he's
bullshit about it! Upon inspection of
the trigger mechanism I found that the
trigger does not return after every shot
and consequently on the following round,
the gun would discharge upon moving.

FORM 6-87 • DISTRIBUTED BY BULL CORPORATION • 100 S. SCHLEIER ROAD • LINCOLNSHIRE, ILLINOIS 60069