

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R92-10723

ITAL	CUSTOMER ORDER NO.	L/FLOOR PLATE, SCREWS				
S	E53974					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE	VAR
1/20/92	04/28/92	PB 6-B1	B6320340		700 7MM-08	
ACCESSORIES	L/MAG BOX	L/WOOD	L/FOLLOWER	L/MAG SPRING	SCOPE BASE	

FROM:	SHIP TO:
ENGLISHTOWN SPTG GOODS CO	ENGLISHTOWN SPTG GOODS CO
38 MAIN ST	38 MAIN ST
ENGLISHTOWN	ENGLISHTOWN
NJ 07726	NJ 07726

CUST NO: 003483 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
263103		☐			5-19-92	UPS

IN CONDITION	REPAIR CHARGE
NEW	EXCISE
LIGHTLY WORN	TAX
WORN	INSURANCE
VERY WORN	UPS
UNREPAIRABLE	PARCEL POST
MARRED	TOTAL

Quote

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
TRIGGER GROUP	A1	B1			E1	F1
TRIGGER ASSY		B2			E2	F2
TRIGGER ASSY		B3			E3	F3
TRIGGER ASSY		B4		D1	E4	F4
TRIGGER ASSY		B5		D2	E5	F5
TRIGGER ASSY			C1	D3		
TRIGGER ASSY			C2			

IN FAULT

Trigger Assy adjusted outside factory, unable to readjust. Trigger assembly has been adjusted to prevent firing pin from falling when trigger is pulled - no over-travel at all. Cannot duplicate complaint as rifle will not fire at all.

RT	COMMENTS
26345 Trigger Assy.	Quote for new trigger assembly at 1/2 normal cost, as guarantee of good-will. Warn customer about adjusting trigger.
	Test w/ spare parts.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
DE			☒		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PPS 01641