

RECEIVING AND ESTIMATING REPORT

DATE RECEIVED		DATE OPENED		DATE CODE		SERIAL NUMBER		MOORE AND GRADE		ORDER NUMBER	
08/18/98		08/19/98		0047-7871		A4482657		701 220		BDL	
HUNT/STUDS		SCOPE BASE		5		L/SIGHTS					
FROM						SHIP TO:					
FARRINGTON, ROBERT 3626 LAKE PONTCHORTRAIN ARLINGTON TX 76016						FARRINGTON, ROBERT 3626 LAKE PONTCHORTRAIN ARLINGTON TX 76016					
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		WRITE		PROML DATE		ESTIMATED		MIA	
										UPS	
REPAIR CHARGE		TAX		INSURANCE		UPS		PARCEL POST		TOTAL	
GUN CONDITION:		☐ NEW		☒ SLIGHTLY WORN		☐ VERY WORN		☐ MISUSED		☒ MARRED	
CUSTOMER'S REQUEST											
MAIN FAULT		<i>"The gun discharged when the safety was released"</i> <i>Could not duplicate complaint. However, trigger pull felt like a gun spec. at 2 3/4 # and also tried out of spec also (excessive) 2 ear lift .0105". Bolt stop has accumulation of dirt oil and sludge sometimes.</i>									
PARTS		<i>Offer to either re-adjust present trigger assembly back into specification or, if it will better restore confidence in upb, we can install a new trigger assembly, at no charge, as a gesture of good-will.</i> <i>Either option is subject to handling plus return shipping charges/25/00 Jts.</i>									
REPAIRMAN		PROOF		CLEAN		TEST		TARGET		PATTERN	
GALLERY TESTER		DATE		DATE		DATE		DATE		DATE	

RD6925 REV. 6/88