

November 15, 1986

R. H. Potter, Supervisor  
Product Service  
Remington Arms Co., Inc.  
Ilion, New York 13357

Dear Mr. Potter,

Enclosed is my Remington Mohawk 600 ser. # A6390843 as requested.

Since my letter of October 27, 1986 regarding the accidental firing of the above rifle it has come to my attention that Remington recalled many Model 600 triggers due to a product defect. The safety, trigger and bolt being interrelated sheds a new light on the responsibility of Remington. It is my firm belief that the manufacturer in this case bears responsibility for the damages due to its recall of the Model 600 trigger assemblies, which admittedly could cause a misfire.


At this time I have not had my truck repaired and thus do not have a bill. This is because the parts have not come to the dealer as yet. As for the gun I find it very handy in the brush and accurate. I doubt I will ever have complete confidence in it again.

I would prefer this situation be resolved in the following manner:

- (1) Replace my 600 with a comparable gun (model seven—308 Winchester)
- (2) Reimbursement of parts and labor, only; to repair my truck from bullet damages.

I do thank you for your prompt attention and concern in regard to this matter.

Sincerely,



Charles E. Fenner, III