

Five Points Sport Shop, Inc.

P. O. Box 132

ROUTE 512 — BANGOR, PENNSYLVANIA 18013

215-588-4143

Remington Arms:

GUN FIRES when safety mechanism
is disengaged, before trigger function
is employed. This happened when
RIFLE was still in manufacturers condition,
CAUSING A discharge in the buyers home.
PLEASE REPAIR. IF ANY CHARGE notify:

John L. Zeruth, mgr.
Five Points Sport Shop.
 mgr.