



FOOTHILLS SHOOTING CENTER

7860 W. JEWELL AVE. / LAKEWOOD, COLORADO 80226 / PHONE (303) 985-4417

November 9, 1990

Mr. Fred D. Emhof
Sr Field Service Representative
Remington Arms Co, Inc.
14 Hoefler Avenue
Ilion, NY 13357

Dear Fred:

Enclosed is the rifle I spoke to you about on November 8, 1990.
(Remington 700 BDL, 30/06, SN 674-8705).

The gun came into the shop because the stricker was following when the bolt was closed. I disassembled the action from the stock and thoroughly cleaned the bolt release and trigger assembly, using a solvent that does an excellent job on this type of repair. I checked the gun thoroughly upon completion of the work.

The customer went downstairs to our rifle range and fired a minimum of thirteen shots with no problem. She got out of the shooting position with the bolt closed. My range officer stepped over to ask her to open the bolt and the rifle fired at that time. The customer claims the gun fired by itself. She sustained a cut on the web between her index finger and middle finger of her right hand. This leads me to believe she had her finger on the trigger, firing the gun herself.

If you would give the piece a thorough exam for defects, I would very much appreciate it.

Thank You,

Anthony Didamo

Anthony "Tony" Didamo
President