

*Carl Conyers*

P.I. NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700 ADL

GENERAL CONDITION: NEW R #: 003187

OUTSIDE WORK: NO DATE: 1-30-73

FROM: J. FOSTER

FIRED AMMO TYPE: - LYNCHBURG, VA.

& CONDITION: \_\_\_\_\_ GUN #: 6326074

PROOF: R.E.P.-A INSP.: 9 TEST: 55 CODE: CT = 4/70

HEADING: O.K. GA./CAL.: 25-06

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_

CHAMBER: O.K. APPROVED: \_\_\_\_\_

TEST: NO APPROVED: \_\_\_\_\_

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

CONNECTOR-TRIGGER CLEARANCE = 1.084 (MODEL 1.080 DRAWING 1.083) TRIGGER-CONNECTOR CLEARANCE = 1.072 (1.076) CENTER LINE OF PIN HOLE TO TOP OF TRIGGER = .974 (973) CENTER OF PIVOT HOLE IN SAFETY TO TOP OF CAM = .291 (1.292) (1.296)

COMPLAINT: "FIRED WITH SAFETY ON"

INCIDENT: FOLLOW DOWN

COMMENTS: THE RIFLE WILL NOT FIRE WITH THE SAFETY ON. THE CONDITIONS LISTED ABOVE: .005 TOO MUCH CLEARANCE BETWEEN CONNECTOR & TRIGGER, TOP OF TRIGGER .001 OVER MAX. AND SAFETY .001 UNDER MIN., ALL CONTRIBUTE TO AN INTERFERANCE BETWEEN THE CONNECTOR AND SEAR WHICH WOULD PREVENT RETRACTION INTO COCKED POSITION TO CAUSE FOLLOW DOWN.