

RECEIVING AND ESTIMATING REPORT

COMMENTS
ATTN K. GREEN

INITIAL JJM	CUSTOMER ORDER NO.				
DATE RECEIVED 10/30/90	DATE OPENED 10/31/90	DATE CODE PI 6-88	SERIAL NUMBER C6265415	MODEL AND GRADE 700 7HMMAG BDL	ORDER R 90-2865
ACCESSORIES W/STUBS					

FROM:

BURNS, JOHNNY 3336 COUNTRY CLUB DR CHARLOTTE, NC 28205	SHIP TO: BURNS, JOHNNY 3336 COUNTRY CLUB DR CHARLOTTE, NC 28205
--	--

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

↓ J. P. FOSTER
5018 CARILION DR.
CHARLOTTE, NC 28226

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
GUN CONDITION: <input checked="" type="checkbox"/> LIKE NEW <input type="checkbox"/> SLIGHTLY WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> MISUSED <input type="checkbox"/> MARRED CUSTOMER'S REQUEST					

"GUN FIRED WHEN SAFETY WAS PUSHED OFF"

MAIN FAULT: Trigger assembly rusted from unknown source. Internal parts not moving properly.

Note: found rusty at previous point location and, rear guard seems rusty. Appears rifle was wet at some time & not properly maintained.

PARTS: Per J. Foster (Sales Rep) instructions, rifle to be return shipped to him via U.P.S. NEXT DAY

Repair trigger assembly at no charge as gesture of good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE